LOCATIONAL IDENTIFIER ADDRESS	LOCATIONAL IDENTIFIER STREET NAME	LOCATIONAL IDENTIFIER UNIT OR SUITE #	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
3546	AERTS LANE			P	N	1"		P			SF						Field inspection only	Y			Field inspection only	Y		Visual insp during install or repair	
3490	AERTS LANE			C	N	3/4"		C	3/4"		SF						Field inspection only	Y			Installation record	N			
3492	AERTS LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y			Installation record	N			
3520	AERTS LANE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
3534	AERTS LANE			C	N	3/4"		P	1"		SF						Installation record	Y			Installation record	N			
3491	AERTS LANE			C	N	3/4"		P	1"		SF						Installation record	Y			Installation record	N			
3505	AERTS LANE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
3535	AERTS LANE			P	N	1"		P			SF						Field inspection only	Y			Field inspection only	Y		Visual insp during install or repair	
320	Aldon Circle			P	N	1"		P			SF						Installation record	Y			Field inspection only	Y		Visual insp during install or repair	
324	Aldon Circle			P	N	1"		P			SF						Installation record	Y			Field inspection only	Y		Visual insp during install or repair	
466	Aldon Circle			P	N	1"		P			SF						Installation record	Y			Field inspection only	Y		Visual insp during install or repair	
470	Aldon Circle			P	N	1"		P			SF						Installation record	Y			Field inspection only	Y		Visual insp during install or repair	
474	Aldon Circle			P	N	1"		P			SF						Installation record	Y			Field inspection only	Y		Visual insp during install or repair	
478	Aldon Circle			P	N	1"		P			SF						Installation record	Y			Field inspection only	Y		Visual insp during install or repair	
375	Aldon Circle			P	N	1"		P			SF						Installation record	Y			Field inspection only	Y		Visual insp during install or repair	
379	Aldon Circle			P	N	1"		P			SF						Installation record	Y			Field inspection only	Y		Visual insp during install or repair	
352	Aldon Circle			P	N	1"		P			SF						Installation record	Y			Field inspection only	Y		Visual insp during install or repair	
355	Aldon Circle			P	N	1"		P			SF						Installation record	Y			Field inspection only	Y		Visual insp during install or repair	
335	Aldon Circle			P	N	1"		P			SF						Installation record	Y			Field inspection only	Y		Visual insp during install or repair	
348	Aldon Circle			P	N	1"		P			SF						Installation record	Y			Field inspection only	Y		Visual insp during install or repair	
383	Aldon Circle			P	N	1"		P			SF						Installation record	Y			Field inspection only	Y		Visual insp during install or repair	
387	Aldon Circle			P	N	1"		P			SF						Installation record	Y			Field inspection only	Y		Visual insp during install or repair	
366	Aldon Circle			P	N	1"		P			SF						Installation record	Y			Field inspection only	Y		Visual insp during install or repair	
363	Aldon Circle			P	N	1"		P			SF						Installation record	Y			Field inspection only	Y		Visual insp during install or repair	
382	Aldon Circle			P	N	1"		P			SF						Installation record	Y			Field inspection only	Y		Visual insp during install or repair	
391	Aldon Circle			P	N	1"		P			SF						Installation record	Y			Field inspection only	Y		Visual insp during install or repair	
395	Aldon Circle			P	N	1"		P			SF						Installation record	Y			Field inspection only	Y		Visual insp during install or repair	
355	Aldon Circle			P	N	1"		P			SF						Installation record	Y			Field inspection only	Y		Visual insp during install or repair	
359	Aldon Circle			P	N	1"		P			SF						Installation record	Y			Field inspection only	Y		Visual insp during install or repair	
390	Aldon Circle			P	N	1"		P			SF						Installation record	Y			Field inspection only	Y		Visual insp during install or repair	
367	Aldon Circle			P	N	1"		P			SF						Installation record	Y			Field inspection only	Y		Visual insp during install or repair	
399	Aldon Circle			P	N	1"		P			SF						Installation record	Y			Field inspection only	Y		Visual insp during install or repair	
403	Aldon Circle			P	N	1"		P			SF						Installation record	Y			Field inspection only	Y		Visual insp during install or repair	
347	Aldon Circle			P	N	1"		P			SF						Installation record	Y			Field inspection only	Y		Visual insp during install or repair	
339	Aldon Circle			P	N	1"		P			SF						Installation record	Y			Field inspection only	Y		Visual insp during install or repair	
331	Aldon Circle			P	N	1"		P			SF						Installation record	Y			Field inspection only	Y		Visual insp during install or repair	
343	Aldon Circle			P	N	1"		P			SF						Installation record	Y			Field inspection only	Y		Visual insp during install or repair	
340	Aldon Circle			P	N	1"		P			SF						Installation record	Y			Field inspection only	Y		Visual insp during install or repair	
344	Aldon Circle			P	N	1"		P			SF						Installation record	Y			Field inspection only	Y		Visual insp during install or repair	
434	Aldon Circle			P	N	1"		P			SF						Installation record	Y			Field inspection only	Y		Visual insp during install or repair	
430	Aldon Circle			P	N	1"		P			SF						Installation record	Y			Field inspection only	Y		Visual insp during install or repair	
442	Aldon Circle			P	N	1"		P			SF						Installation record	Y			Field inspection only	Y		Visual insp during install or repair	
438	Aldon Circle			P	N	1"		P			SF						Installation record	Y			Field inspection only	Y		Visual insp during install or repair	
300	Aldon Circle			P	N	1"		P			SF						Installation record	Y			Field inspection only	Y		Visual insp during install or repair	
450	Aldon Circle			P	N	1"		P			SF						Installation record	Y			Field inspection only	Y		Visual insp during install or repair	
446	Aldon Circle			P	N	1"		P			SF						Installation record	Y			Field inspection only	Y		Visual insp during install or repair	
458	Aldon Circle			P	N	1"		P			SF						Installation record	Y			Field inspection only	Y		Visual insp during install or repair	
454	Aldon Circle			P	N	1"		P			SF						Installation record	Y			Field inspection only	Y		Visual insp during install or repair	
304	Aldon Circle			P	N	1"		P			SF						Installation record	Y			Field inspection only	Y		Visual insp during install or repair	
323	Aldon Circle			P	N	1"		P			SF						Installation record	Y			Field inspection only	Y		Visual insp during install or repair	
327	Aldon Circle			P	N	1"		P			SF						Installation record	Y			Field inspection only	Y		Visual insp during install or repair	
351	Aldon Circle			P	N	1"		P			SF						Installation record	Y			Field inspection only	Y		Visual insp during install or repair	
396	Aldon Circle			P	N	1"		P			SF						Installation record	Y			Field inspection only	Y		Visual insp during install or repair	
1205	ALICE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1217	ALICE DRIVE			C	N	3/4"		C	3/4"		SF						Installation record	N			Installation record	N			
1210	ALICE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1256	ALICE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1178	ALICE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1255	ALICE DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1249	ALICE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1166	ALICE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1281	ALICE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1275	ALICE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1269	ALICE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1263	ALICE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1243	ALICE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1211	ALICE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1199	ALICE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1193	ALICE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1185	ALICE DRIVE			C	N	3/4"		C	1"		SF						Installation record	N			Installation record	N			
1179	ALICE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1173	ALICE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1167	ALICE DRIVE			C	N	3/4"		C			SF						Installation record	Y			Installation record	Y		Visual insp during install or repair	
1161	ALICE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1160	ALICE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1172	ALICE DRIVE			C	N	3/4"		C	3/4"		SF						Installation record	N			Installation record	N			
1184	ALICE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1192	ALICE DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1198	ALICE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1204	ALICE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1216	ALICE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1242	ALICE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1248	ALICE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1262	ALICE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1268	ALICE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			

LOCATIONAL IDENTIFIER ADDRESS	LOCATIONAL IDENTIFIER STREET NAME	LOCATIONAL IDENTIFIER UNIT OR SUITE #	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
1274	ALICE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1280	ALICE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1286	ALICE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1294	ALICE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1293	ALICE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1287	ALICE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
977	ANDERSON DRIVE			C	N	1"		C			MF						Installation record	N			Installation record	N			
973	ANDERSON DRIVE			C	N	1"		C			MF						Installation record	N			Installation record	N			
967	ANDERSON DRIVE			C	N	1"		C			MF						Installation record	N			Installation record	N			
965	ANDERSON DRIVE			C	N	1"		C			MF						Installation record	N			Installation record	N			
953	ANDERSON DRIVE			C	N	1"		C			MF						Installation record	N			Installation record	N			
949	ANDERSON DRIVE			C	N	1"		C			MF						Installation record	N			Installation record	N			
1269	APACHE AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1570	APACHE AVENUE			P	N	1"		P			SF						SL repair/replace record	Y			Field inspection only	Y			
1255	APACHE AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installed after lead ban	N			
1475	APACHE AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installed after lead ban	N			
1254	APACHE AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installed after lead ban	N			
1497	APACHE AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installed after lead ban	N			
1410	APACHE AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installed after lead ban	N			
1295	APACHE AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installed after lead ban	N			
1445	APACHE AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installed after lead ban	N			
1411	APACHE AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installed after lead ban	N			
1590	APACHE AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installed after lead ban	N			
1294	APACHE AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installed after lead ban	N			
1508	APACHE AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installed after lead ban	N			
1452	APACHE AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installed after lead ban	N			
1426	APACHE AVENUE			C	N	3/4"		C	1"		SF						Installation record	Y			Installed after lead ban	N			
1483	APACHE AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installed after lead ban	N			
1287	APACHE AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installed after lead ban	N			
1514	APACHE AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installed after lead ban	N			
1599	APACHE AVENUE			C	N	1"		P			SF						Installation record	Y			Installed after lead ban	N			
1602	APACHE AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installed after lead ban	N			
1596	APACHE AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installed after lead ban	N			
1582	APACHE AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installed after lead ban	N			
1576	APACHE AVENUE			C	N	1"		C			SF						Installation record	Y			Installed after lead ban	N			
1560	APACHE AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installed after lead ban	N			
1556	APACHE AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installed after lead ban	N			
1552	APACHE AVENUE			C	N	3/4"		P			SF						Installation record	Y			Installed after lead ban	N			
1540	APACHE AVENUE			C	N	1"		C			SF						Installation record	Y			Installed after lead ban	N			
1561	APACHE AVENUE			C	N	1"		C			SF						Installation record	Y			Installed after lead ban	N			
1565	APACHE AVENUE			C	N	1"		C			SF						Installation record	Y			Installed after lead ban	N			
1571	APACHE AVENUE			C	N	1"		C			SF						Installation record	Y			Installed after lead ban	N			
1579	APACHE AVENUE			C	N	1"		C			SF						Installation record	Y			Installed after lead ban	N			
1585	APACHE AVENUE			C	N	1"		C			SF						Installation record	Y			Installed after lead ban	N			
1591	APACHE AVENUE			C	N	1"		C			SF						Installation record	Y			Installed after lead ban	N			
1605	APACHE AVENUE			C	N	1"		C			SF						Installation record	Y			Installed after lead ban	N			
1392	APACHE AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1404	APACHE AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1416	APACHE AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1420	APACHE AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1432	APACHE AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1442	APACHE AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1446	APACHE AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	Y			Installation record	N			
1474	APACHE AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1482	APACHE AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1490	APACHE AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1496	APACHE AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1502	APACHE AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1520	APACHE AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1526	APACHE AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1527	APACHE AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1523	APACHE AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1515	APACHE AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1509	APACHE AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1505	APACHE AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1491	APACHE AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1451	APACHE AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1439	APACHE AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1431	APACHE AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1425	APACHE AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1417	APACHE AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1403	APACHE AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1397	APACHE AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1248	APACHE AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1260	APACHE AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1266	APACHE AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1274	APACHE AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1280	APACHE AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1286	APACHE AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1281	APACHE AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1275	APACHE AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1261	APACHE AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1249	APACHE AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1174	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1126	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			

LOCATIONAL IDENTIFIER ADDRESS	LOCATIONAL IDENTIFIER STREET NAME	LOCATIONAL IDENTIFIER UNIT OR SUITE #	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
1243	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1135	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1114	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1127	APRIL LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y			Installation record	N			
1194	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1306	APRIL LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y			Installation record	N			
1261	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1179	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1268	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1281	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1288	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1086	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1269	APRIL LANE			C	N	3/4"		C	1"		SF						Installation record	Y			Installation record	N			
1249	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1202	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1321	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1120	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1095	APRIL LANE			C	N	3/4"		C	1"		SF						Installation record	Y			Installation record	N			
1199	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1280	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1300	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1121	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1107	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1254	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1275	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1255	APRIL LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y			Installation record	N			
1087	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1210	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1315	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1205	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1260	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1173	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1115	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1101	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1216	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1289	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Field inspection only	Y			
1217	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1134	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1167	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1100	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1188	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1248	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1295	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1193	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1072	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Field inspection only	Y			Cross-connection survey
1166	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1274	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1081	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Field inspection only	Y			Cross-connection survey
1180	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1211	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Field inspection only	Y			Cross-connection survey
1307	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1320	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1314	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1242	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1301	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Field inspection only	Y			Cross-connection survey
1073	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1106	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1294	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1185	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1067	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1060	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Field inspection only	Y			Cross-connection survey
1062	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Field inspection only	Y			Cross-connection survey
1066	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1080	APRIL LANE			C	N	3/4"		C	1"		SF						Installation record	Y			Installation record	N			
1094	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1160	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1326	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Field inspection only	Y			Cross-connection survey
2025	ARGONNE STREET			C	N	3/4"		C			SF						Installation record	Y			Field inspection only	Y			Cross-connection survey
1961	ARGONNE STREET			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1985	ARGONNE STREET			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1993	ARGONNE STREET			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1995	ARGONNE STREET			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2011	ARGONNE STREET			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2039	ARGONNE STREET			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2041	ARGONNE STREET			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2051	ARGONNE STREET			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2049	ARGONNE STREET			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2073	ARGONNE STREET			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
3011	ASHBROOKE COURT			P	N	1"		P			SF						Installation record	N			Installed after lead ban	Y			Visual insp during install or repair
3003	ASHBROOKE COURT			P	N	1"		P			SF						Installation record	N			Installed after lead ban	Y			Visual insp during install or repair
3008	ASHBROOKE COURT			P	N	1"		P			SF						Installation record	N			Installed after lead ban	Y			Visual insp during install or repair
3016	ASHBROOKE COURT			P	N	1"		P	1"		SF						Installation record	N			Installed after lead ban	Y			Visual insp during install or repair
1508	ASHLEY COURT			C	N	1"		C			SF						Installation record	N	1986		Field inspection only	Y			Cross-connection survey
1486	ASHLEY COURT			C	N	1"		C			SF						Installation record	N	1986		Installation record	N			
1494	ASHLEY COURT			C	N	1"		C			SF						Installation record	N	1986		Field inspection only	Y			Cross-connection survey

LOCATIONAL IDENTIFIER ADDRESS	LOCATIONAL IDENTIFIER STREET NAME	LOCATIONAL IDENTIFIER UNIT OR SUITE #	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
1515	ASHLEY COURT			C	N	1"		C			SF						Installation record	N	1986		Installation record	N			
1520	ASHLEY COURT			C	N	1"		C			SF						Installation record	N	1986		Field inspection only	Y		Cross-connection survey	
1477	ASHLEY COURT			C	N	1"		C			SF						Installation record	N	1986		Installation record	N			
1485	ASHLEY COURT			C	N	1"		C			SF						Installation record	N	1986		Field inspection only	Y		Cross-connection survey	
1495	ASHLEY COURT			C	N	1"		C			SF						Installation record	N	1986		Installation record	N			
1505	ASHLEY COURT			C	N	1"		C			SF						Installation record	N	1986		Field inspection only	Y		Cross-connection survey	
1525	ASHLEY COURT			C	N	1"		C			SF						Installation record	N	1986		Installation record	N			
1529	ASHLEY COURT			C	N	1"		C			SF						Installation record	N	1986		Field inspection only	Y		Cross-connection survey	
1514	ASHLEY COURT			C	N	1"		C			SF						Installation record	N	1986		Field inspection only	Y		Cross-connection survey	
1476	ASHLEY COURT			C	N	1"		C			SF						Installation record	N	1986		Installation record	N			
1000	ASTER COURT			P	N	1"		P			SF						Installation record	Y			Installed after lead ban	Y		Visual insp during install or repair	
1024	ASTER COURT			P	N	1"		P			SF						Installation record	Y			Installed after lead ban	Y		Visual insp during install or repair	
1008	ASTER COURT			P	N	1"		P			SF						Installation record	Y			Installed after lead ban	Y		Visual insp during install or repair	
1016	ASTER COURT			P	N	1"		P			SF						Installation record	Y			Installed after lead ban	Y		Visual insp during install or repair	
992	ASTER COURT			P	N	1"		P			SF						Installation record	Y			Installed after lead ban	Y		Visual insp during install or repair	
999	ASTER COURT			P	N	1"		P			SF						Installation record	Y			Installed after lead ban	Y		Visual insp during install or repair	
1015	ASTER COURT			P	N	1"		P			SF						Installation record	Y			Installed after lead ban	Y		Visual insp during install or repair	
1007	ASTER COURT			P	N	1"		P			SF						Installation record	Y			Installed after lead ban	Y		Visual insp during install or repair	
1023	ASTER COURT			P	N	1"		P			SF						Installation record	Y			Installed after lead ban	Y		Visual insp during install or repair	
1040	ASTER COURT			P	N	1"		P			SF						Installation record	Y			Installed after lead ban	Y		Visual insp during install or repair	
2043	AUTUMN LEAVES CIRCLE			C	N	1"		C			SF						Installed after lead ban	Y	1987		Installed after lead ban	N			
3013	AUTUMN LEAVES CIRCLE			C	N	1"		C			SF						Installed after lead ban	Y	1987		Installed after lead ban	N			
3007	AUTUMN LEAVES CIRCLE			C	N	1"		C			SF						Installed after lead ban	Y	1987		Installed after lead ban	N			
2088	AUTUMN LEAVES CIRCLE			C	N	1"		C			SF						Installed after lead ban	Y	1987		Field inspection only	Y		Cross-connection survey	
2050	AUTUMN LEAVES CIRCLE			C	N	1"		C			SF						Installed after lead ban	Y	1987		Field inspection only	Y		Cross-connection survey	
2094	AUTUMN LEAVES CIRCLE			C	N	1"		C			SF						Installed after lead ban	Y	1987		Installed after lead ban	N			
3032	AUTUMN LEAVES CIRCLE			C	N	1"		C			SF						Installed after lead ban	Y	1987		Installed after lead ban	N			
3012	AUTUMN LEAVES CIRCLE			C	N	1"		C			SF						Installed after lead ban	Y	1987		Installed after lead ban	N			
2074	AUTUMN LEAVES CIRCLE			C	N	1"		C			SF						Installed after lead ban	Y	1987		Installed after lead ban	N			
2083	AUTUMN LEAVES CIRCLE			C	N	1"		C			SF						Installed after lead ban	Y	1987		Installed after lead ban	N			
2046	AUTUMN LEAVES CIRCLE			C	N	1"		C			SF						Installed after lead ban	Y	1987		Field inspection only	Y		Cross-connection survey	
2060	AUTUMN LEAVES CIRCLE			C	N	1"		C			SF						Installed after lead ban	Y	1987		Installed after lead ban	N			
2066	AUTUMN LEAVES CIRCLE			C	N	1"		C			SF						Installed after lead ban	Y	1987		Field inspection only	Y		Cross-connection survey	
2080	AUTUMN LEAVES CIRCLE			C	N	1"		C			SF						Installed after lead ban	Y	1987		Installed after lead ban	N			
3000	AUTUMN LEAVES CIRCLE			C	N	1"		C			SF						Installed after lead ban	Y	1987		Installed after lead ban	N			
3017	AUTUMN LEAVES CIRCLE			C	N	1"		C			SF						Installed after lead ban	Y	1987		Field inspection only	Y		Cross-connection survey	
3027	AUTUMN LEAVES CIRCLE			C	N	1"		C			SF						Installed after lead ban	Y	1987		Installed after lead ban	N			
3022	AUTUMN LEAVES CIRCLE			C	N	1"		C			SF						Installed after lead ban	Y	1987		Installed after lead ban	N			
2077	AUTUMN LEAVES CIRCLE			C	N	1"		C			SF						Installed after lead ban	Y	1987		Installed after lead ban	N			
2071	AUTUMN LEAVES CIRCLE			C	N	1"		C			SF						Installed after lead ban	Y	1987		Installed after lead ban	N			
2055	AUTUMN LEAVES CIRCLE			C	N	1"		C			SF						Installed after lead ban	Y	1987		Installed after lead ban	N			
2047	AUTUMN LEAVES CIRCLE			C	N	1"		C			SF						Installed after lead ban	Y	1987		Installed after lead ban	N			
1366	AVONDALE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1446	AVONDALE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1415	AVONDALE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1530	AVONDALE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1498	AVONDALE DRIVE			C	N	3/4"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1501	AVONDALE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1416	AVONDALE DRIVE			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1517	AVONDALE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1462	AVONDALE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1538	AVONDALE DRIVE			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1409	AVONDALE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1485	AVONDALE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1475	AVONDALE DRIVE			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1465	AVONDALE DRIVE			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1455	AVONDALE DRIVE			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1445	AVONDALE DRIVE			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1437	AVONDALE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1427	AVONDALE DRIVE			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1401	AVONDALE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1377	AVONDALE DRIVE			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1369	AVONDALE DRIVE			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1361	AVONDALE DRIVE			C	N	3/4"		C	3/4"		SF						Installation record	N			Installation record	N			
1353	AVONDALE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1345	AVONDALE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1337	AVONDALE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1340	AVONDALE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1350	AVONDALE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1400	AVONDALE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1408	AVONDALE DRIVE			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1424	AVONDALE DRIVE			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1432	AVONDALE DRIVE			C	N	1"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1440	AVONDALE DRIVE			C	N	1"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1454	AVONDALE DRIVE			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1482	AVONDALE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1490	AVONDALE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1504	AVONDALE DRIVE			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1510	AVONDALE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1518	AVONDALE DRIVE			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1524	AVONDALE DRIVE			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1539	AVONDALE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1531	AVONDALE DRIVE			C	N	1"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1523	AVONDALE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1509	AVONDALE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			

LOCATIONAL IDENTIFIER ADDRESS	LOCATIONAL IDENTIFIER STREET NAME	LOCATIONAL IDENTIFIER UNIT OR SUITE #	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
2452	BABCOCK ROAD			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2459	BABCOCK ROAD			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2445	BABCOCK ROAD			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2436	BABCOCK ROAD			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2689	BABCOCK ROAD			C	N	1"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2571	BABCOCK ROAD			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2580	BABCOCK ROAD			C	N	1"		P			SF						Installation record	N			SL repair/replace record	Y		Visual insp during install or repair	
2437	BABCOCK ROAD			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2620	BABCOCK ROAD			C	N	3/4"		C	3/4"		SF						Installation record	N			Installation record	N			
2650	BABCOCK ROAD			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2658	BABCOCK ROAD			C	N	3/4"		C			MF						Installation record	N			Installation record	N			
2660	BABCOCK ROAD			C	N	3/4"		C			MF						Installation record	N			Installation record	N			
2574	BABCOCK ROAD			C	N	3/4"		C			MF						Installation record	N			Installation record	N			
2676	BABCOCK ROAD			C	N	3/4"		C			MF						Installation record	N			Installation record	N			
2561	BABCOCK ROAD			C	N	1"		C			MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2559	BABCOCK ROAD			C	N	1"		C			MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2551	BABCOCK ROAD			C	N	3/4"		C			MF						Installation record	N			Installation record	N			
2549	BABCOCK ROAD			C	N	3/4"		C			MF						Installation record	N			Installation record	N			
2744	BABCOCK ROAD			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2444	BABCOCK ROAD			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2460	BABCOCK ROAD			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2467	BABCOCK ROAD			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2453	BABCOCK ROAD			C	N	1"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2585	BABCOCK ROAD			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2601	BABCOCK ROAD			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2611	BABCOCK ROAD			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2653	BABCOCK ROAD			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2679	BABCOCK ROAD			C	N	3/4"		C			MF						Installation record	N			Installation record	N			
2681	BABCOCK ROAD			C	N	3/4"		C			MF						Installation record	N			Installation record	N			
2707	BABCOCK ROAD			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2715	BABCOCK ROAD			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2732	BABCOCK ROAD			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2736	BABCOCK ROAD			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
615	BAETEN ROAD			C	N	1"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2197	BALSAM WAY			C	N	1"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2307	BALSAM WAY			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2280	BALSAM WAY			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2119	BALSAM WAY			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2120	BALSAM WAY			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2271	BALSAM WAY			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2114	BALSAM WAY			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2246	BALSAM WAY			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2322	BALSAM WAY			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2245	BALSAM WAY			C	N	1"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2308	BALSAM WAY			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2113	BALSAM WAY			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2257	BALSAM WAY			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2232	BALSAM WAY			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2211	BALSAM WAY			C	N	1"		P			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2223	BALSAM WAY			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2203	BALSAM WAY			C	N	1"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2272	BALSAM WAY			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2373	BALSAM WAY			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2118	BALSAM WAY			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2229	BALSAM WAY			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2091	BALSAM WAY			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2263	BALSAM WAY			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2332	BALSAM WAY			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2235	BALSAM WAY			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2107	BALSAM WAY			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2153	BALSAM WAY			C	N	1"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2141	BALSAM WAY			C	N	1"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2161	BALSAM WAY			C	N	1"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2101	BALSAM WAY			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2210	BALSAM WAY			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2277	BALSAM WAY			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2251	BALSAM WAY			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2217	BALSAM WAY			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2191	BALSAM WAY			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2183	BALSAM WAY			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2175	BALSAM WAY			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2169	BALSAM WAY			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2145	BALSAM WAY			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2140	BALSAM WAY			C	N	1"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2144	BALSAM WAY			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2152	BALSAM WAY			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2160	BALSAM WAY			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2168	BALSAM WAY			C	N	1"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2174	BALSAM WAY			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2182	BALSAM WAY			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2190	BALSAM WAY			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2196	BALSAM WAY			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2204	BALSAM WAY			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2218	BALSAM WAY			C	N	1"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2224	BALSAM WAY			C	N	3/4"		C			SF						Installation record	N			Installation record	N			

LOCATIONAL IDENTIFIER ADDRESS	LOCATIONAL IDENTIFIER STREET NAME	LOCATIONAL IDENTIFIER UNIT OR SUITE #	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
2331	BALSAM WAY			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2321	BALSAM WAY			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2396	BALSAM WAY			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2397	BALSAM WAY			C	N	3/4"		C			MF						Installation record	N			Installation record	N			
2399	BALSAM WAY			C	N	3/4"		C			MF						Installation record	N			Installation record	N			
2383	BALSAM WAY			C	N	3/4"		C			MF						Installation record	N			Installation record	N			
2385	BALSAM WAY			C	N	3/4"		C			MF						Installation record	N			Installation record	N			
2382	BALSAM WAY			C	N	1"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2372	BALSAM WAY			C	N	3/4"		C			MF						Installation record	N			Installation record	N			
2375	BALSAM WAY			C	N	3/4"		C			MF						Installation record	N			Installation record	N			
2355	BALSAM WAY			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2356	BALSAM WAY			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2346	BALSAM WAY			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2347	BALSAM WAY			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2433	BALSAM WAY			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2434	BALSAM WAY			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2211	BARBERRY LANE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2120	BARBERRY LANE			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2166	BARBERRY LANE			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2104	BARBERRY LANE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2108	BARBERRY LANE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2244	BARBERRY LANE			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2222	BARBERRY LANE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2116	BARBERRY LANE			P	N	3/4"		P			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2220	BARBERRY LANE			P	N	1"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2253	BARBERRY LANE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2130	BARBERRY LANE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2158	BARBERRY LANE			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2195	BARBERRY LANE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2138	BARBERRY LANE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2112	BARBERRY LANE			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2217	BARBERRY LANE			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2225	BARBERRY LANE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2119	BARBERRY LANE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2233	BARBERRY LANE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2152	BARBERRY LANE			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2171	BARBERRY LANE			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2252	BARBERRY LANE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2203	BARBERRY LANE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2236	BARBERRY LANE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2230	BARBERRY LANE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2218	BARBERRY LANE			C	N	1"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2266	BARBERRY LANE			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2258	BARBERRY LANE			P	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2144	BARBERRY LANE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2133	BARBERRY LANE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2091	BARBERRY LANE			C	N	1"		P			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2107	BARBERRY LANE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2083	BARBERRY LANE			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2055	BARBERRY LANE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2063	BARBERRY LANE			P	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2071	BARBERRY LANE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2076	BARBERRY LANE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2068	BARBERRY LANE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2062	BARBERRY LANE			P	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2174	BARBERRY LANE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2151	BARBERRY LANE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2452	BASSWOOD STREET			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2453	BASSWOOD STREET			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2436	BASSWOOD STREET			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2444	BASSWOOD STREET			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2458	BASSWOOD STREET			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2466	BASSWOOD STREET			C	N	1"		C			MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2467	BASSWOOD STREET			C	N	1"		C			MF						Installation record	N			Installation record	N			
2459	BASSWOOD STREET			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2445	BASSWOOD STREET			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2437	BASSWOOD STREET			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2499	BAY AREA PLACE			C	N	1"		C			MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2497	BAY AREA PLACE			C	N	1"		C			MF						Installation record	N			Installation record	N			
2491	BAY AREA PLACE			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2485	BAY AREA PLACE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2475	BAY AREA PLACE			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2469	BAY AREA PLACE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2463	BAY AREA PLACE			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2455	BAY AREA PLACE			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2625	BAY HARBOR CIRCLE	4		P	N	1"		P			SF						Installed after lead ban	N	2008		Installed after lead ban	Y		Visual insp during install or repair	
2625	BAY HARBOR CIRCLE	1		P	N	1"		P			SF						Installed after lead ban	N	2008		Installed after lead ban	Y		Visual insp during install or repair	
2609	BAY HARBOR CIRCLE	WOM		P	N	1"		P			SF						Installed after lead ban	N	2008		Installed after lead ban	Y		Visual insp during install or repair	
2609	BAY HARBOR CIRCLE	1		P	N	1"		P			SF						Installed after lead ban	N	2008		Installed after lead ban	Y		Visual insp during install or repair	
2609	BAY HARBOR CIRCLE	2		P	N	1"		P			SF						Installed after lead ban	N	2008		Installed after lead ban	Y		Visual insp during install or repair	
2609	BAY HARBOR CIRCLE	3		P	N	1"		P			SF						Installed after lead ban	N	2008		Installed after lead ban	Y		Visual insp during install or repair	
2625	BAY HARBOR CIRCLE	3		P	N	1"		P			SF						Installed after lead ban	N	2008		Installed after lead ban	Y		Visual insp during install or repair	
2625	BAY HARBOR CIRCLE	2		P	N	1"		P			SF						Installed after lead ban	N	2008		Installed after lead ban	Y		Visual insp during install or repair	
2621	BAY HARBOR CIRCLE	4		P	N	1"		P			SF						Installed after lead ban	N	2008		Installed after lead ban	Y		Visual insp during install or repair	
2621	BAY HARBOR CIRCLE	3		P	N	1"		P			SF						Installed after lead ban	N	2008		Installed after lead ban	Y		Visual insp during install or repair	

LOCATIONAL IDENTIFIER ADDRESS	LOCATIONAL IDENTIFIER STREET NAME	LOCATIONAL IDENTIFIER UNIT OR SUITE #	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
2621	BAY HARBOR CIRCLE	1		P	N	1"		P			SF						Installed after lead ban	N	2008		Installed after lead ban	Y		Visual insp during install or repair	
2580	BAY HARBOR CIRCLE	3		P	N	1"		P			SF						Installed after lead ban	N	2008		Installed after lead ban	Y		Visual insp during install or repair	
2580	BAY HARBOR CIRCLE	4		P	N	1"		P			SF						Installed after lead ban	N	2008		Installed after lead ban	Y		Visual insp during install or repair	
2621	BAY HARBOR CIRCLE	2		P	N	1"		P			SF						Installed after lead ban	N	2008		Installed after lead ban	Y		Visual insp during install or repair	
2580	BAY HARBOR CIRCLE	1		P	N	1"		P			SF						Installed after lead ban	N	2008		Installed after lead ban	Y		Visual insp during install or repair	
2580	BAY HARBOR CIRCLE	2		P	N	1"		P			SF						Installed after lead ban	N	2008		Installed after lead ban	Y		Visual insp during install or repair	
2592	BAY HARBOR CIRCLE	4		P	N	1"		P			SF						Installed after lead ban	N	2008		Installed after lead ban	Y		Visual insp during install or repair	
2592	BAY HARBOR CIRCLE	3		P	N	1"		P			SF						Installed after lead ban	N	2008		Installed after lead ban	Y		Visual insp during install or repair	
2592	BAY HARBOR CIRCLE	2		P	N	1"		P			SF						Installed after lead ban	N	2008		Installed after lead ban	Y		Visual insp during install or repair	
2592	BAY HARBOR CIRCLE	1		P	N	1"		P			SF						Installed after lead ban	N	2008		Installed after lead ban	Y		Visual insp during install or repair	
2617	BAY HARBOR CIRCLE	3		P	N	1"		P			SF						Installed after lead ban	N	2008		Installed after lead ban	Y		Visual insp during install or repair	
2617	BAY HARBOR CIRCLE	1		P	N	1"		P			SF						Installed after lead ban	N	2008		Installed after lead ban	Y		Visual insp during install or repair	
2617	BAY HARBOR CIRCLE	2		P	N	1"		P			SF						Installed after lead ban	N	2008		Installed after lead ban	Y		Visual insp during install or repair	
2617	BAY HARBOR CIRCLE	4		P	N	1"		P			SF						Installed after lead ban	N	2008		Installed after lead ban	Y		Visual insp during install or repair	
2584	BAY HARBOR CIRCLE	4		P	N	1"		P			SF						Installed after lead ban	N	2008		Installed after lead ban	Y		Visual insp during install or repair	
2584	BAY HARBOR CIRCLE	3		P	N	1"		P			SF						Installed after lead ban	N	2008		Installed after lead ban	Y		Visual insp during install or repair	
2584	BAY HARBOR CIRCLE	2		P	N	1"		P			SF						Installed after lead ban	N	2008		Installed after lead ban	Y		Visual insp during install or repair	
2584	BAY HARBOR CIRCLE	1		P	N	1"		P			SF						Installed after lead ban	N	2008		Installed after lead ban	Y		Visual insp during install or repair	
2613	BAY HARBOR CIRCLE	2		P	N	1"		P			SF						Installed after lead ban	N	2008		Installed after lead ban	Y		Visual insp during install or repair	
2609	BAY HARBOR CIRCLE	4		P	N	1"		P			SF						Installed after lead ban	N	2008		Installed after lead ban	Y		Visual insp during install or repair	
2613	BAY HARBOR CIRCLE	4		P	N	1"		P			SF						Installed after lead ban	N	2008		Installed after lead ban	Y		Visual insp during install or repair	
2613	BAY HARBOR CIRCLE	WOM		P	N	1"		P			SF						Installed after lead ban	N	2008		Installed after lead ban	Y		Visual insp during install or repair	
2613	BAY HARBOR CIRCLE	1		P	N	1"		P			SF						Installed after lead ban	N	2008		Installed after lead ban	Y		Visual insp during install or repair	
2613	BAY HARBOR CIRCLE	3		P	N	1"		P			SF						Installed after lead ban	N	2008		Installed after lead ban	Y		Visual insp during install or repair	
2605	BAY HARBOR CIRCLE	WOM		P	N	1"		P			SF						Installed after lead ban	N	2008		Installed after lead ban	Y		Visual insp during install or repair	
2605	BAY HARBOR CIRCLE	1		P	N	1"		P			SF						Installed after lead ban	N	2008		Installed after lead ban	Y		Visual insp during install or repair	
2605	BAY HARBOR CIRCLE	2		P	N	1"		P			SF						Installed after lead ban	N	2008		Installed after lead ban	Y		Visual insp during install or repair	
2605	BAY HARBOR CIRCLE	3		P	N	1"		P			SF						Installed after lead ban	N	2008		Installed after lead ban	Y		Visual insp during install or repair	
2605	BAY HARBOR CIRCLE	4		P	N	1"		P			SF						Installed after lead ban	N	2008		Installed after lead ban	Y		Visual insp during install or repair	
2601	Bay Harbor Circle	1		P	N	1"		P			SF						Installed after lead ban	N	2008		Installed after lead ban	Y		Visual insp during install or repair	
2601	Bay Harbor Circle	2		P	N	1"		P			SF						Installed after lead ban	N	2008		Installed after lead ban	Y		Visual insp during install or repair	
2601	Bay Harbor Circle	3		P	N	1"		P			SF						Installed after lead ban	N	2008		Installed after lead ban	Y		Visual insp during install or repair	
2588	BAY HARBOR CIRCLE	WOM		P	N	1"		P			SF						Installed after lead ban	N	2008		Installed after lead ban	Y		Visual insp during install or repair	
2588	BAY HARBOR CIRCLE	3		P	N	1"		P			SF						Installed after lead ban	N	2008		Installed after lead ban	Y		Visual insp during install or repair	
2588	BAY HARBOR CIRCLE	4		P	N	1"		P			SF						Installed after lead ban	N	2008		Installed after lead ban	Y		Visual insp during install or repair	
2588	BAY HARBOR CIRCLE	1		P	N	1"		P			SF						Installed after lead ban	N	2008		Installed after lead ban	Y		Visual insp during install or repair	
2588	BAY HARBOR CIRCLE	2		P	N	1"		P			SF						Installed after lead ban	N	2008		Installed after lead ban	Y		Visual insp during install or repair	
3608	Becker Ct			P	N	1"		P			SF						Installed after lead ban	Y	2008		Installed after lead ban	Y		Visual insp during install or repair	
3613	Becker Ct			P	N	1"		P			SF						Installed after lead ban	Y	2008		Installed after lead ban	Y		Visual insp during install or repair	
2761	BERKEN COURT			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2760	BERKEN COURT			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2861	BERKEN COURT			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2746	BERKEN COURT			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2737	BERKEN COURT			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2754	BERKEN COURT			C	N	1"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2741	BERKEN COURT			C	N	3/4"		C	1"		SF						Installation record	N			Installation record	N			
2855	BERKEN COURT			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2849	BERKEN COURT			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2843	BERKEN COURT			C	N	1"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2835	BERKEN COURT			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2829	BERKEN COURT			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2813	BERKEN COURT			C	N	3/4"		C	1"		SF						Installation record	N			Installation record	N			
2805	BERKEN COURT			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2799	BERKEN COURT			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2783	BERKEN COURT			C	N	1"		P			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2775	BERKEN COURT			C	N	1"		P			MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2773	BERKEN COURT			C	N	1"		P			MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2767	BERKEN COURT			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2781	BERKEN COURT			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2757	BERKEN COURT			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2749	BERKEN COURT			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2736	BERKEN COURT			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2740	BERKEN COURT			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2766	BERKEN COURT			C	N	3/4"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2772	BERKEN COURT			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2778	BERKEN COURT			C	N	3/4"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2784	BERKEN COURT			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2792	BERKEN COURT			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2798	BERKEN COURT			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2804	BERKEN COURT			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2810	BERKEN COURT			C	N	3/4"		C	1"		SF						Installation record	N			Installation record	N			
2816	BERKEN COURT			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2824	BERKEN COURT			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2830	BERKEN COURT			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2836	BERKEN COURT			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2842	BERKEN COURT			C	N	1"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2848	BERKEN COURT			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2856	BERKEN COURT			C	N	1"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2862	BERKEN COURT			C	N	3/4"		C	3/4"		SF						Installation record	N			Installation record	N			
1070	BETHANY PLACE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1079	BETHANY PLACE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1058	BETHANY PLACE			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1064	BETHANY PLACE			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1076	BETHANY PLACE			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1084	BETHANY PLACE			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	

LOCATIONAL IDENTIFIER ADDRESS	LOCATIONAL IDENTIFIER STREET NAME	LOCATIONAL IDENTIFIER UNIT OR SUITE #	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
1092	BETHANY PLACE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2121	BETHANY PLACE			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1087	BETHANY PLACE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1071	BETHANY PLACE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1065	BETHANY PLACE			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1098	BLACKBERRY WINTER LA			P	N	1"		P			SF						Installation record	Y			Installed after lead ban	Y		Visual insp during install or repair	
1058	BLACKBERRY WINTER LA			P	N	1"		P			SF						Installation record	Y			Installed after lead ban	Y		Visual insp during install or repair	
1089	BLACKBERRY WINTER LA			P	N	1"		P			SF						Installation record	Y			Installed after lead ban	Y		Visual insp during install or repair	
1081	BLACKBERRY WINTER LA			P	N	1"		P			SF						Installation record	Y			Installed after lead ban	Y		Visual insp during install or repair	
1106	BLACKBERRY WINTER LA			P	N	1"		P			SF						Installation record	Y			Installed after lead ban	Y		Visual insp during install or repair	
1066	BLACKBERRY WINTER LA			P	N	1"		P			SF						Installation record	Y			Installed after lead ban	Y		Visual insp during install or repair	
1090	BLACKBERRY WINTER LA			P	N	1"		P			SF						Installation record	Y			Installed after lead ban	Y		Visual insp during install or repair	
1082	BLACKBERRY WINTER LA			P	N	1"		P			SF						Installation record	Y			Installed after lead ban	Y		Visual insp during install or repair	
1074	BLACKBERRY WINTER LA			P	N	1"		P			SF						Installation record	Y			Installed after lead ban	Y		Visual insp during install or repair	
1050	BLACKBERRY WINTER LA			P	N	1"		P			SF						Installation record	Y			Installed after lead ban	Y		Visual insp during install or repair	
1057	BLACKBERRY WINTER LA			P	N	1"		P			SF						Installation record	Y			Installed after lead ban	Y		Visual insp during install or repair	
1065	BLACKBERRY WINTER LA			P	N	1"		P			SF						Installation record	Y			Installed after lead ban	Y		Visual insp during install or repair	
1073	BLACKBERRY WINTER LA			P	N	1"		P			SF						Installation record	Y			Installed after lead ban	Y		Visual insp during install or repair	
1097	BLACKBERRY WINTER LA			P	N	1"		P			SF						Installation record	Y			Installed after lead ban	Y		Visual insp during install or repair	
2859	BLUE JAY LANE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2866	BLUE JAY LANE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2851	BLUE JAY LANE			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2865	BLUE JAY LANE			C	N	1"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1091	BLUE RIDGE DRIVE			C	N	1"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1270	BLUE RIDGE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1071	BLUE RIDGE DRIVE			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1203	BLUE RIDGE DRIVE			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1126	BLUE RIDGE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1313	BLUE RIDGE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1097	BLUE RIDGE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1265	BLUE RIDGE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1106	BLUE RIDGE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1287	BLUE RIDGE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1172	BLUE RIDGE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1301	BLUE RIDGE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1217	BLUE RIDGE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1326	BLUE RIDGE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1112	BLUE RIDGE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1198	BLUE RIDGE DRIVE			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1167	BLUE RIDGE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1098	BLUE RIDGE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1293	BLUE RIDGE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1090	BLUE RIDGE DRIVE			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1120	BLUE RIDGE DRIVE			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1134	BLUE RIDGE DRIVE			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1135	BLUE RIDGE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1129	BLUE RIDGE DRIVE			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1123	BLUE RIDGE DRIVE			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1115	BLUE RIDGE DRIVE			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1109	BLUE RIDGE DRIVE			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1103	BLUE RIDGE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	Y			
1083	BLUE RIDGE DRIVE			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1077	BLUE RIDGE DRIVE			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1063	BLUE RIDGE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1160	BLUE RIDGE DRIVE			C	N	1"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1166	BLUE RIDGE DRIVE			C	N	1"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1178	BLUE RIDGE DRIVE			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1184	BLUE RIDGE DRIVE			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1192	BLUE RIDGE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1204	BLUE RIDGE DRIVE			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1210	BLUE RIDGE DRIVE			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1216	BLUE RIDGE DRIVE			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1238	BLUE RIDGE DRIVE			C	N	3/4"		C			MF						Installation record	N			Installation record	N			
1240	BLUE RIDGE DRIVE			C	N	3/4"		C			MF						Installation record	N			Installation record	N			
1244	BLUE RIDGE DRIVE			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1250	BLUE RIDGE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1260	BLUE RIDGE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1264	BLUE RIDGE DRIVE			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1280	BLUE RIDGE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1286	BLUE RIDGE DRIVE			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1292	BLUE RIDGE DRIVE			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1300	BLUE RIDGE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1306	BLUE RIDGE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1312	BLUE RIDGE DRIVE			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1320	BLUE RIDGE DRIVE			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1321	BLUE RIDGE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1307	BLUE RIDGE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1279	BLUE RIDGE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1271	BLUE RIDGE DRIVE			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1257	BLUE RIDGE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1251	BLUE RIDGE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1245	BLUE RIDGE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1211	BLUE RIDGE DRIVE			C	N	3/4"		C	1"		SF						Installation record	N			Installation record	N			
1197	BLUE RIDGE DRIVE			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1189	BLUE RIDGE DRIVE			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	

LOCATIONAL IDENTIFIER ADDRESS	LOCATIONAL IDENTIFIER STREET NAME	LOCATIONAL IDENTIFIER UNIT OR SUITE #	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
1181	BLUE RIDGE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1175	BLUE RIDGE DRIVE			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1161	BLUE RIDGE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1061	BLUEGRASS COURT			P	N	1"		P			SF						Installation record	Y			Installed after lead ban	Y		Visual insp during install or repair	
1062	BLUEGRASS COURT			P	N	1"		P			SF						Installation record	Y			Installed after lead ban	Y		Visual insp during install or repair	
845	BORVAN AVENUE			C	N	1"		C			SF						Installation record	Y			Field inspection only	Y		Cross-connection survey	
643	BORVAN AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
651	BORVAN AVENUE			C	N	1"		C			MF						Installation record	Y			Field inspection only	Y		Cross-connection survey	
653	BORVAN AVENUE			C	N	1"		C			MF						Installation record	Y			Field inspection only	Y		Cross-connection survey	
661	BORVAN AVENUE			C	N	1"		P			MF						Installation record	Y			Field inspection only	Y		Cross-connection survey	
663	BORVAN AVENUE			C	N	1"		P			MF						Installation record	Y			Field inspection only	Y		Cross-connection survey	
428	BOSAR AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
438	BOSAR AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
459	BOSAR AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	Y			Installation record	N			
411	BOSAR AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
471	BOSAR AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
455	BOSAR AVENUE			C	N	3/4"		C			SF						Installation record	Y			Field inspection only	Y		Cross-connection survey	
447	BOSAR AVENUE			C	N	3/4"		C			SF						Installation record	Y			Field inspection only	Y		Cross-connection survey	
433	BOSAR AVENUE			C	N	3/4"		C			SF						Installation record	Y			Field inspection only	Y		Cross-connection survey	
414	BOSAR AVENUE			C	N	1"		C			SF						Installation record	Y			Field inspection only	Y		Cross-connection survey	
444	BOSAR AVENUE			C	N	3/4"		C			SF						Installation record	Y			Field inspection only	Y		Cross-connection survey	
450	BOSAR AVENUE			C	N	3/4"		C			SF						Installation record	Y			Field inspection only	Y		Cross-connection survey	
458	BOSAR AVENUE			C	N	3/4"		C			SF						Installation record	Y			Field inspection only	Y		Cross-connection survey	
466	BOSAR AVENUE			C	N	3/4"		C			SF						Installation record	Y			Field inspection only	Y		Cross-connection survey	
462	BOSAR AVENUE			C	N	3/4"		C			SF						Installation record	Y			Field inspection only	Y		Cross-connection survey	
441	BOSAR AVENUE			C	N	3/4"		C			SF						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1516	BRADBURY COURT			P	N	1"		P			SF						Installed after lead ban	Y	1992		Installed after lead ban	N			
1465	BRADBURY COURT			P	N	1"		P			SF						Installed after lead ban	Y	1992		Installed after lead ban	Y		Cross-connection survey	
1475	BRADBURY COURT			P	N	1"		P			SF						Installed after lead ban	Y	1992		Installed after lead ban	Y		Cross-connection survey	
1485	BRADBURY COURT			P	N	1"		P			SF						Installed after lead ban	Y	1992		Installed after lead ban	Y		Cross-connection survey	
1495	BRADBURY COURT			P	N	1"		P			SF						Installed after lead ban	Y	1992		Installed after lead ban	N			
1511	BRADBURY COURT			P	N	1"		P			SF						Installed after lead ban	Y	1992		Installed after lead ban	Y		Cross-connection survey	
1515	BRADBURY COURT			P	N	1"		P			SF						Installed after lead ban	Y	1992		Installed after lead ban	Y		Cross-connection survey	
1510	BRADBURY COURT			P	N	1"		C			SF						Installed after lead ban	Y	1992		Installed after lead ban	Y		Cross-connection survey	
1492	BRADBURY COURT			P	N	1"		P			SF						Installed after lead ban	Y	1992		Installed after lead ban	N			
1484	BRADBURY COURT			P	N	1"		P			SF						Installed after lead ban	Y	1992		Installed after lead ban	Y		Cross-connection survey	
1476	BRADBURY COURT			P	N	1"		C			SF						Installed after lead ban	Y	1992		Installed after lead ban	Y		Cross-connection survey	
1464	BRADBURY COURT			P	N	1"		P			SF						Installed after lead ban	Y	1992		Installed after lead ban	Y			
2065	BRADBURY LANE			P	N	1"		C			SF						Installed after lead ban		1991		Installed after lead ban	N			
2074	BRADBURY LANE			P	N	1"		C			SF						Installed after lead ban		1991		Installed after lead ban	Y		Cross-connection survey	
2073	BRADBURY LANE			P	N	1"		C			SF						Installed after lead ban		1991		Installed after lead ban	N			
2013	BRADBURY LANE			P	N	1"		C			SF						Installed after lead ban		1991		Installed after lead ban	N			
2025	BRADBURY LANE			P	N	1"		C			SF						Installed after lead ban		1991		Installed after lead ban	Y		Cross-connection survey	
2031	BRADBURY LANE			P	N	1"		C			SF						Installed after lead ban		1991		Installed after lead ban	Y		Cross-connection survey	
2043	BRADBURY LANE			P	N	1"		P			SF						Installed after lead ban		1991		Installed after lead ban	Y		Cross-connection survey	
2040	BRADBURY LANE			P	N	1"		P			SF						Installed after lead ban		1991		Installed after lead ban	Y		Cross-connection survey	
2016	BRADBURY LANE			P	N	1"		C			SF						Installed after lead ban		1991		Installed after lead ban	Y		Cross-connection survey	
2057	BRADBURY LANE			P	N	1"		C			SF						Installed after lead ban		1991		Installed after lead ban	Y		Cross-connection survey	
2326	BRADLEY TERRACE			P	N	1"		C			SF						SL repair/replace record		2000		Field inspection only	Y		Cross-connection survey	
2092	S BROADWAY			P	N	1"		C			SF						SL repair/replace record		2000		Installation record	N			
2132	S BROADWAY			P	N	1"		C			SF						SL repair/replace record		2000		Field inspection only	Y		Cross-connection survey	
2108	S BROADWAY			P	N	1"		C			SF						SL repair/replace record		2000		Installation record	N			
2128	S BROADWAY			P	N	1"		C			SF						SL repair/replace record		2000		Installation record	N			
2120	S BROADWAY			P	N	1"		C			SF						SL repair/replace record		2000		Installation record	N			
2153	S BROADWAY			P	N	1"		C			MF						SL repair/replace record		2000		Installation record	N			
2151	S BROADWAY			P	N	1"		C			MF						SL repair/replace record		2000		Installation record	N			
2273	S BROADWAY			P	N	1"		C			SF						SL repair/replace record		2000		Installation record	N			
2741	S BROADWAY			P	N	1"		C			SF						SL repair/replace record		2000		Field inspection only	Y		Cross-connection survey	
2121	S BROADWAY			P	N	1"		C			SF						SL repair/replace record		2000		Field inspection only	Y		Cross-connection survey	
2109	S BROADWAY			P	N	1"		C			SF						SL repair/replace record		2000		Field inspection only	Y		Cross-connection survey	
2191	S BROADWAY			P	N	1"		C			SF						SL repair/replace record		2000		Installation record	N			
2056	S BROADWAY			P	N	1"		C			SF						SL repair/replace record		2000		Field inspection only	Y		Cross-connection survey	
2817	S BROADWAY			P	N	1"		C			SF						SL repair/replace record		1998		Installation record	N			
2871	S BROADWAY			P	N	1"		C			MF						SL repair/replace record		1998		Installation record	N			
2873	S BROADWAY			P	N	1"		C			MF						SL repair/replace record		1998		Installation record	N			
2253	S BROADWAY			P	N	1"		C			SF						SL repair/replace record		2000		Installation record	N			
2222	S BROADWAY			P	N	1"		C			SF						SL repair/replace record		2000		Installation record	N			
2224	S BROADWAY			P	N	1"		C			SF						SL repair/replace record		2000		Field inspection only	Y		Cross-connection survey	
2205	S BROADWAY			P	N	1"		C	2"		MF						SL repair/replace record		2000		Installation record	N			
2207	S BROADWAY	1/2		P	N	1"		C	2"		MF						SL repair/replace record		2000		Installation record	N			
2207	S BROADWAY			P	N	1"		C	2"		MF						SL repair/replace record		2000		Installation record	N			
2197	S BROADWAY			P	N	1"		C			SF						SL repair/replace record		2000		Field inspection only	Y		Cross-connection survey	
2159	S BROADWAY			P	N	1"		P			SF						SL repair/replace record		2000		Field inspection only	Y		Cross-connection survey	
2157	S BROADWAY			P	N	1"		C			SF						SL repair/replace record		2000		Installation record	N			
2149	S BROADWAY			P	N	1"		C			SF						SL repair/replace record		2000		Installation record	N			
2203	S BROADWAY			P	N	1"		C	3/4"		MF						SL repair/replace record		2000		Installation record	N			
2203	S BROADWAY	1/2		P	N	1"		C	3/4"		MF						SL repair/replace record		2000		Installation record	N			
2208	S BROADWAY			P	N	1"		C	3/4"		SF						SL repair/replace record		2000		Field inspection only	Y		Cross-connection survey	
2196	S BROADWAY			P	N	1"		C	3/4"		SF						SL repair/replace record		2000		Field inspection only	Y		Cross-connection survey	
2192	S BROADWAY			P	N	1"		P	1"		SF						SL repair/replace record		2000		Field inspection only	Y		Cross-connection survey	
2150	S BROADWAY			P	N	1"		C			SF						SL repair/replace record		2000		Installation record	N			
2136	S BROADWAY			P	N	1"		C	3/4"		SF						SL repair/replace record		2000		Field inspection only	Y		Cross-connection survey	
2116	S BROADWAY			P	N	1"		C	3/4"		SF						SL repair/replace record		2000		Field inspection only	Y		Cross-connection survey	
2135	S BROADWAY			P	N	1"		P	1"		SF						SL repair/replace record		2000		Field inspection only	Y		Cross-connection survey	
2137	S BROADWAY			P	N	1"		C			SF						SL repair/replace record		2000		Installation record	N			

LOCATIONAL IDENTIFIER ADDRESS	LOCATIONAL IDENTIFIER STREET NAME	LOCATIONAL IDENTIFIER UNIT OR SUITE #	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
2129	S BROADWAY			P	N	1"		C			SF						SL repair/replace record		2000		Installation record	N			
2125	S BROADWAY			P	N	1"		C			SF						SL repair/replace record		2000		Installation record	N			
2117	S BROADWAY			P	N	1"		C	3/4"		SF						SL repair/replace record		2000		Field inspection only	Y		Cross-connection survey	
2096	S BROADWAY			P	N	1"		C	3/4"		SF						SL repair/replace record		2000		Field inspection only	Y		Cross-connection survey	
2218	S BROADWAY			P	N	1"		C	3/4"		SF						SL repair/replace record		2000		Field inspection only	Y		Cross-connection survey	
2236	S BROADWAY			P	N	1"		C	3/4"		SF						SL repair/replace record		2000		Field inspection only	Y		Cross-connection survey	
2261	S BROADWAY			P	N	1"		C	3/4"		SF						SL repair/replace record		2000		Field inspection only	Y		Cross-connection survey	
2257	S BROADWAY			P	N	1"		C	3/4"		SF						SL repair/replace record		2000		Field inspection only	Y		Cross-connection survey	
2249	S BROADWAY			P	N	1"		C	3/4"		SF						SL repair/replace record		2000		Field inspection only	Y		Cross-connection survey	
2245	S BROADWAY			P	N	1"		C			SF						SL repair/replace record		2000		Installation record	N			
2221	S BROADWAY			P	N	1"		C	3/4"		SF						SL repair/replace record		2000		Field inspection only	Y		Cross-connection survey	
2052	S BROADWAY			P	N	1"		C	3/4"		SF						SL repair/replace record		2000		Field inspection only	Y		Cross-connection survey	
2785	S BROADWAY			P	N	1"		C	3/4"		SF						SL repair/replace record		1998		Field inspection only	Y		Cross-connection survey	
2795	S BROADWAY			P	N	1"		C	3/4"		SF						SL repair/replace record		1998		Field inspection only	Y		Cross-connection survey	
2805	S BROADWAY			P	N	1"		P	1"		SF						SL repair/replace record		1998		Field inspection only	Y		Cross-connection survey	
2839	S BROADWAY			P	N	1"		C	3/4"		SF						SL repair/replace record		1998		Field inspection only	Y		Cross-connection survey	
2853	S BROADWAY			P	N	1"		P	1"		SF						SL repair/replace record		1998		Field inspection only	Y		Cross-connection survey	
2855	S BROADWAY			P	N	1"		P	1"		SF						SL repair/replace record		1998		Field inspection only	Y		Cross-connection survey	
2867	S BROADWAY			P	N	1"		C	1"		SF						SL repair/replace record		1998		Field inspection only	Y		Cross-connection survey	
2869	S BROADWAY			P	N	1"		C	1"		SF						SL repair/replace record		1998		Field inspection only	Y		Cross-connection survey	
2650	BROOKDALE AVENUE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2661	BROOKDALE AVENUE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2622	BROOKDALE AVENUE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2571	BROOKDALE AVENUE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2556	BROOKDALE AVENUE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2555	BROOKDALE AVENUE			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2549	BROOKDALE AVENUE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2548	BROOKDALE AVENUE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2572	BROOKDALE AVENUE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2633	BROOKDALE AVENUE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2634	BROOKDALE AVENUE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2651	BROOKDALE AVENUE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2581	BROOKDALE AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2582	BROOKDALE AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2600	BROOKDALE AVENUE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2601	BROOKDALE AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2611	BROOKDALE AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2610	BROOKDALE AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2623	BROOKDALE AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2688	BROOKDALE AVENUE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1321	BROOKWOOD DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1325	BROOKWOOD DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1319	BROOKWOOD DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1313	BROOKWOOD DRIVE			C	N	3/4"		C			MF						Installation record	N			Installation record	N			
1311	BROOKWOOD DRIVE			C	N	3/4"		C			MF						Installation record	N			Installation record	N			
1305	BROOKWOOD DRIVE			C	N	3/4"		C			MF						Installation record	N			Installation record	N			
1303	BROOKWOOD DRIVE			C	N	3/4"		C			MF						Installation record	N			Installation record	N			
1297	BROOKWOOD DRIVE			C	N	3/4"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1295	BROOKWOOD DRIVE			C	N	3/4"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1291	BROOKWOOD DRIVE			C	N	3/4"		C	1"		MF						Installation record	N			Installation record	N			
1289	BROOKWOOD DRIVE			C	N	3/4"		C	1"		MF						Installation record	N			Installation record	N			
1283	BROOKWOOD DRIVE			C	N	1"		C	1"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1281	BROOKWOOD DRIVE			C	N	1"		C	1"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1275	BROOKWOOD DRIVE			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1273	BROOKWOOD DRIVE			C	N	1"		P	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1267	BROOKWOOD DRIVE			C	N	1"		C			MF						Installation record	N			Installation record	N			
1265	BROOKWOOD DRIVE			C	N	1"		C			MF						Installation record	N			Installation record	N			
1261	BROOKWOOD DRIVE			C	N	1"		C			MF						Installation record	N			Installation record	N			
1259	BROOKWOOD DRIVE			C	N	1"		C			MF						Installation record	N			Installation record	N			
1253	BROOKWOOD DRIVE			C	N	1"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1251	BROOKWOOD DRIVE			C	N	1"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1245	BROOKWOOD DRIVE			C	N	1"		C			MF						Installation record	N			Installation record				
1243	BROOKWOOD DRIVE			C	N	1"		C	1"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1511	BRUCE LANE			C	N	1"		C	3/4"		SF						Installation record	N			Installation record				
1412	BRUCE LANE			C	N	1"		C			SF						Installation record	N			Installation record				
1635	BRUCE LANE			C	N	1"		C			SF						Installation record	N			Installation record				
1361	BRUCE LANE			C	N	1"		C			SF						Installation record	N			Installation record				
1433	BRUCE LANE			C	N	1"		C			SF						Installation record	N			Installation record				
1623	BRUCE LANE			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1338	BRUCE LANE			C	N	1"		C			SF						Installation record	N			Installation record				
1400	BRUCE LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1644	BRUCE LANE			C	N	1"		C			SF						Installation record	N			Installation record				
1444	BRUCE LANE			C	N	1"		C			SF						Installation record	N			Installation record				
1439	BRUCE LANE			C	N	1"		C			SF						Installation record	N			Installation record				
1567	BRUCE LANE			C	N	1"		C			SF						Installation record	N			Installation record				
1394	BRUCE LANE			C	N	1"		C			SF						Installation record	N			Installation record				
1505	BRUCE LANE			C	N	1"		C			SF						Installation record	N			Installation record				
1352	BRUCE LANE			C	N	1"		C			SF						Installation record	N			Installation record				
1332	BRUCE LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1346	BRUCE LANE			C	N	1"		C			SF						Installation record	N			Installation record				
1360	BRUCE LANE			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1366	BRUCE LANE			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1372	BRUCE LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1378	BRUCE LANE			C	N	1"		C			SF						Installation record	N			Installation record				
1384	BRUCE LANE			C	N	1"		C			SF						Installation record	N			Installation record				

LOCATIONAL IDENTIFIER ADDRESS	LOCATIONAL IDENTIFIER STREET NAME	LOCATIONAL IDENTIFIER UNIT OR SUITE #	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
1406	BRUCE LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1418	BRUCE LANE			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1424	BRUCE LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1430	BRUCE LANE			C	N	1"		C			SF						Installation record	N			Installation record				
1440	BRUCE LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1452	BRUCE LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1480	BRUCE LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1486	BRUCE LANE			C	N	1"		C			SF						Installation record	N			Installation record				
1494	BRUCE LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1531	BRUCE LANE			C	N	1"		C			SF						Installation record	N			Installation record				
1525	BRUCE LANE			C	N	1"		C			SF						Installation record	N			Installation record				
1519	BRUCE LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1499	BRUCE LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1493	BRUCE LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1485	BRUCE LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1481	BRUCE LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1453	BRUCE LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1445	BRUCE LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1427	BRUCE LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1421	BRUCE LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1415	BRUCE LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1407	BRUCE LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1401	BRUCE LANE			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1395	BRUCE LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1387	BRUCE LANE			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1381	BRUCE LANE			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1375	BRUCE LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1367	BRUCE LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1355	BRUCE LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1349	BRUCE LANE			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1341	BRUCE LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1333	BRUCE LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1558	BRUCE LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1564	BRUCE LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1572	BRUCE LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1580	BRUCE LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1588	BRUCE LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1594	BRUCE LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1602	BRUCE LANE			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1608	BRUCE LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1616	BRUCE LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1622	BRUCE LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1630	BRUCE LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1638	BRUCE LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1650	BRUCE LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1641	BRUCE LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1629	BRUCE LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1617	BRUCE LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1611	BRUCE LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1603	BRUCE LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1595	BRUCE LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1589	BRUCE LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1581	BRUCE LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1575	BRUCE LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1561	BRUCE LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1434	BUFFALO STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
1368	BUFFALO STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
1469	BUFFALO STREET			C	N	1"		C			MF						Installation record	N			Installation record	N			
1467	BUFFALO STREET			C	N	1"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1386	BUFFALO STREET			C	N	1"		C	1"		SF						Installation record	N			Installation record	N			
1533	BUFFALO STREET			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1454	BUFFALO STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
1359	BUFFALO STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
1371	BUFFALO STREET			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1377	BUFFALO STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
1383	BUFFALO STREET			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1388	BUFFALO STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
1382	BUFFALO STREET			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1378	BUFFALO STREET			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1374	BUFFALO STREET			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1364	BUFFALO STREET			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1358	BUFFALO STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
1354	BUFFALO STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
1350	BUFFALO STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
1445	BUFFALO STREET			C	N	1"		C	1"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1443	BUFFALO STREET			C	N	1"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1435	BUFFALO STREET			C	N	1"		C	1"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1433	BUFFALO STREET			C	N	1"		C	1"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1419	BUFFALO STREET			C	N	1"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1417	BUFFALO STREET			C	N	1"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1411	BUFFALO STREET			C	N	1"		C			MF						Installation record	N			Installation record	N			
1409	BUFFALO STREET			C	N	1"		C			MF						Installation record	N			Installation record	N			
1408	BUFFALO STREET			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1414	BUFFALO STREET			C	N	1"					SF						Installation record	N			Installation record	N			
1420	BUFFALO STREET			C	N	1"					SF						Installation record	N			Installation record	N			

LOCATIONAL IDENTIFIER ADDRESS	LOCATIONAL IDENTIFIER STREET NAME	LOCATIONAL IDENTIFIER UNIT OR SUITE #	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
1428	BUFFALO STREET			C	N	1"					SF						Installation record	N			Installation record	N			
1440	BUFFALO STREET			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1446	BUFFALO STREET			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1478	BUFFALO STREET			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1484	BUFFALO STREET			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1490	BUFFALO STREET			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1498	BUFFALO STREET			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1504	BUFFALO STREET			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1510	BUFFALO STREET			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1516	BUFFALO STREET			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1522	BUFFALO STREET			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1528	BUFFALO STREET			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1536	BUFFALO STREET			C	N	1"					SF						Installation record	N			Installation record	N			
1543	BUFFALO STREET			C	N	1"		C	1"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1541	BUFFALO STREET			C	N	1"		C	1"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1531	BUFFALO STREET			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1519	BUFFALO STREET			C	N	1"					MF						Installation record	N			Installation record	N			
1517	BUFFALO STREET			C	N	1"					MF						Installation record	N			Installation record	N			
1511	BUFFALO STREET			C	N	1"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1509	BUFFALO STREET			C	N	1"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1493	BUFFALO STREET			C	N	1"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1491	BUFFALO STREET			C	N	1"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1485	BUFFALO STREET			C	N	1"		C	1"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1483	BUFFALO STREET			C	N	1"		C	1"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1463	BUFFALO STREET			C	N	1"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1461	BUFFALO STREET			C	N	1"		C			MF						Installation record	N			Installation record	N			
2323	CANTER LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2399	CANTER LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2393	CANTER LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2333	CANTER LANE			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2301	CANTER LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2309	CANTER LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2355	CANTER LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2432	CANTER LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2385	CANTER LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2373	CANTER LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1097	CANTERBURY ROAD			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1114	CANTERBURY ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1243	CANTERBURY ROAD			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1307	CANTERBURY ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1083	CANTERBURY ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1211	CANTERBURY ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1100	CANTERBURY ROAD			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1274	CANTERBURY ROAD			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1185	CANTERBURY ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1115	CANTERBURY ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1106	CANTERBURY ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1120	CANTERBURY ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1128	CANTERBURY ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1134	CANTERBURY ROAD			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1135	CANTERBURY ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1129	CANTERBURY ROAD			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1123	CANTERBURY ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1109	CANTERBURY ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1103	CANTERBURY ROAD			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1091	CANTERBURY ROAD			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1077	CANTERBURY ROAD			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1071	CANTERBURY ROAD			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1065	CANTERBURY ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1066	CANTERBURY ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1072	CANTERBURY ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1080	CANTERBURY ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1086	CANTERBURY ROAD			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1094	CANTERBURY ROAD			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1166	CANTERBURY ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1172	CANTERBURY ROAD			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1178	CANTERBURY ROAD			C	N	1"					SF						Installation record	N			Installation record	N			
1184	CANTERBURY ROAD			C	N	1"					SF						Installation record	N			Installation record	N			
1192	CANTERBURY ROAD			C	N	1"					SF						Installation record	N			Installation record	N			
1198	CANTERBURY ROAD			C	N	1"					SF						Installation record	N			Installation record	N			
1204	CANTERBURY ROAD			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1210	CANTERBURY ROAD			C	N	1"					SF						Installation record	N			Installation record	N			
1216	CANTERBURY ROAD			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1242	CANTERBURY ROAD			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1248	CANTERBURY ROAD			C	N	1"					SF						Installation record	N			Installation record	N			
1254	CANTERBURY ROAD			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1260	CANTERBURY ROAD			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1268	CANTERBURY ROAD			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1280	CANTERBURY ROAD			C	N	1"					SF						Installation record	N			Installation record	N			
1288	CANTERBURY ROAD			C	N	1"					SF						Installation record	N			Installation record	N			
1294	CANTERBURY ROAD			C	N	1"					SF						Installation record	N			Installation record	N			
1300	CANTERBURY ROAD			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1306	CANTERBURY ROAD			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1314	CANTERBURY ROAD			C	N	1"					SF						Installation record	N			Installation record	N			
1320	CANTERBURY ROAD			C	N	1"					SF						Installation record	N			Installation record	N			

LOCATIONAL IDENTIFIER ADDRESS	LOCATIONAL IDENTIFIER STREET NAME	LOCATIONAL IDENTIFIER UNIT OR SUITE #	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
1327	CANTERBURY ROAD			C	N	1"					SF						Installation record	N			Installation record	N			
1321	CANTERBURY ROAD			C	N	1"					SF						Installation record	N			Installation record	N			
1315	CANTERBURY ROAD			C	N	1"					SF						Installation record	N			Installation record	N			
1301	CANTERBURY ROAD			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1295	CANTERBURY ROAD			C	N	1"					SF						Installation record	N			Installation record	N			
1289	CANTERBURY ROAD			C	N	1"					SF						Installation record	N			Installation record	N			
1281	CANTERBURY ROAD			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1275	CANTERBURY ROAD			C	N	1"					SF						Installation record	N			Installation record	N			
1269	CANTERBURY ROAD			C	N	1"					SF						Installation record	N			Installation record	N			
1261	CANTERBURY ROAD			C	N	1"					SF						Installation record	N			Installation record	N			
1255	CANTERBURY ROAD			C	N	1"					SF						Installation record	N			Installation record	N			
1249	CANTERBURY ROAD			C	N	1"					SF						Installation record	N			Installation record	N			
1217	CANTERBURY ROAD			C	N	1"					SF						Installation record	N			Installation record	N			
1205	CANTERBURY ROAD			C	N	1"					SF						Installation record	N			Installation record	N			
1199	CANTERBURY ROAD			C	N	1"					SF						Installation record	N			Installation record	N			
1191	CANTERBURY ROAD			C	N	1"		C	3/4"		SF						Installation record	N			Installation record	N			
1179	CANTERBURY ROAD			C	N	1"					SF						Installation record	N			Installation record	N			
1173	CANTERBURY ROAD			C	N	1"					SF						Installation record	N			Installation record	N			
1167	CANTERBURY ROAD			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1161	CANTERBURY ROAD			C	N	1"					SF						Installation record	N			Installation record	N			
1401	CAREFREE COURT			C	N	1"					SF						Installation record	N			Installation record	N			
1404	CAREFREE COURT			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1405	CAREFREE COURT			C	N	1"					SF						Installation record	N			Installation record	N			
1393	CAREFREE COURT			C	N	1"					SF						Installation record	N			Installation record	N			
1385	CAREFREE COURT			C	N	1"					SF						Installation record	N			Installation record	N			
1377	CAREFREE COURT			C	N	1"					SF						Installation record	N			Installation record	N			
1371	CAREFREE COURT			C	N	1"					SF						Installation record	N			Installation record	N			
1370	CAREFREE COURT			C	N	1"					SF						Installation record	N			Installation record	N			
1374	CAREFREE COURT			C	N	1"					SF						Installation record	N			Installation record	N			
1382	CAREFREE COURT			C	N	1"					SF						Installation record	N			Installation record	N			
1586	CAROLE LANE			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1311	CAROLE LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1574	CAROLE LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1441	CAROLE LANE			C	N	1"					SF						Installation record	N			Installation record	N			
1577	CAROLE LANE			C	N	1"					SF						Installation record	N			Installation record	N			
1401	CAROLE LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1421	CAROLE LANE			C	N	1"					SF						Installation record	N			Installation record	N			
1687	CAROLE LANE			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1471	CAROLE LANE			C	N	1"					SF						Installation record	N			Installation record	N			
1254	CAROLE LANE			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1568	CAROLE LANE			C	N	1"					SF						Installation record	N			Installation record	N			
1353	CAROLE LANE			C	N	1"					SF						Installation record	N			Installation record	N			
1618	CAROLE LANE			C	N	1"					SF						Installation record	N			Installation record	N			
1499	CAROLE LANE			C	N	1"					SF						Installation record	N			Installation record	N			
1479	CAROLE LANE			C	N	1"					SF						Installation record	N			Installation record	N			
1268	CAROLE LANE			C	N	1"					SF						Installation record	N			Installation record	N			
1294	CAROLE LANE			C	N	1"					SF						Installation record	N			Installation record	N			
1595	CAROLE LANE			C	N	1"					SF						Installation record	N			Installation record	N			
1647	CAROLE LANE			C	N	1"					SF						Installation record	N			Installation record	N			
1295	CAROLE LANE			C	N	1"					SF						Installation record	N			Installation record	N			
1656	CAROLE LANE			C	N	1"					SF						Installation record	N			Installation record	N			
1633	CAROLE LANE			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1413	CAROLE LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1583	CAROLE LANE			C	N	1"					SF						Installation record	N			Installation record	N			
1275	CAROLE LANE			C	N	1"					SF						Installation record	N			Installation record	N			
1447	CAROLE LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1283	CAROLE LANE			C	N	1"					SF						Installation record	N			Installation record	N			
1424	CAROLE LANE			C	N	1"					SF						Installation record	N			Installation record	N			
1681	CAROLE LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1679	CAROLE LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1407	CAROLE LANE			C	N	1"					SF						Installation record	N			Installation record	N			
1478	CAROLE LANE			C	N	1"					SF						Installation record	N			Installation record	N			
1556	CAROLE LANE			C	N	1"					SF						Installation record	N			Installation record	N			
1562	CAROLE LANE			C	N	1"					SF						Installation record	N			Installation record	N			
1580	CAROLE LANE			C	N	1"					SF						Installation record	N			Installation record	N			
1592	CAROLE LANE			C	N	1"					SF						Installation record	N			Installation record	N			
1600	CAROLE LANE			C	N	1"					SF						Installation record	N			Installation record	N			
1606	CAROLE LANE			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1624	CAROLE LANE			C	N	1"					SF						Installation record	N			Installation record	N			
1630	CAROLE LANE			C	N	1"					SF						Installation record	N			Installation record	N			
1636	CAROLE LANE			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1642	CAROLE LANE			C	N	1"					SF						Installation record	N			Installation record	N			
1648	CAROLE LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1660	CAROLE LANE			C	N	1"					MF						Installation record	N			Installation record	N			
1662	CAROLE LANE			C	N	1"					MF						Installation record	N			Installation record	N			
1670	CAROLE LANE			C	N	1"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1672	CAROLE LANE			C	N	1"		C	1"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1673	CAROLE LANE			C	N	1"					MF						Installation record	N			Installation record	N			
1671	CAROLE LANE			C	N	1"					MF						Installation record	N			Installation record	N			
1667	CAROLE LANE			C	N	1"		C	1"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1665	CAROLE LANE			C	N	1"					MF						Installation record	N			Installation record	N			
1659	CAROLE LANE			C	N	1"					SF						Installation record	N			Installation record	N			
1653	CAROLE LANE			C	N	1"					SF						Installation record	N			Installation record	N			
1641	CAROLE LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1627	CAROLE LANE			C	N	1"					SF						Installation record	N			Installation record	N			

LOCATIONAL IDENTIFIER ADDRESS	LOCATIONAL IDENTIFIER STREET NAME	LOCATIONAL IDENTIFIER UNIT OR SUITE #	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
1601	CAROLE LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1589	CAROLE LANE			C	N	1"					SF						Installation record	N			Installation record	N			
1571	CAROLE LANE			C	N	1"					SF						Installation record	N			Installation record	N			
1563	CAROLE LANE			C	N	1"					SF						Installation record	N			Installation record	N			
1557	CAROLE LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1549	CAROLE LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1248	CAROLE LANE			C	N	1"					SF						Installation record	N			Installation record	N			
1260	CAROLE LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1274	CAROLE LANE			C	N	1"					SF						Installation record	N			Installation record	N			
1282	CAROLE LANE			C	N	1"					SF						Installation record	N			Installation record	N			
1288	CAROLE LANE			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1300	CAROLE LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1308	CAROLE LANE			C	N	1"					SF						Installation record	N			Installation record	N			
1318	CAROLE LANE			C	N	1"					SF						Installation record	N			Installation record	N			
1324	CAROLE LANE			C	N	1"					SF						Installation record	N			Installation record	N			
1336	CAROLE LANE			C	N	1"					SF						Installation record	N			Installation record	N			
1340	CAROLE LANE			C	N	1"		C	3/4"		SF						Installation record	N			Installation record	N			
1350	CAROLE LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1356	CAROLE LANE			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1364	CAROLE LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1370	CAROLE LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1396	CAROLE LANE			C	N	1"					SF						Installation record	N			Installation record	N			
1400	CAROLE LANE			C	N	1"					SF						Installation record	N			Installation record	N			
1410	CAROLE LANE			C	N	1"					SF						Installation record	N			Installation record	N			
1416	CAROLE LANE			C	N	1"					SF						Installation record	N			Installation record	N			
1430	CAROLE LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1438	CAROLE LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1444	CAROLE LANE			C	N	1"		C	3/4"		SF						Installation record	N			Installation record	N			
1450	CAROLE LANE			C	N	1"					SF						Installation record	N			Installation record	N			
1472	CAROLE LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1482	CAROLE LANE			C	N	1"					SF						Installation record	N			Installation record	N			
1486	CAROLE LANE			C	N	1"					SF						Installation record	N			Installation record	N			
1492	CAROLE LANE			C	N	1"					SF						Installation record	N			Installation record	N			
1500	CAROLE LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1510	CAROLE LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1520	CAROLE LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1521	CAROLE LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1515	CAROLE LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			
1491	CAROLE LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1485	CAROLE LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1453	CAROLE LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1433	CAROLE LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1427	CAROLE LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1393	CAROLE LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1377	CAROLE LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1369	CAROLE LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1361	CAROLE LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1343	CAROLE LANE			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1337	CAROLE LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1301	CAROLE LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1259	CAROLE LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1251	CAROLE LANE			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1241	CAROLE LANE			C	N	1"		C	1"		SF						Installation record	N			Installation record	N			
1242	CAROLE LANE			C	N	1"		C	3/4"		SF						Installation record	N			Installation record	N			
2117	CARSTENSEN LANE			C	N	1"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2115	CARSTENSEN LANE			C	N	1"		C			MF						Installation record	N			Installation record	N			
2113	CARSTENSEN LANE			C	N	1"		C			MF						Installation record	N			Installation record	N			
2111	CARSTENSEN LANE			C	N	1"		C			MF						Installation record	N			Installation record	N			
2192	CARSTENSEN LANE			C	N	1"		C			MF						Installation record	N			Installation record	N			
2194	CARSTENSEN LANE			C	N	1"		C			MF						Installation record	N			Installation record	N			
2196	CARSTENSEN LANE			C	N	1"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2198	CARSTENSEN LANE			C	N	1"		C			MF						Installation record	N			Installation record	N			
2200	CARSTENSEN LANE			C	N	1"		C			MF						Installation record	N			Installation record	N			
2202	CARSTENSEN LANE			C	N	1"		C			MF						Installation record	N			Installation record	N			
2204	CARSTENSEN LANE			C	N	1"		C			MF						Installation record	N			Installation record	N			
2206	CARSTENSEN LANE			C	N	1"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2208	CARSTENSEN LANE			C	N	1"		C			MF						Installation record	N			Installation record	N			
2210	CARSTENSEN LANE			C	N	1"		C			MF						Installation record	N			Installation record	N			
2212	CARSTENSEN LANE			C	N	1"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2214	CARSTENSEN LANE			C	N	1"		C			MF						Installation record	N			Installation record	N			
2216	CARSTENSEN LANE			C	N	1"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2218	CARSTENSEN LANE			C	N	1"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2220	CARSTENSEN LANE			C	N	1"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2222	CARSTENSEN LANE			C	N	1"		C			MF						Installation record	N			Installation record	N			
2224	CARSTENSEN LANE			C	N	1"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2226	CARSTENSEN LANE			C	N	1"		C			MF						Installation record	N			Installation record	N			
2228	CARSTENSEN LANE			C	N	1"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2230	CARSTENSEN LANE			C	N	1"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2232	CARSTENSEN LANE			C	N	1"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2234	CARSTENSEN LANE			C	N	1"		C			MF						Installation record	N			Installation record	N			
2127	CARSTENSEN LANE			C	N	1"		C			MF						Installation record	N			Installation record	N			
2125	CARSTENSEN LANE			C	N	1"		C			MF						Installation record	N			Installation record	N			
2851	CASTLEBAR COURT			P	N	1"		C			SF						Installed after lead ban	Y	1996		Installed after lead ban	N			
2865	CASTLEBAR COURT			P	N	1"		C	1"		SF						Installed after lead ban	Y	1996		Installed after lead ban	Y		Cross-connection survey	
2850	CASTLEBAR COURT			P	N	1"					SF						Installed after lead ban	Y	1996		Installed after lead ban	N			

LOCATIONAL IDENTIFIER ADDRESS	LOCATIONAL IDENTIFIER STREET NAME	LOCATIONAL IDENTIFIER UNIT OR SUITE #	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
2860	CASTLEBAR COURT			P	N	1"					SF						Installed after lead ban	Y	1996		Installed after lead ban	N			
2867	CASTLEBAR COURT			P	N	1"		P			SF						Installed after lead ban	Y	1996		Installed after lead ban	Y		Cross-connection survey	
2861	CASTLEBAR COURT			P	N	1"		P			SF						Installed after lead ban	Y	1996		Installed after lead ban	Y		Cross-connection survey	
2392	CEDAR RIDGE			C	N	1 1/2"		C	1 1/2"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2322	CEDAR RIDGE			C	N	1"					SF						Installation record	N			Installation record	N			
2324	CEDAR RIDGE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2330	CEDAR RIDGE			C	N	1"					SF						Installation record	N			Installation record	N			
2332	CEDAR RIDGE			C	N	1"					SF						Installation record	N			Installation record	N			
2336	CEDAR RIDGE			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2338	CEDAR RIDGE			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2344	CEDAR RIDGE			C	N	1"					SF						Installation record	N			Installation record	N			
2346	CEDAR RIDGE			C	N	1"					SF						Installation record	N			Installation record	N			
2352	CEDAR RIDGE			C	N	1"					SF						Installation record	N			Installation record	N			
2354	CEDAR RIDGE			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2358	CEDAR RIDGE			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2360	CEDAR RIDGE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2364	CEDAR RIDGE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2366	CEDAR RIDGE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2370	CEDAR RIDGE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2372	CEDAR RIDGE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2378	CEDAR RIDGE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2380	CEDAR RIDGE			C	N	1"		P	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2384	CEDAR RIDGE			C	N	3/4"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2386	CEDAR RIDGE			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2390	CEDAR RIDGE			C	N	3/4"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2398	CEDAR RIDGE			C	N	1"		C			SF						Installation record	N							
2400	CEDAR RIDGE			C	N	3/4"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2404	CEDAR RIDGE	B		C	N	1 1/2"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2404	CEDAR RIDGE	D		C	N	3/4"		C			MF						Installation record	N							
2404	CEDAR RIDGE	C		C	N	3/4"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2404	CEDAR RIDGE	A		C	N	3/4"		C			MF						Installation record	N							
2404	CEDAR RIDGE	WOM		C	N	3/4"		C			MF						Installation record	N							
2408	CEDAR RIDGE	WOM		C	N	1 1/2"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2408	CEDAR RIDGE	B		C	N	3/4"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2408	CEDAR RIDGE	A		C	N	3/4"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2408	CEDAR RIDGE	C		C	N	3/4"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2408	CEDAR RIDGE	D		C	N	3/4"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2412	CEDAR RIDGE	D		C	N	1 1/2"		C			MF						Installation record	N			Installation record	N			
2412	CEDAR RIDGE	B		C	N	3/4"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2412	CEDAR RIDGE	C		C	N	3/4"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2412	CEDAR RIDGE	WOM		C	N	3/4"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2412	CEDAR RIDGE	A		C	N	3/4"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2416	CEDAR RIDGE	WOM		C	N	1"		C	1"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2416	CEDAR RIDGE	A		C	N	1 1/2"		C	1 1/2"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2416	CEDAR RIDGE	C		C	N	1"		C	1"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2416	CEDAR RIDGE	D		C	N	1"		C	1"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2416	CEDAR RIDGE	B		C	N	1"		C	1"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2409	CEDAR RIDGE	D		C	N	1"		C	1"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2409	CEDAR RIDGE	B		C	N	1 1/2"		C	1 1/2"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2409	CEDAR RIDGE	C		C	N	3/4"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2409	CEDAR RIDGE	A		C	N	1 1/2"		C	1 1/2"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2409	CEDAR RIDGE	WOM		C	N	1 1/2"		C	1 1/2"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2405	CEDAR RIDGE	WOM		C	N	1"		C	1"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2405	CEDAR RIDGE	A		C	N	3/4"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2405	CEDAR RIDGE	C		C	N	3/4"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2405	CEDAR RIDGE	B		C	N	3/4"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2405	CEDAR RIDGE	D		C	N	3/4"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2395	CEDAR RIDGE	WOM		C	N	1 1/2"		C			MF						Installation record	N			Installation record	N			
2395	CEDAR RIDGE	B		C	N	3/4"		C			MF						Installation record	N			Installation record	N			
2395	CEDAR RIDGE	A		C	N	3/4"		C			MF						Installation record	N			Installation record	N			
2395	CEDAR RIDGE	D		C	N	3/4"		C			MF						Installation record	N			Installation record	N			
2395	CEDAR RIDGE	C		C	N	3/4"		C			MF						Installation record	N			Installation record	N			
2391	CEDAR RIDGE	A		C	N	1 1/2"		C			MF						Installation record	N			Installation record	N			
2391	CEDAR RIDGE	C		C	N	3/4"		C			MF						Installation record	N			Installation record	N			
2391	CEDAR RIDGE	WOM		C	N	3/4"		C			MF						Installation record	N			Installation record	N			
2391	CEDAR RIDGE	D		C	N	3/4"		C			MF						Installation record	N			Installation record	N			
2391	CEDAR RIDGE	B		C	N	3/4"		C			MF						Installation record	N			Installation record	N			
2385	CEDAR RIDGE	A		C	N	1 1/2"		C	1 1/2"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2385	CEDAR RIDGE	B		C	N	3/4"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2385	CEDAR RIDGE	C		C	N	3/4"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2385	CEDAR RIDGE	D		C	N	3/4"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2385	CEDAR RIDGE	WOM		C	N	3/4"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2381	CEDAR RIDGE	B		C	N	1 1/2"		C			MF						Installation record	N			Installation record	N			
2381	CEDAR RIDGE	A		C	N	3/4"		C			MF						Installation record	N			Installation record	N			
2381	CEDAR RIDGE	C		C	N	3/4"		C			MF						Installation record	N			Installation record	N			
2381	CEDAR RIDGE	D		C	N	3/4"		C			MF						Installation record	N			Installation record	N			
2381	CEDAR RIDGE	WOM		C	N	3/4"		C			MF						Installation record	N			Installation record	N			
2369	CEDAR RIDGE	B		C	N	1 1/2"		C	1/2"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2369	CEDAR RIDGE	A		C	N	3/4"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2369	CEDAR RIDGE	C		C	N	3/4"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2369	CEDAR RIDGE	D		C	N	3/4"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2369	CEDAR RIDGE	WOM		C	N	3/4"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2365	CEDAR RIDGE	WOM		C	N	3/4"		C			MF						Installation record	N			Installation record	N			
2365	CEDAR RIDGE	B		C	N	3/4"		C			MF						Installation record	N			Installation record	N			
2365	CEDAR RIDGE	C		C	N	3/4"		C			MF						Installation record	N			Installation record	N			

LOCATIONAL IDENTIFIER ADDRESS	LOCATIONAL IDENTIFIER STREET NAME	LOCATIONAL IDENTIFIER UNIT OR SUITE #	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
2365	CEDAR RIDGE	A		C	N	1 1/2"		C			MF						Installation record	N			Installation record	N			
2365	CEDAR RIDGE	D		C	N	3/4"		C			MF						Installation record	N			Installation record	N			
2355	CEDAR RIDGE	D		C	N	3/4"		C			MF						Installation record	N			Installation record	N			
2355	CEDAR RIDGE	A		C	N	1 1/2"		C			MF						Installation record	N			Installation record	N			
2355	CEDAR RIDGE	B		C	N	3/4"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2355	CEDAR RIDGE	C		C	N	3/4"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2355	CEDAR RIDGE	WOM		C	N	3/4"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2351	CEDAR RIDGE	B		C	N	3/4"		C			MF						Installation record	N			Installation record	N			
2351	CEDAR RIDGE	A		C	N	1 1/2"		C			MF						Installation record	N			Installation record	N			
2351	CEDAR RIDGE	C		C	N	3/4"		C			MF						Installation record	N			Installation record	N			
2351	CEDAR RIDGE	D		C	N	3/4"		C			MF						Installation record	N			Installation record	N			
2351	CEDAR RIDGE	WOM		C	N	3/4"		C			MF						Installation record	N			Installation record	N			
2086	CENTER STREET			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2096	CENTER STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2274	CENTER STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2256	CENTER STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2115	CENTER STREET			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2119	CENTER STREET			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2210	CENTER STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2227	CENTER STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2230	CENTER STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2214	CENTER STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2189	CENTER STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2246	CENTER STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2242	CENTER STREET			C	N	1"		C	3/4"		SF						Installation record	N			Installation record	N			
2252	CENTER STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2218	CENTER STREET			C	N	1"		C	3/4"		SF						Installation record	N			Installation record	N			
2215	CENTER STREET			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2266	CENTER STREET			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2110	CENTER STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2224	CENTER STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2280	CENTER STREET			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2270	CENTER STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2262	CENTER STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2238	CENTER STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2234	CENTER STREET			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2198	CENTER STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2194	CENTER STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2190	CENTER STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2195	CENTER STREET			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2199	CENTER STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2225	CENTER STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2231	CENTER STREET			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1353	CIRCLE DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1279	CIRCLE DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1224	CIRCLE DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1191	CIRCLE DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1080	CIRCLE DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1355	CIRCLE DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1294	CIRCLE DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1105	CIRCLE DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1253	CIRCLE DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1297	CIRCLE DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1233	CIRCLE DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1086	CIRCLE DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1104	CIRCLE DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1183	CIRCLE DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1161	CIRCLE DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1147	CIRCLE DRIVE			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1143	CIRCLE DRIVE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1137	CIRCLE DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1131	CIRCLE DRIVE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1125	CIRCLE DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1095	CIRCLE DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1091	CIRCLE DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1298	CIRCLE DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1288	CIRCLE DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1280	CIRCLE DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1274	CIRCLE DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1266	CIRCLE DRIVE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1258	CIRCLE DRIVE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1250	CIRCLE DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1240	CIRCLE DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1299	CIRCLE DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1291	CIRCLE DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1285	CIRCLE DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1273	CIRCLE DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1267	CIRCLE DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1261	CIRCLE DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1212	CIRCLE DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1320	CIRCLE DRIVE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1336	CIRCLE DRIVE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1350	CIRCLE DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1360	CIRCLE DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1374	CIRCLE DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			

LOCATIONAL IDENTIFIER ADDRESS	LOCATIONAL IDENTIFIER STREET NAME	LOCATIONAL IDENTIFIER UNIT OR SUITE #	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
1377	CIRCLE DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1369	CIRCLE DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1343	CIRCLE DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1335	CIRCLE DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1327	CIRCLE DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1319	CIRCLE DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1221	CIRCLE DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1211	CIRCLE DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2931	CIRCLE OAKS LANE			P	N	1"		C	1"		SF						Installed after lead ban	Y	1992		Field inspection only	Y		Cross-connection survey	
2930	CIRCLE OAKS LANE			P	N	1"		C			SF						Installed after lead ban	Y	1992		Installed after lead ban	N			
2920	CIRCLE OAKS LANE			P	N	1"		C			SF						Installed after lead ban	Y	1992		Installed after lead ban	N			
2690	CLIVE STREET			C	N	1"		C	1"		SF						Installation record	N			Installation record	N			
2679	CLIVE STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2609	CLIVE STREET			C	N	1"		C			MF						Installation record	N			Installation record	N			
2611	CLIVE STREET			C	N	1"		C			MF						Installation record	N			Installation record	N			
2678	CLIVE STREET			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2594	CLIVE STREET			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2590	CLIVE STREET			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2650	CLIVE STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2706	CLIVE STREET			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2610	CLIVE STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2600	CLIVE STREET			C	N	1"		C	1"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2598	CLIVE STREET			C	N	1"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2584	CLIVE STREET			C	N	1"		C			MF						Installation record	N			Installation record	N			
2582	CLIVE STREET			C	N	1"		C			MF						Installation record	N			Installation record	N			
2570	CLIVE STREET			C	N	1"		C			MF						Installation record	N			Installation record	N			
2651	CLIVE STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2661	CLIVE STREET			C	N	1"		C	1"		SF						Installation record	N			Installation record	N			
2660	CLIVE STREET			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2583	CLIVE STREET			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2601	CLIVE STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2716	CLIVE STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2732	CLIVE STREET			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2744	CLIVE STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2743	CLIVE STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2733	CLIVE STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2717	CLIVE STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2711	CLIVE STREET			C	N	1"		C	3/4"		SF						Installation record	N			Installation record	N			
2705	CLIVE STREET			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2697	CLIVE STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2689	CLIVE STREET			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
539	COLLETTE AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
520	COLLETTE AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
495	COLLETTE AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
446	COLLETTE AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
525	COLLETTE AVENUE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
527	COLLETTE AVENUE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
528	COLLETTE AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
490	COLLETTE AVENUE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
524	COLLETTE AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
501	COLLETTE AVENUE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
484	COLLETTE AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
451	COLLETTE AVENUE			C	N	1"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
455	COLLETTE AVENUE			C	N	1"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
463	COLLETTE AVENUE			C	N	1"		C			MF						Installation record	N			Installation record	N			
467	COLLETTE AVENUE			C	N	1"		C			MF						Installation record	N			Installation record	N			
454	COLLETTE AVENUE			C	N	1"		C	3/4"		MF						Installation record	N			Installation record	N			
456	COLLETTE AVENUE			C	N	1"		C	3/4"		MF						Installation record	N			Installation record	N			
551	COLLETTE AVENUE			C	N	1"		C	1"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
542	COLLETTE AVENUE			C	N	1"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
538	COLLETTE AVENUE			C	N	1"		C			MF						Installation record	N			Installation record	N			
534	COLLETTE AVENUE			C	N	1"		C			MF						Installation record	N			Installation record	N			
496	COLLETTE AVENUE			C	N	1"		C			MF						Installation record	N			Installation record	N			
491	COLLETTE AVENUE			C	N	1"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1497	COMMANCHE AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1488	COMMANCHE AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1424	COMMANCHE AVENUE			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1295	COMMANCHE AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1452	COMMANCHE AVENUE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1509	COMMANCHE AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1411	COMMANCHE AVENUE			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1429	COMMANCHE AVENUE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1427	COMMANCHE AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1541	COMMANCHE AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1440	COMMANCHE AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1587	COMMANCHE AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1589	COMMANCHE AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1504	COMMANCHE AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1483	COMMANCHE AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1525	COMMANCHE AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1439	COMMANCHE AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1477	COMMANCHE AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1621	COMMANCHE AVENUE			C	N	1"		C			MF						Installation record	N			Installation record	N			
1549	COMMANCHE AVENUE			C	N	1"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1551	COMMANCHE AVENUE			C	N	1"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	

LOCATIONAL IDENTIFIER ADDRESS	LOCATIONAL IDENTIFIER STREET NAME	LOCATIONAL IDENTIFIER UNIT OR SUITE #	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
1557	COMMANCHE AVENUE			C	N	1"		C	1"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1559	COMMANCHE AVENUE			C	N	1"		C			MF						Installation record	N			Installation record	N			
1565	COMMANCHE AVENUE			C	N	1"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1567	COMMANCHE AVENUE			C	N	1"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1571	COMMANCHE AVENUE			C	N	1"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1573	COMMANCHE AVENUE			C	N	1"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1579	COMMANCHE AVENUE			C	N	1"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1581	COMMANCHE AVENUE			C	N	1"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1595	COMMANCHE AVENUE			C	N	1"		C			MF						Installation record	N			Installation record	N			
1597	COMMANCHE AVENUE			C	N	1"		C			MF						Installation record	N			Installation record	N			
1601	COMMANCHE AVENUE			C	N	1"		C	1"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1603	COMMANCHE AVENUE			C	N	1"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1390	COMMANCHE AVENUE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1410	COMMANCHE AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1426	COMMANCHE AVENUE			C	N	1"		C			MF						Installation record	N			Installation record	N			
1428	COMMANCHE AVENUE			C	N	1"		C			MF						Installation record	N			Installation record	N			
1432	COMMANCHE AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1446	COMMANCHE AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1476	COMMANCHE AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1482	COMMANCHE AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1494	COMMANCHE AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1498	COMMANCHE AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1510	COMMANCHE AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1518	COMMANCHE AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1521	COMMANCHE AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1517	COMMANCHE AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1503	COMMANCHE AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1491	COMMANCHE AVENUE			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1451	COMMANCHE AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1445	COMMANCHE AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1433	COMMANCHE AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1425	COMMANCHE AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1401	COMMANCHE AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1391	COMMANCHE AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1289	COMMANCHE AVENUE			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1281	COMMANCHE AVENUE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1275	COMMANCHE AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1267	COMMANCHE AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1261	COMMANCHE AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1255	COMMANCHE AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1249	COMMANCHE AVENUE			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1247	COMMANCHE AVENUE			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1869	CORMIER RD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1308	CORMIER ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1139	CORMIER ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1512	CORMIER ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1785	CORMIER ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1613	CORMIER ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1186	CORMIER ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1528	CORMIER ROAD			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1374	CORMIER ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1557	CORMIER ROAD			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1638	CORMIER ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1098	CORMIER ROAD			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1386	CORMIER ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1111	CORMIER ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1210	CORMIER ROAD			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1681	CORMIER ROAD			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1668	CORMIER ROAD			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1200	CORMIER ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1591	CORMIER ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1106	CORMIER ROAD			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1116	CORMIER ROAD			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1521	CORMIER ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1481	CORMIER ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1216	CORMIER ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1520	CORMIER ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1105	CORMIER ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1157	CORMIER ROAD			C	N	1"		C	1"		SF						Installation record	N			Installation record	N			
1487	CORMIER ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1293	CORMIER ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1125	CORMIER ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1493	CORMIER ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1140	CORMIER ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1151	CORMIER ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1305	CORMIER ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1657	CORMIER ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1599	CORMIER ROAD			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1365	CORMIER ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1454	CORMIER ROAD			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1695	CORMIER ROAD			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
986	CORMIER ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1664	CORMIER ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1767	CORMIER ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1507	CORMIER ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			

LOCATIONAL IDENTIFIER ADDRESS	LOCATIONAL IDENTIFIER STREET NAME	LOCATIONAL IDENTIFIER UNIT OR SUITE #	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
1753	CORMIER ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1751	CORMIER ROAD			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1513	CORMIER ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
568	CORMIER ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
566	CORMIER ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1556	CORMIER ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1299	CORMIER ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
966	CORMIER ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1290	CORMIER ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1145	CORMIER ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1165	CORMIER ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1606	CORMIER ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1124	CORMIER ROAD			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1162	CORMIER ROAD			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1351	CORMIER ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1488	CORMIER ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1737	CORMIER ROAD			C	N	1"		C			MF						Installation record	N			Installation record	N			
1735	CORMIER ROAD			C	N	1"		C			MF						Installation record	N			Installation record	N			
1652	CORMIER ROAD			C	N	1"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1654	CORMIER ROAD			C	N	1"		C			MF						Installation record	N			Installation record	N			
1439	CORMIER ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1501	CORMIER ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1357	CORMIER ROAD			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1777	CORMIER ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1411	CORMIER ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1395	CORMIER ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1171	CORMIER ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1573	CORMIER ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1550	CORMIER ROAD			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1412	CORMIER ROAD			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1300	CORMIER ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1306	CORMIER ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1320	CORMIER ROAD			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1340	CORMIER ROAD			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1342	CORMIER ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1350	CORMIER ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1360	CORMIER ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1368	CORMIER ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1382	CORMIER ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1400	CORMIER ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1404	CORMIER ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1430	CORMIER ROAD			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1446	CORMIER ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1531	CORMIER ROAD			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1473	CORMIER ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1469	CORMIER ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1451	CORMIER ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1445	CORMIER ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1431	CORMIER ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1423	CORMIER ROAD			C	N	1"		C	3/4"		SF						Installation record	N			Installation record	N			
1417	CORMIER ROAD			C	N	1"		C	1"		SF						Installation record	N			Installation record	N			
1405	CORMIER ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1387	CORMIER ROAD			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1379	CORMIER ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1371	CORMIER ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1345	CORMIER ROAD			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1323	CORMIER ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1317	CORMIER ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1311	CORMIER ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
558	CORMIER ROAD			C	N	1"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
556	CORMIER ROAD			C	N	1"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
523	CORMIER ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1131	CORMIER ROAD			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1119	CORMIER ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1080	CORMIER ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1088	CORMIER ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1132	CORMIER ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1154	CORMIER ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1170	CORMIER ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1178	CORMIER ROAD			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1194	CORMIER ROAD			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1474	CORMIER ROAD			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1480	CORMIER ROAD			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1494	CORMIER ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1500	CORMIER ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1506	CORMIER ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1544	CORMIER ROAD			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1560	CORMIER ROAD			C	N	1"		C			MF						Installation record	N			Installation record	N			
1562	CORMIER ROAD			C	N	1"		C			MF						Installation record	N			Installation record	N			
1566	CORMIER ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1576	CORMIER ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1584	CORMIER ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1596	CORMIER ROAD			C	N	1"		C			MF						Installation record	N			Installation record	N			
1598	CORMIER ROAD			C	N	1"		C			MF						Installation record	N			Installation record	N			
1618	CORMIER ROAD			C	N	1"		C	3/4"		SF						Installation record	N			Installation record	N			

LOCATIONAL IDENTIFIER ADDRESS	LOCATIONAL IDENTIFIER STREET NAME	LOCATIONAL IDENTIFIER UNIT OR SUITE #	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
1624	CORMIER ROAD			C	N	1"		C	1"		MF						Installation record	N			Installation record	N			
1630	CORMIER ROAD			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1646	CORMIER ROAD			C	N	1"		C	1"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1648	CORMIER ROAD			C	N	1"		C	1"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1680	CORMIER ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1686	CORMIER ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
944	CORMIER ROAD			C	N	1"		C	1"		SF						Installation record	N			Installation record	N			
950	CORMIER ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
956	CORMIER ROAD			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
976	CORMIER ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
980	CORMIER ROAD			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
988	CORMIER ROAD			C	N	1"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
990	CORMIER ROAD			C	N	1"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
996	CORMIER ROAD			C	N	1"		C	1"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
998	CORMIER ROAD			C	N	1"		C	1"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1006	CORMIER ROAD			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1861	CORMIER ROAD			C	N	1"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1857	CORMIER ROAD	DOWN		C	N	1"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1849	CORMIER ROAD			C	N	1"		C			MF						Installation record	N			Installation record	N			
1847	CORMIER ROAD			C	N	1"		C			MF						Installation record	N			Installation record	N			
1843	CORMIER ROAD			C	N	1"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1841	CORMIER ROAD			C	N	1"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1837	CORMIER ROAD			C	N	1"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1835	CORMIER ROAD			C	N	1"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1829	CORMIER ROAD			C	N	1"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1827	CORMIER ROAD			C	N	1"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1823	CORMIER ROAD			C	N	1"		C			MF						Installation record	N			Installation record	N			
1821	CORMIER ROAD			C	N	1"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1815	CORMIER ROAD			C	N	1"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1813	CORMIER ROAD			C	N	1"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1801	CORMIER ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1761	CORMIER ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1745	CORMIER ROAD			C	N	1"		C			MF						Installation record	N			Installation record	N			
1741	CORMIER ROAD			C	N	1"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1725	CORMIER ROAD			C	N	1"		C			MF						Installation record	N			Installation record	N			
1723	CORMIER ROAD			C	N	1"		C			MF						Installation record	N			Installation record	N			
1705	CORMIER ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1665	CORMIER ROAD			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1647	CORMIER ROAD			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1639	CORMIER ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1631	CORMIER ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1623	CORMIER ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1607	CORMIER ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1583	CORMIER ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1563	CORMIER ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1553	CORMIER ROAD			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1545	CORMIER ROAD			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
454	COTTAGE GROVE AVENUE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
495	COTTAGE GROVE AVENUE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
489	COTTAGE GROVE AVENUE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
485	COTTAGE GROVE AVENUE			C	N	1"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
483	COTTAGE GROVE AVENUE			C	N	1"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
457	COTTAGE GROVE AVENUE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
527	COTTAGE GROVE AVENUE			C	N	1"		C			MF						Installation record	N			Installation record	N			
525	COTTAGE GROVE AVENUE			C	N	1"		C			MF						Installation record	N			Installation record	N			
533	COTTAGE GROVE AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
440	COTTAGE GROVE AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
484	COTTAGE GROVE AVENUE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
492	COTTAGE GROVE AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
475	COTTAGE GROVE AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
436	COTTAGE GROVE AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
470	COTTAGE GROVE AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
528	COTTAGE GROVE AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
460	COTTAGE GROVE AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
437	COTTAGE GROVE AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
521	COTTAGE GROVE AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
464	COTTAGE GROVE AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
505	COTTAGE GROVE AVENUE			C	N	1"		C			MF						Installation record	N			Installation record	N			
503	COTTAGE GROVE AVENUE			C	N	1"		C			MF						Installation record	N			Installation record	N			
471	COTTAGE GROVE AVENUE			C	N	1"		C			MF						Installation record	N			Installation record	N			
469	COTTAGE GROVE AVENUE			C	N	1"		C			MF						Installation record	N			Installation record	N			
488	COTTAGE GROVE AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
446	COTTAGE GROVE AVENUE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
522	COTTAGE GROVE AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
467	COTTAGE GROVE AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
443	COTTAGE GROVE AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
532	COTTAGE GROVE AVENUE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
453	COTTAGE GROVE AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
511	COTTAGE GROVE AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
514	COTTAGE GROVE AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
478	COTTAGE GROVE AVENUE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
447	COTTAGE GROVE AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
474	COTTAGE GROVE AVENUE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
508	COTTAGE GROVE AVENUE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
450	COTTAGE GROVE AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			

LOCATIONAL IDENTIFIER ADDRESS	LOCATIONAL IDENTIFIER STREET NAME	LOCATIONAL IDENTIFIER UNIT OR SUITE #	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
431	COTTAGE GROVE AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
461	COTTAGE GROVE AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
518	COTTAGE GROVE AVENUE			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
504	COTTAGE GROVE AVENUE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
529	COTTAGE GROVE AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
515	COTTAGE GROVE AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2116	N COURTLAND DRIVE			P	N	1"		C			SF						Installed after lead ban	Y	1992		Installation record	N			
2170	S COURTLAND DRIVE			P	N	1"		C			SF						Installed after lead ban	Y	1992		Installation record	N			
2166	S COURTLAND DRIVE			P	N	1"		C	3/4"		SF						Installed after lead ban	Y	1992		Field inspection only	Y		Cross-connection survey	
2117	N COURTLAND DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	1992		Field inspection only	Y		Cross-connection survey	
2121	N COURTLAND DRIVE			P	N	1"		P	3/4"		SF						Installed after lead ban	Y	1992		Field inspection only	Y		Cross-connection survey	
2120	N COURTLAND DRIVE			P	N	1"		C	3/4"		SF						Installed after lead ban	Y	1992		Field inspection only	Y		Cross-connection survey	
2110	N COURTLAND DRIVE			P	N	1"		C	3/4"		SF						Installed after lead ban	Y	1992		Field inspection only	Y		Cross-connection survey	
2115	N COURTLAND DRIVE			P	N	1"		C			SF						Installed after lead ban	Y	1992		Installation record	N			
2141	S COURTLAND DRIVE			P	N	1"		C			SF						Installed after lead ban	Y	1992		Installation record	N			
2151	S COURTLAND DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	1992		Field inspection only	Y		Cross-connection survey	
2161	S COURTLAND DRIVE			P	N	1"		C	3/4"		SF						Installed after lead ban	Y	1992		Field inspection only	Y		Cross-connection survey	
2167	S COURTLAND DRIVE			P	N	1"		C	1"		SF						Installed after lead ban	Y	1992		Field inspection only	Y		Cross-connection survey	
2171	S COURTLAND DRIVE			P	N	1"		C			SF						Installed after lead ban	Y	1992		Installation record	N			
2175	S COURTLAND DRIVE			P	N	1"		C			SF						Installed after lead ban	Y	1992		Installation record	N			
2174	S COURTLAND DRIVE			P	N	1"		C			SF						Installed after lead ban	Y	1992		Installation record	N			
2160	S COURTLAND DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	1992		Field inspection only	Y		Cross-connection survey	
2150	S COURTLAND DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	1992		Field inspection only	Y		Cross-connection survey	
2150	CRARY STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2191	CRARY STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2082	CRARY STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2119	CRARY STREET			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2058	CRARY STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2118	CRARY STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2215	CRARY STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2144	CRARY STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2231	CRARY STREET			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2246	CRARY STREET			C	N	1"		C			MF						Installation record	N			Installation record	N			
2250	CRARY STREET			C	N	1"		C			MF						Installation record	N			Installation record	N			
2136	CRARY STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2158	CRARY STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2146	CRARY STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2262	CRARY STREET			C	N	1"		C			MF						Installation record	N			Installation record	N			
2264	CRARY STREET			C	N	1"		C			MF						Installation record	N			Installation record	N			
2223	CRARY STREET			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2132	CRARY STREET			C	N	1"		C			MF						Installation record	N			Installation record	N			
2130	CRARY STREET			C	N	1"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2126	CRARY STREET			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2114	CRARY STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2106	CRARY STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2102	CRARY STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2074	CRARY STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2078	CRARY STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2138	CRARY STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2152	CRARY STREET			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2160	CRARY STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2164	CRARY STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2166	CRARY STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2172	CRARY STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2174	CRARY STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2178	CRARY STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2180	CRARY STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2188	CRARY STREET			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2190	CRARY STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2196	CRARY STREET			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2198	CRARY STREET			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2204	CRARY STREET			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2206	CRARY STREET			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2212	CRARY STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2214	CRARY STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2218	CRARY STREET			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2220	CRARY STREET			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2228	CRARY STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2230	CRARY STREET			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2232	CRARY STREET			C	N	1"		P	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2234	CRARY STREET			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2240	CRARY STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2242	CRARY STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2254	CRARY STREET			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2258	CRARY STREET			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2213	CRARY STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2221	CRARY STREET			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2229	CRARY STREET			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2235	CRARY STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2239	CRARY STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2243	CRARY STREET			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2245	CRARY STREET			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2251	CRARY STREET			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2255	CRARY STREET			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2257	CRARY STREET			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	

LOCATIONAL IDENTIFIER ADDRESS	LOCATIONAL IDENTIFIER STREET NAME	LOCATIONAL IDENTIFIER UNIT OR SUITE #	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
2259	CRARY STREET			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2265	CRARY STREET			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2267	CRARY STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2273	CRARY STREET			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2275	CRARY STREET			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2279	CRARY STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2207	CRARY STREET			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2193	CRARY STREET			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2050	CRARY STREET			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2054	CRARY STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2066	CRARY STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2070	CRARY STREET			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2068	CRARY STREET			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
3571	CROCUS DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2005		Installed after lead ban	Y		Visual insp during install or repair	
3554	CROCUS DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2005		Installed after lead ban	Y		Visual insp during install or repair	
3610	CROCUS DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2005		Installed after lead ban	Y		Visual insp during install or repair	
3634	CROCUS DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2005		Installed after lead ban	Y		Visual insp during install or repair	
3594	CROCUS DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2005		Installed after lead ban	Y		Visual insp during install or repair	
3498	CROCUS DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2005		Installed after lead ban	Y		Visual insp during install or repair	
3635	CROCUS DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2005		Installed after lead ban	Y		Visual insp during install or repair	
3547	CROCUS DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2005		Installed after lead ban	Y		Visual insp during install or repair	
3539	CROCUS DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2005		Installed after lead ban	Y		Visual insp during install or repair	
3563	CROCUS DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2005		Installed after lead ban	Y		Visual insp during install or repair	
3499	CROCUS DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2005		Installed after lead ban	Y		Visual insp during install or repair	
3530	CROCUS DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2005		Installed after lead ban	Y		Visual insp during install or repair	
3579	CROCUS DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2005		Installed after lead ban	Y		Visual insp during install or repair	
3522	CROCUS DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2005		Installed after lead ban	Y		Visual insp during install or repair	
3595	CROCUS DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2005		Installed after lead ban	Y		Visual insp during install or repair	
3587	CROCUS DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2005		Installed after lead ban	Y		Visual insp during install or repair	
3603	CROCUS DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2005		Installed after lead ban	Y		Visual insp during install or repair	
3538	CROCUS DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2005		Installed after lead ban	Y		Visual insp during install or repair	
3619	CROCUS DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2005		Installed after lead ban	Y		Visual insp during install or repair	
3611	CROCUS DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2005		Installed after lead ban	Y		Visual insp during install or repair	
3514	CROCUS DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2005		Installed after lead ban	Y		Visual insp during install or repair	
3602	CROCUS DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2005		Installed after lead ban	Y		Visual insp during install or repair	
3586	CROCUS DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2005		Installed after lead ban	Y		Visual insp during install or repair	
3618	CROCUS DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2005		Installed after lead ban	Y		Visual insp during install or repair	
3506	CROCUS DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2005		Installed after lead ban	Y		Visual insp during install or repair	
3570	CROCUS DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2005		Installed after lead ban	Y		Visual insp during install or repair	
3507	CROCUS DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2005		Installed after lead ban	Y		Visual insp during install or repair	
3555	CROCUS DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2005		Installed after lead ban	Y		Visual insp during install or repair	
3578	CROCUS DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2005		Installed after lead ban	Y		Visual insp during install or repair	
3626	CROCUS DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2005		Installed after lead ban	Y		Visual insp during install or repair	
2891	CROSSHAVEN AVENUE			P	N	1"		C			SF						Installed after lead ban	Y	1994		Installed after lead ban	Y		Visual insp during install or repair	
2919	CROSSHAVEN AVENUE			P	N	1"		C			SF						Installed after lead ban	Y	1994		Installed after lead ban	Y		Visual insp during install or repair	
2905	CROSSHAVEN AVENUE			P	N	1"		C			SF						Installed after lead ban	Y	1994		Installed after lead ban	Y		Visual insp during install or repair	
2866	CROSSHAVEN AVENUE			P	N	1"		C			SF						Installed after lead ban	Y	1994		Installed after lead ban	Y		Visual insp during install or repair	
2867	CROSSHAVEN AVENUE			P	N	1"		C	1"		SF						Installed after lead ban	Y	1994		Field inspection only	Y		Cross-connection survey	
2861	CROSSHAVEN AVENUE			P	N	1"		C	1"		SF						Installed after lead ban	Y	1994		Field inspection only	Y		Cross-connection survey	
2871	CROSSHAVEN AVENUE			P	N	1"		C	1"		SF						Installed after lead ban	Y	1994		Installed after lead ban	Y		Visual insp during install or repair	
2879	CROSSHAVEN AVENUE			P	N	1"		C	3/4"		SF						Installed after lead ban	Y	1994		Field inspection only	Y		Cross-connection survey	
2870	CROSSHAVEN AVENUE			P	N	1"		C			SF						Installed after lead ban	Y	1994		Installed after lead ban	Y		Visual insp during install or repair	
2910	CROSSHAVEN AVENUE			P	N	1"		C			SF						Installed after lead ban	Y	1994		Installed after lead ban	Y		Visual insp during install or repair	
2885	CROSSHAVEN AVENUE			P	N	1"		C			SF						Installed after lead ban	Y	1994		Installed after lead ban	Y		Visual insp during install or repair	
2911	CROSSHAVEN AVENUE			P	N	1"		C			SF						Installed after lead ban	Y	1994		Installed after lead ban	Y		Visual insp during install or repair	
2901	CROSSHAVEN AVENUE			P	N	1"		C	1"		SF						Installed after lead ban	Y	1994		Installed after lead ban	Y		Visual insp during install or repair	
2860	CROSSHAVEN AVENUE			P	N	1"		C			SF						Installed after lead ban	Y	1994		Installed after lead ban	Y		Visual insp during install or repair	
2920	CROSSHAVEN AVENUE			P	N	1"		C			SF						Installed after lead ban	Y	1994		Installed after lead ban	Y		Visual insp during install or repair	
971	DAFFODIL DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2005		Installed after lead ban	Y		Visual insp during install or repair	
1006	DAFFODIL DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2005		Installed after lead ban	Y		Visual insp during install or repair	
985	DAFFODIL DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2005		Installed after lead ban	Y		Visual insp during install or repair	
975	DAFFODIL DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2005		Installed after lead ban	Y		Visual insp during install or repair	
965	DAFFODIL DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2005		Installed after lead ban	Y		Visual insp during install or repair	
1030	DAFFODIL DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2005		Installed after lead ban	Y		Visual insp during install or repair	
1014	DAFFODIL DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2005		Installed after lead ban	Y		Visual insp during install or repair	
979	DAFFODIL DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2005		Installed after lead ban	Y		Visual insp during install or repair	
976	DAFFODIL DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2005		Installed after lead ban	Y		Visual insp during install or repair	
966	DAFFODIL DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2005		Installed after lead ban	Y		Visual insp during install or repair	
950	DAFFODIL DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2005		Installed after lead ban	Y		Visual insp during install or repair	
949	DAFFODIL DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2005		Installed after lead ban	Y		Visual insp during install or repair	
972	DAFFODIL DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2005		Installed after lead ban	Y		Visual insp during install or repair	
980	DAFFODIL DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2005		Installed after lead ban	Y		Visual insp during install or repair	
986	DAFFODIL DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2005		Installed after lead ban	Y		Visual insp during install or repair	
998	DAFFODIL DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2005		Installed after lead ban	Y		Visual insp during install or repair	
997	DAFFODIL DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2005		Installed after lead ban	Y		Visual insp during install or repair	
1038	DAFFODIL DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2005		Installed after lead ban	Y		Visual insp during install or repair	
990	DAFFODIL DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2005		Installed after lead ban	Y		Visual insp during install or repair	
1037	DAFFODIL DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2005		Installed after lead ban	Y		Visual insp during install or repair	
1029	DAFFODIL DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2005		Installed after lead ban	Y		Visual insp during install or repair	
1022	DAFFODIL DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2005		Installed after lead ban	Y		Visual insp during install or repair	
1021	DAFFODIL DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2005		Installed after lead ban	Y		Visual insp during install or repair	
989	DAFFODIL DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2005		Installed after lead ban	Y		Visual insp during install or repair	
1005	DAFFODIL DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2005		Installed after lead ban	Y		Visual insp during install or repair	
1013	DAFFODIL DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2005		Installed after lead ban	Y		Visual insp during install or repair	
1093	DAISY LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			

LOCATIONAL IDENTIFIER ADDRESS	LOCATIONAL IDENTIFIER STREET NAME	LOCATIONAL IDENTIFIER UNIT OR SUITE #	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
1120	DAISY LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1084	DAISY LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1064	DAISY LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1070	DAISY LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1078	DAISY LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1090	DAISY LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1098	DAISY LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1099	DAISY LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1095	DAISY LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1079	DAISY LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1071	DAISY LANE			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1065	DAISY LANE			C	N	1"		C	3/4"		SF						Installation record	N			Installation record	N			
1134	DAISY LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1124	DAISY LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1112	DAISY LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1104	DAISY LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1107	DAISY LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1113	DAISY LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1121	DAISY LANE			C	N	1"		C	1"		SF						Installation record	N			Installation record	N			
1127	DAISY LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1135	DAISY LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2347	DEW LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2391	DEW LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2388	DEW LANE			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2376	DEW LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2362	DEW LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2336	DEW LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2342	DEW LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2381	DEW LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2375	DEW LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2369	DEW LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2361	DEW LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2355	DEW LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2348	DEW LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2356	DEW LANE			C	N	1"		C	3/4"		SF						Installation record	N			Installation record	N			
2370	DEW LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2382	DEW LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2394	DEW LANE			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2466	DONEY STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2445	DONEY STREET			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2452	DONEY STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2436	DONEY STREET			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2444	DONEY STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2458	DONEY STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2467	DONEY STREET			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2459	DONEY STREET			C	N	1"		C	3/4"		SF						Installation record	N			Installation record	N			
2453	DONEY STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2437	DONEY STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2352	DORN DRIVE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2346	DORN DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2357	DORN DRIVE			C	N	1"		C	1"		SF						Installation record	N			Installation record	N			
2297	DORN DRIVE			C	N	1"		C	1"		SF						Installation record	N			Installation record	Y		Cross-connection survey	
2305	DORN DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2306	DORN DRIVE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2326	DORN DRIVE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2336	DORN DRIVE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2349	DORN DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2341	DORN DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2331	DORN DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2191	DOROTHY LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2143	DOROTHY LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2152	DOROTHY LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2213	DOROTHY LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2178	DOROTHY LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2221	DOROTHY LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2219	DOROTHY LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2205	DOROTHY LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2197	DOROTHY LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2185	DOROTHY LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2177	DOROTHY LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2171	DOROTHY LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2163	DOROTHY LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2157	DOROTHY LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2149	DOROTHY LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2146	DOROTHY LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2160	DOROTHY LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2166	DOROTHY LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2172	DOROTHY LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2186	DOROTHY LANE			C	N	1"		C	1"		SF						Installation record	N			Installation record	N			
2192	DOROTHY LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2198	DOROTHY LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2206	DOROTHY LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2212	DOROTHY LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2220	DOROTHY LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2140	DOROTHY LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			

LOCATIONAL IDENTIFIER ADDRESS	LOCATIONAL IDENTIFIER STREET NAME	LOCATIONAL IDENTIFIER UNIT OR SUITE #	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
2141	DOROTHY LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2110	DOVE STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2080	DOVE STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2099	DOVE STREET			C	N	1"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2101	DOVE STREET			C	N	1"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2109	DOVE STREET			C	N	1"		C	1/2"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2111	DOVE STREET			C	N	1"		C	1/2"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2100	DOVE STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2070	DOVE STREET			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1250	DOVER LANE			C	N	1"		C			SF						Installation record	N			Installation record	Y			
1275	DOVER LANE			C	N	1"		C	1"		SF						Installation record	N			Installation record	Y			
1280	DOVER LANE			C	N	1"		C			SF						Installation record	N			Installation record	Y			
1276	DOVER LANE			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1272	DOVER LANE			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1266	DOVER LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1260	DOVER LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1281	DOVER LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1241	DOVER LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1247	DOVER LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1253	DOVER LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1261	DOVER LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1267	DOVER LANE			C	N	1"		C			SF						Installation record	N			Field inspection only	N			
945	DUCHATEAU AVENUE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
920	DUCHATEAU AVENUE			C	N	1"		C	1"		SF						Installation record	N			Installation record	N			
917	DUCHATEAU AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
913	DUCHATEAU AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
921	DUCHATEAU AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
931	DUCHATEAU AVENUE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
937	DUCHATEAU AVENUE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
951	DUCHATEAU AVENUE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
957	DUCHATEAU AVENUE			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
965	DUCHATEAU AVENUE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
971	DUCHATEAU AVENUE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
979	DUCHATEAU AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
985	DUCHATEAU AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
984	DUCHATEAU AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
976	DUCHATEAU AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
970	DUCHATEAU AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
964	DUCHATEAU AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
956	DUCHATEAU AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
950	DUCHATEAU AVENUE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
944	DUCHATEAU AVENUE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
936	DUCHATEAU AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
932	DUCHATEAU AVENUE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
924	DUCHATEAU AVENUE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
912	DUCHATEAU AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
505	DUTTON AVENUE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
464	DUTTON AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
502	DUTTON AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
473	DUTTON AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
483	DUTTON AVENUE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
480	DUTTON AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
468	DUTTON AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
482	DUTTON AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
516	DUTTON AVENUE			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
469	DUTTON AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
533	DUTTON AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
526	DUTTON AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
514	DUTTON AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
493	DUTTON AVENUE			C	N	1"		C			MF						Installation record	N			Installation record	N			
493	DUTTON AVENUE	B		C	N	1"		C			MF						Installation record	N			Installation record	N			
525	DUTTON AVENUE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
509	DUTTON AVENUE			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
508	DUTTON AVENUE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
460	DUTTON AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
537	DUTTON AVENUE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
532	DUTTON AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
485	DUTTON AVENUE			C	N	1"		C			MF						Installation record	N			Installation record	N			
487	DUTTON AVENUE			C	N	1"		C			MF						Installation record	N			Installation record	N			
536	DUTTON AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
513	DUTTON AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
479	DUTTON AVENUE			C	N	1"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
477	DUTTON AVENUE			C	N	1"		C			MF						Installation record	N			Installation record	N			
465	DUTTON AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
517	DUTTON AVENUE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
543	DUTTON AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
538	DUTTON AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
520	DUTTON AVENUE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
512	DUTTON AVENUE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2127	EARLY ST			C	N	1"		C			SF						Installation record	N			Installation record	N			
2122	EARLY STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2217	Early Street			C	N	1"		P	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2159	EARLY STREET			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2227	EARLY STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2205	EARLY STREET			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	

LOCATIONAL IDENTIFIER ADDRESS	LOCATIONAL IDENTIFIER STREET NAME	LOCATIONAL IDENTIFIER UNIT OR SUITE #	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
2155	EARLY STREET			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2151	EARLY STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2134	EARLY STREET			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2241	EARLY STREET			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2130	EARLY STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2139	EARLY STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2131	EARLY STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2212	EARLY STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2206	EARLY STREET			C	N	1"		C	1"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2204	EARLY STREET			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2118	EARLY STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2248	EARLY STREET			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2230	EARLY STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2207	EARLY STREET			C	N	1"		C	1"		SF						Installation record	N			Installation record	N			
2157	EARLY STREET			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2187	EARLY STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2154	EARLY STREET			C	N	1"		C	1"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2152	EARLY STREET			C	N	1"		C	1"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2135	EARLY STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2250	EARLY STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2255	EARLY STREET			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2249	EARLY STREET			C	N	1"		C	1"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2247	EARLY STREET			C	N	1"		C			MF						Installation record	N			Installation record	N			
2246	EARLY STREET			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2158	EARLY STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2231	EARLY STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2190	EARLY STREET	UPPER		C	N	1"		C			SF						Installation record	N			Installation record	N			
2190	EARLY STREET	LOWER		C	N	1"		C			SF						Installation record	N			Installation record	N			
2237	EARLY STREET			C	N	1"		C			MF						Installation record	N			Installation record	N			
2238	EARLY STREET			C	N	1"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2240	EARLY STREET			C	N	1"		C			MF						Installation record	N			Installation record	N			
2143	EARLY STREET			C	N	1"		C			MF						Installation record	N			Installation record	N			
2156	EARLY STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2126	EARLY STREET			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2153	EARLY STREET			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2200	EARLY STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2198	EARLY STREET			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2160	EARLY STREET			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1261	ECHO LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1191	ECHO LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1295	ECHO LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1274	ECHO LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1127	ECHO LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1204	ECHO LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1247	ECHO LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1097	ECHO LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1285	ECHO LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1064	ECHO LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1070	ECHO LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1078	ECHO LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1084	ECHO LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1091	ECHO LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1085	ECHO LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1077	ECHO LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1071	ECHO LANE			C	N	1"		C	3/4"		SF						Installation record	N			Installation record	N			
1065	ECHO LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1140	ECHO LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1130	ECHO LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1154	ECHO LANE			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1160	ECHO LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1166	ECHO LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1172	ECHO LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1178	ECHO LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1184	ECHO LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1192	ECHO LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1198	ECHO LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1210	ECHO LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1216	ECHO LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1242	ECHO LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1248	ECHO LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1254	ECHO LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1262	ECHO LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1268	ECHO LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1280	ECHO LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1284	ECHO LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1294	ECHO LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1302	ECHO LANE			C	N	1"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1304	ECHO LANE			C	N	1"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1289	ECHO LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1267	ECHO LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1253	ECHO LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1239	ECHO LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1237	ECHO LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1217	ECHO LANE			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1163	ECHO LANE			C	N	1"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	

LOCATIONAL IDENTIFIER ADDRESS	LOCATIONAL IDENTIFIER STREET NAME	LOCATIONAL IDENTIFIER UNIT OR SUITE #	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
1161	ECHO LANE			C	N	1"		C			MF						Installation record	N			Installation record	N			
1135	ECHO LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1121	ECHO LANE			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1115	ECHO LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1105	ECHO LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
3641	Ella Jo Wy			P	N	1"		P	1"		SF						Installed after lead ban	Y	2022		Installed after lead ban	Y		Visual insp during install or repair	
2101	ELMVIEW DRIVE			C	N	3/4"		C	3/4"		SF						Installation record	N			Installation record	N			
2130	ELMVIEW DRIVE	C		C	N	3/4"		C			MF						Installation record	N			Installation record	N			
2130	ELMVIEW DRIVE	D		C	N	3/4"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2130	ELMVIEW DRIVE	B		C	N	3/4"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2130	ELMVIEW DRIVE	E		C	N	3/4"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2130	ELMVIEW DRIVE	F		C	N	3/4"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2130	ELMVIEW DRIVE	A		C	N	3/4"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2130	ELMVIEW DRIVE	G		C	N	3/4"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2130	ELMVIEW DRIVE	H		C	N	3/4"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2120	ELMVIEW DRIVE	I		C	N	3/4"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2120	ELMVIEW DRIVE	J		C	N	3/4"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2120	ELMVIEW DRIVE	K		C	N	3/4"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2120	ELMVIEW DRIVE	L		C	N	3/4"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2120	ELMVIEW DRIVE	M		C	N	3/4"		C			MF						Installation record	N			Installation record	N			
2120	ELMVIEW DRIVE	N		C	N	3/4"		C			MF						Installation record	N			Installation record	N			
2112	ELMVIEW DRIVE			C	N	3/4"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2110	ELMVIEW DRIVE			C	N	3/4"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2106	ELMVIEW DRIVE			C	N	3/4"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2104	ELMVIEW DRIVE			C	N	3/4"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2100	ELMVIEW DRIVE			C	N	3/4"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2111	ELMVIEW DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1357	EMINENCE STREET			C	N	1"		C	1"		SF						Installation record	N			Installation record	N			
1389	EMINENCE STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
1415	EMINENCE STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
1351	EMINENCE STREET			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1366	EMINENCE STREET			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1412	EMINENCE STREET			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1380	EMINENCE STREET			C	N	1"		C	1"		SF						Installation record	N			Installation record	N			
1421	EMINENCE STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
1407	EMINENCE STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
1401	EMINENCE STREET			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1395	EMINENCE STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
1383	EMINENCE STREET			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1377	EMINENCE STREET			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1369	EMINENCE STREET			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1363	EMINENCE STREET			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1341	EMINENCE STREET			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1339	EMINENCE STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
1350	EMINENCE STREET			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1354	EMINENCE STREET			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1360	EMINENCE STREET			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1374	EMINENCE STREET			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1386	EMINENCE STREET			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1394	EMINENCE STREET			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1398	EMINENCE STREET			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1404	EMINENCE STREET			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1418	EMINENCE STREET			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1368	EMIR STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
1351	EMIR STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
1402	EMIR STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
1414	EMIR STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
1343	EMIR STREET			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1377	EMIR STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
1342	EMIR STREET			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1391	EMIR STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
1423	EMIR STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
1415	EMIR STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
1409	EMIR STREET			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1403	EMIR STREET			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1397	EMIR STREET			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1383	EMIR STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
1371	EMIR STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
1363	EMIR STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
1357	EMIR STREET			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1350	EMIR STREET			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1356	EMIR STREET			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1362	EMIR STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
1374	EMIR STREET			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1382	EMIR STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
1388	EMIR STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
1394	EMIR STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
1408	EMIR STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
1420	EMIR STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2721	FENTON WAY			C	N	1"		C			SF						Installation record	N			Installation record	N			
2710	FENTON WAY			C	N	1"		C			SF						Installation record	N			Installation record	N			
1450	FERNANDO DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1445	FERNANDO DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1453	FERNANDO DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1437	FERNANDO DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			

LOCATIONAL IDENTIFIER ADDRESS	LOCATIONAL IDENTIFIER STREET NAME	LOCATIONAL IDENTIFIER UNIT OR SUITE #	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
1610	FERNANDO DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1490	FERNANDO DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1440	FERNANDO DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1420	FERNANDO DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1400	FERNANDO DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1390	FERNANDO DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1340	FERNANDO DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1330	FERNANDO DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1310	FERNANDO DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1319	FERNANDO DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1333	FERNANDO DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1345	FERNANDO DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1351	FERNANDO DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1371	FERNANDO DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1380	FERNANDO DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1385	FERNANDO DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1471	FERNANDO DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1489	FERNANDO DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1501	FERNANDO DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1511	FERNANDO DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1531	FERNANDO DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1486	FERNANDO DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1311	FINCH LANE			C	N	1"		C			SF						Installed after lead ban	Y	1987		Installed after lead ban	N			
1330	FINCH LANE			C	N	1"		C			SF						Installed after lead ban	Y	1987		Installed after lead ban	N			
1284	FINCH LANE			C	N	1"		C	1"		SF						Installed after lead ban	Y	1987		Field inspection only	Y		Cross-connection survey	
1420	FINCH LANE			C	N	1"		C			SF						Installed after lead ban	Y	1987		Installed after lead ban	N			
1350	FINCH LANE			C	N	1"		C			SF						Installed after lead ban	Y	1987		Installed after lead ban	N			
1259	FINCH LANE			C	N	1"		C			SF						Installed after lead ban	Y	1987		Installed after lead ban	N			
1469	FINCH LANE			C	N	1"		C			SF						Installed after lead ban	Y	1987		Installed after lead ban	N			
1341	FINCH LANE			C	N	1"		C			SF						Installed after lead ban	Y	1987		Installed after lead ban	N			
1450	FINCH LANE			C	N	1"		C			SF						Installed after lead ban	Y	1987		Installed after lead ban	N			
1321	FINCH LANE			C	N	1"		C			SF						Installed after lead ban	Y	1987		Installed after lead ban	N			
1291	FINCH LANE			C	N	1"		C	1"		SF						Installed after lead ban	Y	1987		Field inspection only	Y		Cross-connection survey	
1380	FINCH LANE			C	N	1"		C	1"		SF						Installed after lead ban	Y	1987		Field inspection only	Y		Cross-connection survey	
1451	FINCH LANE			P	N	1"		P	1"		SF						Installed after lead ban	Y	1987		Field inspection only	Y		Cross-connection survey	
1441	FINCH LANE			P	N	1"		C			SF						Installed after lead ban	Y	1987		Installed after lead ban	N			
1265	FINCH LANE			C	N	1"		C	3/4"		SF						Installed after lead ban	Y	1987		Field inspection only	Y		Cross-connection survey	
1271	FINCH LANE			C	N	1"		C			SF						Installed after lead ban	Y	1987		Installed after lead ban	N			
1279	FINCH LANE			C	N	1"		C			SF						Installed after lead ban	Y	1987		Installed after lead ban	N			
1285	FINCH LANE			C	N	1"		C			SF						Installed after lead ban	Y	1987		Installed after lead ban	N			
1331	FINCH LANE			C	N	1"		C	1"		SF						Installed after lead ban	Y	1987		Field inspection only	Y		Cross-connection survey	
1351	FINCH LANE			C	N	1"		C			SF						Installed after lead ban	Y	1987		Installed after lead ban	N			
1371	FINCH LANE			P	N	1"		C	1"		SF						Installed after lead ban	Y	1992		Field inspection only	Y		Cross-connection survey	
1391	FINCH LANE			P	N	1"		C	1"		SF						Installed after lead ban	Y	1992		Field inspection only	Y		Cross-connection survey	
1401	FINCH LANE			P	N	1"		C			SF						Installed after lead ban	Y	1992		Installed after lead ban	N			
1411	FINCH LANE			P	N	1"		C			SF						Installed after lead ban	Y	1992		Installed after lead ban	N			
1421	FINCH LANE			P	N	1"		P	1"		SF						Installed after lead ban	Y	1992		Field inspection only	Y		Cross-connection survey	
1431	FINCH LANE			P	N	1"		P	1"		SF						Installed after lead ban	Y	1992		Field inspection only	Y		Cross-connection survey	
1461	FINCH LANE			P	N	1"		C			SF						Installed after lead ban	Y	1992		Installed after lead ban	N			
1470	FINCH LANE			P	N	1"		C			SF						Installed after lead ban	Y	1992		Installed after lead ban	N			
1474	FINCH LANE			P	N	1"		P	1"		SF						Installed after lead ban	Y	1992		Field inspection only	Y		Cross-connection survey	
1466	FINCH LANE			P	N	1"		P			SF						Installed after lead ban	Y	1992		Installed after lead ban	N			
1456	FINCH LANE			P	N	1"		P			SF						Installed after lead ban	Y	1992		Installed after lead ban	N			
1454	FINCH LANE			P	N	1"		P			SF						Installed after lead ban	Y	1992		Installed after lead ban	N			
1440	FINCH LANE			P	N	1"		P			SF						Installed after lead ban	Y	1992		Installed after lead ban	N			
1430	FINCH LANE			P	N	1"		P			SF						Installed after lead ban	Y	1992		Installed after lead ban	N			
1410	FINCH LANE			P	N	1"		P			SF						Installed after lead ban	Y	1992		Installed after lead ban	N			
1400	FINCH LANE			P	N	1"		P	3/4"		SF						Installed after lead ban	Y	1992		Field inspection only	Y		Cross-connection survey	
1390	FINCH LANE			P	N	1"		C	1"		SF						Installed after lead ban	Y	1992		Field inspection only	Y		Cross-connection survey	
1370	FINCH LANE			P	N	1"		C			SF						Installed after lead ban	Y	1987		Installed after lead ban	N			
1360	FINCH LANE			P	N	1"		C			SF						Installed after lead ban	Y	1987		Installed after lead ban	N			
1340	FINCH LANE			P	N	1"		C			SF						Installed after lead ban	Y	1987		Installed after lead ban	N			
1320	FINCH LANE			P	N	1"		P	1"		SF						Installed after lead ban	Y	1987		Field inspection only	Y		Cross-connection survey	
1310	FINCH LANE			P	N	1"		C			SF						Installed after lead ban	Y	1987		Installed after lead ban	N			
1296	FINCH LANE			P	N	1"		C			SF						Installed after lead ban	Y	1987		Installed after lead ban	N			
1290	FINCH LANE			C	N	1"		C	1"		SF						Installed after lead ban	Y	1987		Installation record	Y		Visual insp during install or repair	
1278	FINCH LANE			C	N	1"		C			SF						Installed after lead ban	Y	1987		Installed after lead ban	N			
1270	FINCH LANE			C	N	1"		C			SF						Installed after lead ban	Y	1987		Installed after lead ban	N			
1264	FINCH LANE			C	N	1"		C			SF						Installed after lead ban	Y	1987		Installed after lead ban	N			
2244	FOX HEIGHTS LANE	Ste 101		C	N	1"		C	3/4"		SF						Installation record	N			Installation record	N			
2244	FOX HEIGHTS LANE	UPPER		C	N	1"		C	3/4"		SF						Installation record	N			Installation record	N			
2879	FOXFORD COURT			P	N	1"		P			SF						Installed after lead ban	Y	1994		Installed after lead ban	N			
2885	FOXFORD COURT			P	N	1"		P			SF						Installed after lead ban	Y	1994		Installed after lead ban	N			
2875	FOXFORD COURT			P	N	1"		P			SF						Installed after lead ban	Y	1994		Installed after lead ban	N			
2876	FOXFORD COURT			P	N	1"		P			SF						Installed after lead ban	Y	1994		Installed after lead ban	N			
2870	FOXFORD COURT			P	N	1"		P			SF						Installed after lead ban	Y	1994		Installed after lead ban	N			
2890	FOXFORD COURT			P	N	1"		P			SF						Installed after lead ban	Y	1994		Installed after lead ban	N			
2880	FOXFORD COURT			P	N	1"		P	1"		SF						Installed after lead ban	Y	1994		Field inspection only	Y		Cross-connection survey	
2895	FOXFORD COURT			P	N	1"		P			SF						Installed after lead ban	Y	1994		Installed after lead ban	N			
2881	FOXFORD COURT			P	N	1"		P			SF						Installed after lead ban	Y	1994		Installed after lead ban	N			
2877	FOXFORD COURT			P	N	1"		P			SF						Installed after lead ban	Y	1994		Installed after lead ban	N			
2959	FOXFORD DRIVE			P	N	1"		P			SF						Installed after lead ban	Y	1994		Installed after lead ban	N			
2936	FOXFORD DRIVE			P	N	1"		P			SF						Installed after lead ban	Y	1994		Installed after lead ban	N			
2930	FOXFORD DRIVE			P	N	1"		P			SF						Installed after lead ban	Y	1994		Installed after lead ban	N			
2960	FOXFORD DRIVE			P	N	1"		P			SF						Installed after lead ban	Y	1994		Installed after lead ban	N			

LOCATIONAL IDENTIFIER ADDRESS	LOCATIONAL IDENTIFIER STREET NAME	LOCATIONAL IDENTIFIER UNIT OR SUITE #	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
2970	FOXFORD DRIVE			P	N	1"		P			SF						Installed after lead ban	Y	1994		Installed after lead ban	N			
2920	FOXFORD DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	1994		Field inspection only	Y		Cross-connection survey	
2940	FOXFORD DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	1994		Field inspection only	Y		Cross-connection survey	
2946	FOXFORD DRIVE			P	N	1"		P			SF						Installed after lead ban	Y	1994		Installed after lead ban	N			
2950	FOXFORD DRIVE			P	N	1"		P			SF						Installed after lead ban	Y	1994		Installed after lead ban	N			
2925	FOXFORD DRIVE			P	N	1"		P			SF						Installed after lead ban	Y	1994		Installed after lead ban	N			
1230	GERHARDT LANE			C	N	1"		C			SF						Installation record	N	1980		Installation record	N			
1275	GERHARDT LANE			C	N	1"		C	1"		SF						Installation record	N	1980		Field inspection only	Y		Cross-connection survey	
1268	GERHARDT LANE			C	N	1"		C			SF						Installation record	N	1980		Installation record	N			
1277	GERHARDT LANE			C	N	1"		P	1"		SF						Installation record	N	1980		Field inspection only	Y		Cross-connection survey	
1269	GERHARDT LANE			C	N	1"		C	1"		SF						Installation record	N	1980		Field inspection only	Y		Cross-connection survey	
1261	GERHARDT LANE			C	N	1"		C	3/4"		SF						Installation record	N	1980		Field inspection only	Y		Cross-connection survey	
1258	GERHARDT LANE			C	N	1"		C	3/4"		SF						Installation record	N	1980		Field inspection only	Y		Cross-connection survey	
1255	GERHARDT LANE			C	N	1"		C			SF						Installation record	N	1980		Installation record	N			
1247	GERHARDT LANE			C	N	1"		C			SF						Installation record	N	1980		Installation record	N			
1239	GERHARDT LANE			C	N	1"		C			SF						Installation record	N	1980		Installation record	N			
1231	GERHARDT LANE			C	N	1"		C	3/4"		SF						Installation record	N	1980		Field inspection only	Y		Cross-connection survey	
1223	GERHARDT LANE			C	N	1"		C			SF						Installation record	N	1980		Installation record	N			
1219	GERHARDT LANE			C	N	1"		C			SF						Installation record	N	1980		Installation record	N			
1218	GERHARDT LANE			C	N	1"		C	1"		SF						Installation record	N	1980		Field inspection only	Y		Cross-connection survey	
1242	GERHARDT LANE			C	N	1"		C			SF						Installation record	N	1980		Installation record	N			
2130	GILSON COURT			C	N	1 1/2"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2183	GILSON COURT			C	N	1 1/2"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2112	GILSON COURT			C	N	1 1/2"		C			SF						Installation record	N			Installation record	N			
2217	GILSON COURT			C	N	1 1/2"		C			SF						Installation record	N			Installation record	N			
2203	GILSON COURT			C	N	1 1/2"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2195	GILSON COURT			C	N	1 1/2"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2189	GILSON COURT			C	N	1 1/2"		C			SF						Installation record	N			Installation record	N			
2175	GILSON COURT			C	N	1 1/2"		C			SF						Installation record	N			Installation record	N			
2169	GILSON COURT			C	N	1 1/2"		C			SF						Installation record	N			Installation record	N			
2161	GILSON COURT			C	N	1 1/2"		C			SF						Installation record	N			Installation record	N			
2155	GILSON COURT			C	N	1 1/2"		C			SF						Installation record	N			Installation record	N			
2153	GILSON COURT			C	N	1 1/2"		C			SF						Installation record	N			Installation record	N			
2146	GILSON COURT			C	N	1 1/2"		C			SF						Installation record	N			Installation record	N			
2138	GILSON COURT			C	N	1 1/2"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2124	GILSON COURT			C	N	1 1/2"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1644	GLEN ROAD			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1601	GLEN ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1435	GLEN ROAD			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1367	GLEN ROAD			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1499	GLEN ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1440	GLEN ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1434	GLEN ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1630	GLEN ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1452	GLEN ROAD			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1523	GLEN ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1484	GLEN ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1541	GLEN ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1539	GLEN ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1531	GLEN ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1517	GLEN ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1511	GLEN ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1505	GLEN ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1493	GLEN ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1485	GLEN ROAD			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1479	GLEN ROAD			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1453	GLEN ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1447	GLEN ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1441	GLEN ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1429	GLEN ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1421	GLEN ROAD			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1415	GLEN ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1414	GLEN ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1420	GLEN ROAD			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1428	GLEN ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1446	GLEN ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1478	GLEN ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1492	GLEN ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1498	GLEN ROAD			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1504	GLEN ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1510	GLEN ROAD			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1516	GLEN ROAD			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1524	GLEN ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1530	GLEN ROAD			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1538	GLEN ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1386	GLEN ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1378	GLEN ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1372	GLEN ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1366	GLEN ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1360	GLEN ROAD			C	N	1"		C	3/4"		SF						Installation record	N			Installation record	N			
1352	GLEN ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1346	GLEN ROAD			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1340	GLEN ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1332	GLEN ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1333	GLEN ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			

LOCATIONAL IDENTIFIER ADDRESS	LOCATIONAL IDENTIFIER STREET NAME	LOCATIONAL IDENTIFIER UNIT OR SUITE #	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
1343	GLEN ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1373	GLEN ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1381	GLEN ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1387	GLEN ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1560	GLEN ROAD			C	N	1"		C	3/4"		SF						Installation record	N			Installation record	N			
1566	GLEN ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1572	GLEN ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1578	GLEN ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1584	GLEN ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1592	GLEN ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1616	GLEN ROAD			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1622	GLEN ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1638	GLEN ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1665	GLEN ROAD			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1657	GLEN ROAD			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1649	GLEN ROAD			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1641	GLEN ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1633	GLEN ROAD			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1625	GLEN ROAD			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1617	GLEN ROAD			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1611	GLEN ROAD			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1595	GLEN ROAD			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1587	GLEN ROAD			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1579	GLEN ROAD			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1571	GLEN ROAD			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
765	GLORY ROAD			C	N	1"		C			SF						Installed after lead ban	Y	1986		Installation record	N			
775	GLORY ROAD			C	N	1"		C			SF						Installed after lead ban	Y	1986		Installation record	N			
937	GLORY ROAD			C	N	1"		C			SF						Installed after lead ban	Y	1986		Installation record	N			
820	GLORY ROAD			C	N	1"		C			SF						Installed after lead ban	Y	1986		Installation record	N			
750	GLORY ROAD			C	N	1"		C			SF						Installed after lead ban	Y	1986		Installation record	N			
778	GLORY ROAD			C	N	1"		C	3/4"		SF						Installed after lead ban	Y	1986		Field inspection only	Y		Cross-connection survey	
784	GLORY ROAD			C	N	1"		C			SF						Installed after lead ban	Y	1986		Installation record	N			
790	GLORY ROAD			C	N	1"		C			SF						Installed after lead ban	Y	1986		Installation record	N			
796	GLORY ROAD			C	N	1"		C			SF						Installed after lead ban	Y	1986		Installation record	N			
802	GLORY ROAD			C	N	1"		C			SF						Installed after lead ban	Y	1986		Installation record	N			
814	GLORY ROAD			C	N	1"		C			SF						Installed after lead ban	Y	1986		Installation record	N			
1055	GLORY ROAD			C	N	1"		C	3/4"		SF						Installed after lead ban	Y	1986		Field inspection only	Y		Cross-connection survey	
1620	GRANT STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2024	GRANT STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
1080	GRIFFITHS LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1083	GRIFFITHS LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1086	GRIFFITHS LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
3591	E. Hank Av			P	N	1"		P	1"		SF						Installed after lead ban	Y	2022		Installed after lead ban	Y		Visual insp during install or repair	
3576	E. Hank Av			P	N	1"		P	1"		SF						Installed after lead ban	Y	2022		Installed after lead ban	Y		Visual insp during install or repair	
3597	E. Hank Av			P	N	1"		P	1"		SF						Installed after lead ban	Y	2022		Installed after lead ban	Y		Visual insp during install or repair	
3639	E. Hank Av			P	N	1"		P	1"		SF						Installed after lead ban	Y	2022		Installed after lead ban	Y		Visual insp during install or repair	
3582	E. Hank Av			P	N	1"		P	1"		SF						Installed after lead ban	Y	2022		Installed after lead ban	Y		Visual insp during install or repair	
3603	E. Hank Av			P	N	1"		P			SF						Installed after lead ban	Y	2022		Installed after lead ban	Y		Visual insp during install or repair	
3585	E. Hank Av			P	N	1"		P			SF						Installed after lead ban	Y	2022		Installed after lead ban	Y		Visual insp during install or repair	
3627	E. Hank Av			P	N	1"		P			SF						Installed after lead ban	Y	2022		Installed after lead ban	Y		Visual insp during install or repair	
3573	E. Hank Av			P	N	1"		P	1"		SF						Installed after lead ban	Y	2022		Installed after lead ban	Y		Visual insp during install or repair	
3579	E. Hank Av			P	N	1"		P			SF						Installed after lead ban	Y	2022		Installed after lead ban	Y		Visual insp during install or repair	
3615	E. Hank Av			P	N	1"		P			SF						Installed after lead ban	Y	2022		Installed after lead ban	Y		Visual insp during install or repair	
3609	E. Hank Av			P	N	1"		P	1"		SF						Installed after lead ban	Y	2022		Installed after lead ban	Y		Visual insp during install or repair	
3612	E. Hank Av			P	N	1"		P	1"		SF						Installed after lead ban	Y	2022		Installed after lead ban	Y		Visual insp during install or repair	
3594	E. Hank Av			P	N	1"		P	1"		SF						Installed after lead ban	Y	2022		Installed after lead ban	Y		Visual insp during install or repair	
2680	HARMONY DRIVE			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2701	HARMONY DRIVE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2691	HARMONY DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2683	HARMONY DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2677	HARMONY DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2671	HARMONY DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2655	HARMONY DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2654	HARMONY DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2674	HARMONY DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2688	HARMONY DRIVE			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1144	HAWTHORN ROAD			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1133	HAWTHORN ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1138	HAWTHORN ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1124	HAWTHORN ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1132	HAWTHORN ROAD			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1150	HAWTHORN ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1139	HAWTHORN ROAD			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1125	HAWTHORN ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1300	HIAWATHA CIRCLE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1375	HIAWATHA CIRCLE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1365	HIAWATHA CIRCLE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1351	HIAWATHA CIRCLE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1352	HIAWATHA CIRCLE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1345	HIAWATHA CIRCLE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1331	HIAWATHA CIRCLE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1315	HIAWATHA CIRCLE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1310	HIAWATHA CIRCLE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1374	HIAWATHA CIRCLE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	N		Cross-connection survey	
1350	Highland Ridge Dr			P	N	1"		P			SF						Installed after lead ban	Y	2022		Installed after lead ban	Y		Visual insp during install or repair	

LOCATIONAL IDENTIFIER ADDRESS	LOCATIONAL IDENTIFIER STREET NAME	LOCATIONAL IDENTIFIER UNIT OR SUITE #	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
1320	Highland Ridge Dr			P	N	1"		P			SF						Installed after lead ban	Y	2022		Installed after lead ban	Y		Visual insp during install or repair	
1345	Highland Ridge Dr			P	N	1"		P	1"		SF						Installed after lead ban	Y	2022		Installed after lead ban	Y		Visual insp during install or repair	
2160	HILLTOP DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2100	HILLTOP DRIVE			C	N	1"		P	1"		SF						Installation record	N			Installation record	N			
2191	HILLTOP DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2119	HILLTOP DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2173	HILLTOP DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2116	HILLTOP DRIVE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2152	HILLTOP DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2035	HILLTOP DRIVE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2143	HILLTOP DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2058	HILLTOP DRIVE			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2038	HILLTOP DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2262	HILLTOP DRIVE			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2182	HILLTOP DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2245	HILLTOP DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2242	HILLTOP DRIVE			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2250	HILLTOP DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2256	HILLTOP DRIVE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2268	HILLTOP DRIVE			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2272	HILLTOP DRIVE			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2271	HILLTOP DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2269	HILLTOP DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2235	HILLTOP DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2217	HILLTOP DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2209	HILLTOP DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2181	HILLTOP DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2167	HILLTOP DRIVE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2159	HILLTOP DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2151	HILLTOP DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2109	HILLTOP DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2101	HILLTOP DRIVE			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2095	HILLTOP DRIVE			C	N	1"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2093	HILLTOP DRIVE			C	N	1"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2089	HILLTOP DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2090	HILLTOP DRIVE			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2094	HILLTOP DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2146	HILLTOP DRIVE			C	N	1"		C	1"		SF						Installation record	N			Installation record	N			
2170	HILLTOP DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2174	HILLTOP DRIVE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2190	HILLTOP DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2198	HILLTOP DRIVE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2204	HILLTOP DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2210	HILLTOP DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2218	HILLTOP DRIVE			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2224	HILLTOP DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2230	HILLTOP DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2236	HILLTOP DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2013	HILLTOP DRIVE			C	N	1"		C	1"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2015	HILLTOP DRIVE			C	N	1"		C	1"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2019	HILLTOP DRIVE			C	N	1"		C			MF						Installation record	N			Installation record	N			
2021	HILLTOP DRIVE			C	N	1"		C			MF						Installation record	N			Installation record	N			
2027	HILLTOP DRIVE			C	N	1"		C	1"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2029	HILLTOP DRIVE			C	N	1"		C	1"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2033	HILLTOP DRIVE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2041	HILLTOP DRIVE			C	N	1"		C			MF						Installation record	N			Installation record	N			
2043	HILLTOP DRIVE			C	N	1"		C			MF						Installation record	N			Installation record	N			
2072	HILLTOP DRIVE			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2066	HILLTOP DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2050	HILLTOP DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2044	HILLTOP DRIVE			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2030	HILLTOP DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2020	HILLTOP DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2300	HOCK STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2325	HOCK STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2324	HOCK STREET			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2332	HOCK STREET			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2345	HOCK STREET			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2343	HOCK STREET			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2337	HOCK STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2331	HOCK STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2317	HOCK STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2311	HOCK STREET			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2305	HOCK STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2299	HOCK STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2306	HOCK STREET			C	N	1"		C	1"		SF						Installation record	N	1980		Field inspection only	Y		Cross-connection survey	
2433	INGOLD COURT			C	N	1"		C			SF						Installation record	N	1980		Installation record	N			
2446	INGOLD COURT			C	N	1"		C	1"		SF						Installation record	N	1980		Field inspection only	Y		Cross-connection survey	
2441	INGOLD COURT			C	N	1"		C	1"		SF						Installation record	N	1980		Field inspection only	Y		Cross-connection survey	
2391	INGOLD COURT			C	N	1"		C	3/4"		SF						Installation record	N	1980		Field inspection only	Y		Cross-connection survey	
2406	INGOLD COURT			C	N	1"		C	1"		SF						Installation record	N	1980		Field inspection only	Y		Cross-connection survey	
2400	INGOLD COURT			C	N	1"		C			SF						Installation record	N	1980		Installation record	N			
2416	INGOLD COURT			C	N	1"		C			SF						Installation record	N	1980		Installation record	N			
2420	INGOLD COURT			C	N	1"		C			SF						Installation record	N	1980		Installation record	N			
2428	INGOLD COURT			C	N	1"		C			SF						Installation record	N	1980		Installation record	N			

LOCATIONAL IDENTIFIER ADDRESS	LOCATIONAL IDENTIFIER STREET NAME	LOCATIONAL IDENTIFIER UNIT OR SUITE #	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
2434	INGOLD COURT			C	N	1"		P	1"		SF						Installation record	N	1980		Installation record	N			
2440	INGOLD COURT			C	N	1"		C	3/4"		SF						Installation record	N	1980		Field inspection only	Y		Cross-connection survey	
2450	INGOLD COURT			C	N	1"		C			SF						Installation record	N	1980		Installation record	N			
2456	INGOLD COURT			C	N	1"		C	1"		SF						Installation record	N	1980		Field inspection only	Y		Cross-connection survey	
2453	INGOLD COURT			C	N	1"		C			SF						Installation record	N	1980		Installation record	N			
2445	INGOLD COURT			C	N	1"		C			SF						Installation record	N	1980		Installation record	N			
2427	INGOLD COURT			C	N	1"		C	1"		SF						Installation record	N	1980		Field inspection only	Y		Cross-connection survey	
2421	INGOLD COURT			C	N	1"		C	3/4"		SF						Installation record	N	1980		Field inspection only	Y		Cross-connection survey	
2413	INGOLD COURT			C	N	1"		C	3/4"		SF						Installation record	N	1980		Field inspection only	Y		Cross-connection survey	
2407	INGOLD COURT			C	N	1"		C			SF						Installation record	N	1980		Installation record	N			
2401	INGOLD COURT			C	N	1"		C	1"		SF						Installation record	N	1980		Field inspection only	Y		Cross-connection survey	
2395	INGOLD COURT			C	N	1"		C	1"		SF						Installation record	N	1980		Installation record	N			
2385	INGOLD COURT			C	N	1"		C			SF						Installation record	N	1980		Installation record	N			
2828	JEAN COURT			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2825	JEAN COURT			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2837	JEAN COURT			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2065	KASSNER DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2139	KASSNER DRIVE			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2113	KASSNER DRIVE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2039	KASSNER DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2131	KASSNER DRIVE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2125	KASSNER DRIVE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2230	KASSNER DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2077	KASSNER DRIVE			C	N	1"		C	3/4"		SF						Installation record	N			Installation record	N			
2220	KASSNER DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2072	KASSNER DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2161	KASSNER DRIVE			C	N	1"		P	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2130	KASSNER DRIVE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2153	KASSNER DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2231	KASSNER DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2107	KASSNER DRIVE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2215	KASSNER DRIVE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2059	KASSNER DRIVE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2147	KASSNER DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2144	KASSNER DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2117	KASSNER DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2120	KASSNER DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2110	KASSNER DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2101	KASSNER DRIVE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2100	KASSNER DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2080	KASSNER DRIVE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2071	KASSNER DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2060	KASSNER DRIVE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2053	KASSNER DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2045	KASSNER DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2050	KASSNER DRIVE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2237	KASSNER DRIVE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2223	KASSNER DRIVE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2206	KASSNER DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2207	KASSNER DRIVE			C	N	1"		C	1"		SF						Installation record	N			Installation record	N			
2201	KASSNER DRIVE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2195	KASSNER DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2194	KASSNER DRIVE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2178	KASSNER DRIVE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2173	KASSNER DRIVE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2165	KASSNER DRIVE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2170	KASSNER DRIVE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2154	KASSNER DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1266	KEN COURT			C	N	3/4"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1265	KEN COURT			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1273	KEN COURT			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1347	KEN DRIVE			C	N	3/4"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1330	KEN DRIVE			C	N	3/4"		P	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1345	KEN DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1302	KEN DRIVE			C	N	3/4"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1295	KEN DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1294	KEN DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1338	KEN DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1346	KEN DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1354	KEN DRIVE			C	N	3/4"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1374	KEN DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1357	KEN DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1339	KEN DRIVE			C	N	3/4"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1327	KEN DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1321	KEN DRIVE			C	N	3/4"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2385	KEY WAY			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2379	KEY WAY			C	N	3/4"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2372	KEY WAY			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2378	KEY WAY			C	N	3/4"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2384	KEY WAY			C	N	3/4"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2390	KEY WAY			C	N	3/4"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1252	KILLDEER LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1243	KILLDEER LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1251	KILLDEER LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1259	KILLDEER LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	

LOCATIONAL IDENTIFIER ADDRESS	LOCATIONAL IDENTIFIER STREET NAME	LOCATIONAL IDENTIFIER UNIT OR SUITE #	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
1267	KILLDEER LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1275	KILLDEER LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1283	KILLDEER LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1278	KILLDEER LANE			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1268	KILLDEER LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1260	KILLDEER LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2431	KIMBERLY STREET			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2444	KIMBERLY STREET			C	N	3/4"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2453	KIMBERLY STREET			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2459	KIMBERLY STREET			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2467	KIMBERLY STREET			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2398	KIMBERLY STREET			C	N	1"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2396	KIMBERLY STREET			C	N	1"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2380	KIMBERLY STREET			C	N	1"		C	1"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2382	KIMBERLY STREET			C	N	1"		C	1"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2370	KIMBERLY STREET			C	N	1"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2372	KIMBERLY STREET			C	N	1"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2371	KIMBERLY STREET			C	N	1"		C			MF						Installation record	N			Installation record	N			
2381	KIMBERLY STREET			C	N	1"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2383	KIMBERLY STREET			C	N	1"		C	1"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2397	KIMBERLY STREET			C	N	1"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2399	KIMBERLY STREET			C	N	1"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2415	KIMBERLY STREET			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2437	KIMBERLY STREET			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2445	KIMBERLY STREET			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2436	KIMBERLY STREET			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2452	KIMBERLY STREET			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2460	KIMBERLY STREET			C	N	3/4"		C	1"		SF						Installation record	N			Field inspection only	Y			
2466	KIMBERLY STREET			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2443	KUBALE LANE			C	N	1"		C			SF						Installation record	N	1981		Installation record	N			
2365	KUBALE LANE			C	N	1"		C	3/4"		SF						Installation record	N	1981		Field inspection only	Y		Cross-connection survey	
2388	KUBALE LANE			C	N	1"		C			SF						Installation record	N	1981		Installation record	N			
2376	KUBALE LANE			C	N	1"		C	1"		SF						Installation record	N	1981		Field inspection only	Y		Cross-connection survey	
2364	KUBALE LANE			C	N	1"		C			SF						Installation record	N	1981		Installation record	N			
2350	KUBALE LANE			C	N	1"		C	3/4"		SF						Installation record	N	1981		Field inspection only	Y		Cross-connection survey	
2382	KUBALE LANE			C	N	1"		C			SF						Installation record	N	1981		Installation record	N			
2394	KUBALE LANE			C	N	1"		C			SF						Installation record	N	1981		Installation record	N			
2400	KUBALE LANE			C	N	1"		C			SF						Installation record	N	1981		Installation record	N			
2406	KUBALE LANE			C	N	1"		C	1"		SF						Installation record	N	1981		Field inspection only	Y		Cross-connection survey	
2412	KUBALE LANE			C	N	1"		C			SF						Installation record	N	1981		Installation record	N			
2420	KUBALE LANE			C	N	1"		C	3/4"		SF						Installation record	N	1981		Field inspection only	Y		Cross-connection survey	
2426	KUBALE LANE			C	N	1"		C			SF						Installation record	N	1981		Installation record	N			
2434	KUBALE LANE			C	N	1"		C	1"		SF						Installation record	N	1981		Field inspection only	Y		Cross-connection survey	
2440	KUBALE LANE			C	N	1"		C	1"		SF						Installation record	N	1981		Installation record	N			
2446	KUBALE LANE			C	N	1"		C	1"		SF						Installation record	N	1981		Field inspection only	Y		Cross-connection survey	
2437	KUBALE LANE			C	N	1"		C	1"		SF						Installation record	N	1981		Field inspection only	Y		Cross-connection survey	
2431	KUBALE LANE			C	N	1"		C			SF						Installation record	N	1981		Installation record	N			
2423	KUBALE LANE			C	N	1"		C	3/4"		SF						Installation record	N	1981		Field inspection only	Y		Cross-connection survey	
2417	KUBALE LANE			C	N	1"		C			SF						Installation record	N	1981		Installation record	N			
2411	KUBALE LANE			C	N	1"		C	1"		SF						Installation record	N	1981		Installation record	N			
2405	KUBALE LANE			C	N	1"		C			SF						Installation record	N	1981		Installation record	N			
2399	KUBALE LANE			C	N	1"		C	3/4"		SF						Installation record	N	1981		Installation record	N			
2393	KUBALE LANE			C	N	1"		C	1"		SF						Installation record	N	1981		Field inspection only	Y		Cross-connection survey	
2387	KUBALE LANE			C	N	1"		C	1"		SF						Installation record	N	1981		Field inspection only	Y		Cross-connection survey	
2383	KUBALE LANE			C	N	1"		C	1"		SF						Installation record	N	1981		Field inspection only	Y		Cross-connection survey	
2377	KUBALE LANE			C	N	1"		C			SF						Installation record	N	1981		Installation record	N			
2371	KUBALE LANE			C	N	1"		C			SF						Installation record	N	1981		Installation record	N			
2357	KUBALE LANE			C	N	1"		C	3/4"		SF						Installation record	N	1981		Field inspection only	Y		Cross-connection survey	
2351	KUBALE LANE			C	N	1"		C	3/4"		SF						Installation record	N	1981		Field inspection only	Y		Cross-connection survey	
931	LA CROIX AVENUE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
924	LA CROIX AVENUE			C	N	3/4"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
979	LA CROIX AVENUE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
945	LA CROIX AVENUE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
911	LA CROIX AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
917	LA CROIX AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
925	LA CROIX AVENUE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
937	LA CROIX AVENUE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
951	LA CROIX AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
959	LA CROIX AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
965	LA CROIX AVENUE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
973	LA CROIX AVENUE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
985	LA CROIX AVENUE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
980	LA CROIX AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	N			Installation record	N			
972	LA CROIX AVENUE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
964	LA CROIX AVENUE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
958	LA CROIX AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
950	LA CROIX AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
944	LA CROIX AVENUE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
936	LA CROIX AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
930	LA CROIX AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2	LA CROIX AVENUE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
912	LA CROIX AVENUE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2376	LARUE LANE			C	N	1"		C			SF						Installed after lead ban	Y	1987		Installed after lead ban	N			
2366	LARUE LANE			C	N	1"		C			SF						Installed after lead ban	Y	1987		Installed after lead ban	N			
2425	LARUE LANE			C	N	1"		C			SF						Installed after lead ban	Y	1987		Installed after lead ban	N			

LOCATIONAL IDENTIFIER ADDRESS	LOCATIONAL IDENTIFIER STREET NAME	LOCATIONAL IDENTIFIER UNIT OR SUITE #	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
2386	LARUE LANE			C	N	1"		C	3/4"		SF						Installed after lead ban	Y	1987		Field inspection only	Y		Cross-connection survey	
2419	LARUE LANE			C	N	1"		C	3/4"		SF						Installed after lead ban	Y	1987		Field inspection only	Y		Cross-connection survey	
2349	LARUE LANE			C	N	1"		C			SF						Installed after lead ban	Y	1987		Installed after lead ban	N			
2330	LARUE LANE			C	N	1"		C			SF						Installed after lead ban	Y	1987		Installed after lead ban	N			
2430	LARUE LANE			C	N	1"		C			SF						Installed after lead ban	Y	1987		Installed after lead ban	N			
2353	LARUE LANE			C	N	1"		C	3/4"		SF						Installed after lead ban	Y	1987		Field inspection only	Y		Cross-connection survey	
2398	LARUE LANE			C	N	1"		C	3/4"		SF						Installed after lead ban	Y	1987		Field inspection only	Y		Cross-connection survey	
2363	LARUE LANE			C	N	1"		C			SF						Installed after lead ban	Y	1987		Installed after lead ban	N			
2410	LARUE LANE			C	N	1"		C			SF						Installed after lead ban	Y	1987		Installed after lead ban	N			
2391	LARUE LANE			C	N	1"		C			SF						Installed after lead ban	Y	1987		Installed after lead ban	N			
2424	LARUE LANE			C	N	1"		C			SF						Installed after lead ban	Y	1987		Installed after lead ban	N			
2375	LARUE LANE			C	N	1"		C	1"		SF						Installed after lead ban	Y	1987		Field inspection only	Y		Cross-connection survey	
2360	LARUE LANE			C	N	1"		P	1"		SF						Installed after lead ban	Y	1987		Field inspection only	Y		Cross-connection survey	
2359	LARUE LANE			C	N	1"		C			SF						Installed after lead ban	Y	1987		Installed after lead ban	N			
2418	LARUE LANE			C	N	1"		C			SF						Installed after lead ban	Y	1987		Installed after lead ban	N			
2439	LARUE LANE			C	N	1"		C			SF						Installed after lead ban	Y	1987		Installed after lead ban	N			
2320	LARUE LANE			C	N	1"		C			SF						Installed after lead ban	Y	1987		Installed after lead ban	N			
2340	LARUE LANE			C	N	1"		C			SF						Installed after lead ban	Y	1987		Installed after lead ban	N			
2350	LARUE LANE			C	N	1"		C	3/4"		SF						Installed after lead ban	Y	1987		Field inspection only	Y		Cross-connection survey	
2356	LARUE LANE			C	N	1"		C			SF						Installed after lead ban	Y	1987		Installed after lead ban	N			
2370	LARUE LANE			C	N	1"		C			SF						Installed after lead ban	Y	1987		Installed after lead ban	N			
2382	LARUE LANE			C	N	1"		C			SF						Installed after lead ban	Y	1987		Installed after lead ban	N			
2394	LARUE LANE			C	N	1"		C			SF						Installed after lead ban	Y	1987		Installed after lead ban	N			
2404	LARUE LANE			C	N	1"		C	1"		SF						Installed after lead ban	Y	1987		Field inspection only	Y		Cross-connection survey	
2436	LARUE LANE			C	N	1"		C	3/4"		SF						Installed after lead ban	Y	1987		Field inspection only	Y		Cross-connection survey	
2444	LARUE LANE			C	N	1"		C	3/4"		SF						Installed after lead ban	Y	1987		Field inspection only	Y		Cross-connection survey	
2445	LARUE LANE			C	N	1"		C			SF						Installed after lead ban	Y	1987		Installed after lead ban	N			
2431	LARUE LANE			C	N	1"		C			SF						Installed after lead ban	Y	1987		Installed after lead ban	N			
2413	LARUE LANE			C	N	1"		C			SF						Installed after lead ban	Y	1987		Installed after lead ban	N			
2407	LARUE LANE			C	N	1"		C			SF						Installed after lead ban	Y	1987		Installed after lead ban	N			
2401	LARUE LANE			C	N	1"		C			SF						Installed after lead ban	Y	1987		Installed after lead ban	N			
2397	LARUE LANE			C	N	1"		C			SF						Installed after lead ban	Y	1987		Installed after lead ban	N			
2385	LARUE LANE			C	N	1"		C			SF						Installed after lead ban	Y	1987		Installed after lead ban	N			
2379	LARUE LANE			C	N	1"		C			SF						Installed after lead ban	Y	1987		Installed after lead ban	N			
2369	LARUE LANE			C	N	1"		C			SF						Installed after lead ban	Y	1987		Installed after lead ban	N			
2343	LARUE LANE			C	N	1"		C	3/4"		SF						Installed after lead ban	Y	1987		Field inspection only	Y		Cross-connection survey	
2339	LARUE LANE			C	N	1"		C			SF						Installed after lead ban	Y	1987		Installed after lead ban	N			
2331	LARUE LANE			C	N	1"		C			SF						Installed after lead ban	Y	1987		Installed after lead ban	N			
2321	LARUE LANE			C	N	1"		C			SF						Installed after lead ban	Y	1987		Installed after lead ban	N			
2317	LARUE LANE			C	N	1"		C			SF						Installed after lead ban	Y	1987		Installed after lead ban	N			
1682	LEDGESTONE COURT			P	N	1"		P	1"		SF						Installed after lead ban	Y	2005		Installed after lead ban	Y		Visual insp during install or repair	
1678	LEDGESTONE COURT			P	N	1"		P	1"		SF						Installed after lead ban	Y	2005		Installed after lead ban	Y		Visual insp during install or repair	
1683	LEDGESTONE COURT			P	N	1"		P	1"		SF						Installed after lead ban	Y	2005		Installed after lead ban	Y		Visual insp during install or repair	
1679	LEDGESTONE COURT			P	N	1"		P	1"		SF						Installed after lead ban	Y	2005		Installed after lead ban	Y		Visual insp during install or repair	
1674	LEDGESTONE COURT			P	N	1"		P	1"		SF						Installed after lead ban	Y	2005		Installed after lead ban	Y		Visual insp during install or repair	
2254	LEDVINA CIRCLE			C	N	1"		C	3/4"		SF						Installation record	Y	1984		Field inspection only	Y		Cross-connection survey	
2247	LEDVINA CIRCLE			C	N	1"		C	3/4"		SF						Installation record	Y	1984		Field inspection only	Y		Cross-connection survey	
2241	LEDVINA CIRCLE			C	N	1"		C			SF						Installation record	Y	1984		Installation record	N			
2235	LEDVINA CIRCLE			C	N	1"		C	1"		SF						Installation record	Y	1984		Field inspection only	Y		Cross-connection survey	
2229	LEDVINA CIRCLE			C	N	1"		C	3/4"		SF						Installation record	Y	1984		Field inspection only	Y		Cross-connection survey	
2223	LEDVINA CIRCLE			C	N	1"		C	1"		SF						Installation record	Y	1984		Installation record	N			
2224	LEDVINA CIRCLE			C	N	1"		C			SF						Installation record	Y	1984		Installation record	N			
2230	LEDVINA CIRCLE			C	N	1"		C			SF						Installation record	Y	1984		Installation record	N			
2236	LEDVINA CIRCLE			C	N	1"		C	1"		SF						Installation record	Y	1984		Field inspection only	Y		Cross-connection survey	
2242	LEDVINA CIRCLE			C	N	1"		C	1"		SF						Installation record	Y	1984		Field inspection only	Y		Cross-connection survey	
2248	LEDVINA CIRCLE			C	N	1"		C	3/4"		SF						Installation record	Y	1984		Field inspection only	Y		Cross-connection survey	
1675	LEDVINA STREET			C	N	1"		C	1"		SF						Installation record	Y	1984		Field inspection only	Y		Cross-connection survey	
1635	LEDVINA STREET			C	N	1"		C			SF						Installation record	Y	1984		Installation record	N			
1652	LEDVINA STREET			C	N	1"		C			SF						Installation record	Y	1984		Installation record	N			
1624	LEDVINA STREET			C	N	1"		C	1"		SF						Installation record	Y	1984		Field inspection only	Y		Cross-connection survey	
1632	LEDVINA STREET			C	N	1"		C	3/4"		SF						Installation record	Y	1984		Field inspection only	Y		Cross-connection survey	
1640	LEDVINA STREET			C	N	1"		C			SF						Installation record	Y	1984		Installation record	N			
1646	LEDVINA STREET			C	N	1"		C			SF						Installation record	Y	1984		Installation record	N			
1660	LEDVINA STREET			C	N	1"		C			SF						Installation record	Y	1984		Installation record	N			
1681	LEDVINA STREET			C	N	1"		C	1"		SF						Installation record	Y	1984		Field inspection only	Y		Cross-connection survey	
1669	LEDVINA STREET			C	N	1"		C	3/4"		SF						Installation record	Y	1984		Field inspection only	Y		Cross-connection survey	
1661	LEDVINA STREET			C	N	1"		C	3/4"		SF						Installation record	Y	1984		Field inspection only	Y		Cross-connection survey	
1657	LEDVINA STREET			C	N	1"		C	3/4"		SF						Installation record	Y	1984		Field inspection only	Y		Cross-connection survey	
1649	LEDVINA STREET			C	N	1"		C			SF						Installation record	Y	1984		Installation record	N			
1641	LEDVINA STREET			C	N	1"		C			SF						Installation record	Y	1984		Installation record	N			
1629	LEDVINA STREET			C	N	1"		C			SF						Installation record	Y	1984		Installation record	N			
1619	LEDVINA STREET			C	N	1"		C	1"		SF						Installation record	Y	1984		Installation record	N			
2432	LEONA DRIVE			C	N	1"		C			SF						Installation record	Y	1973		Installation record	N			
2400	LEONA DRIVE			C	N	1"		C	3/4"		SF						Installation record	Y	1973		Field inspection only	Y		Cross-connection survey	
2406	LEONA DRIVE			C	N	1"		C			SF						Installation record	Y	1973		Installation record	N			
2444	LEONA DRIVE			C	N	1"		C			SF						Installation record	Y	1973		Installation record	N			
2405	LEONA DRIVE			C	N	1"		C			SF						Installation record	Y	1973		Installation record	N			
2411	LEONA DRIVE			C	N	1"		C			SF						Installation record	Y	1973		Installation record	N			
2417	LEONA DRIVE			C	N	1"		C			SF						Installation record	Y	1973		Installation record	N			
2429	LEONA DRIVE			C	N	1"		C			SF						Installation record	Y	1973		Installation record	N			
2440	LEONA DRIVE			C	N	1"		C			SF						Installation record	Y	1973		Installation record	N			
2436	LEONA DRIVE			C	N	1"		C			SF						Installation record	Y	1973		Installation record	N			
2428	LEONA DRIVE			C	N	1"		C			SF						Installation record	Y	1973		Installation record	N			
2424	LEONA DRIVE			C	N	1"		C			SF						Installation record	Y	1973		Installation record	N			
2418	LEONA DRIVE			C	N	1"		C			SF						Installation record	Y	1973		Installation record	N			

LOCATIONAL IDENTIFIER ADDRESS	LOCATIONAL IDENTIFIER STREET NAME	LOCATIONAL IDENTIFIER UNIT OR SUITE #	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
2412	LEONA DRIVE			C	N	1"		C			SF						Installation record	Y	1973		Installation record	N			
635	LIDA LANE			C	N	3/4"		C			SF						Installation record	Y	1982		Installation record	N			
672	LIDA LANE			C	N	3/4"		C			SF						Installation record	Y	1982		Installation record	N			
611	LIDA LANE			C	N	3/4"		C			SF						Installation record	Y	1982		Installation record	N			
675	LIDA LANE			C	N	3/4"		C			SF						Installation record	Y	1982		Installation record	N			
685	LIDA LANE			C	N	3/4"		C			SF						Installation record	Y	1982		Installation record	N			
646	LIDA LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1982		Field inspection only	Y		Cross-connection survey	
610	LIDA LANE			C	N	3/4"		C			SF						Installation record	Y	1982		Installation record	N			
651	LIDA LANE			C	N	3/4"		C			SF						Installation record	Y	1982		Installation record	N			
639	LIDA LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1982		Field inspection only	Y		Cross-connection survey	
660	LIDA LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1982		Field inspection only	Y		Cross-connection survey	
663	LIDA LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1982		Field inspection only	Y		Cross-connection survey	
654	LIDA LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1982		Field inspection only	Y		Cross-connection survey	
645	LIDA LANE			C	N	3/4"		C			SF						Installation record	Y	1982		Installation record	N			
650	LIDA LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1982		Field inspection only	Y		Cross-connection survey	
669	LIDA LANE			C	N	3/4"		C	1"		SF						Installation record	Y	1982		Field inspection only	Y		Cross-connection survey	
613	LIDA LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1982		Field inspection only	Y		Cross-connection survey	
612	LIDA LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1982		Field inspection only	Y		Cross-connection survey	
620	LIDA LANE			C	N	3/4"		C			SF						Installation record	Y	1982		Installation record	N			
608	LIDA LANE			C	N	3/4"		C			SF						Installation record	Y	1982		Installation record	N			
621	LIDA LANE			C	N	3/4"		C			SF						Installation record	Y	1982		Installation record	N			
631	LIDA LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1982		Field inspection only	Y		Cross-connection survey	
653	LIDA LANE			C	N	3/4"		C			SF						Installation record	Y	1982		Installation record	N			
679	LIDA LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1982		Field inspection only	Y		Cross-connection survey	
691	LIDA LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1982		Field inspection only	Y		Cross-connection survey	
695	LIDA LANE			C	N	3/4"		C			SF						Installation record	Y	1982		Installation record	N			
701	LIDA LANE			C	N	3/4"		C	1"		SF						Installation record	Y	1982		Installation record	N			
707	LIDA LANE			C	N	3/4"		C			SF						Installation record	Y	1982		Installation record	N			
700	LIDA LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1982		Field inspection only	Y		Cross-connection survey	
694	LIDA LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1982		Field inspection only	Y		Cross-connection survey	
690	LIDA LANE			C	N	3/4"		C			SF						Installation record	Y	1982		Installation record	N			
684	LIDA LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1982		Installation record	N			
678	LIDA LANE			C	N	3/4"		C			SF						Installation record	Y	1982		Installation record	N			
664	LIDA LANE			C	N	3/4"		C			SF						Installation record	Y	1982		Installation record	N			
1655	LILY DRIVE			C	N	3/4"		C			SF						Installation record	Y	1966		Installation record	N			
1641	LILY DRIVE			C	N	3/4"		C			SF						Installation record	Y	1966		Installation record	N			
1669	LILY DRIVE			C	N	1"		C			MF						Installation record	Y	1966		Installation record	N			
1667	LILY DRIVE			C	N	1"		C			MF						Installation record	Y	1966		Installation record	N			
1663	LILY DRIVE			C	N	1"		C	3/4"		MF						Installation record	Y	1966		Field inspection only	Y		Cross-connection survey	
1661	LILY DRIVE			C	N	1"		C	3/4"		MF						Installation record	Y	1966		Field inspection only	Y		Cross-connection survey	
1647	LILY DRIVE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1966		Field inspection only	Y		Cross-connection survey	
1635	LILY DRIVE			C	N	3/4"		C			SF						Installation record	Y	1966		Installation record	N			
1629	LILY DRIVE			C	N	3/4"		C			SF						Installation record	Y	1966		Installation record	N			
1626	LILY DRIVE			C	N	3/4"		C			SF						Installation record	Y	1966		Installation record	N			
1632	LILY DRIVE			C	N	3/4"		C			SF						Installation record	Y	1966		Installation record	N			
1640	LILY DRIVE			C	N	3/4"		C			SF						Installation record	Y	1966		Installation record	N			
1646	LILY DRIVE			C	N	3/4"		C			SF						Installation record	Y	1966		Installation record	N			
1652	LILY DRIVE			C	N	3/4"		C			SF						Installation record	Y	1966		Installation record	N			
1660	LILY DRIVE			C	N	3/4"		C	1"		SF						Installation record	Y	1966		Field inspection only	Y		Cross-connection survey	
1470	LIMERICK COURT			P	N	1"		C			SF						Installed after lead ban	Y	1995		Installed after lead ban	N			
1454	LIMERICK COURT			P	N	1"		C			SF						Installed after lead ban	Y	1995		Installed after lead ban	N			
1440	LIMERICK COURT			P	N	1"		P	1"		SF						Installed after lead ban	Y	1995		Installed after lead ban	Y		Cross-connection survey	
1444	LIMERICK COURT			P	N	1"		P	1"		SF						Installed after lead ban	Y	1995		Installed after lead ban	Y		Cross-connection survey	
1460	LIMERICK COURT			P	N	1"		P			SF						Installed after lead ban	Y	1995		Installed after lead ban	N			
1435	LIMERICK COURT			P	N	1"		P			SF						Installed after lead ban	Y	1995		Installed after lead ban	N			
1465	LIMERICK COURT			P	N	1"		P	1"		SF						Installed after lead ban	Y	1995		Installed after lead ban	Y		Cross-connection survey	
1475	LIMERICK COURT			P	N	1"		P	3/4"		SF						Installed after lead ban	Y	1995		Installed after lead ban	Y		Cross-connection survey	
2893	LIMERICK LANE			P	N	1"		P			SF						Installed after lead ban	Y	1995		Installed after lead ban	N			
2896	LIMERICK LANE			P	N	1"		P			SF						Installed after lead ban	Y	1995		Installed after lead ban	N			
2895	LIMERICK LANE			P	N	1"		P			SF						Installed after lead ban	Y	1995		Installed after lead ban	N			
2898	LIMERICK LANE			P	N	1"		P			SF						Installed after lead ban	Y	1995		Installed after lead ban	N			
2900	LIMERICK LANE			P	N	1"		P			SF						Installed after lead ban	Y	1995		Installed after lead ban	N			
2430	LINA LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2425	LINA LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2421	LINA LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2417	LINA LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2411	LINA LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2405	LINA LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2410	LINA LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2414	LINA LANE			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2404	LINA LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1441	LINDALE LANE			C	N	3/4"		C	3/4"		SF						Installation record	N	1982		Field inspection only	Y		Cross-connection survey	
1511	LINDALE LANE			C	N	3/4"		C	3/4"		SF						Installation record	N	1982		Field inspection only	Y		Cross-connection survey	
1480	LINDALE LANE			C	N	3/4"		C	3/4"		SF						Installation record	N	1982		Field inspection only	Y		Cross-connection survey	
1434	LINDALE LANE			C	N	3/4"		C			SF						Installation record	N	1982		Installation record	N			
1584	LINDALE LANE			C	N	3/4"		C			SF						Installation record	N	1982		Installation record	N			
1395	LINDALE LANE			C	N	3/4"		C	3/4"		SF						Installation record	N	1982		Field inspection only	Y		Cross-connection survey	
1499	LINDALE LANE			C	N	3/4"		C			SF						Installation record	N	1982		Installation record	N			
1635	LINDALE LANE			C	N	3/4"		C			SF						Installation record	N	1982		Installation record	N			
1435	LINDALE LANE			C	N	3/4"		C			SF						Installation record	N	1982		Installation record	N			
1530	LINDALE LANE			C	N	3/4"		C	3/4"		SF						Installation record	N	1982		Field inspection only	Y		Cross-connection survey	
1479	LINDALE LANE			C	N	3/4"		C	1"		SF						Installation record	N	1982		Field inspection only	Y		Cross-connection survey	
1579	LINDALE LANE			C	N	3/4"		C	3/4"		SF						Installation record	N	1982		Field inspection only	Y		Cross-connection survey	
1573	LINDALE LANE			C	N	3/4"		C	3/4"		SF						Installation record	N	1982		Field inspection only	Y		Cross-connection survey	
1518	LINDALE LANE			C	N	3/4"		C	1"		SF						Installation record	N	1982		Field inspection only	Y		Cross-connection survey	

LOCATIONAL IDENTIFIER ADDRESS	LOCATIONAL IDENTIFIER STREET NAME	LOCATIONAL IDENTIFIER UNIT OR SUITE #	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
1498	LINDALE LANE			C	N	3/4"		C			SF						Installation record	N	1982		Installation record	N			
1371	LINDALE LANE			C	N	3/4"		C	3/4"		SF						Installation record	N	1982		Field inspection only	Y		Cross-connection survey	
1336	LINDALE LANE			C	N	3/4"		C			SF						Installation record	N	1982		Installation record	N			
1360	LINDALE LANE			C	N	3/4"		C	3/4"		SF						Installation record	N	1982		Field inspection only	Y		Cross-connection survey	
1348	LINDALE LANE			C	N	3/4"		C			SF						Installation record	N	1982		Installation record	N			
1558	LINDALE LANE			C	N	3/4"		C			SF						Installation record	N	1982		Installation record	N			
1420	LINDALE LANE			C	N	3/4"		C			SF						Installation record	N	1982		Installation record	N			
1421	LINDALE LANE			C	N	3/4"		C	3/4"		SF						Installation record	N	1982		Installation record	N			
1524	LINDALE LANE			C	N	3/4"		C			SF						Installation record	N	1982		Installation record	N			
1619	LINDALE LANE			C	N	3/4"		C			SF						Installation record	N	1982		Installation record	N			
1427	LINDALE LANE			C	N	3/4"		C			SF						Installation record	N	1982		Installation record	N			
1359	LINDALE LANE			C	N	3/4"		C	3/4"		SF						Installation record	N	1982		Field inspection only	Y		Cross-connection survey	
1342	LINDALE LANE			C	N	3/4"		C	1"		SF						Installation record	N	1982		Field inspection only	Y		Cross-connection survey	
1345	LINDALE LANE			C	N	3/4"		C			SF						Installation record	N	1982		Installation record	N			
1636	LINDALE LANE			C	N	3/4"		C			SF						Installation record	N	1982		Installation record	N			
1453	LINDALE LANE			C	N	3/4"		C			SF						Installation record	N	1982		Installation record	N			
1596	LINDALE LANE			C	N	3/4"		C	3/4"		SF						Installation record	N	1982		Field inspection only	Y		Cross-connection survey	
1447	LINDALE LANE			C	N	3/4"		C			SF						Installation record	N	1982		Installation record	N			
1491	LINDALE LANE			C	N	3/4"		C	1"		SF						Installation record	N	1982		Field inspection only	Y		Cross-connection survey	
1353	LINDALE LANE			C	N	3/4"		C	3/4"		SF						Installation record	N	1982		Field inspection only	Y		Cross-connection survey	
1374	LINDALE LANE			C	N	3/4"		C	3/4"		SF						Installation record	N	1982		Field inspection only	Y		Cross-connection survey	
1610	LINDALE LANE			C	N	3/4"		C			SF						Installation record	N	1982		Installation record	N			
1384	LINDALE LANE			C	N	3/4"		C	1"		SF						Installation record	N	1982		Field inspection only	Y		Cross-connection survey	
1602	LINDALE LANE			C	N	3/4"		C			SF						Installation record	N	1982		Installation record	N			
1505	LINDALE LANE			C	N	3/4"		C	3/4"		SF						Installation record	N	1982		Field inspection only	Y		Cross-connection survey	
1578	LINDALE LANE			C	N	3/4"		C			SF						Installation record	N	1982		Installation record	N			
1622	LINDALE LANE			C	N	3/4"		C			SF						Installation record	N	1982		Installation record	N			
1417	LINDALE LANE			C	N	3/4"		C	1"		SF						Installation record	N	1982		Field inspection only	Y		Cross-connection survey	
1446	LINDALE LANE			C	N	3/4"		C	3/4"		SF						Installation record	N	1982		Field inspection only	Y		Cross-connection survey	
1452	LINDALE LANE			C	N	3/4"		C			SF						Installation record	N	1982		Installation record	N			
1504	LINDALE LANE			C	N	3/4"		C			SF						Installation record	N	1982		Installation record	N			
1539	LINDALE LANE			C	N	3/4"		C	3/4"		SF						Installation record	N	1982		Field inspection only	Y		Cross-connection survey	
1531	LINDALE LANE			C	N	3/4"		C			SF						Installation record	N	1982		Installation record	N			
1523	LINDALE LANE			C	N	3/4"		C			SF						Installation record	N	1982		Installation record	N			
1517	LINDALE LANE			C	N	3/4"		C			SF						Installation record	N	1982		Installation record	N			
1485	LINDALE LANE			C	N	3/4"		C	3/4"		SF						Installation record	N	1982		Field inspection only	Y		Cross-connection survey	
1387	LINDALE LANE			C	N	3/4"		C			SF						Installation record	N	1982		Installation record	N			
1375	LINDALE LANE			C	N	3/4"		C			SF						Installation record	N	1982		Installation record	N			
1365	LINDALE LANE			C	N	3/4"		C	3/4"		SF						Installation record	N	1982		Field inspection only	Y		Cross-connection survey	
1339	LINDALE LANE			C	N	3/4"		C	3/4"		SF						Installation record	N	1982		Field inspection only	Y		Cross-connection survey	
1331	LINDALE LANE			C	N	3/4"		C	1"		SF						Installation record	N	1982		Field inspection only	Y		Cross-connection survey	
1354	LINDALE LANE			C	N	3/4"		C	3/4"		SF						Installation record	N	1982		Installation record	N			
1368	LINDALE LANE			C	N	3/4"		C	3/4"		SF						Installation record	N	1982		Field inspection only	Y		Cross-connection survey	
1380	LINDALE LANE			C	N	3/4"		C			SF						Installation record	N	1982		Installation record	N			
1392	LINDALE LANE			C	N	3/4"		C	1"		SF						Installation record	N	1982		Field inspection only	Y		Cross-connection survey	
1400	LINDALE LANE			C	N	3/4"		C	1"		SF						Installation record	N	1982		Field inspection only	Y		Cross-connection survey	
1408	LINDALE LANE			C	N	3/4"		C	1"		SF						Installation record	N	1982		Field inspection only	Y		Cross-connection survey	
1414	LINDALE LANE			C	N	3/4"		C			SF						Installation record	N	1982		Installation record	N			
1428	LINDALE LANE			C	N	3/4"		C			SF						Installation record	N	1982		Installation record	N			
1440	LINDALE LANE			C	N	3/4"		C			SF						Installation record	N	1982		Installation record	N			
1486	LINDALE LANE			C	N	3/4"		C			SF						Installation record	N	1982		Installation record	N			
1492	LINDALE LANE			C	N	3/4"		C			SF						Installation record	N	1982		Installation record	N			
1510	LINDALE LANE			C	N	3/4"		C			SF						Installation record	N	1982		Installation record	N			
1538	LINDALE LANE			C	N	3/4"		C			SF						Installation record	N	1982		Installation record	N			
1564	LINDALE LANE			C	N	3/4"		C			SF						Installation record	N	1982		Installation record	N			
1570	LINDALE LANE			C	N	3/4"		C			SF						Installation record	N	1982		Installation record	N			
1590	LINDALE LANE			C	N	3/4"		C	3/4"		SF						Installation record	N	1982		Field inspection only	Y		Cross-connection survey	
1616	LINDALE LANE			C	N	3/4"		C	3/4"		SF						Installation record	N	1982		Field inspection only	Y		Cross-connection survey	
1628	LINDALE LANE			C	N	3/4"		C	1"		SF						Installation record	N	1982		Field inspection only	Y		Cross-connection survey	
1627	LINDALE LANE			C	N	3/4"		C			SF						Installation record	N	1982		Installation record	N			
1593	LINDALE LANE			C	N	3/4"		C	1"		SF						Installation record	N	1982		Field inspection only	Y		Cross-connection survey	
1585	LINDALE LANE			C	N	3/4"		C	3/4"		SF						Installation record	N	1982		Field inspection only	Y		Cross-connection survey	
1569	LINDALE LANE			C	N	3/4"		C	3/4"		SF						Installation record	N	1982		Field inspection only	Y		Cross-connection survey	
1561	LINDALE LANE			C	N	3/4"		C			SF						Installation record	N	1982		Installation record	N			
3621	LOST LANE			C	N	1"		C			SF						Installed after lead ban	Y	1999		Installed after lead ban	N			
3630	LOST LANE			C	N	1"		C			SF						Installed after lead ban	Y	1999		Installed after lead ban	N			
3611	LOST LANE			C	N	1"		C			SF						Installed after lead ban	Y	1999		Installed after lead ban	N			
3631	LOST LANE			C	N	1"		C			SF						Installed after lead ban	Y	1999		Installed after lead ban	N			
3620	LOST LANE			C	N	1"		C			SF						Installed after lead ban	Y	1999		Installed after lead ban	N			
3640	LOST LANE			C	N	1"		C			SF						Installed after lead ban	Y	1999		Installed after lead ban	N			
1331	Lucy Ln			P	N	1"		P			SF						Installed after lead ban	Y	2022		Installed after lead ban	Y		Visual insp during install or repair	
1354	Lucy Ln			P	N	1"		P	1"		SF						Installed after lead ban	Y	2022		Installed after lead ban	Y		Visual insp during install or repair	
1343	Lucy Ln			P	N	1"		P	1"		SF						Installed after lead ban	Y	2022		Installed after lead ban	Y		Visual insp during install or repair	
1325	Lucy Ln			P	N	1"		P									Installed after lead ban	Y	2022		Installed after lead ban	Y		Visual insp during install or repair	
1355	Lucy Ln			P	N	1"		P			SF						Installed after lead ban	Y	2022		Installed after lead ban	Y		Visual insp during install or repair	
1337	Lucy Ln			P	N	1"		P	1"		SF						Installed after lead ban	Y	2022		Installed after lead ban	Y		Visual insp during install or repair	
1349	Lucy Ln			P	N	1"		P	1"		SF						Installed after lead ban	Y	2022		Installed after lead ban	Y		Visual insp during install or repair	
2880	LUMBER LANE			C	N	1"		C	1"		SF						Installed after lead ban	Y	1987		Installed after lead ban	N			
2946	LUMBER LANE			C	N	1"		C			SF						Installed after lead ban	Y	1987		Installed after lead ban	N			
2940	LUMBER LANE			C	N	1"		C			SF						Installed after lead ban	Y	1987		Installed after lead ban	N			
2934	LUMBER LANE			C	N	1"		C			SF						Installed after lead ban	Y	1987		Installed after lead ban	N			
2922	LUMBER LANE			C	N	1"		C	1"		SF						Installed after lead ban	Y	1987		Installed after lead ban	N			
2892	LUMBER LANE			C	N	1"		C			SF						Installed after lead ban	Y	1987		Installed after lead ban	N			
2925	LUMBER LANE			C	N	1"		C			SF						Installed after lead ban	Y	1987		Installed after lead ban	N			
2931	LUMBER LANE			C	N	1"		C			SF						Installed after lead ban	Y	1987		Installed after lead ban	N			

LOCATIONAL IDENTIFIER ADDRESS	LOCATIONAL IDENTIFIER STREET NAME	LOCATIONAL IDENTIFIER UNIT OR SUITE #	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
2939	LUMBER LANE			C	N	1"		C	1"		SF						Installed after lead ban	Y	1987		Field inspection only	Y		Cross-connection survey	
2945	LUMBER LANE			C	N	1"		C			SF						Installed after lead ban	Y	1987		Installed after lead ban	N			
2949	LUMBER LANE			C	N	1"		C	1"		SF						Installed after lead ban	Y	1987		Field inspection only	Y		Cross-connection survey	
2955	LUMBER LANE			C	N	1"		C	1"		SF						Installed after lead ban	Y	1987		Field inspection only	Y		Cross-connection survey	
2959	LUMBER LANE			C	N	1"		C			SF						Installed after lead ban	Y	1987		Installed after lead ban	N			
2963	LUMBER LANE			C	N	1"		C			SF						Installed after lead ban	Y	1987		Installed after lead ban	N			
2971	LUMBER LANE			C	N	1"		C	1"		SF						Installed after lead ban	Y	1987		Field inspection only	Y		Cross-connection survey	
2975	LUMBER LANE			C	N	1"		C	1"		SF						Installed after lead ban	Y	1987		Field inspection only	Y		Cross-connection survey	
2978	LUMBER LANE			C	N	1"		C			SF						Installed after lead ban	Y	1987		Installed after lead ban	N			
2970	LUMBER LANE			C	N	1"		C			SF						Installed after lead ban	Y	1987		Installed after lead ban	N			
2960	LUMBER LANE			C	N	1"		C	1"		SF						Installed after lead ban	Y	1987		Field inspection only	Y		Cross-connection survey	
2954	LUMBER LANE			C	N	1"		C			SF						Installed after lead ban	Y	1987		Installed after lead ban	N			
2911	LUMBER LANE			C	N	1"		C			SF						Installed after lead ban	Y	1987		Installed after lead ban	N			
2905	LUMBER LANE			C	N	1"		C			SF						Installed after lead ban	Y	1987		Installed after lead ban	N			
2901	LUMBER LANE			C	N	1"		C			SF						Installed after lead ban	Y	1987		Installed after lead ban	N			
2893	LUMBER LANE			C	N	1"		C			SF						Installed after lead ban	Y	1987		Installed after lead ban	N			
2885	LUMBER LANE			C	N	1"		C	1"		SF						Installed after lead ban	Y	1987		Installed after lead ban	N			
2227	MAGNOLIA LANE			C	N	3/4"		C			SF						Installation record	Y	1982		Installation record	N			
2238	MAGNOLIA LANE			C	N	3/4"		C			SF						Installation record	Y	1982		Installation record	N			
2272	MAGNOLIA LANE			C	N	3/4"		C			SF						Installation record	Y	1982		Installation record	N			
2233	MAGNOLIA LANE			C	N	3/4"		C			SF						Installation record	Y	1982		Installation record	N			
2220	MAGNOLIA LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1982		Field inspection only	Y		Cross-connection survey	
2219	MAGNOLIA LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1982		Field inspection only	Y		Cross-connection survey	
2276	MAGNOLIA LANE			C	N	3/4"		C			SF						Installation record	Y	1982		Installation record	N			
2265	MAGNOLIA LANE			C	N	3/4"		C			SF						Installation record	Y	1982		Installation record	N			
2232	MAGNOLIA LANE			C	N	3/4"		C			SF						Installation record	Y	1982		Installation record	N			
2279	MAGNOLIA LANE			C	N	3/4"		C			SF						Installation record	Y	1982		Installation record	N			
2243	MAGNOLIA LANE			C	N	3/4"		C			SF						Installation record	Y	1982		Installation record	N			
2258	MAGNOLIA LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1982		Field inspection only	Y		Cross-connection survey	
2251	MAGNOLIA LANE			C	N	3/4"		C			SF						Installation record	Y	1982		Installation record	N			
2275	MAGNOLIA LANE			C	N	3/4"		C			SF						Installation record	Y	1982		Installation record	N			
2245	MAGNOLIA LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1982		Field inspection only	Y		Cross-connection survey	
2211	MAGNOLIA LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1982		Field inspection only	Y		Cross-connection survey	
2212	MAGNOLIA LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1982		Field inspection only	Y		Cross-connection survey	
2216	MAGNOLIA LANE			C	N	3/4"		C			SF						Installation record	Y	1982		Installation record	N			
2271	MAGNOLIA LANE			C	N	3/4"		C			SF						Installation record	Y	1982		Installation record	N			
2261	MAGNOLIA LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1982		Field inspection only	Y		Cross-connection survey	
2248	MAGNOLIA LANE			C	N	3/4"		C			SF						Installation record	Y	1982		Installation record	N			
2257	MAGNOLIA LANE			C	N	3/4"		C			SF						Installation record	Y	1982		Installation record	N			
2242	MAGNOLIA LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1982		Field inspection only	Y		Cross-connection survey	
2215	MAGNOLIA LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1982		Field inspection only	Y		Cross-connection survey	
2280	MAGNOLIA LANE			C	N	3/4"		C			SF						Installation record	Y	1982		Installation record	N			
2264	MAGNOLIA LANE			C	N	3/4"		C			SF						Installation record	Y	1982		Installation record	N			
2262	MAGNOLIA LANE			C	N	3/4"		C			SF						Installation record	Y	1982		Installation record	N			
2252	MAGNOLIA LANE			C	N	3/4"		C			SF						Installation record	Y	1982		Installation record	N			
2228	MAGNOLIA LANE			C	N	3/4"		C			SF						Installation record	Y	1982		Installation record	N			
2224	MAGNOLIA LANE			C	N	3/4"		C			SF						Installation record	Y	1982		Installation record	N			
2225	MAGNOLIA LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1982		Field inspection only	Y		Cross-connection survey	
2237	MAGNOLIA LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1982		Field inspection only	Y		Cross-connection survey	
2285	MAGNOLIA LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1982		Field inspection only	Y		Cross-connection survey	
1061	W MAIN AVENUE			C	N	1"		C	1"		SF						Installed after lead ban	Y	1997		Installed after lead ban	N			
1011	W MAIN AVENUE			C	N	1"		C	1"		SF						Installed after lead ban	Y	1997		Installed after lead ban	N			
1050	W MAIN AVENUE			C	N	1"		C	1"		SF						Installed after lead ban	Y	1997		Installed after lead ban	N			
1270	W MAIN AVENUE			C	N	1"		C	1"		SF						Installed after lead ban	Y	1997		Installed after lead ban	N			
1694	W MAIN CIRCLE	1		P	N	2"		P	2"		SF						Installed after lead ban	Y	2006		Installed after lead ban	Y		Visual insp during install or repair	
1694	W MAIN CIRCLE	2		P	N			P	1"		SF						Installed after lead ban	Y	2006		Installed after lead ban	Y		Visual insp during install or repair	
1694	W MAIN CIRCLE	3		P	N			P	1"		SF						Installed after lead ban	Y	2006		Installed after lead ban	Y		Visual insp during install or repair	
1694	W MAIN CIRCLE	4		P	N			P	1"		SF						Installed after lead ban	Y	2006		Installed after lead ban	Y		Visual insp during install or repair	
1694	W MAIN CIRCLE	5		P	N			P	1"		SF						Installed after lead ban	Y	2006		Installed after lead ban	Y		Visual insp during install or repair	
1694	W MAIN CIRCLE	6		P	N			P	1"		SF						Installed after lead ban	Y	2006		Installed after lead ban	Y		Visual insp during install or repair	
1693	W MAIN CIRCLE	1		P	N	2"		P	2"		SF						Installed after lead ban	Y	2006		Installed after lead ban	Y		Visual insp during install or repair	
1693	W MAIN CIRCLE	2		P	N			P	1"		SF						Installed after lead ban	Y	2006		Installed after lead ban	Y		Visual insp during install or repair	
1693	W MAIN CIRCLE	3		P	N			P	1"		SF						Installed after lead ban	Y	2006		Installed after lead ban	Y		Visual insp during install or repair	
1693	W MAIN CIRCLE	4		P	N			P	1"		SF						Installed after lead ban	Y	2006		Installed after lead ban	Y		Visual insp during install or repair	
1693	W MAIN CIRCLE	5		P	N			P	1"		SF						Installed after lead ban	Y	2006		Installed after lead ban	Y		Visual insp during install or repair	
1693	W MAIN CIRCLE	6		P	N			P	1"		SF						Installed after lead ban	Y	2006		Installed after lead ban	Y		Visual insp during install or repair	
1695	W MAIN CIRCLE	2		P	N			P	1"		SF						Installed after lead ban	Y	2006		Installed after lead ban	Y		Visual insp during install or repair	
1695	W MAIN CIRCLE	3		P	N			P	1"		SF						Installed after lead ban	Y	2006		Installed after lead ban	Y		Visual insp during install or repair	
1695	W MAIN CIRCLE	1		P	N	2"		P	2"		SF						Installed after lead ban	Y	2006		Installed after lead ban	Y		Visual insp during install or repair	
1695	W MAIN CIRCLE	4		P	N			P	1"		SF						Installed after lead ban	Y	2006		Installed after lead ban	Y		Visual insp during install or repair	
1695	W MAIN CIRCLE	5		P	N			P	1"		SF						Installed after lead ban	Y	2006		Installed after lead ban	Y		Visual insp during install or repair	
1695	W MAIN CIRCLE	6		P	N			P	1"		SF						Installed after lead ban	Y	2006		Installed after lead ban	Y		Visual insp during install or repair	
1690	W MAIN CIRCLE	1		P	N	2"		P	2"		SF						Installed after lead ban	Y	2006		Installed after lead ban	Y		Visual insp during install or repair	
1690	W MAIN CIRCLE	2		P	N			P	1"		SF						Installed after lead ban	Y	2006		Installed after lead ban	Y		Visual insp during install or repair	
1690	W MAIN CIRCLE	3		P	N			P	1"		SF						Installed after lead ban	Y	2006		Installed after lead ban	Y		Visual insp during install or repair	
1690	W MAIN CIRCLE	4		P	N			P	1"		SF						Installed after lead ban	Y	2006		Installed after lead ban	Y		Visual insp during install or repair	
1690	W MAIN CIRCLE	5		P	N			P	1"		SF						Installed after lead ban	Y	2006		Installed after lead ban	Y		Visual insp during install or repair	
1690	W MAIN CIRCLE	6		P	N			P	1"		SF						Installed after lead ban	Y	2006		Installed after lead ban	Y		Visual insp during install or repair	
1686	W MAIN CIRCLE	5		P	N			P	1"		SF						Installed after lead ban	Y	2006		Installed after lead ban	Y		Visual insp during install or repair	
1686	W MAIN CIRCLE	3		P	N			P	1"		SF						Installed after lead ban	Y	2006		Installed after lead ban	Y		Visual insp during install or repair	
1686	W MAIN CIRCLE	2		P	N			P	1"		SF						Installed after lead ban	Y	2006		Installed after lead ban	Y		Visual insp during install or repair	
1686	W MAIN CIRCLE	6		P	N			P	1"		SF						Installed after lead ban	Y	2006		Installed after lead ban	Y		Visual insp during install or repair	
1686	W MAIN CIRCLE	4		P	N			P	1"		SF						Installed after lead ban	Y	2006		Installed after lead ban	Y		Visual insp during install or repair	
1689	W MAIN CIRCLE	1		P	N	2"		P	2"		SF						Installed after lead ban	Y	2006		Installed after lead ban	Y		Visual insp during install or repair	
1689	W MAIN CIRCLE	2		P	N			P	1"		SF						Installed after lead ban	Y	2006		Installed after lead ban	Y		Visual insp during install or repair	

LOCATIONAL IDENTIFIER ADDRESS	LOCATIONAL IDENTIFIER STREET NAME	LOCATIONAL IDENTIFIER UNIT OR SUITE #	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
1689	W MAIN CIRCLE	3		P	N			P	1"		SF						Installed after lead ban	Y	2006		Installed after lead ban	Y		Visual insp during install or repair	
1689	W MAIN CIRCLE	4		P	N			P	1"		SF						Installed after lead ban	Y	2006		Installed after lead ban	Y		Visual insp during install or repair	
1689	W MAIN CIRCLE	5		P	N			P	1"		SF						Installed after lead ban	Y	2006		Installed after lead ban	Y		Visual insp during install or repair	
1689	W MAIN CIRCLE	6		P	N			P	1"		SF						Installed after lead ban	Y	2006		Installed after lead ban	Y		Visual insp during install or repair	
1691	W MAIN CIRCLE	2		P	N			P	1"		SF						Installed after lead ban	Y	2006		Installed after lead ban	Y		Visual insp during install or repair	
1691	W MAIN CIRCLE	6		P	N			P	1"		SF						Installed after lead ban	Y	2006		Installed after lead ban	Y		Visual insp during install or repair	
1691	W MAIN CIRCLE	1		P	N	2"		P	2"		SF						Installed after lead ban	Y	2006		Installed after lead ban	Y		Visual insp during install or repair	
1691	W MAIN CIRCLE	3		P	N			P	1"		SF						Installed after lead ban	Y	2006		Installed after lead ban	Y		Visual insp during install or repair	
1691	W MAIN CIRCLE	4		P	N			P	1"		SF						Installed after lead ban	Y	2006		Installed after lead ban	Y		Visual insp during install or repair	
1691	W MAIN CIRCLE	5		P	N			P	1"		SF						Installed after lead ban	Y	2006		Installed after lead ban	Y		Visual insp during install or repair	
1685	W MAIN CIRCLE	1		P	N	2"		P	2"		SF						Installed after lead ban	Y	2006		Installed after lead ban	Y		Visual insp during install or repair	
1685	W MAIN CIRCLE	2		P	N			P	1"		SF						Installed after lead ban	Y	2006		Installed after lead ban	Y		Visual insp during install or repair	
1685	W MAIN CIRCLE	3		P	N			P	1"		SF						Installed after lead ban	Y	2006		Installed after lead ban	Y		Visual insp during install or repair	
1685	W MAIN CIRCLE	4		P	N			P	1"		SF						Installed after lead ban	Y	2006		Installed after lead ban	Y		Visual insp during install or repair	
1685	W MAIN CIRCLE	5		P	N			P	1"		SF						Installed after lead ban	Y	2006		Installed after lead ban	Y		Visual insp during install or repair	
1685	W MAIN CIRCLE	6		P	N			P	1"		SF						Installed after lead ban	Y	2006		Installed after lead ban	Y		Visual insp during install or repair	
1681	W MAIN CIRCLE	1		P	N	2"		P	2"		SF						Installed after lead ban	Y	2006		Installed after lead ban	Y		Visual insp during install or repair	
1681	W MAIN CIRCLE	2		P	N			P	1"		SF						Installed after lead ban	Y	2006		Installed after lead ban	Y		Visual insp during install or repair	
1681	W MAIN CIRCLE	4		P	N			P	1"		SF						Installed after lead ban	Y	2006		Installed after lead ban	Y		Visual insp during install or repair	
1681	W MAIN CIRCLE	3		P	N			P	1"		SF						Installed after lead ban	Y	2006		Installed after lead ban	Y		Visual insp during install or repair	
1681	W MAIN CIRCLE	5		P	N			P	1"		SF						Installed after lead ban	Y	2006		Installed after lead ban	Y		Visual insp during install or repair	
1681	W MAIN CIRCLE	6		P	N			P	1"		SF						Installed after lead ban	Y	2006		Installed after lead ban	Y		Visual insp during install or repair	
951	MANCEL LANE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
943	MANCEL LANE			C	N	3/4"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
948	MANCEL LANE			C	N	3/4"		C	1"		SF						Installation record	N			Installation record	N			
974	MANCEL LANE			C	N	3/4"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
930	MANCEL LANE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
912	MANCEL LANE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
991	MANCEL LANE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
971	MANCEL LANE			C	N	3/4"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
986	MANCEL LANE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
957	MANCEL LANE			C	N	3/4"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
942	MANCEL LANE			C	N	3/4"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
964	MANCEL LANE			C	N	3/4"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
958	MANCEL LANE			C	N	3/4"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
920	MANCEL LANE			C	N	3/4"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
965	MANCEL LANE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
983	MANCEL LANE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
977	MANCEL LANE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
980	MANCEL LANE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
970	MANCEL LANE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
974	MANOR PLACE			C	N	3/4"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
964	MANOR PLACE			C	N	3/4"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
950	MANOR PLACE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
986	MANOR PLACE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1001	MANOR PLACE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
971	MANOR PLACE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
951	MANOR PLACE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
957	MANOR PLACE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
990	MANOR PLACE			C	N	3/4"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
942	MANOR PLACE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
977	MANOR PLACE			C	N	3/4"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
983	MANOR PLACE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
958	MANOR PLACE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
970	MANOR PLACE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
943	MANOR PLACE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
965	MANOR PLACE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
993	MANOR PLACE			C	N	3/4"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1540	W MARHILL ROAD			C	N	3/4"		C			SF						Installation record	Y			Installation record	Y			
1587	W MARHILL ROAD			C	N	3/4"		C	1"		SF						Installation record	Y	1965	ısp during install o	Field inspection only	Y		Cross-connection survey	
1648	W MARHILL ROAD			C	N	3/4"		C			SF						Installation record	Y	1965	ısp during install o	Installation record	N			
1408	E MARHILL ROAD			C	N	3/4"		C			SF						Installation record	Y	1965	ısp during install o	Installation record	N			
1424	E MARHILL ROAD			C	N	3/4"		C	3/4"		SF						Installation record	Y	1965	ısp during install o	Installation record	N			
1500	W MARHILL ROAD			C	N	3/4"		C	3/4"		SF						Installation record	Y	1965	ısp during install o	Field inspection only	Y		Cross-connection survey	
1586	W MARHILL ROAD			C	N	3/4"		C			SF						Installation record	Y	1965	ısp during install o	Installation record	N			
1656	W MARHILL ROAD			C	N	3/4"		C			MF						Installation record	Y	1965	ısp during install o	Installation record	N			
1658	W MARHILL ROAD			C	N	3/4"		C			MF						Installation record	Y	1965	ısp during install o	Installation record	N			
1573	W MARHILL ROAD			C	N	3/4"		C			SF						Installation record	Y	1965	ısp during install o	Installation record	N			
1665	W MARHILL ROAD			C	N	3/4"		C	1"		MF						Installation record	Y	1965	ısp during install o	Installation record	N			
1663	W MARHILL ROAD			C	N	3/4"		C	3/4"		MF						Installation record	Y	1965	ısp during install o	Installation record	N			
1628	W MARHILL ROAD			C	N	3/4"		C			SF						Installation record	Y	1965	ısp during install o	Installation record	N			
1636	W MARHILL ROAD			C	N	3/4"		C			SF						Installation record	Y	1965	ısp during install o	Installation record	N			
1642	W MARHILL ROAD			C	N	3/4"		C	1"		SF						Installation record	Y	1965	ısp during install o	Field inspection only	Y		Cross-connection survey	
1662	W MARHILL ROAD			C	N	3/4"		C	3/4"		MF						Installation record	Y	1965	ısp during install o	Field inspection only	Y		Cross-connection survey	
1664	W MARHILL ROAD			C	N	3/4"		C	1"		MF						Installation record	Y	1965	ısp during install o	Field inspection only	Y		Cross-connection survey	
1659	W MARHILL ROAD			C	N	3/4"		C			MF						Installation record	Y	1965	ısp during install o	Installation record	N			
1657	W MARHILL ROAD			C	N	3/4"		C			MF						Installation record	Y	1965	ısp during install o	Installation record	N			
1649	W MARHILL ROAD			C	N	3/4"		C	1"		SF						Installation record	Y	1965	ısp during install o	Field inspection only	Y		Cross-connection survey	
1643	W MARHILL ROAD			C	N	3/4"		C			SF						Installation record	Y	1965	ısp during install o	Installation record	N			
1637	W MARHILL ROAD			C	N	3/4"		C			SF						Installation record	Y	1965	ısp during install o	Installation record	N			
1631	W MARHILL ROAD			C	N	3/4"		C			SF						Installation record	Y	1965	ısp during install o	Installation record	N			
1625	W MARHILL ROAD			C	N	3/4"		C			SF						Installation record	Y	1965	ısp during install o	Installation record	N			
1619	W MARHILL ROAD			C	N	3/4"		C			SF						Installation record	Y	1965	ısp during install o	Installation record	N			
1613	W MARHILL ROAD			C	N	3/4"		C	1"		SF						Installation record	Y	1965	ısp during install o	Installation record	N			
1566	W MARHILL ROAD			C	N	3/4"		C	1"		SF						Installation record	Y	1965	ısp during install o	Field inspection only	Y		Cross-connection survey	

LOCATIONAL IDENTIFIER ADDRESS	LOCATIONAL IDENTIFIER STREET NAME	LOCATIONAL IDENTIFIER UNIT OR SUITE #	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
1574	W MARHILL ROAD			C	N	3/4"		C	3/4"		SF						Installation record	Y	1965	ısp during install o	Field inspection only	Y		Cross-connection survey	
1580	W MARHILL ROAD			C	N	3/4"		C			SF						Installation record	Y	1965	ısp during install o	Installation record	N			
1594	W MARHILL ROAD			C	N	3/4"		C			SF						Installation record	Y	1965	ısp during install o	Installation record	N			
1602	W MARHILL ROAD			C	N	3/4"		C			SF						Installation record	Y	1965	ısp during install o	Installation record	N			
1607	W MARHILL ROAD			C	N	3/4"		C			SF						Installation record	Y	1965	ısp during install o	Installation record	N			
1601	W MARHILL ROAD			C	N	3/4"		C	3/4"		SF						Installation record	Y	1965	ısp during install o	Field inspection only	Y		Cross-connection survey	
1593	W MARHILL ROAD			C	N	3/4"		C	3/4"		SF						Installation record	Y	1965	ısp during install o	Field inspection only	Y		Cross-connection survey	
1581	W MARHILL ROAD			C	N	3/4"		C	3/4"		SF						Installation record	Y	1965	ısp during install o	Field inspection only	Y		Cross-connection survey	
1567	W MARHILL ROAD			C	N	3/4"		C			SF						Installation record	Y	1965	ısp during install o	Installation record	N			
1559	W MARHILL ROAD			C	N	3/4"		C			SF						Installation record	Y	1965	ısp during install o	Installation record	N			
1541	W MARHILL ROAD			C	N	3/4"		C	3/4"		SF						Installation record	Y	1965	ısp during install o	Field inspection only	Y		Cross-connection survey	
1533	W MARHILL ROAD			C	N	3/4"		C	3/4"		SF						Installation record	Y	1965	ısp during install o	Field inspection only	Y		Cross-connection survey	
1525	W MARHILL ROAD			C	N	3/4"		C	3/4"		SF						Installation record	Y	1965	ısp during install o	Field inspection only	Y		Cross-connection survey	
1517	W MARHILL ROAD			C	N	3/4"		C	1"		SF						Installation record	Y	1965	ısp during install o	Field inspection only	Y		Cross-connection survey	
1509	W MARHILL ROAD			C	N	3/4"		C	1"		SF						Installation record	Y	1965	ısp during install o	Field inspection only	Y		Cross-connection survey	
1501	W MARHILL ROAD			C	N	3/4"		C	3/4"		SF						Installation record	Y	1965	ısp during install o	Field inspection only	Y		Cross-connection survey	
1491	W MARHILL ROAD			C	N	3/4"		C			SF						Installation record	Y	1965	ısp during install o	Installation record	N			
1485	W MARHILL ROAD			C	N	3/4"		C	3/4"		SF						Installation record	Y	1965	ısp during install o	Field inspection only	Y		Cross-connection survey	
1475	W MARHILL ROAD			C	N	3/4"		C	3/4"		SF						Installation record	Y	1965	ısp during install o	Field inspection only	Y		Cross-connection survey	
1480	W MARHILL ROAD			C	N	3/4"		C			SF						Installation record	Y	1965	ısp during install o	Installation record	N			
1490	W MARHILL ROAD			C	N	3/4"		C	3/4"		SF						Installation record	Y	1965	ısp during install o	Field inspection only	Y		Cross-connection survey	
1508	W MARHILL ROAD			C	N	3/4"		C			SF						Installation record	Y	1965	ısp during install o	Installation record	N			
1516	W MARHILL ROAD			C	N	3/4"		C	3/4"		SF						Installation record	Y	1965	ısp during install o	Field inspection only	Y		Cross-connection survey	
1524	W MARHILL ROAD			C	N	3/4"		C	3/4"		SF						Installation record	Y	1965	ısp during install o	Field inspection only	Y		Cross-connection survey	
1532	W MARHILL ROAD			C	N	3/4"		C			SF						Installation record	Y	1965	ısp during install o	Installation record	N			
1410	E MARHILL ROAD			C	N	3/4"		C	3/4"		SF						Installation record	Y	1964	ısp during install o	Field inspection only	Y		Cross-connection survey	
1434	E MARHILL ROAD			C	N	3/4"		P	1"		SF						Installation record	Y	1964	ısp during install o	Field inspection only	Y		Cross-connection survey	
1437	E MARHILL ROAD			C	N	3/4"		C			SF						Installation record	Y	1964	ısp during install o	Installation record	N			
1423	E MARHILL ROAD			C	N	3/4"		C			SF						Installation record	Y	1964	ısp during install o	Installation record	N			
1411	E MARHILL ROAD			C	N	3/4"		C	3/4"		SF						Installation record	Y	1964	ısp during install o	Field inspection only	Y		Cross-connection survey	
1401	E MARHILL ROAD			C	N	3/4"		C			SF						Installation record	Y	1964	ısp during install o	Installation record	N			
2425	MARINA CIRCLE	C		P	N	1"		P	1"		SF						Installed after lead ban	Y	2003		Field inspection only	Y		Cross-connection survey	
2427	MARINA CIRCLE	D		P	N	1"		C	3/4"		SF						Installed after lead ban	Y	2003		Field inspection only	Y		Cross-connection survey	
2421	MARINA CIRCLE	A		P	N	1"		P			SF						Installed after lead ban	Y	2003		Installed after lead ban	N			
2423	MARINA CIRCLE	B		P	N	1"		P			SF						Installed after lead ban	Y	2003		Installed after lead ban	N			
2209	MARLEE LANE			C	N	3/4"		C			SF						Installation record	Y	1964	ısp during install o	Installation record	N			
2235	MARLEE LANE			C	N	3/4"		C	3/4"		MF						Installation record	Y	1964	ısp during install o	Field inspection only	Y		Cross-connection survey	
2233	MARLEE LANE			C	N	3/4"		C	3/4"		MF						Installation record	Y	1964	ısp during install o	Field inspection only	Y		Cross-connection survey	
2022	MARLEE LANE			C	N	3/4"		C	1"		SF						Installation record	Y	1964	ısp during install o	Installation record	N			
2210	MARLEE LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1964	ısp during install o	Field inspection only	Y		Cross-connection survey	
2216	MARLEE LANE			C	N	3/4"		C			SF						Installation record	Y	1964	ısp during install o	Installation record	N			
2195	MARLEE LANE			C	N	3/4"		C			SF						Installation record	Y	1964	ısp during install o	Installation record	N			
2147	MARLEE LANE			C	N	3/4"		C			SF						Installation record	Y	1964	ısp during install o	Installation record	N			
2164	MARLEE LANE			C	N	3/4"		C			SF						Installation record	Y	1964	ısp during install o	Installation record	N			
2161	MARLEE LANE			C	N	3/4"		C			SF						Installation record	Y	1964	ısp during install o	Installation record	N			
2217	MARLEE LANE			C	N	3/4"		C			SF						Installation record	Y	1964	ısp during install o	Installation record	N			
2167	MARLEE LANE			C	N	3/4"		C			SF						Installation record	Y	1964	ısp during install o	Installation record	N			
2181	MARLEE LANE			C	N	3/4"		C			SF						Installation record	Y	1964	ısp during install o	Installation record	N			
2178	MARLEE LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1964	ısp during install o	Field inspection only	Y		Cross-connection survey	
1995	MARLEE LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1964	ısp during install o	Field inspection only	Y		Cross-connection survey	
2175	MARLEE LANE			C	N	3/4"		C			SF						Installation record	Y	1964	ısp during install o	Installation record	N			
1992	MARLEE LANE			C	N	3/4"		C			MF						Installation record	Y	1964	ısp during install o	Installation record	N			
1994	MARLEE LANE			C	N	3/4"		C			MF						Installation record	Y	1964	ısp during install o	Installation record	N			
2090	MARLEE LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1964	ısp during install o	Field inspection only	Y		Cross-connection survey	
2116	MARLEE LANE			C	N	3/4"		C			SF						Installation record	Y	1964	ısp during install o	Installation record	N			
2125	MARLEE LANE			C	N	3/4"		C			SF						Installation record	Y	1964	ısp during install o	Installation record	N			
2155	MARLEE LANE			C	N	3/4"		C			SF						Installation record	Y	1964	ısp during install o	Installation record	N			
2050	MARLEE LANE			C	N	3/4"		C			SF						Installation record	Y	1964	ısp during install o	Installation record	N			
2250	MARLEE LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1964	ısp during install o	Field inspection only	Y		Cross-connection survey	
2051	MARLEE LANE			C	N	3/4"		C	1"		SF						Installation record	Y	1964	ısp during install o	Field inspection only	Y		Cross-connection survey	
2091	MARLEE LANE			C	N	3/4"		C			SF						Installation record	Y	1964	ısp during install o	Installation record	N			
2064	MARLEE LANE			C	N	3/4"		C	3/4"		MF						Installation record	Y	1964	ısp during install o	Field inspection only	Y		Cross-connection survey	
2066	MARLEE LANE			C	N	3/4"		C	3/4"		MF						Installation record	Y	1964	ısp during install o	Field inspection only	Y		Cross-connection survey	
2201	MARLEE LANE			C	N	3/4"		C			SF						Installation record	Y	1964	ısp during install o	Installation record	N			
2187	MARLEE LANE			C	N	3/4"		C			SF						Installation record	Y	1964	ısp during install o	Installation record	N			
2146	MARLEE LANE			C	N	3/4"		C	1"		SF						Installation record	Y	1964	ısp during install o	Field inspection only	Y		Cross-connection survey	
2152	MARLEE LANE			C	N	3/4"		C			SF						Installation record	Y	1964	ısp during install o	Installation record	N			
2158	MARLEE LANE			C	N	3/4"		C			SF						Installation record	Y	1964	ısp during install o	Installation record	N			
2172	MARLEE LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1964	ısp during install o	Field inspection only	Y		Cross-connection survey	
2186	MARLEE LANE			C	N	3/4"		C			SF						Installation record	Y	1964	ısp during install o	Installation record	N			
2190	MARLEE LANE			C	N	3/4"		C			SF						Installation record	Y	1964	ısp during install o	Installation record	N			
2198	MARLEE LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1964	ısp during install o	Installation record	N			
2204	MARLEE LANE			C	N	3/4"		C			SF						Installation record	Y	1964	ısp during install o	Installation record	N			
2230	MARLEE LANE			C	N	3/4"		C			SF						Installation record	Y	1964	ısp during install o	Installation record	N			
2236	MARLEE LANE			C	N	3/4"		C			SF						Installation record	Y	1964	ısp during install o	Installation record	N			
2244	MARLEE LANE			C	N	3/4"		C			SF						Installation record	Y	1964	ısp during install o	Installation record	N			
1958	MARLEE LANE			C	N	3/4"		C			MF						Installation record	Y	1964	ısp during install o	Installation record	N			
1960	MARLEE LANE			C	N	3/4"		C			MF						Installation record	Y	1964	ısp during install o	Installation record	N			
1971	MARLEE LANE			C	N	3/4"		C			SF						Installation record	Y	1964	ısp during install o	Installation record	N			
1984	MARLEE LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1964	ısp during install o	Field inspection only	Y		Cross-connection survey	
1986	MARLEE LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1964	ısp during install o	Field inspection only	Y		Cross-connection survey	
1985	MARLEE LANE			C	N	3/4"		C			SF						Installation record	Y	1964	ısp during install o	Installation record	N			
1993	MARLEE LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1964	ısp during install o	Field inspection only	Y		Cross-connection survey	
2115	MARLEE LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1964	ısp during install o	Field inspection only	Y		Cross-connection survey	
2124	MARLEE LANE			C	N	3/4"		C			SF						Installation record	Y	1964	ısp during install o	Installation record	N			

LOCATIONAL IDENTIFIER ADDRESS	LOCATIONAL IDENTIFIER STREET NAME	LOCATIONAL IDENTIFIER UNIT OR SUITE #	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
2128	MARLEE LANE			C	N	3/4"		C			SF						Installation record	Y	1964	nsp during install o	Installation record	N			
2141	MARLEE LANE			C	N	3/4"		C	3/4"		MF						Installation record	Y	1964	nsp during install o	Field inspection only	Y		Cross-connection survey	
2139	MARLEE LANE			C	N	3/4"		C	3/4"		MF						Installation record	Y	1964	nsp during install o	Field inspection only	Y		Cross-connection survey	
2010	MARLEE LANE			C	N	3/4"		C	1"		MF						Installation record	Y	1964	nsp during install o	Field inspection only	Y		Cross-connection survey	
2012	MARLEE LANE			C	N	3/4"		C	1"		MF						Installation record	Y	1964	nsp during install o	Field inspection only	Y		Cross-connection survey	
2011	MARLEE LANE			C	N	3/4"		C			SF						Installation record	Y	1964	nsp during install o	Installation record	N			
2023	MARLEE LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1964	nsp during install o	Field inspection only	Y		Cross-connection survey	
2040	MARLEE LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1964	nsp during install o	Field inspection only	Y		Cross-connection survey	
2041	MARLEE LANE			C	N	3/4"		C	3/4"		MF						Installation record	Y	1964	nsp during install o	Field inspection only	Y		Cross-connection survey	
2043	MARLEE LANE			C	N	3/4"		C	3/4"		MF						Installation record	Y	1964	nsp during install o	Field inspection only	Y		Cross-connection survey	
2067	MARLEE LANE			C	N	3/4"		C			SF						Installation record	Y	1964	nsp during install o	Installation record	N			
2075	MARLEE LANE			C	N	3/4"		C			MF						Installation record	Y	1964	nsp during install o	Installation record	N			
2073	MARLEE LANE			C	N	3/4"		C			MF						Installation record	Y	1964	nsp during install o	Installation record	N			
2074	MARLEE LANE			C	N	3/4"		C	3/4"		MF						Installation record	Y	1964	nsp during install o	Field inspection only	Y		Cross-connection survey	
2076	MARLEE LANE			C	N	3/4"		C	3/4"		MF						Installation record	Y	1964	nsp during install o	Field inspection only	Y		Cross-connection survey	
2101	MARLEE LANE			C	N	3/4"		C	3/4"		MF						Installation record	Y	1964	nsp during install o	Field inspection only	Y		Cross-connection survey	
2099	MARLEE LANE			C	N	3/4"		C	3/4"		MF						Installation record	Y	1964	nsp during install o	Field inspection only	Y		Cross-connection survey	
2100	MARLEE LANE			C	N	3/4"		C			SF						Installation record	Y	1964	nsp during install o	Installation record	N			
1084	MARVELLE LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1965	nsp during install o	Installation record	N			
1070	MARVELLE LANE			C	N	3/4"		C			SF						Installation record	Y	1965	nsp during install o	Installation record	N			
942	MARVELLE LANE			C	N	3/4"		C			SF						Installation record	Y	1965	nsp during install o	Installation record	N			
1043	MARVELLE LANE	A5		C	N	3/4"		C			MF						Installation record	Y	1965	nsp during install o	Installation record	N			
921	MARVELLE LANE			C	N	3/4"		C			SF						Installation record	Y	1965	nsp during install o	Installation record	N			
1045	MARVELLE LANE	B10		C	N	3/4"		C			MF						Installation record	Y	1965	nsp during install o	Installation record	N			
924	MARVELLE LANE			C	N	3/4"		C			SF						Installation record	Y	1965	nsp during install o	Installation record	N			
1096	MARVELLE LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1965	nsp during install o	Field inspection only	Y		Cross-connection survey	
883	MARVELLE LANE			C	N	3/4"		C			SF						Installation record	Y	1965	nsp during install o	Installation record	N			
1044	MARVELLE LANE			C	N	3/4"		C			SF						Installation record	Y	1965	nsp during install o	Installation record	N			
1042	MARVELLE LANE			C	N	3/4"		C			SF						Installation record	Y	1965	nsp during install o	Installation record	N			
1136	MARVELLE LANE			C	N	3/4"		C			SF						Installation record	Y	1965	nsp during install o	Installation record	N			
1130	MARVELLE LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1965	nsp during install o	Field inspection only	Y		Cross-connection survey	
1122	MARVELLE LANE			C	N	3/4"		C			SF						Installation record	Y	1965	nsp during install o	Installation record	N			
1116	MARVELLE LANE			C	N	3/4"		C	1"		SF						Installation record	Y	1965	nsp during install o	Installation record	N			
1110	MARVELLE LANE			C	N	3/4"		C			SF						Installation record	Y	1965	nsp during install o	Installation record	N			
1102	MARVELLE LANE			C	N	3/4"		C			SF						Installation record	Y	1965	nsp during install o	Installation record	N			
1090	MARVELLE LANE			C	N	3/4"		C			SF						Installation record	Y	1965	nsp during install o	Installation record	N			
1076	MARVELLE LANE			C	N	3/4"		C			SF						Installation record	Y	1965	nsp during install o	Installation record	N			
1064	MARVELLE LANE			C	N	3/4"		C			SF						Installation record	Y	1965	nsp during install o	Installation record	N			
1051	MARVELLE LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1965	nsp during install o	Field inspection only	Y		Cross-connection survey	
1043	MARVELLE LANE	A2		DI	N	8"	1965	DI			MF						Installation record	Y	1965	nsp during install o	Installation record	N			
1043	MARVELLE LANE	A3		C	N	3/4"		C			MF						Installation record	N			Installation record	N			
1043	MARVELLE LANE	A4		C	N	3/4"		C			MF						Installation record	N			Installation record	N			
1043	MARVELLE LANE	A5		C	N	3/4"		C			MF						Installation record	N			Installation record	N			
1043	MARVELLE LANE	A5		C	N	3/4"		C			MF						Installation record	N			Installation record	N			
1043	MARVELLE LANE	A5		C	N	3/4"		C			MF						Installation record	N			Installation record	N			
1043	MARVELLE LANE	A5		C	N	3/4"		C			MF						Installation record	N			Installation record	N			
1043	MARVELLE LANE	A5		C	N	3/4"		C			MF						Installation record	N			Installation record	N			
1043	MARVELLE LANE	A5		C	N	3/4"		C			MF						Installation record	N			Installation record	N			
1043	MARVELLE LANE	A5		C	N	3/4"		C			MF						Installation record	N			Installation record	N			
1043	MARVELLE LANE	A11		C	N	3/4"		C			MF						Installation record	N			Installation record	N			
1043	MARVELLE LANE	A14		C	N	3/4"		C			MF						Installation record	N			Installation record	N			
1043	MARVELLE LANE	A13		C	N	3/4"		C			MF						Installation record	N			Installation record	N			
1043	MARVELLE LANE	A9		C	N	3/4"		C			MF						Installation record	N			Installation record	N			
1043	MARVELLE LANE	A7		C	N	3/4"		C	3/4"		MF						Installation record	N			Installation record	N			
1043	MARVELLE LANE	A15		C	N	3/4"		C			MF						Installation record	N			Installation record	N			
1043	MARVELLE LANE	A1		C	N	3/4"		C			MF						Installation record	N			Installation record	N			
1045	MARVELLE LANE	B1		DI	N	6"		DI			MF						Installation record	Y	1965	nsp during install o	Installation record	N			
1045	MARVELLE LANE	B2		C	N	3/4"		C			MF						Installation record	N	1965		Installation record	N			
1045	MARVELLE LANE	B3		C	N	3/4"		C			MF						Installation record	N	1965		Installation record	N			
1045	MARVELLE LANE	B4		C	N	3/4"		C	3/4"		MF						Installation record	N	1965		Field inspection only	Y		Visual insp at meter	
1045	MARVELLE LANE	B5		C	N	3/4"		C			MF						Installation record	N	1965		Installation record	N			
1045	MARVELLE LANE	B6		C	N	3/4"		C			MF						Installation record	N	1965		Installation record	N			
1045	MARVELLE LANE	B7		C	N	3/4"		C			MF						Installation record	N	1965		Installation record	N			
1045	MARVELLE LANE	B8		C	N	3/4"		C			MF						Installation record	N	1965		Installation record	N			
1045	MARVELLE LANE	B9		C	N	3/4"		C			MF						Installation record	N	1965		Installation record	N			
1045	MARVELLE LANE	B10		C	N	3/4"		C			MF						Installation record	N	1965		Installation record	N			
1045	MARVELLE LANE	B11		C	N	3/4"		C			MF						Installation record	N	1965		Installation record	N			
1045	MARVELLE LANE	B12		C	N	3/4"		C			MF						Installation record	N	1965		Installation record	N			
1045	MARVELLE LANE	WOM		C	N	3/4"		C			MF						Installation record	N	1965		Installation record	N			
1004	MARVELLE LANE			C	N	3/4"		C			SF						Installation record	Y	1965	nsp during install o	Installation record	N			
1006	MARVELLE LANE			C	N	3/4"		C	1"		SF						Installation record	Y	1965	nsp during install o	Field inspection only	Y		Cross-connection survey	
915	MARVELLE LANE			C	N	3/4"		C			SF						Installation record	Y	1965	nsp during install o	Installation record	N			
929	MARVELLE LANE			C	N	3/4"		C			SF						Installation record	Y	1965	nsp during install o	Installation record	N			
935	MARVELLE LANE			C	N	3/4"		C			SF						Installation record	Y	1965	nsp during install o	Installation record	N			
943	MARVELLE LANE			C	N	3/4"		C			SF						Installation record	Y	1965	nsp during install o	Installation record	N			
951	MARVELLE LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1965	nsp during install o	Field inspection only	Y		Cross-connection survey	
961	MARVELLE LANE			C	N	3/4"		C	1"		SF						Installation record	Y	1965	nsp during install o	Installation record	N			
963	MARVELLE LANE			C	N	3/4"		C			SF						Installation record	Y	1965	nsp during install o	Installation record	N			
986	MARVELLE LANE			C	N	3/4"		C			SF						Installation record	Y	1965	nsp during install o	Installation record	N			
980	MARVELLE LANE			C	N	3/4"		C			SF						Installation record	Y	1965	nsp during install o	Installation record	N			
972	MARVELLE LANE			C	N	3/4"		C			SF						Installation record	Y	1965	nsp during install o	Installation record	N			
964	MARVELLE LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1965	nsp during install o	Field inspection only	Y		Cross-connection survey	
956	MARVELLE LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1965	nsp during install o	Field inspection only	Y		Cross-connection survey	
950	MARVELLE LANE			C	N	3/4"		C			SF						Installation record	Y	1965	nsp during install o	Installation record	N			
936	MARVELLE LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1965	nsp during install o	Field inspection only	Y		Cross-connection survey	

LOCATIONAL IDENTIFIER ADDRESS	LOCATIONAL IDENTIFIER STREET NAME	LOCATIONAL IDENTIFIER UNIT OR SUITE #	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
930	MARVELLE LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1965	nsp during install o	Field inspection only	Y		Cross-connection survey	
918	MARVELLE LANE			C	N	3/4"		C			SF						Installation record	Y	1965	nsp during install o	Installation record	N			
912	MARVELLE LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1965	nsp during install o	Field inspection only	Y		Cross-connection survey	
892	MARVELLE LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1965	nsp during install o	Field inspection only	Y		Cross-connection survey	
3650	MAY LANE			P	N	1"		P	1"		SF						Installation record	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3711	MAY LANE			P	N	1"		P	1"		SF						Installation record	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3658	MAY LANE			P	N	1"		P	1"		SF						Installation record	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3671	MAY LANE			P	N	1"		P	1"		SF						Installation record	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3642	MAY LANE			P	N	1"		P	1"		SF						Installation record	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3712	MAY LANE			P	N	1"		P	1"		SF						Installation record	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3668	MAY LANE			P	N	1"		P	1"		SF						Installation record	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3676	MAY LANE			P	N	1"		P	1"		SF						Installation record	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3756	MAY LANE			P	N	1"		P	1"		SF						Installation record	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3748	MAY LANE			P	N	1"		P	1"		SF						Installation record	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3730	MAY LANE			P	N	1"		P	1"		SF						Installation record	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3694	MAY LANE			P	N	1"		P	1"		SF						Installation record	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3634	MAY LANE			P	N	1"		P	1"		SF						Installation record	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3633	MAY LANE			P	N	1"		P	1"		SF						Installation record	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3618	MAY LANE			P	N	1"		P	1"		SF						Installation record	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3617	MAY LANE			P	N	1"		P	1"		SF						Installation record	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3784	MAY LANE			P	N	1"		P	1"		SF						Installation record	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3776	MAY LANE			P	N	1"		P	1"		SF						Installation record	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3764	MAY LANE			P	N	1"		P	1"		SF						Installation record	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3777	MAY LANE			P	N	1"		P	1"		SF						Installation record	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3691	MAY LANE			P	N	1"		P	1"		SF						Installation record	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3657	MAY LANE			P	N	1"		P	1"		SF						Installation record	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3626	MAY LANE			P	N	1"		P	1"		SF						Installation record	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3649	MAY LANE			P	N	1"		P	1"		SF						Installation record	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3625	MAY LANE			P	N	1"		P	1"		SF						Installation record	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1539	MESA DRIVE			C	N	1"		C	1"		SF						Installation record	Y	1986	nsp during install o	Installation record	N			
1601	MESA DRIVE			C	N	1"		C			SF						Installation record	Y	1986	nsp during install o	Installation record	N			
1551	MESA DRIVE			C	N	1"		P	1"		SF						Installation record	Y	1986	nsp during install o	Field inspection only	Y		Cross-connection survey	
1561	MESA DRIVE			C	N	1"		C			SF						Installation record	Y	1986	nsp during install o	Installation record	N			
1570	MESA DRIVE			C	N	1"		C	1"		SF						Installation record	Y	1986	nsp during install o	Field inspection only	Y		Cross-connection survey	
1369	MESA DRIVE			C	N	1"		C			SF						Installation record	Y	1986	nsp during install o	Installation record	N			
1401	MESA DRIVE			C	N	1"		C			SF						Installation record	Y	1986	nsp during install o	Installation record	N			
1541	MESA DRIVE			C	N	1"		C	3/4"		SF						Installation record	Y	1986	nsp during install o	Field inspection only	Y		Cross-connection survey	
1575	MESA DRIVE			C	N	1"		C			SF						Installation record	Y	1986	nsp during install o	Installation record	N			
1415	MESA DRIVE			C	N	1"		C			SF						Installation record	Y	1986	nsp during install o	Installation record	N			
1407	MESA DRIVE			C	N	1"		C			SF						Installation record	Y	1986	nsp during install o	Installation record	N			
1383	MESA DRIVE			C	N	1"		C			SF						Installation record	Y	1986	nsp during install o	Installation record	N			
1375	MESA DRIVE			C	N	1"		P	1"		SF						Installation record	Y	1986	nsp during install o	Field inspection only	Y		Cross-connection survey	
1400	MESA DRIVE			C	N	1"		C	1"		SF						Installation record	Y	1986	nsp during install o	Field inspection only	Y		Cross-connection survey	
1410	MESA DRIVE			C	N	1"		C			SF						Installation record	Y	1986	nsp during install o	Installation record	N			
1412	MESA DRIVE			C	N	1"		C			SF						Installation record	Y	1986	nsp during install o	Installation record	N			
1420	MESA DRIVE			C	N	1"		C	1"		SF						Installation record	Y	1986	nsp during install o	Field inspection only	Y		Cross-connection survey	
1436	MESA DRIVE			C	N	1"		C	3/4"		SF						Installation record	Y	1986	nsp during install o	Field inspection only	Y		Cross-connection survey	
1437	MESA DRIVE			C	N	1"		C			SF						Installation record	Y	1986	nsp during install o	Installation record	N			
1475	MESA DRIVE			C	N	1"		C	1"		SF						Installation record	Y	1986	nsp during install o	Field inspection only	Y		Cross-connection survey	
1505	MESA DRIVE			C	N	1"		C			SF						Installation record	Y	1986	nsp during install o	Installation record	N			
1515	MESA DRIVE			C	N	1"		C	1"		SF						Installation record	Y	1986	nsp during install o	Field inspection only	Y		Cross-connection survey	
1605	MESA DRIVE			C	N	1"		P	1"		SF						Installation record	Y	1986	nsp during install o	Field inspection only	Y		Cross-connection survey	
1591	MESA DRIVE			C	N	1"		P	1"		SF						Installation record	Y	1986	nsp during install o	Field inspection only	Y		Cross-connection survey	
1581	MESA DRIVE			C	N	1"		P	1"		SF						Installation record	Y	1986	nsp during install o	Field inspection only	Y		Cross-connection survey	
1571	MESA DRIVE			C	N	1"		C			SF						Installation record	Y	1986	nsp during install o	Installation record	N			
1542	MESA DRIVE			C	N	1"		C	3/4"		SF						Installation record	Y	1986	nsp during install o	Field inspection only	Y		Cross-connection survey	
1550	MESA DRIVE			C	N	1"		C			SF						Installation record	Y	1986	nsp during install o	Installation record	N			
1560	MESA DRIVE			C	N	1"		C			SF						Installation record	Y	1986	nsp during install o	Installation record	N			
1580	MESA DRIVE			C	N	1"		P	1"		SF						Installation record	Y	1986	nsp during install o	Field inspection only	Y		Cross-connection survey	
1446	MESA DRIVE			C	N	1"		P	1"		SF						Installation record	Y	1986	nsp during install o	Field inspection only	Y		Cross-connection survey	
1071	MISTY MEADOW CIRCLE	2		P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1075	MISTY MEADOW CIRCLE	1		P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1075	MISTY MEADOW CIRCLE	2		P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1042	MISTY MEADOW CIRCLE	1		P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1071	MISTY MEADOW CIRCLE	1		P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1083	MISTY MEADOW CIRCLE	1		P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1083	MISTY MEADOW CIRCLE	2		P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1035	MISTY MEADOW CIRCLE	2		P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1035	MISTY MEADOW CIRCLE	1		P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1067	MISTY MEADOW CIRCLE	2		P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1067	MISTY MEADOW CIRCLE	1		P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1127	MISTY MEADOW CIRCLE	1		P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1127	MISTY MEADOW CIRCLE	2		P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1124	MISTY MEADOW CIRCLE	1		P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1124	MISTY MEADOW CIRCLE	2		P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1132	MISTY MEADOW CIRCLE	1		P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1059	MISTY MEADOW CIRCLE	1		P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1059	MISTY MEADOW CIRCLE	2		P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1132	MISTY MEADOW CIRCLE	2		P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1028	MISTY MEADOW CIRCLE	1		P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1028	MISTY MEADOW CIRCLE	2		P	N	1"		P	2"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1089	MISTY MEADOW CIRCLE	2		P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1089	MISTY MEADOW CIRCLE	1		P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1031	MISTY MEADOW CIRCLE	1		P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1031	MISTY MEADOW CIRCLE	2		P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	

LOCATIONAL IDENTIFIER ADDRESS	LOCATIONAL IDENTIFIER STREET NAME	LOCATIONAL IDENTIFIER UNIT OR SUITE #	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
1043	MISTY MEADOW CIRCLE	2		P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1043	MISTY MEADOW CIRCLE	1		P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1043	MISTY MEADOW CIRCLE	3		P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1039	MISTY MEADOW CIRCLE	1		P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1039	MISTY MEADOW CIRCLE	2		P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1052	MISTY MEADOW CIRCLE	2		P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1052	MISTY MEADOW CIRCLE	1		P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1090	MISTY MEADOW CIRCLE	1		P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1090	MISTY MEADOW CIRCLE	2		P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1036	MISTY MEADOW CIRCLE	1		P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1036	MISTY MEADOW CIRCLE	2		P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1042	MISTY MEADOW CIRCLE	2		P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1051	MISTY MEADOW CIRCLE	2		P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1051	MISTY MEADOW CIRCLE	3		P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1051	MISTY MEADOW CIRCLE	1		P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1068	MISTY MEADOW CIRCLE	1		P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1068	MISTY MEADOW CIRCLE	2		P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1076	MISTY MEADOW CIRCLE	1		P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1076	MISTY MEADOW CIRCLE	2		P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3701	MISTY MEADOW LANE	1		P	N			P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3701	MISTY MEADOW LANE	2		P	N			P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3744	MISTY MEADOW LANE			P	N			P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3711	MISTY MEADOW LANE	2		P	N			P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3711	MISTY MEADOW LANE	1		P	N			P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3736	MISTY MEADOW LANE			P	N			P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3728	MISTY MEADOW LANE			P	N			P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3767	MISTY MEADOW LANE			P	N			P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3775	MISTY MEADOW LANE			P	N			P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3791	MISTY MEADOW LANE			P	N			P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3782	MISTY MEADOW LANE			P	N			P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3790	MISTY MEADOW LANE			P	N			P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1491	MOHICAN COURT			C	N	1"		C			SF						Installed after lead ban	Y	1991	nsp during install o	Installed after lead ban	N			
1400	MOHICAN COURT			C	N	1"		C			SF						Installed after lead ban	Y	1991	nsp during install o	Installed after lead ban	N			
1401	MOHICAN COURT			C	N	1"		C			SF						Installed after lead ban	Y	1991	nsp during install o	Installed after lead ban	N			
1440	MOHICAN COURT			C	N	1"		P	1"		SF						Installed after lead ban	Y	1991	nsp during install o	Field inspection only	Y		Cross-connection survey	
1412	MOHICAN COURT			C	N	1"		C			SF						Installed after lead ban	Y	1991	nsp during install o	Installed after lead ban	N			
1421	MOHICAN COURT			C	N	1"		C			SF						Installed after lead ban	Y	1991	nsp during install o	Installed after lead ban	N			
1420	MOHICAN COURT			C	N	1"		C			SF						Installed after lead ban	Y	1991	nsp during install o	Installed after lead ban	N			
1380	MOHICAN COURT			C	N	1"		C			SF						Installed after lead ban	Y	1991	nsp during install o	Installed after lead ban	N			
1390	MOHICAN COURT			C	N	1"		C			SF						Installed after lead ban	Y	1991	nsp during install o	Installed after lead ban	N			
1451	MOHICAN COURT			C	N	1"		C	3/4"		SF						Installed after lead ban	Y	1991	nsp during install o	Field inspection only	Y		Cross-connection survey	
1445	MOHICAN COURT			C	N	1"		C			SF						Installed after lead ban	Y	1991	nsp during install o	Installed after lead ban	N			
1441	MOHICAN COURT			C	N	1"		C	1"		SF						Installed after lead ban	Y	1991	nsp during install o	Installed after lead ban	N			
1435	MOHICAN COURT			C	N	1"		P	1"		SF						Installed after lead ban	Y	1991	nsp during install o	Installed after lead ban	N			
1427	MOHICAN COURT			C	N	1"		C			SF						Installed after lead ban	Y	1991	nsp during install o	Installed after lead ban	N			
1384	MOHICAN COURT			C		1"		P	1"		SF						Installed after lead ban	Y	1991	nsp during install o	Field inspection only	Y		Cross-connection survey	
1415	MOHICAN COURT			C	N	1"		C			SF						Installed after lead ban	Y	1991	nsp during install o	Installed after lead ban	N			
1407	MOHICAN COURT			C	N	1"		P	1"		SF						Installed after lead ban	Y	1991	nsp during install o	Field inspection only	Y		Cross-connection survey	
1406	MOHICAN COURT			C	N	1"		C			SF						Installed after lead ban	Y	1991	nsp during install o	Installed after lead ban	N			
1426	MOHICAN COURT			C	N	1"		C	1"		SF						Installed after lead ban	Y	1991	nsp during install o	Field inspection only	Y		Cross-connection survey	
1430	MOHICAN COURT			C	N	1"		C			SF						Installed after lead ban	Y	1991	nsp during install o	Installed after lead ban	N			
1444	MOHICAN COURT			C	N	1"		P	1"		SF						Installed after lead ban	Y	1991	nsp during install o	Field inspection only	Y		Cross-connection survey	
1450	MOHICAN COURT			C	N	1"		C			SF						Installed after lead ban	Y	1991	nsp during install o	Installed after lead ban	N			
1458	MOHICAN COURT			C	N	1"		C	3/4"		SF						Installed after lead ban	Y	1991	nsp during install o	Field inspection only	Y		Cross-connection survey	
1464	MOHICAN COURT			C	N	1"		C			SF						Installed after lead ban	Y	1991	nsp during install o	Installed after lead ban	N			
1470	MOHICAN COURT			C	N	1"		C			SF						Installed after lead ban	Y	1991	nsp during install o	Installed after lead ban	N			
1476	MOHICAN COURT			C	N	1"		C	1"		SF						Installed after lead ban	Y	1991	nsp during install o	Installed after lead ban	N			
1482	MOHICAN COURT			C	N	1"		C			SF						Installed after lead ban	Y	1991	nsp during install o	Installed after lead ban	N			
1490	MOHICAN COURT			C	N	1"		C			SF						Installed after lead ban	Y	1991	nsp during install o	Installed after lead ban	N			
1496	MOHICAN COURT			C	N	1"		C			SF						Installed after lead ban	Y	1991	nsp during install o	Installed after lead ban	N			
1502	MOHICAN COURT			C	N	1"		C			SF						Installed after lead ban	Y	1991	nsp during install o	Installed after lead ban	N			
1506	MOHICAN COURT			C	N	1"		C			SF						Installed after lead ban	Y	1991	nsp during install o	Installed after lead ban	N			
1510	MOHICAN COURT			C	N	1"		C			SF						Installed after lead ban	Y	1991	nsp during install o	Installed after lead ban	N			
1511	MOHICAN COURT			C	N	1"		C			SF						Installed after lead ban	Y	1991	nsp during install o	Installed after lead ban	N			
1505	MOHICAN COURT			C	N	1"		C			SF						Installed after lead ban	Y	1991	nsp during install o	Installed after lead ban	N			
1499	MOHICAN COURT			C	N	1"		C			SF						Installed after lead ban	Y	1991	nsp during install o	Installed after lead ban	N			
1485	MOHICAN COURT			C	N	1"		C	3/4"		SF						Installed after lead ban	Y	1991	nsp during install o	Field inspection only	Y		Cross-connection survey	
1479	MOHICAN COURT			C	N	1"		C			SF						Installed after lead ban	Y	1991	nsp during install o	Installed after lead ban	N			
1450	MOHICAN COURT	WOM		C	N	1"		C			SF						Installed after lead ban	Y	1991	nsp during install o	Installed after lead ban	N			
458	MORRIS AVENUE			C	N	3/4"		C	1"		SF						Installed after lead ban	Y	1991	nsp during install o	Installation record	N			
691	MORRIS AVENUE			C	N	3/4"		C			SF						Installation record	Y	1961	nsp during install o	Installation record	N			
1065	MORRIS AVENUE			C	N	3/4"		C	1"		SF						Installation record	Y	1961	nsp during install o	Field inspection only	Y		Cross-connection survey	
1461	MORRIS AVENUE			C	N	3/4"		C			SF						Installation record	Y	1961	nsp during install o	Installation record	N			
944	MORRIS AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1961	nsp during install o	Field inspection only	Y		Cross-connection survey	
1122	MORRIS AVENUE			C	N	3/4"		C			SF						Installation record	Y	1961	nsp during install o	Installation record	N			
1295	MORRIS AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1961	nsp during install o	Field inspection only	Y		Cross-connection survey	
695	MORRIS AVENUE			C	N	3/4"		C			SF						Installation record	Y	1961	nsp during install o	Installation record	N			
918	MORRIS AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1961	nsp during install o	Field inspection only	Y		Cross-connection survey	
616	MORRIS AVENUE			C	N	3/4"		C	1"		SF						Installation record	Y	1961	nsp during install o	Field inspection only	Y		Cross-connection survey	
1108	MORRIS AVENUE			C	N	3/4"		C			SF						Installation record	Y	1961	nsp during install o	Installation record	N			
1014	MORRIS AVENUE			C	N	3/4"		C	1"		SF						Installation record	Y	1961	nsp during install o	Installation record	N			
936	MORRIS AVENUE			C	N	3/4"		C			SF						Installation record	Y	1961	nsp during install o	Installation record	N			
1006	MORRIS AVENUE			C	N	3/4"		C			SF						Installation record	Y	1961	nsp during install o	Installation record	N			
667	MORRIS AVENUE			C	N	3/4"		C			SF						Installation record	Y	1961	nsp during install o	Installation record	N			
913	MORRIS AVENUE			C	N	3/4"		C			SF						Installation record	Y	1961	nsp during install o	Installation record	N			

LOCATIONAL IDENTIFIER ADDRESS	LOCATIONAL IDENTIFIER STREET NAME	LOCATIONAL IDENTIFIER UNIT OR SUITE #	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
1090	MORRIS AVENUE			C	N	3/4"		C			SF						Installation record	Y	1961	nsp during install o	Installation record	N			
1076	MORRIS AVENUE			C	N	3/4"		C			SF						Installation record	Y	1961	nsp during install o	Installation record	N			
1116	MORRIS AVENUE			C	N	3/4"		C			SF						Installation record	Y	1961	nsp during install o	Installation record	N			
912	MORRIS AVENUE			C	N	3/4"		C			SF						Installation record	Y	1961	nsp during install o	Installation record	N			
522	MORRIS AVENUE			C	N	3/4"		C			SF						Installation record	Y	1961	nsp during install o	Installation record	N			
979	MORRIS AVENUE			C	N	3/4"		C			SF						Installation record	Y	1961	nsp during install o	Installation record	N			
679	MORRIS AVENUE			C	N	3/4"		C			SF						Installation record	Y	1961	nsp during install o	Installation record	N			
950	MORRIS AVENUE			C	N	3/4"		C			SF						Installation record	Y	1961	nsp during install o	Installation record	N			
496	MORRIS AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1961	nsp during install o	Field inspection only	Y		Cross-connection survey	
529	MORRIS AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1961	nsp during install o	Field inspection only	Y		Cross-connection survey	
1084	MORRIS AVENUE			C	N	3/4"		C			SF						Installation record	Y	1961	nsp during install o	Installation record	N			
657	MORRIS AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1961	nsp during install o	Field inspection only	Y		Cross-connection survey	
614	MORRIS AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1961	nsp during install o	Field inspection only	Y		Cross-connection survey	
464	MORRIS AVENUE			C	N	3/4"		C			SF						Installation record	Y	1961	nsp during install o	Installation record	N			
661	MORRIS AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1961	nsp during install o	Field inspection only	Y		Cross-connection survey	
681	MORRIS AVENUE			C	N	3/4"		C			SF						Installation record	Y	1961	nsp during install o	Installation record	N			
602	MORRIS AVENUE			C	N	3/4"		C	1"		SF						Installation record	Y	1961	nsp during install o	Field inspection only	Y		Cross-connection survey	
452	MORRIS AVENUE			C	N	3/4"		C			SF						Installation record	Y	1961	nsp during install o	Installation record	N			
621	MORRIS AVENUE			C	N	3/4"		C			SF						Installation record	Y	1961	nsp during install o	Installation record	N			
485	MORRIS AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1961	nsp during install o	Field inspection only	Y		Cross-connection survey	
1064	MORRIS AVENUE			C	N	3/4"		C			SF						Installation record	Y	1961	nsp during install o	Installation record	N			
1096	MORRIS AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1961	nsp during install o	Field inspection only	Y		Cross-connection survey	
1102	MORRIS AVENUE			C	N	3/4"		C			SF						Installation record	Y	1961	nsp during install o	Installation record	N			
490	MORRIS AVENUE			C	N	3/4"		C			SF						Installation record	Y	1961	nsp during install o	Installation record	N			
971	MORRIS AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1961	nsp during install o	Field inspection only	Y		Cross-connection survey	
930	MORRIS AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1961	nsp during install o	Field inspection only	Y		Cross-connection survey	
1300	MORRIS AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1961	nsp during install o	Field inspection only	Y		Cross-connection survey	
1210	MORRIS AVENUE			C	N	3/4"		C			SF						Installation record	Y	1961	nsp during install o	Field inspection only	N			
461	MORRIS AVENUE			C	N	3/4"		C			SF						Installation record	Y	1961	nsp during install o	Field inspection only	N			
457	MORRIS AVENUE			C	N	3/4"		C			SF						Installation record	Y	1961	nsp during install o	Field inspection only	N			
511	MORRIS AVENUE			C	N	3/4"		C			SF						Installation record	Y	1961	nsp during install o	Field inspection only	N			
515	MORRIS AVENUE			C	N	3/4"		C			SF						Installation record	Y	1961	nsp during install o	Field inspection only	N			
523	MORRIS AVENUE			C	N	3/4"		C			SF						Installation record	Y	1961	nsp during install o	Field inspection only	N			
540	MORRIS AVENUE			C	N	3/4"		C			SF						Installation record	Y	1961	nsp during install o	Field inspection only	N			
538	MORRIS AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1961	nsp during install o	Field inspection only	Y		Cross-connection survey	
514	MORRIS AVENUE			C	N	3/4"		C			SF						Installation record	Y	1961	nsp during install o	Installation record	N			
508	MORRIS AVENUE			C	N	3/4"		C			SF						Installation record	Y	1961	nsp during install o	Installation record	N			
518	MORRIS AVENUE			C	N	3/4"		C			SF						Installation record	Y	1961	nsp during install o	Installation record	N			
721	MORRIS AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1961	nsp during install o	Field inspection only	Y		Cross-connection survey	
530	MORRIS AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1961	nsp during install o	Field inspection only	Y		Cross-connection survey	
521	MORRIS AVENUE			C	N	3/4"		P	3/4"		SF						Installation record	Y	1961	nsp during install o	Field inspection only	Y		Cross-connection survey	
473	MORRIS AVENUE			C	N	3/4"		C			SF						Installation record	Y	1961	nsp during install o	Installation record	N			
493	MORRIS AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1961	nsp during install o	Field inspection only	Y		Cross-connection survey	
539	MORRIS AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1961	nsp during install o	Field inspection only	Y		Cross-connection survey	
481	MORRIS AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1961	nsp during install o	Field inspection only	Y		Cross-connection survey	
477	MORRIS AVENUE			C	N	3/4"		C			SF						Installation record	Y	1961	nsp during install o	Installation record	N			
644	MORRIS AVENUE			C	N	3/4"		C			SF						Installation record	Y	1961	nsp during install o	Installation record	N			
476	MORRIS AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1961	nsp during install o	Installation record	N			
484	MORRIS AVENUE			C	N	3/4"		C			SF						Installation record	Y	1961	nsp during install o	Installation record	N			
924	MORRIS AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1961	nsp during install o	Field inspection only	Y		Cross-connection survey	
1211	MORRIS AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1961	nsp during install o	Field inspection only	Y		Cross-connection survey	
1280	MORRIS AVENUE			C	N	3/4"		C			SF						Installation record	Y	1961	nsp during install o	Installation record	N			
673	MORRIS AVENUE			C	N	3/4"		C			SF						Installation record	Y	1961	nsp during install o	Installation record	N			
486	MORRIS AVENUE			C	N	3/4"		C			SF						Installation record	Y	1961	nsp during install o	Installation record	N			
1128	MORRIS AVENUE			C	N	3/4"		C	1"		SF						Installation record	Y	1961	nsp during install o	Field inspection only	Y		Cross-connection survey	
1507	MORRIS AVENUE			C	N	3/4"		C			SF						Installation record	Y	1961	nsp during install o	Installation record	N			
537	MORRIS AVENUE			C	N	3/4"		C			SF						Installation record	Y	1961	nsp during install o	Installation record	N			
468	MORRIS AVENUE			C	N	3/4"		C			SF						Installation record	Y	1961	nsp during install o	Installation record	N			
489	MORRIS AVENUE			C	N	3/4"		C			SF						Installation record	Y	1961	nsp during install o	Installation record	N			
983	MORRIS AVENUE			C	N	3/4"		C	3/4"		MF						Installation record	Y	1961	nsp during install o	Field inspection only	Y		Cross-connection survey	
985	MORRIS AVENUE			C	N	3/4"		C			MF						Installation record	Y	1961	nsp during install o	Installation record	N			
587	MORRIS AVENUE			C	N	3/4"		C			SF						Installation record	Y	1961	nsp during install o	Installation record	N			
1115	MORRIS AVENUE			C	N	3/4"		C			SF						Installation record	Y	1961	nsp during install o	Installation record	N			
947	MORRIS AVENUE			C	N	3/4"		C	1"		SF						Installation record	Y	1961	nsp during install o	Field inspection only	Y		Cross-connection survey	
656	MORRIS AVENUE			C	N	3/4"		C			SF						Installation record	Y	1961	nsp during install o	Installation record	N			
595	MORRIS AVENUE			C	N	3/4"		C			SF						Installation record	Y	1961	nsp during install o	Installation record	N			
456	MORRIS AVENUE			C	N	3/4"		C			SF						Installation record	Y	1961	nsp during install o	Installation record	N			
1199	MORRIS AVENUE			C	N	3/4"		C			SF						Installation record	Y	1961	nsp during install o	Installation record	N			
1134	MORRIS AVENUE			C	N	3/4"		C			SF						Installation record	Y	1961	nsp during install o	Installation record	N			
1275	MORRIS AVENUE			C	N	3/4"		C			SF						Installation record	Y	1961	nsp during install o	Installation record	N			
1496	MORRIS AVENUE			C	N	3/4"		C			SF						Installation record	Y	1961	nsp during install o	Installation record	N			
860	MORRIS AVENUE			C	N	3/4"		C			SF						Installation record	Y	1961	nsp during install o	Installation record	N			
527	MORRIS AVENUE			C	N	3/4"		C			SF						Installation record	Y	1961	nsp during install o	Installation record	N			
478	MORRIS AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1961	nsp during install o	Field inspection only	Y		Cross-connection survey	
1044	MORRIS AVENUE			C	N	3/4"		C			SF						Installation record	Y	1961	nsp during install o	Installation record	N			
1070	MORRIS AVENUE			C	N	3/4"		C			SF						Installation record	Y	1961	nsp during install o	Installation record	N			
1135	MORRIS AVENUE			C	N	3/4"		C			SF						Installation record	Y	1961	nsp during install o	Installation record	N			
1129	MORRIS AVENUE			C	N	3/4"		C			SF						Installation record	Y	1961	nsp during install o	Installation record	N			
1123	MORRIS AVENUE			C	N	3/4"		C	1"		SF						Installation record	Y	1961	nsp during install o	Field inspection only	Y		Cross-connection survey	
1109	MORRIS AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1961	nsp during install o	Field inspection only	Y		Cross-connection survey	
1103	MORRIS AVENUE			C	N	3/4"		C			SF						Installation record	Y	1961	nsp during install o	Installation record	N			
1095	MORRIS AVENUE			C	N	3/4"		C			SF						Installation record	Y	1961	nsp during install o	Installation record	N			
1091	MORRIS AVENUE			C	N	3/4"		C			SF						Installation record	Y	1961	nsp during install o	Installation record	N			
1085	MORRIS AVENUE			C	N	3/4"		C			SF						Installation record	Y	1961	nsp during install o	Installation record	N			
1077	MORRIS AVENUE			C	N	3/4"		C			SF						Installation record	Y	1961	nsp during install o	Installation record	N			

LOCATIONAL IDENTIFIER ADDRESS	LOCATIONAL IDENTIFIER STREET NAME	LOCATIONAL IDENTIFIER UNIT OR SUITE #	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
1071	MORRIS AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1961	nsp during install o	Field inspection only	Y		Cross-connection survey	
597	MORRIS AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1961	nsp during install o	Field inspection only	Y		Cross-connection survey	
599	MORRIS AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1961	nsp during install o	Field inspection only	Y		Cross-connection survey	
603	MORRIS AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1961	nsp during install o	Field inspection only	Y		Cross-connection survey	
605	MORRIS AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1961	nsp during install o	Field inspection only	Y		Cross-connection survey	
617	MORRIS AVENUE			C	N	3/4"		C			SF						Installation record	Y	1961	nsp during install o	Installation record	N			
619	MORRIS AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1961	nsp during install o	Field inspection only	Y		Cross-connection survey	
645	MORRIS AVENUE			C	N	3/4"		C			SF						Installation record	Y	1961	nsp during install o	Installation record	N			
651	MORRIS AVENUE			C	N	3/4"		C			SF						Installation record	Y	1961	nsp during install o	Installation record	N			
701	MORRIS AVENUE			C	N	3/4"		C			SF						Installation record	Y	1961	nsp during install o	Installation record	N			
712	MORRIS AVENUE			C	N	3/4"		C			SF						Installation record	Y	1961	nsp during install o	Installation record	N			
706	MORRIS AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1961	nsp during install o	Field inspection only	Y		Cross-connection survey	
702	MORRIS AVENUE			C	N	3/4"		C			SF						Installation record	Y	1961	nsp during install o	Installation record	N			
700	MORRIS AVENUE			C	N	3/4"		C			SF						Installation record	Y	1961	nsp during install o	Installation record	N			
690	MORRIS AVENUE			C	N	3/4"		C			SF						Installation record	Y	1961	nsp during install o	Installation record	N			
678	MORRIS AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1961	nsp during install o	Field inspection only	Y		Cross-connection survey	
672	MORRIS AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1961	nsp during install o	Field inspection only	Y		Cross-connection survey	
666	MORRIS AVENUE			C	N	3/4"		C			SF						Installation record	Y	1961	nsp during install o	Installation record	N			
662	MORRIS AVENUE			C	N	3/4"		C	1"		SF						Installation record	Y	1961	nsp during install o	Field inspection only	Y		Cross-connection survey	
650	MORRIS AVENUE			C	N	3/4"		C			SF						Installation record	Y	1961	nsp during install o	Installation record	N			
1417	MORRIS AVENUE			C	N	3/4"		C			SF						Installation record	Y	1961	nsp during install o	Installation record	N			
919	MORRIS AVENUE			C	N	3/4"		C			SF						Installation record	Y	1961	nsp during install o	Installation record	N			
927	MORRIS AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1961	nsp during install o	Field inspection only	Y		Cross-connection survey	
931	MORRIS AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1961	nsp during install o	Field inspection only	Y		Cross-connection survey	
939	MORRIS AVENUE			C	N	3/4"		C			SF						Installation record	Y	1961	nsp during install o	Installation record	N			
951	MORRIS AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1961	nsp during install o	Field inspection only	Y		Cross-connection survey	
959	MORRIS AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1961	nsp during install o	Field inspection only	Y		Cross-connection survey	
965	MORRIS AVENUE			C	N	3/4"		C	1"		SF						Installation record	Y	1961	nsp during install o	Installation record	N			
990	MORRIS AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1961	nsp during install o	Field inspection only	Y		Cross-connection survey	
980	MORRIS AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1961	nsp during install o	Field inspection only	Y		Cross-connection survey	
964	MORRIS AVENUE			C	N	3/4"		C			SF						Installation record	Y	1961	nsp during install o	Installation record	N			
956	MORRIS AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1961	nsp during install o	Field inspection only	Y		Cross-connection survey	
890	MORRIS AVENUE			C	N	3/4"		C			SF						Installation record	Y	1961	nsp during install o	Installation record	N			
1160	MORRIS AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1961	nsp during install o	Field inspection only	Y		Cross-connection survey	
1166	MORRIS AVENUE			C	N	3/4"		C			SF						Installation record	Y	1961	nsp during install o	Installation record	N			
1172	MORRIS AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1961	nsp during install o	Installation record	N			
1178	MORRIS AVENUE			C	N	3/4"		C			SF						Installation record	Y	1961	nsp during install o	Installation record	N			
1184	MORRIS AVENUE			C	N	3/4"		C			SF						Installation record	Y	1961	nsp during install o	Installation record	N			
1192	MORRIS AVENUE			C	N	3/4"		C			SF						Installation record	Y	1961	nsp during install o	Installation record	N			
1198	MORRIS AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1961	nsp during install o	Field inspection only	Y		Cross-connection survey	
1204	MORRIS AVENUE			C	N	3/4"		C			SF						Installation record	Y	1961	nsp during install o	Installation record	N			
1216	MORRIS AVENUE			C	N	3/4"		C			SF						Installation record	Y	1961	nsp during install o	Installation record	N			
1242	MORRIS AVENUE			C	N	3/4"		C			SF						Installation record	Y	1961	nsp during install o	Installation record	N			
1248	MORRIS AVENUE			C	N	3/4"		C	1"		SF						Installation record	Y	1961	nsp during install o	Field inspection only	Y		Cross-connection survey	
1254	MORRIS AVENUE			C	N	3/4"		C			SF						Installation record	Y	1961	nsp during install o	Installation record	N			
1260	MORRIS AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1961	nsp during install o	Field inspection only	Y		Cross-connection survey	
1268	MORRIS AVENUE			C	N	3/4"		C			SF						Installation record	Y	1961	nsp during install o	Installation record	N			
1274	MORRIS AVENUE			C	N	3/4"		C			SF						Installation record	Y	1961	nsp during install o	Installation record	N			
1286	MORRIS AVENUE			C	N	3/4"		C			SF						Installation record	Y	1961	nsp during install o	Installation record	N			
1294	MORRIS AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1961	nsp during install o	Field inspection only	Y		Cross-connection survey	
1306	MORRIS AVENUE			C	N	3/4"		C			SF						Installation record	Y	1961	nsp during install o	Installation record	N			
1314	MORRIS AVENUE			C	N	3/4"		C			SF						Installation record	Y	1961	nsp during install o	Installation record	N			
1320	MORRIS AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1961	nsp during install o	Field inspection only	Y		Cross-connection survey	
1326	MORRIS AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1961	nsp during install o	Field inspection only	Y		Cross-connection survey	
1289	MORRIS AVENUE			C	N	3/4"		C			SF						Installation record	Y	1961	nsp during install o	Installation record	N			
1281	MORRIS AVENUE			C	N	3/4"		C			SF						Installation record	Y	1961	nsp during install o	Installation record	N			
1269	MORRIS AVENUE			C	N	3/4"		C			SF						Installation record	Y	1961	nsp during install o	Installation record	N			
1263	MORRIS AVENUE			C	N	3/4"		C			SF						Installation record	Y	1961	nsp during install o	Installation record	N			
1255	MORRIS AVENUE			C	N	3/4"		C			SF						Installation record	Y	1961	nsp during install o	Installation record	N			
1249	MORRIS AVENUE			C	N	3/4"		C			SF						Installation record	Y	1961	nsp during install o	Installation record	N			
1243	MORRIS AVENUE			C	N	3/4"		C			SF						Installation record	Y	1961	nsp during install o	Installation record	N			
1217	MORRIS AVENUE			C	N	3/4"		C			SF						Installation record	Y	1961	nsp during install o	Installation record	N			
1205	MORRIS AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1961	nsp during install o	Field inspection only	Y		Cross-connection survey	
1191	MORRIS AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1961	nsp during install o	Field inspection only	Y		Cross-connection survey	
1185	MORRIS AVENUE			C	N	3/4"		C			SF						Installation record	Y	1961	nsp during install o	Installation record	N			
1179	MORRIS AVENUE			C	N	3/4"		C			SF						Installation record	Y	1961	nsp during install o	Installation record	N			
1173	MORRIS AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1961	nsp during install o	Field inspection only	Y		Cross-connection survey	
1167	MORRIS AVENUE			C	N	3/4"		C			SF						Installation record	Y	1961	nsp during install o	Installation record	N			
1161	MORRIS AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1961	nsp during install o	Field inspection only	Y		Cross-connection survey	
1500	MORRIS AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1961	nsp during install o	Field inspection only	Y		Cross-connection survey	
1486	MORRIS AVENUE			C	N	3/4"		C			SF						Installation record	Y	1961	nsp during install o	Installation record	N			
1476	MORRIS AVENUE			C	N	3/4"		C			SF						Installation record	Y	1961	nsp during install o	Installation record	N			
1440	MORRIS AVENUE			C	N	3/4"		C			SF						Installation record	Y	1961	nsp during install o	Installation record	N			
1471	MORRIS AVENUE			C	N	3/4"		C			SF						Installation record	Y	1961	nsp during install o	Installation record	N			
1481	MORRIS AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1961	nsp during install o	Field inspection only	Y		Cross-connection survey	
1489	MORRIS AVENUE			C	N	3/4"		C			SF						Installation record	Y	1961	nsp during install o	Installation record	N			
1497	MORRIS AVENUE			C	N	3/4"		C			SF						Installation record	Y	1961	nsp during install o	Installation record	N			
913	MYRTLE LANE			C	N	3/4"		C			SF						Installation record	Y	1962	nsp during install o	Installation record	N			
917	MYRTLE LANE			C	N	3/4"		C			SF						Installation record	Y	1962	nsp during install o	Installation record	N			
925	MYRTLE LANE			C	N	3/4"		C			SF						Installation record	Y	1962	nsp during install o	Installation record	N			
931	MYRTLE LANE			C	N	3/4"		C			SF						Installation record	Y	1962	nsp during install o	Installation record	N			
939	MYRTLE LANE			C	N	3/4"		C			SF						Installation record	Y	1962	nsp during install o	Installation record	N			
945	MYRTLE LANE			C	N	3/4"		C			SF						Installation record	Y	1962	nsp during install o	Installation record	N			
949	MYRTLE LANE			C	N	3/4"		C			SF						Installation record	Y	1962	nsp during install o	Installation record	N			
957	MYRTLE LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1962	nsp during install o	Field inspection only	Y		Cross-connection survey	

LOCATIONAL IDENTIFIER ADDRESS	LOCATIONAL IDENTIFIER STREET NAME	LOCATIONAL IDENTIFIER UNIT OR SUITE #	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
965	MYRTLE LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1962	nsp during install o	Field inspection only	Y		Cross-connection survey	
924	MYRTLE LANE			C	N	3/4"		C			SF						Installation record	Y	1962	nsp during install o	Installation record	N			
918	MYRTLE LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1962	nsp during install o	Field inspection only	Y		Cross-connection survey	
910	MYRTLE LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1990	nsp during install o	Installed after lead ban	N			
2827	NEWCASTLE AVENUE			C	N	1"		C			SF						Installation record	Y	1990	nsp during install o	Installed after lead ban	N			
2874	NEWCASTLE AVENUE			C	N	1"		C	3/4"		SF						Installation record	Y	1990	nsp during install o	Field inspection only	Y		Cross-connection survey	
2880	NEWCASTLE AVENUE			C	N	1"		C			SF						Installation record	Y	1990	nsp during install o	Installed after lead ban	N			
2864	NEWCASTLE AVENUE			C	N	1"		C			SF						Installation record	Y	1990	nsp during install o	Installed after lead ban	N			
2856	NEWCASTLE AVENUE			C	N	1"		C			SF						Installation record	Y	1990	nsp during install o	Installed after lead ban	N			
2871	NEWCASTLE AVENUE			C	N	1"		C	1"		SF						Installation record	Y	1990	nsp during install o	Field inspection only	Y		Cross-connection survey	
2861	NEWCASTLE AVENUE			C	N	1"		C			SF						Installation record	Y	1990	nsp during install o	Installed after lead ban	N			
2851	NEWCASTLE AVENUE			C	N	1"		C	1"		SF						Installation record	Y	1990	nsp during install o	Field inspection only	Y		Cross-connection survey	
2841	NEWCASTLE AVENUE			C	N	1"		C			SF						Installation record	Y	1990	nsp during install o	Installed after lead ban	N			
2835	NEWCASTLE AVENUE			C	N	1"		C			SF						Installation record	Y	1990	nsp during install o	Installed after lead ban	N			
2819	NEWCASTLE AVENUE			C	N	1"		C			SF						Installation record	Y	1990	nsp during install o	Installed after lead ban	N			
2830	NEWCASTLE AVENUE			C	N	1"		C			SF						Installation record	Y	1990	nsp during install o	Installed after lead ban	N			
2764	NEWCASTLE COURT			C	N	1"		C	1"		SF						Installation record	Y	1990	nsp during install o	Field inspection only	Y		Cross-connection survey	
2789	NEWCASTLE COURT			C	N	1"		C			SF						Installation record	Y	1990	nsp during install o	Installed after lead ban	N			
2801	NEWCASTLE COURT			C	N	1"		C	1"		SF						Installation record	Y	1990	nsp during install o	Installed after lead ban	N			
2800	NEWCASTLE COURT			C	N	1"		P	1"		SF						Installation record	Y	1990	nsp during install o	Field inspection only	Y		Cross-connection survey	
2760	NEWCASTLE COURT			C	N	1"		C			SF						Installation record	Y	1990	nsp during install o	Installed after lead ban	N			
2795	NEWCASTLE COURT			C	N	1"		P	1"		SF						Installation record	Y	1990	nsp during install o	Field inspection only	Y		Cross-connection survey	
2781	NEWCASTLE COURT			C	N	1"		C			SF						Installation record	Y	1990	nsp during install o	Installed after lead ban	N			
2775	NEWCASTLE COURT			C	N	1"		C	1"		SF						Installation record	Y	1990	nsp during install o	Field inspection only	Y		Cross-connection survey	
2765	NEWCASTLE COURT			C	N	1"		C			SF						Installation record	Y	1990	nsp during install o	Installed after lead ban	N			
2774	NEWCASTLE COURT			C	N	1"		C			SF						Installation record	Y	1990	nsp during install o	Installed after lead ban	N			
1575	NORTH ROAD			C	N	1"		C			SF						Installation record	Y	1974	nsp during install o	Installation record	N			
1378	NORTH ROAD			C	N	1"		C	3/4"		MF						Installation record	Y	1974	nsp during install o	Field inspection only	Y		Cross-connection survey	
1376	NORTH ROAD			C	N	1"		C	1"		MF						Installation record	Y	1974	nsp during install o	Field inspection only	Y		Cross-connection survey	
1434	NORTH ROAD			C	N	1"		C			SF						Installation record	Y	1974	nsp during install o	Installation record	N			
1386	NORTH ROAD			C	N	1"		C	1"		SF						Installation record	Y	1974	nsp during install o	Field inspection only	Y		Cross-connection survey	
1384	NORTH ROAD			C	N	1"		C			SF						Installation record	Y	1974	nsp during install o	Installation record	N			
1610	NORTH ROAD			C	N	1"		C			SF						Installation record	Y	1974	nsp during install o	Installation record	N			
1620	NORTH ROAD			C	N	1"		C	3/4"		SF						Installation record	Y	1974	nsp during install o	Field inspection only	Y		Cross-connection survey	
1316	NORTH ROAD			C	N	1"		C			SF						Installation record	Y	1974	nsp during install o	Installation record	N			
1567	NORTH ROAD			C	N	1"		C			SF						Installation record	Y	1974	nsp during install o	Installation record	N			
1370	NORTH ROAD			C	N	1"		C			SF						Installation record	Y	1974	nsp during install o	Installation record	N			
1368	NORTH ROAD			C	N	1"		C			SF						Installation record	Y	1974	nsp during install o	Installation record	N			
1392	NORTH ROAD			C	N	1"		C			SF						Installation record	Y	1974	nsp during install o	Installation record	N			
1364	NORTH ROAD			C	N	1"		C			SF						Installation record	Y	1974	nsp during install o	Installation record	N			
1346	NORTH ROAD			C	N	1"		C			MF						Installation record	Y	1974	nsp during install o	Installation record	N			
1344	NORTH ROAD			C	N	1"		C			MF						Installation record	Y	1974	nsp during install o	Installation record	N			
1340	NORTH ROAD			C	N	1"		C	1"		MF						Installation record	Y	1974	nsp during install o	Field inspection only	Y		Cross-connection survey	
1338	NORTH ROAD			C	N	1"		C	1"		MF						Installation record	Y	1974	nsp during install o	Field inspection only	Y		Cross-connection survey	
1330	NORTH ROAD			C	N	1"		C	1"		SF						Installation record	Y	1974	nsp during install o	Field inspection only	Y		Cross-connection survey	
1324	NORTH ROAD			C	N	1"		C	3/4"		SF						Installation record	Y	1974	nsp during install o	Installation record	N			
1320	NORTH ROAD			C	N	1"		C			SF						Installation record	Y	1974	nsp during install o	Installation record	N			
1310	NORTH ROAD			C	N	1"		C			SF						Installation record	Y	1974	nsp during install o	Installation record	N			
1304	NORTH ROAD			C	N	1"		C			SF						Installation record	Y	1974	nsp during install o	Installation record	N			
1298	NORTH ROAD			C	N	1"		C			SF						Installation record	Y	1974	nsp during install o	Installation record	N			
1288	NORTH ROAD			C	N	1"		C			SF						Installation record	Y	1974	nsp during install o	Installation record	N			
1280	NORTH ROAD			C	N	1"		C			SF						Installation record	Y	1974	nsp during install o	Installation record	N			
1270	NORTH ROAD			C	N	1"		C			SF						Installation record	Y	1974	nsp during install o	Installation record	N			
1260	NORTH ROAD			C	N	1"		C			SF						Installation record	Y	1974	nsp during install o	Installation record	N			
1250	NORTH ROAD			C	N	1"		C			SF						Installation record	Y	1974	nsp during install o	Installation record	N			
1754	NORTH ROAD			C	N	1"		C			SF						Installation record	Y	1974	nsp during install o	Installation record	N			
1768	NORTH ROAD			C	N	1"		C	1"		SF						Installation record	Y	1974	nsp during install o	Field inspection only	Y		Cross-connection survey	
1819	NORTH ROAD			C	N	1"		C	3/4"		SF						Installation record	Y	1974	nsp during install o	Installation record	N			
1460	NORTH ROAD			C	N	1"		C			SF						Installation record	Y	1974	nsp during install o	Installation record	N			
1442	NORTH ROAD			C	N	1"		C			SF						Installation record	Y	1974	nsp during install o	Installation record	N			
1418	NORTH ROAD			C	N	1"		C	1"		SF						Installation record	Y	1974	nsp during install o	Field inspection only	Y		Cross-connection survey	
1410	NORTH ROAD			C	N	1"		C			SF						Installation record	Y	1974	nsp during install o	Installation record	N			
1566	NORTH ROAD			C	N	1"		C			MF						Installation record	Y	1974	nsp during install o	Installation record	N			
1568	NORTH ROAD			C	N	1"		C			MF						Installation record	Y	1974	nsp during install o	Installation record	N			
1596	NORTH ROAD			C	N	1"		C			SF						Installation record	Y	1974	nsp during install o	Installation record	N			
1604	NORTH ROAD			C	N	1"		C	1"		SF						Installation record	Y	1974	nsp during install o	Installation record	N			
1532	NORTH ROAD			C	N	1"		C			SF						Installation record	Y	1974	nsp during install o	Installation record	N			
1520	NORTH ROAD			C	N	1"		C	3/4"		SF						Installation record	Y	1974	nsp during install o	Field inspection only	Y		Cross-connection survey	
1510	NORTH ROAD			C	N	1"		C			SF						Installation record	Y	1974	nsp during install o	Installation record	N			
1492	NORTH ROAD			C	N	1"		C			SF						Installation record	Y	1974	nsp during install o	Installation record	N			
1484	NORTH ROAD			C	N	1"		C	1"		SF						Installation record	Y	1974	nsp during install o	Field inspection only	Y		Cross-connection survey	
1468	NORTH ROAD			C	N	1"		C			MF						Installation record	Y	1974	nsp during install o	Installation record	N			
1175	NOVA LANE			C	N	3/4"		C			SF						Installation record	Y	1966	nsp during install o	Installation record	N			
1209	NOVA LANE			C	N	3/4"		C			SF						Installation record	Y	1966	nsp during install o	Installation record	N			
1221	NOVA LANE			C	N	3/4"		C			SF						Installation record	Y	1966	nsp during install o	Installation record	N			
1215	NOVA LANE			C	N	3/4"		C			SF						Installation record	Y	1966	nsp during install o	Installation record	N			
1201	NOVA LANE			C	N	3/4"		C			SF						Installation record	Y	1966	nsp during install o	Installation record	N			
1195	NOVA LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1966	nsp during install o	Field inspection only	Y		Cross-connection survey	
1187	NOVA LANE			C	N	3/4"		C			SF						Installation record	Y	1966	nsp during install o	Installation record	N			
1181	NOVA LANE			C	N	3/4"		C			SF						Installation record	Y	1966	nsp during install o	Installation record	N			
1167	NOVA LANE			C	N	3/4"		C	1"		SF						Installation record	Y	1966	nsp during install o	Field inspection only	Y		Cross-connection survey	
1161	NOVA LANE			C	N	3/4"		C	1"		SF						Installation record	Y	1966	nsp during install o	Field inspection only	Y		Cross-connection survey	
1160	NOVA LANE			C	N	3/4"		C	3/4"		MF						Installation record	Y	1966	nsp during install o	Field inspection only	Y		Cross-connection survey	
1162	NOVA LANE			C	N	3/4"		C	3/4"		MF						Installation record	Y	1966	nsp during install o	Field inspection only	Y		Cross-connection survey	
1188	NOVA LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1966	nsp during install o	Field inspection only	Y		Cross-connection survey	

LOCATIONAL IDENTIFIER ADDRESS	LOCATIONAL IDENTIFIER STREET NAME	LOCATIONAL IDENTIFIER UNIT OR SUITE #	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
1214	NOVA LANE			C	N	3/4"		C			SF						Installation record	Y	1966	nsp during install o	Installation record	N			
1222	NOVA LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1966	nsp during install o	Installation record	N			
1306	OAK CREST DRIVE			C	N	3/4"		C			SF						Installation record	Y	1964	nsp during install o	Installation record	N			
1294	OAK CREST DRIVE			C	N	3/4"		C			SF						Installation record	Y	1964	nsp during install o	Installation record	N			
1288	OAK CREST DRIVE			C	N	3/4"		C			SF						Installation record	Y	1964	nsp during install o	Installation record	N			
1293	OAK CREST DRIVE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1964	nsp during install o	Field inspection only	Y		Cross-connection survey	
1305	OAK CREST DRIVE			C	N	3/4"		C	1"		SF						Installation record	Y	1964	nsp during install o	Field inspection only	Y		Cross-connection survey	
1320	OAK CREST DRIVE			C	N	1"		C			SF						Installation record	N	1966		Installation record	N			
1322	OAK CREST DRIVE			C	N	1"		C	3/4"		SF						Installation record	N	1966		Field inspection only	Y		Cross-connection survey	
1327	OAK CREST DRIVE			C	N	1"		C			SF						Installation record	N	1966		Installation record	N			
1321	OAK CREST DRIVE			C	N	1"		C	1"		SF						Installation record	N	1966		Field inspection only	Y		Cross-connection survey	
1319	OAK CREST DRIVE			C	N	1"		C	3/4"		SF						Installation record	N	1966		Field inspection only	Y		Cross-connection survey	
489	OAKLAWN AVENUE			C	N	3/4"		C	1"		SF						Installation record	Y	1982	nsp during install o	Field inspection only	Y		Cross-connection survey	
446	OAKLAWN AVENUE			C	N	3/4"		C			SF						Installation record	Y	1982	nsp during install o	Installation record	N			
523	OAKLAWN AVENUE			C	N	3/4"		C	1"		SF						Installation record	Y	1982	nsp during install o	Field inspection only	Y		Cross-connection survey	
495	OAKLAWN AVENUE			C	N	3/4"		C			SF						Installation record	Y	1982	nsp during install o	Installation record	N			
513	OAKLAWN AVENUE			C	N	3/4"		C			SF						Installation record	Y	1982	nsp during install o	Installation record	N			
533	OAKLAWN AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1982	nsp during install o	Field inspection only	Y		Cross-connection survey	
517	OAKLAWN AVENUE			C	N	3/4"		C			SF						Installation record	Y	1982	nsp during install o	Installation record	N			
527	OAKLAWN AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1982	nsp during install o	Field inspection only	Y		Cross-connection survey	
530	OAKLAWN AVENUE			C	N	3/4"		C			SF						Installation record	Y	1982	nsp during install o	Installation record	N			
504	OAKLAWN AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1982	nsp during install o	Field inspection only	Y		Cross-connection survey	
474	OAKLAWN AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1982	nsp during install o	Field inspection only	Y		Cross-connection survey	
490	OAKLAWN AVENUE			C	N	3/4"		C			SF						Installation record	Y	1982	nsp during install o	Installation record	N			
537	OAKLAWN AVENUE			C	N	3/4"		C			SF						Installation record	Y	1982	nsp during install o	Installation record	N			
447	OAKLAWN AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1982	nsp during install o	Field inspection only	Y		Cross-connection survey	
451	OAKLAWN AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1982	nsp during install o	Field inspection only	Y		Cross-connection survey	
508	OAKLAWN AVENUE			C	N	3/4"		C			SF						Installation record	Y	1982	nsp during install o	Installation record	N			
481	OAKLAWN AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1982	nsp during install o	Field inspection only	Y		Cross-connection survey	
432	OAKLAWN AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1982	nsp during install o	Field inspection only	Y		Cross-connection survey	
440	OAKLAWN AVENUE			C	N	3/4"		C			SF						Installation record	Y	1982	nsp during install o	Installation record	N			
452	OAKLAWN AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1982	nsp during install o	Field inspection only	Y		Cross-connection survey	
454	OAKLAWN AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1982	nsp during install o	Field inspection only	Y		Cross-connection survey	
460	OAKLAWN AVENUE			C	N	3/4"		C			SF						Installation record	Y	1982	nsp during install o	Installation record	N			
464	OAKLAWN AVENUE			C	N	3/4"		C			SF						Installation record	Y	1982	nsp during install o	Installation record	N			
470	OAKLAWN AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1982	nsp during install o	Field inspection only	Y		Cross-connection survey	
480	OAKLAWN AVENUE			C	N	3/4"		C			SF						Installation record	Y	1982	nsp during install o	Installation record	N			
484	OAKLAWN AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1982	nsp during install o	Field inspection only	Y		Cross-connection survey	
494	OAKLAWN AVENUE			C	N	3/4"		C			SF						Installation record	Y	1982	nsp during install o	Installation record	N			
512	OAKLAWN AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1982	nsp during install o	Field inspection only	Y		Cross-connection survey	
520	OAKLAWN AVENUE			C	N	3/4"		C			SF						Installation record	Y	1982	nsp during install o	Installation record	N			
524	OAKLAWN AVENUE			C	N	3/4"		C			SF						Installation record	Y	1982	nsp during install o	Installation record	N			
532	OAKLAWN AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1982	nsp during install o	Field inspection only	Y		Cross-connection survey	
509	OAKLAWN AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1982	nsp during install o	Field inspection only	Y		Cross-connection survey	
485	OAKLAWN AVENUE			C	N	3/4"		C			SF						Installation record	Y	1982	nsp during install o	Installation record	N			
475	OAKLAWN AVENUE			C	N	3/4"		C			SF						Installation record	Y	1982	nsp during install o	Installation record	N			
471	OAKLAWN AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1982	nsp during install o	Field inspection only	Y		Cross-connection survey	
465	OAKLAWN AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1982	nsp during install o	Field inspection only	Y		Cross-connection survey	
461	OAKLAWN AVENUE			C	N	3/4"		C			SF						Installation record	Y	1982	nsp during install o	Installation record	N			
459	OAKLAWN AVENUE			C	N	3/4"		C			SF						Installation record	Y	1982	nsp during install o	Installation record	N			
439	OAKLAWN AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1982	nsp during install o	Field inspection only	Y		Cross-connection survey	
2234	S ONEIDA STREET			P	N	1"		C	1"		SF						Installed after lead ban	Y	1998	nsp during install o	Field inspection only	Y		Cross-connection survey	
2056	S ONEIDA STREET			P	N	1"		C			MF						Installed after lead ban	Y	1998	nsp during install o	Installation record	N			
2058	S ONEIDA STREET			P	N	1"		C			MF						Installed after lead ban	Y	1998	nsp during install o	Installation record	N			
2152	S ONEIDA STREET			P	N	1"		C			SF						Installed after lead ban	Y	1998	nsp during install o	Installation record	N			
2124	S ONEIDA STREET			P	N	1"		C	3/4"		SF						Installed after lead ban	Y	1998	nsp during install o	Installation record	Y		Cross-connection survey	
2022	S ONEIDA STREET			P	N	1"		C	1"		SF						Installed after lead ban	Y	1998	nsp during install o	Installation record	Y		Cross-connection survey	
2026	S ONEIDA STREET			P	N	1"		C	1"		SF						Installed after lead ban	Y	1998	nsp during install o	Installation record	Y		Cross-connection survey	
2064	S ONEIDA STREET			P	N	1"		C			SF						Installed after lead ban	Y	1998	nsp during install o	Installation record	N			
2070	S ONEIDA STREET			P	N	1"		C			SF						Installed after lead ban	Y	1998	nsp during install o	Installation record	N			
2076	S ONEIDA STREET			P	N	1"		C	3/4"		SF						Installed after lead ban	Y	1998	nsp during install o	Installation record	Y		Cross-connection survey	
2080	S ONEIDA STREET			P	N	1"		C	3/4"		MF						Installed after lead ban	Y	1998	nsp during install o	Installation record	Y		Cross-connection survey	
2082	S ONEIDA STREET			P	N	1"		C	3/4"		MF						Installed after lead ban	Y	1998	nsp during install o	Installation record	Y		Cross-connection survey	
2100	S ONEIDA STREET			P	N	1"		C			MF						Installed after lead ban	Y	1998	nsp during install o	Installation record	N			
2104	S ONEIDA STREET			P	N	1"		C	3/4"		MF						Installed after lead ban	Y	1998	nsp during install o	Field inspection only	Y		Cross-connection survey	
2108	S ONEIDA STREET			P	N	1"		C			MF						Installed after lead ban	Y	1998	nsp during install o	Installation record	N			
2112	S ONEIDA STREET			P	N	1"		C	3/4"		MF						Installed after lead ban	Y	1998	nsp during install o	Installation record	N			
2120	S ONEIDA STREET			P	N	1"		C	3/4"		MF						Installed after lead ban	Y	1998	nsp during install o	Field inspection only	Y		Cross-connection survey	
2122	S ONEIDA STREET			P	N	1"		C			MF						Installed after lead ban	Y	1998	nsp during install o	Installation record	N			
2140	S ONEIDA STREET			P	N	1"		C			SF						Installed after lead ban	Y	1998	nsp during install o	Installation record	N			
2150	S ONEIDA STREET			P	N	1"		C	3/4"		SF						Installed after lead ban	Y	1998	nsp during install o	Field inspection only	Y		Cross-connection survey	
2160	S ONEIDA STREET			P	N	1"		C			SF						Installed after lead ban	Y	1998	nsp during install o	Installation record	N			
2166	S ONEIDA STREET			P	N	1"		C			SF						Installed after lead ban	Y	1998	nsp during install o	Installation record	N			
2170	S ONEIDA STREET			P	N	1"		C			SF						Installed after lead ban	Y	1998	nsp during install o	Installation record	N			
2180	S ONEIDA STREET			P	N	1"		C	3/4"		SF						Installed after lead ban	Y	1998	nsp during install o	Field inspection only	Y		Cross-connection survey	
2204	S ONEIDA STREET			P	N	1"		C			SF						Installed after lead ban	Y	1998	nsp during install o	Installation record	N			
2210	S ONEIDA STREET			P	N	1"		C			SF						Installed after lead ban	Y	1998	nsp during install o	Installation record	N			
2220	S ONEIDA STREET			P	N	1"		C			SF						Installed after lead ban	Y	1998	nsp during install o	Installation record	N			
2228	S ONEIDA STREET			P	N	1"		C			SF						Installed after lead ban	Y	1998	nsp during install o	Installation record	N			
2236	S ONEIDA STREET			P	N	1"		C	1"		MF						Installed after lead ban	Y	1998	nsp during install o	Field inspection only	Y		Cross-connection survey	
2238	S ONEIDA STREET			P	N	1"		C			MF						Installed after lead ban	Y	1998	nsp during install o	Installation record	N			
1440	ORCHID LANE			C	N	3/4"		C			SF						Installation record	Y	1967	nsp during install o	Installation record	N			
1576	ORCHID LANE			C	N	3/4"		C			SF						Installation record	Y	1967	nsp during install o	Installation record	N			
1640	ORCHID LANE			C	N	3/4"		C			SF						Installation record	Y	1967	nsp during install o	Installation record	N			
1556	ORCHID LANE			C	N	3/4"		C			SF						Installation record	Y	1967	nsp during install o	Installation record	N			

LOCATIONAL IDENTIFIER ADDRESS	LOCATIONAL IDENTIFIER STREET NAME	LOCATIONAL IDENTIFIER UNIT OR SUITE #	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
1360	ORCHID LANE			C	N	3/4"		C	1"		SF						Installation record	Y	1967	nsp during install o	Field inspection only	Y		Cross-connection survey	
1658	ORCHID LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1967	nsp during install o	Field inspection only	Y		Cross-connection survey	
1564	ORCHID LANE			C	N	3/4"		C	1"		SF						Installation record	Y	1967	nsp during install o	Field inspection only	Y		Cross-connection survey	
1646	ORCHID LANE			C	N	3/4"		C			SF						Installation record	Y	1967	nsp during install o	Installation record	N			
1563	ORCHID LANE			C	N	3/4"		C			SF						Installation record	Y	1967	nsp during install o	Installation record	N			
1633	ORCHID LANE			C	N	3/4"		C			SF						Installation record	Y	1967	nsp during install o	Installation record	N			
1570	ORCHID LANE			C	N	3/4"		C			SF						Installation record	Y	1967	nsp during install o	Installation record	N			
1582	ORCHID LANE			C	N	3/4"		C			SF						Installation record	Y	1967	nsp during install o	Installation record	N			
1588	ORCHID LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1967	nsp during install o	Field inspection only	Y		Cross-connection survey	
1594	ORCHID LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1967	nsp during install o	Field inspection only	Y		Cross-connection survey	
1600	ORCHID LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1967	nsp during install o	Field inspection only	Y		Cross-connection survey	
1626	ORCHID LANE			C	N	3/4"		C			SF						Installation record	Y	1967	nsp during install o	Installation record	N			
1632	ORCHID LANE			C	N	3/4"		C			SF						Installation record	Y	1967	nsp during install o	Installation record	N			
1652	ORCHID LANE			C	N	3/4"		C	1"		SF						Installation record	Y	1967	nsp during install o	Field inspection only	Y		Cross-connection survey	
1664	ORCHID LANE			C	N	3/4"		C			SF						Installation record	Y	1967	nsp during install o	Installation record	N			
1666	ORCHID LANE			C	N	3/4"		C			SF						Installation record	Y	1967	nsp during install o	Installation record	N			
1661	ORCHID LANE			C	N	3/4"		C			SF						Installation record	Y	1967	nsp during install o	Installation record	N			
1653	ORCHID LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1967	nsp during install o	Field inspection only	Y		Cross-connection survey	
1647	ORCHID LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1967	nsp during install o	Field inspection only	Y		Cross-connection survey	
1641	ORCHID LANE			C	N	3/4"		C			SF						Installation record	Y	1967	nsp during install o	Installation record	N			
1627	ORCHID LANE			C	N	3/4"		C			SF						Installation record	Y	1967	nsp during install o	Installation record	N			
1601	ORCHID LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1967	nsp during install o	Field inspection only	Y		Cross-connection survey	
1595	ORCHID LANE			C	N	3/4"		C			SF						Installation record	Y	1967	nsp during install o	Installation record	N			
1589	ORCHID LANE			C	N	3/4"		C			SF						Installation record	Y	1967	nsp during install o	Installation record	N			
1581	ORCHID LANE			C	N	3/4"		C			SF						Installation record	Y	1967	nsp during install o	Installation record	N			
1575	ORCHID LANE			C	N	3/4"		C			SF						Installation record	Y	1967	nsp during install o	Installation record	N			
1569	ORCHID LANE			C	N	3/4"		C			SF						Installation record	Y	1967	nsp during install o	Installation record	N			
1555	ORCHID LANE			C	N	3/4"		C			SF						Installation record	Y	1967	nsp during install o	Installation record	N			
1344	ORCHID LANE			C	N	3/4"		C			SF						Installation record	Y	1967	nsp during install o	Installation record	N			
1352	ORCHID LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1967	nsp during install o	Field inspection only	Y		Cross-connection survey	
1368	ORCHID LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1967	nsp during install o	Field inspection only	Y		Cross-connection survey	
1400	ORCHID LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1967	nsp during install o	Field inspection only	Y		Cross-connection survey	
1408	ORCHID LANE			C	N	3/4"		C			SF						Installation record	Y	1967	nsp during install o	Installation record	N			
1414	ORCHID LANE			C	N	3/4"		C			SF						Installation record	Y	1967	nsp during install o	Installation record	N			
1422	ORCHID LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1967	nsp during install o	Field inspection only	Y		Cross-connection survey	
1428	ORCHID LANE			C	N	3/4"		C			SF						Installation record	Y	1967	nsp during install o	Installation record	N			
1434	ORCHID LANE			C	N	3/4"		C			SF						Installation record	Y	1967	nsp during install o	Installation record	N			
1446	ORCHID LANE			C	N	3/4"		C			SF						Installation record	Y	1967	nsp during install o	Installation record	N			
1452	ORCHID LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1967	nsp during install o	Installation record	N			
1474	ORCHID LANE			C	N	3/4"		C			SF						Installation record	Y	1967	nsp during install o	Installation record	N			
1480	ORCHID LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1967	nsp during install o	Field inspection only	Y		Cross-connection survey	
1488	ORCHID LANE			C	N	3/4"		C			SF						Installation record	Y	1967	nsp during install o	Installation record	N			
1494	ORCHID LANE			C	N	3/4"		C			SF						Installation record	Y	1967	nsp during install o	Installation record	N			
1502	ORCHID LANE			C	N	3/4"		C			SF						Installation record	Y	1967	nsp during install o	Installation record	N			
1510	ORCHID LANE			C	N	3/4"		C			SF						Installation record	Y	1967	nsp during install o	Installation record	N			
1516	ORCHID LANE			C	N	3/4"		C			SF						Installation record	Y	1967	nsp during install o	Installation record	N			
1524	ORCHID LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1967	nsp during install o	Field inspection only	Y		Cross-connection survey	
1529	ORCHID LANE			C	N	3/4"		C			SF						Installation record	Y	1967	nsp during install o	Installation record	N			
1523	ORCHID LANE			C	N	3/4"		C			SF						Installation record	Y	1967	nsp during install o	Installation record	N			
1517	ORCHID LANE			C	N	3/4"		C			SF						Installation record	Y	1967	nsp during install o	Installation record	N			
1509	ORCHID LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1967	nsp during install o	Field inspection only	Y		Cross-connection survey	
1503	ORCHID LANE			C	N	3/4"		C			SF						Installation record	Y	1967	nsp during install o	Installation record	N			
1495	ORCHID LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1967	nsp during install o	Installation record	N			
1489	ORCHID LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1967	nsp during install o	Field inspection only	Y		Cross-connection survey	
1481	ORCHID LANE			C	N	3/4"		C			SF						Installation record	Y	1967	nsp during install o	Installation record	N			
1475	ORCHID LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1967	nsp during install o	Field inspection only	Y		Cross-connection survey	
1461	ORCHID LANE			C	N	3/4"		C			SF						Installation record	Y	1967	nsp during install o	Installation record	N			
1453	ORCHID LANE			C	N	3/4"		C			SF						Installation record	Y	1967	nsp during install o	Installation record	N			
1445	ORCHID LANE			C	N	3/4"		C			SF						Installation record	Y	1967	nsp during install o	Installation record	N			
1439	ORCHID LANE			C	N	3/4"		C			SF						Installation record	Y	1967	nsp during install o	Installation record	N			
1431	ORCHID LANE			C	N	3/4"		C			SF						Installation record	Y	1967	nsp during install o	Installation record	N			
1423	ORCHID LANE			C	N	3/4"		C			SF						Installation record	Y	1967	nsp during install o	Installation record	N			
1415	ORCHID LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1967	nsp during install o	Field inspection only	Y		Cross-connection survey	
1409	ORCHID LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1967	nsp during install o	Field inspection only	Y		Cross-connection survey	
1401	ORCHID LANE			C	N	3/4"		C			SF						Installation record	Y	1967	nsp during install o	Installation record	N			
1369	ORCHID LANE			C	N	3/4"		C	1"		SF						Installation record	Y	1967	nsp during install o	Field inspection only	Y		Cross-connection survey	
1361	ORCHID LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1967	nsp during install o	Field inspection only	Y		Cross-connection survey	
1353	ORCHID LANE			C	N	3/4"		C			SF						Installation record	Y	1967	nsp during install o	Installation record	N			
1345	ORCHID LANE			C	N	3/4"		C			SF						Installation record	Y	1967	nsp during install o	Installation record	N			
1222	ORLANDO DRIVE			C	N	3/4"		C			SF						Installation record	Y	1973	nsp during install o	Installation record	N			
1140	ORLANDO DRIVE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1973	nsp during install o	Field inspection only	Y		Cross-connection survey	
1089	ORLANDO DRIVE			C	N	3/4"		C	1"		SF						Installation record	Y	1973	nsp during install o	Field inspection only	Y		Cross-connection survey	
1162	ORLANDO DRIVE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1973	nsp during install o	Field inspection only	Y		Cross-connection survey	
1125	ORLANDO DRIVE			C	N	3/4"		C			SF						Installation record	Y	1973	nsp during install o	Installation record	N			
1225	ORLANDO DRIVE			C	N	3/4"		C			SF						Installation record	Y	1973	nsp during install o	Installation record	N			
1311	ORLANDO DRIVE			C	N	3/4"		C			SF						Installation record	Y	1973	nsp during install o	Installation record	N			
1100	ORLANDO DRIVE			C	N	3/4"		C			SF						Installation record	Y	1973	nsp during install o	Installation record	N			
1351	ORLANDO DRIVE			C	N	3/4"		C			SF						Installation record	Y	1973	nsp during install o	Installation record	N			
1097	ORLANDO DRIVE			C	N	3/4"		C			SF						Installation record	Y	1973	nsp during install o	Installation record	N			
1154	ORLANDO DRIVE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1973	nsp during install o	Field inspection only	Y		Cross-connection survey	
1230	ORLANDO DRIVE			C	N	3/4"		C			SF						Installation record	Y	1973	nsp during install o	Installation record	N			
1337	ORLANDO DRIVE			C	N	3/4"		C			SF						Installation record	Y	1973	nsp during install o	Installation record	N			
1301	ORLANDO DRIVE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1973	nsp during install o	Field inspection only	Y		Cross-connection survey	
1293	ORLANDO DRIVE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1973	nsp during install o	Field inspection only	Y		Cross-connection survey	
1163	ORLANDO DRIVE			C	N	3/4"		C			SF						Installation record	Y	1973	nsp during install o	Installation record	N			

LOCATIONAL IDENTIFIER ADDRESS	LOCATIONAL IDENTIFIER STREET NAME	LOCATIONAL IDENTIFIER UNIT OR SUITE #	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
1187	ORLANDO DRIVE			C	N	3/4"		C			SF						Installation record	Y	1973	nsp during install o	Installation record	N			
1080	ORLANDO DRIVE			C	N	3/4"		C			SF						Installation record	Y	1973	nsp during install o	Installation record	N			
1084	ORLANDO DRIVE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1973	nsp during install o	Field inspection only	Y		Cross-connection survey	
1090	ORLANDO DRIVE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1973	nsp during install o	Field inspection only	Y		Cross-connection survey	
1106	ORLANDO DRIVE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1973	nsp during install o	Field inspection only	Y		Cross-connection survey	
1116	ORLANDO DRIVE			C	N	3/4"		C			SF						Installation record	Y	1973	nsp during install o	Installation record	N			
1124	ORLANDO DRIVE			C	N	3/4"		C			SF						Installation record	Y	1973	nsp during install o	Installation record	N			
1132	ORLANDO DRIVE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1973	nsp during install o	Field inspection only	Y		Cross-connection survey	
1170	ORLANDO DRIVE			C	N	3/4"		C			SF						Installation record	Y	1973	nsp during install o	Installation record	N			
1176	ORLANDO DRIVE			C	N	3/4"		C			SF						Installation record	Y	1973	nsp during install o	Installation record	N			
1184	ORLANDO DRIVE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1973	nsp during install o	Field inspection only	Y		Cross-connection survey	
1194	ORLANDO DRIVE			C	N	3/4"		C			SF						Installation record	Y	1973	nsp during install o	Installation record	N			
1200	ORLANDO DRIVE			C	N	3/4"		C			SF						Installation record	Y	1973	nsp during install o	Installation record	N			
1210	ORLANDO DRIVE			C	N	3/4"		C			SF						Installation record	Y	1973	nsp during install o	Installation record	N			
1216	ORLANDO DRIVE			C	N	3/4"		C			SF						Installation record	Y	1973	nsp during install o	Installation record	N			
1231	ORLANDO DRIVE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1973	nsp during install o	Field inspection only	Y		Cross-connection survey	
1217	ORLANDO DRIVE			C	N	3/4"		C	1"		SF						Installation record	Y	1973	nsp during install o	Installation record	N			
1211	ORLANDO DRIVE			C	N	3/4"		C			SF						Installation record	Y	1973	nsp during install o	Installation record	N			
1201	ORLANDO DRIVE			C	N	3/4"		C			SF						Installation record	Y	1973	nsp during install o	Installation record	N			
1195	ORLANDO DRIVE			C	N	3/4"		C			SF						Installation record	Y	1973	nsp during install o	Installation record	N			
1321	ORLANDO DRIVE			C	N	3/4"		C			SF						Installation record	Y	1973	nsp during install o	Installation record	N			
1305	ORLANDO DRIVE			C	N	3/4"		C			SF						Installation record	Y	1973	nsp during install o	Installation record	N			
1300	ORLANDO DRIVE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1973	nsp during install o	Field inspection only	Y		Cross-connection survey	
1306	ORLANDO DRIVE			C	N	3/4"		C			SF						Installation record	Y	1973	nsp during install o	Installation record	N			
1314	ORLANDO DRIVE			C	N	3/4"		C			SF						Installation record	Y	1973	nsp during install o	Installation record	N			
1324	ORLANDO DRIVE			C	N	3/4"		C	1"		SF						Installation record	Y	1973	nsp during install o	Field inspection only	Y		Cross-connection survey	
1340	ORLANDO DRIVE			C	N	3/4"		C			SF						Installation record	Y	1973	nsp during install o	Installation record	N			
1348	ORLANDO DRIVE			C	N	3/4"		P	1"		SF						Installation record	Y	1973	nsp during install o	Field inspection only	Y		Cross-connection survey	
1358	ORLANDO DRIVE			C	N	3/4"		C			SF						Installation record	Y	1973	nsp during install o	Installation record	N			
1366	ORLANDO DRIVE			C	N	3/4"		C	1"		SF						Installation record	Y	1973	nsp during install o	Field inspection only	Y		Cross-connection survey	
1376	ORLANDO DRIVE			C	N	3/4"		C			SF						Installation record	Y	1973	nsp during install o	Installation record	N			
1378	ORLANDO DRIVE			C	N	3/4"		C			SF						Installation record	Y	1973	nsp during install o	Installation record	N			
1390	ORLANDO DRIVE			C	N	3/4"		C			SF						Installation record	Y	1973	nsp during install o	Installation record	N			
1398	ORLANDO DRIVE			C	N	3/4"		C			SF						Installation record	Y	1973	nsp during install o	Installation record	N			
1402	ORLANDO DRIVE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1973	nsp during install o	Field inspection only	Y		Cross-connection survey	
1410	ORLANDO DRIVE			C	N	3/4"		C			SF						Installation record	Y	1973	nsp during install o	Installation record	N			
1416	ORLANDO DRIVE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1973	nsp during install o	Field inspection only	Y		Cross-connection survey	
1422	ORLANDO DRIVE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1973	nsp during install o	Field inspection only	Y		Cross-connection survey	
1431	ORLANDO DRIVE			C	N	3/4"		C			SF						Installation record	Y	1973	nsp during install o	Installation record	N			
1417	ORLANDO DRIVE			C	N	3/4"		C			SF						Installation record	Y	1973	nsp during install o	Installation record	N			
1415	ORLANDO DRIVE			C	N	3/4"		C			SF						Installation record	Y	1973	nsp during install o	Installation record	N			
1403	ORLANDO DRIVE			C	N	3/4"		C	1"		SF						Installation record	Y	1973	nsp during install o	Field inspection only	Y		Cross-connection survey	
1399	ORLANDO DRIVE			C	N	3/4"		C			SF						Installation record	Y	1973	nsp during install o	Installation record	N			
1387	ORLANDO DRIVE			C	N	3/4"		C			SF						Installation record	Y	1973	nsp during install o	Installation record	N			
1385	ORLANDO DRIVE			C	N	3/4"		C			SF						Installation record	Y	1973	nsp during install o	Installation record	N			
1377	ORLANDO DRIVE			C	N	3/4"		C	1"		SF						Installation record	Y	1973	nsp during install o	Field inspection only	Y		Cross-connection survey	
1365	ORLANDO DRIVE			C	N	3/4"		C			SF						Installation record	Y	1973	nsp during install o	Installation record	N			
1359	ORLANDO DRIVE			C	N	3/4"		C			SF						Installation record	Y	1973	nsp during install o	Installation record	N			
1343	ORLANDO DRIVE			C	N	3/4"		C	1"		SF						Installation record	Y	1973	nsp during install o	Field inspection only	Y		Cross-connection survey	
1179	ORLANDO DRIVE			C	N	3/4"		C			SF						Installation record	Y	1973	nsp during install o	Installation record	N			
1171	ORLANDO DRIVE			C	N	3/4"		C			SF						Installation record	Y	1973	nsp during install o	Installation record	N			
1155	ORLANDO DRIVE			C	N	3/4"		C			SF						Installation record	Y	1973	nsp during install o	Installation record	N			
1141	ORLANDO DRIVE			C	N	3/4"		C			SF						Installation record	Y	1973	nsp during install o	Installation record	N			
1133	ORLANDO DRIVE			C	N	3/4"		C			SF						Installation record	Y	1973	nsp during install o	Installation record	N			
1117	ORLANDO DRIVE			C	N	3/4"		C			SF						Installation record	Y	1973	nsp during install o	Installation record	N			
1107	ORLANDO DRIVE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1973	nsp during install o	Field inspection only	Y		Cross-connection survey	
1081	ORLANDO DRIVE			C	N	3/4"		C			SF						Installation record	Y	1973	nsp during install o	Installation record	N			
2236	ORRIE LANE			C	N	3/4"		C	1"		SF						Installation record	Y	1966	nsp during install o	Field inspection only	Y		Cross-connection survey	
2234	ORRIE LANE			C	N	3/4"		C	1"		SF						Installation record	Y	1966	nsp during install o	Field inspection only	Y		Cross-connection survey	
2138	ORRIE LANE			C	N	3/4"		C	1"		MF						Installation record	Y	1966	nsp during install o	Field inspection only	Y		Cross-connection survey	
2142	ORRIE LANE			C	N	3/4"		C	3/4"		MF						Installation record	Y	1966	nsp during install o	Field inspection only	Y		Cross-connection survey	
2196	ORRIE LANE			C	N	3/4"		C			SF						Installation record	Y	1966	nsp during install o	Installation record	N			
2148	ORRIE LANE			C	N	3/4"		C			SF						Installation record	Y	1966	nsp during install o	Installation record	N			
1985	ORRIE LANE			C	N	3/4"		C	1"		SF						Installation record	Y	1966	nsp during install o	Field inspection only	Y		Cross-connection survey	
2075	ORRIE LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1966	nsp during install o	Field inspection only	Y		Cross-connection survey	
2065	ORRIE LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1966	nsp during install o	Field inspection only	Y		Cross-connection survey	
2051	ORRIE LANE			C	N	3/4"		C			SF						Installation record	Y	1966	nsp during install o	Installation record	N			
2091	ORRIE LANE			C	N	3/4"		C			SF						Installation record	Y	1966	nsp during install o	Installation record	N			
2177	ORRIE LANE			C	N	3/4"		C	3/4"		MF						Installation record	Y	1966	nsp during install o	Field inspection only	Y		Cross-connection survey	
2179	ORRIE LANE			C	N	3/4"		C	3/4"		MF						Installation record	Y	1966	nsp during install o	Field inspection only	Y		Cross-connection survey	
1967	ORRIE LANE			C	N	3/4"		C			SF						Installation record	Y	1966	nsp during install o	Installation record	N			
1997	ORRIE LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1966	nsp during install o	Field inspection only	Y		Cross-connection survey	
2013	ORRIE LANE			C	N	3/4"		C			SF						Installation record	Y	1966	nsp during install o	Installation record	N			
2025	ORRIE LANE			C	N	3/4"		C			SF						Installation record	Y	1966	nsp during install o	Installation record	N			
2041	ORRIE LANE			C	N	3/4"		C	1"		SF						Installation record	Y	1966	nsp during install o	Installation record	N			
2156	ORRIE LANE			C	N	3/4"		C			SF						Installation record	Y	1966	nsp during install o	Installation record	N			
2151	ORRIE LANE			C	N	3/4"		C	3/4"		MF						Installation record	Y	1966	nsp during install o	Field inspection only	Y		Cross-connection survey	
2153	ORRIE LANE			C	N	3/4"		C	3/4"		MF						Installation record	Y	1966	nsp during install o	Field inspection only	Y		Cross-connection survey	
2167	ORRIE LANE			C	N	3/4"		C	3/4"		MF						Installation record	Y	1966	nsp during install o	Installation record	N			
2169	ORRIE LANE			C	N	3/4"		C	3/4"		MF						Installation record	Y	1966	nsp during install o	Installation record	N			
2162	ORRIE LANE			C	N	3/4"		C			SF						Installation record	Y	1966	nsp during install o	Installation record	N			
2170	ORRIE LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1966	nsp during install o	Field inspection only	Y		Cross-connection survey	
2176	ORRIE LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1966	nsp during install o	Field inspection only	Y		Cross-connection survey	
2182	ORRIE LANE			C	N	3/4"		C			SF						Installation record	Y	1966	nsp during install o	Installation record	N			
2190	ORRIE LANE			C	N	3/4"		C			SF						Installation record	Y	1966	nsp during install o	Installation record	N			

LOCATIONAL IDENTIFIER ADDRESS	LOCATIONAL IDENTIFIER STREET NAME	LOCATIONAL IDENTIFIER UNIT OR SUITE #	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
2204	ORRIE LANE			C	N	3/4"		C			SF						Installation record	Y	1966	ısp during install o	Installation record	N			
2210	ORRIE LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1966	ısp during install o	Installation record	N			
2218	ORRIE LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1966	ısp during install o	Field inspection only	Y		Cross-connection survey	
2220	ORRIE LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1966	ısp during install o	Field inspection only	Y		Cross-connection survey	
1970	ORRIE LANE			C	N	3/4"		C			SF						Installation record	Y	1966	ısp during install o	Installation record	N			
1984	ORRIE LANE			C	N	3/4"		C			SF						Installation record	Y	1966	ısp during install o	Installation record	N			
1996	ORRIE LANE			C	N	3/4"		C	1"		SF						Installation record	Y	1966	ısp during install o	Field inspection only	Y		Cross-connection survey	
2118	ORRIE LANE			C	N	3/4"		C			SF						Installation record	Y	1966	ısp during install o	Installation record	N			
2115	ORRIE LANE			C	N	3/4"		C			SF						Installation record	Y	1966	ısp during install o	Installation record	N			
2121	ORRIE LANE			C	N	3/4"		C			SF						Installation record	Y	1966	ısp during install o	Installation record	N			
2127	ORRIE LANE			C	N	3/4"		C			SF						Installation record	Y	1966	ısp during install o	Installation record	N			
2124	ORRIE LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1966	ısp during install o	Field inspection only	Y		Cross-connection survey	
2141	ORRIE LANE			C	N	3/4"		C	1"		MF						Installation record	Y	1966	ısp during install o	Field inspection only	Y		Cross-connection survey	
2143	ORRIE LANE			C	N	3/4"		C	3/4"		MF						Installation record	Y	1966	ısp during install o	Field inspection only	Y		Cross-connection survey	
2010	ORRIE LANE			C	N	3/4"		C			SF						Installation record	Y	1966	ısp during install o	Installation record	N			
2022	ORRIE LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1966	ısp during install o	Field inspection only	Y		Cross-connection survey	
2064	ORRIE LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1966	ısp during install o	Field inspection only	Y		Cross-connection survey	
2074	ORRIE LANE			C	N	3/4"		C			SF						Installation record	Y	1966	ısp during install o	Installation record	N			
2090	ORRIE LANE			C	N	3/4"		P	1"		SF						Installation record	Y	1966	ısp during install o	Field inspection only	Y		Cross-connection survey	
2101	ORRIE LANE			C	N	3/4"		C			SF						Installation record	Y	1966	ısp during install o	Installation record	N			
2109	ORRIE LANE			C	N	3/4"		C			SF						Installation record	Y	1966	ısp during install o	Installation record	N			
2100	ORRIE LANE			C	N	3/4"		C	1"		SF						Installation record	Y	1966	ısp during install o	Installation record	N			
2824	OTTO COURT			C	N	1"		C	1"		SF						Installation record	Y	1978	ısp during install o	Field inspection only	Y		Cross-connection survey	
2832	OTTO COURT			C	N	1"		UNK-NOLG			SF						Installation record	Y	1978	ısp during install o	Installation record	N			
2811	OTTO COURT			C	N	1"		UNK-NOLG			SF						Installation record	Y	1978	ısp during install o	Installation record	N			
2831	OTTO COURT			C	N	1"		UNK-NOLG			SF						Installation record	Y	1978	ısp during install o	Installation record	N			
2818	OTTO COURT			C	N	1"		UNK-NOLG			SF						Installation record	Y	1978	ısp during install o	Installation record	N			
2785	OTTO COURT			C	N	1"		UNK-NOLG			SF						Installation record	Y	1978	ısp during install o	Installation record	N			
2741	OTTO COURT			C	N	1"		UNK-NOLG			SF						Installation record	Y	1978	ısp during install o	Installation record	N			
2720	OTTO COURT			C	N	1"		UNK-NOLG			SF						Installation record	Y	1978	ısp during install o	Installation record	N			
2746	OTTO COURT			C	N	1"		UNK-NOLG			SF						Installation record	Y	1978	ısp during install o	Installation record	N			
2759	OTTO COURT			C	N	1"		UNK-NOLG			SF						Installation record	Y	1978	ısp during install o	Installation record	N			
2844	OTTO COURT			C	N	1"		C	3/4"		SF						Installation record	Y	1978	ısp during install o	Field inspection only	Y		Cross-connection survey	
2838	OTTO COURT			C	N	1"		UNK-NOLG			SF						Installation record	Y	1978	ısp during install o	Installation record	N			
2786	OTTO COURT			C	N	1"		UNK-NOLG			SF						Installation record	Y	1978	ısp during install o	Installation record	N			
2782	OTTO COURT			C	N	1"		C	3/4"		SF						Installation record	Y	1978	ısp during install o	Installation record	N			
2776	OTTO COURT			C	N	1"		UNK-NOLG			SF						Installation record	Y	1978	ısp during install o	Installation record	N			
2770	OTTO COURT			C	N	1"		C	3/4"		SF						Installation record	Y	1978	ısp during install o	Field inspection only	Y		Cross-connection survey	
2764	OTTO COURT			C	N	1"		UNK-NOLG			SF						Installation record	Y	1978	ısp during install o	Installation record	N			
2758	OTTO COURT			C	N	1"		UNK-NOLG			SF						Installation record	Y	1978	ısp during install o	Installation record	N			
2740	OTTO COURT			C	N	1"		C	3/4"		SF						Installation record	Y	1978	ısp during install o	Field inspection only	Y		Cross-connection survey	
2734	OTTO COURT			C	N	1"		UNK-NOLG			SF						Installation record	Y	1978	ısp during install o	Installation record	N			
2730	OTTO COURT			C	N	1"		C	1"		SF						Installation record	Y	1978	ısp during install o	Field inspection only	Y		Cross-connection survey	
2724	OTTO COURT			C	N	1"		UNK-NOLG			SF						Installation record	Y	1978	ısp during install o	Installation record	N			
2721	OTTO COURT			C	N	1"		C	3/4"		SF						Installation record	Y	1978	ısp during install o	Field inspection only	Y		Cross-connection survey	
2729	OTTO COURT			C	N	1"		C	1"		SF						Installation record	Y	1978	ısp during install o	Field inspection only	Y		Cross-connection survey	
2753	OTTO COURT			C	N	1"		UNK-NOLG			SF						Installation record	Y	1978	ısp during install o	Installation record	N			
2765	OTTO COURT			C	N	1"		UNK-NOLG			SF						Installation record	Y	1978	ısp during install o	Installation record	N			
2771	OTTO COURT			C	N	1"		UNK-NOLG			SF						Installation record	Y	1978	ısp during install o	Installation record	N			
2775	OTTO COURT			C	N	1"		UNK-NOLG			SF						Installation record	Y	1978	ısp during install o	Installation record	N			
2779	OTTO COURT			C	N	1"		UNK-NOLG			SF						Installation record	Y	1978	ısp during install o	Installation record	N			
2793	OTTO COURT			C	N	1"		UNK-NOLG			SF						Installation record	Y	1978	ısp during install o	Installation record	N			
2817	OTTO COURT			C	N	1"		UNK-NOLG			SF						Installation record	Y	1978	ısp during install o	Installation record	N			
2825	OTTO COURT			C	N	1"		UNK-NOLG			SF						Installation record	Y	1978	ısp during install o	Installation record	N			
3685	PACKERLAND DRIVE			C	N	1"		UNK-NOLG			SF						Installation record	N	1973		Installation record	N			
2675	PACKERLAND DRIVE			C	N	1"		UNK-NOLG			MF						Installation record	N	1973		Installation record	N			
2673	PACKERLAND DRIVE			C	N	1"		UNK-NOLG			MF						Installation record	N	1973		Installation record	N			
2651	PACKERLAND DRIVE			C	N	1"		UNK-NOLG			SF						Installation record	N	1973		Installation record	N			
2713	PACKERLAND DRIVE			C	N	1"		C	1"		SF						Installation record	N	1973		Field inspection only	Y		Cross-connection survey	
2735	PACKERLAND DRIVE			C	N	1"		UNK-NOLG			SF						Installation record	N	1973		Installation record	N			
2943	PACKERLAND DRIVE			C	N	1"		C	3/4"		SF						Installation record	N	1973		Field inspection only	Y		Cross-connection survey	
2703	PACKERLAND DRIVE			C	N	1"		UNK-NOLG			MF						Installation record	N	1973		Installation record	N			
2701	PACKERLAND DRIVE			C	N	1"		C	1"		MF						Installation record	N	1973		Field inspection only	Y		Cross-connection survey	
2697	PACKERLAND DRIVE			C	N	1"		C	1"		MF						Installation record	Y	1973	ısp during install o	Field inspection only	Y		Cross-connection survey	
2695	PACKERLAND DRIVE			C	N	1"		C	1"		MF						Installation record	Y	1973	ısp during install o	Field inspection only	Y		Cross-connection survey	
2689	PACKERLAND DRIVE			C	N	1"		C	1"		MF						Installation record	N	1973		Field inspection only	Y		Cross-connection survey	
2687	PACKERLAND DRIVE			C	N	1"		C	3/4"		MF						Installation record	N	1973		Field inspection only	Y		Cross-connection survey	
2681	PACKERLAND DRIVE			C	N	1"		C	3/4"		MF						Installation record	N	1973		Field inspection only	Y		Cross-connection survey	
2679	PACKERLAND DRIVE			C	N	1"		UNK-NOLG			MF						Installation record	N	1973		Installation record	N			
2667	PACKERLAND DRIVE			C	N	1"		UNK-NOLG			MF						Installation record	N	1973		Installation record	N			
2665	PACKERLAND DRIVE			C	N	1"		UNK-NOLG			MF						Installation record	N	1973		Installation record	N			
2659	PACKERLAND DRIVE			C	N	1"		C	3/4"		MF						Installation record	N	1973		Field inspection only	Y		Cross-connection survey	
2657	PACKERLAND DRIVE			C	N	1"		C			MF						Installation record	N	1973		Installation record	N			
2765	PACKERLAND DRIVE			C	N	1"		UNK-NOLG			MF						Installation record	N	1973		Installation record	N			
2763	PACKERLAND DRIVE			C	N	1"		UNK-NOLG			MF						Installation record	N	1973		Installation record	N			
2757	PACKERLAND DRIVE			C	N	1"		UNK-NOLG			MF						Installation record	N	1973		Installation record	N			
2755	PACKERLAND DRIVE			C	N	1"		C	1"		MF						Installation record	N	1973		Field inspection only	Y		Cross-connection survey	
2749	PACKERLAND DRIVE			C	N	1"		C	3/4"		MF						Installation record	N	1973		Field inspection only	Y		Cross-connection survey	
2747	PACKERLAND DRIVE			C	N	1"		C	1"		MF						Installation record	N	1973		Field inspection only	Y		Cross-connection survey	
2741	PACKERLAND DRIVE	A		C	N	1"		C	1"		MF						Installation record	N	1973		Field inspection only	Y		Cross-connection survey	
2741	PACKERLAND DRIVE	B		C	N	1"		C	1"		MF						Installation record	N	1973		Field inspection only	Y		Cross-connection survey	
2739	PACKERLAND DRIVE	WOM		C	N	1"		P	1"		MF						Installation record	N	1973		Field inspection only	Y		Cross-connection survey	
2739	PACKERLAND DRIVE	A		C	N	1"		P	1"		MF						Installation record	N	1973		Field inspection only	Y		Cross-connection survey	
2739	PACKERLAND DRIVE	B		C	N	1"		P	1"		MF						Installation record	N	1973		Field inspection only	Y		Cross-connection survey	
2949	PACKERLAND DRIVE			C	N	1"		UNK-NOLG			SF						Installation record	N	1973		Field inspection only	Y			

LOCATIONAL IDENTIFIER ADDRESS	LOCATIONAL IDENTIFIER STREET NAME	LOCATIONAL IDENTIFIER UNIT OR SUITE #	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
2965	PACKERLAND DRIVE			C	N	1"		UNK-NOLG			SF						Installation record	N	1973		Field inspection only	Y			
3615	PACKERLAND DRIVE			C	N	1"		UNK-NOLG			SF						Installation record	N	1973		Field inspection only	Y			
2304	PACKERLAND DRIVE			C	N	1"		UNK-NOLG			SF						Installation record	N	1973		Field inspection only	Y			
1042	PAGELS PLACE			P	N	1"		P	1"		SF						Installation record	Y	2011	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1017	PAGELS PLACE			P	N	1"		P	1"		SF						Installation record	Y	2011	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1034	PAGELS PLACE			P	N	1"		P	1"		SF						Installation record	Y	2011	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1041	PAGELS PLACE			P	N	1"		P	1"		SF						Installation record	Y	2011	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1058	PAGELS PLACE			P	N	1"		P	1"		SF						Installation record	Y	2011	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1057	PAGELS PLACE			P	N	1"		P	1"		SF						Installation record	Y	2011	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1050	PAGELS PLACE			P	N	1"		P	1"		SF						Installation record	Y	2011	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1049	PAGELS PLACE			P	N	1"		P	1"		SF						Installation record	Y	2011	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1018	PAGELS PLACE			P	N	1"		P	1"		SF						Installation record	Y	2011	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1033	PAGELS PLACE			P	N	1"		P	1"		SF						Installation record	Y	2011	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
922	PARK RIDGE DRIVE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1962	nsp during install o	Field inspection only	Y			
913	PARK RIDGE DRIVE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1962	nsp during install o	Installation record	N			
925	PARK RIDGE DRIVE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1962	nsp during install o	Field inspection only	Y		Cross-connection survey	
919	PARK RIDGE DRIVE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1962	nsp during install o	Installation record	N			
904	PARK RIDGE DRIVE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1962	nsp during install o	Installation record	N			
910	PARK RIDGE DRIVE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1962	nsp during install o	Installation record	N			
916	PARK RIDGE DRIVE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1962	nsp during install o	Installation record	N			
928	PARK RIDGE DRIVE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1962	nsp during install o	Field inspection only	Y		Cross-connection survey	
936	PARK RIDGE DRIVE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1962	nsp during install o	Installation record	N			
3101	PARKVIEW COURT			C	N	1"		P	1"		MF						Installed after lead ban	Y	1995	nsp during install o	Field inspection only	Y		Cross-connection survey	
3099	PARKVIEW COURT			C	N	1"		UNK-NOLG			MF						Installed after lead ban	Y	1995	nsp during install o	Installed after lead ban	N			
3097	PARKVIEW COURT			C	N	1"		UNK-NOLG			MF						Installed after lead ban	Y	1995	nsp during install o	Installed after lead ban	N			
3123	PARKVIEW COURT			C	N	1"		C	1"		MF						Installed after lead ban	Y	1995	nsp during install o	Field inspection only	Y		Cross-connection survey	
3121	PARKVIEW COURT			C	N	1"		C	2"		MF						Installed after lead ban	Y	1995	nsp during install o	Field inspection only	Y		Cross-connection survey	
3103	PARKVIEW COURT			C	N	1"		P	1"		MF						Installed after lead ban	Y	1995	nsp during install o	Field inspection only	Y		Cross-connection survey	
3090	PARKVIEW COURT			C	N	1"		UNK-NOLG			MF						Installed after lead ban	Y	1995	nsp during install o	Installed after lead ban	N			
3092	PARKVIEW COURT			C	N	1"		UNK-NOLG			MF						Installed after lead ban	Y	1995	nsp during install o	Installed after lead ban	N			
3098	PARKVIEW COURT			C	N	1"		P	3/4"		MF						Installed after lead ban	Y	1995	nsp during install o	Field inspection only	Y		Cross-connection survey	
3096	PARKVIEW COURT			C	N	1"		P	3/4"		MF						Installed after lead ban	Y	1995	nsp during install o	Field inspection only	Y		Cross-connection survey	
3122	PARKVIEW COURT			C	N	1"		UNK-NOLG			MF						Installed after lead ban	Y	1995	nsp during install o	Installed after lead ban	N			
3120	PARKVIEW COURT			C	N	1"		UNK-NOLG			MF						Installed after lead ban	Y	1995	nsp during install o	Installed after lead ban	N			
3119	PARKVIEW COURT			C	N	1"		C	1"		MF						Installed after lead ban	Y	1995	nsp during install o	Field inspection only	Y		Cross-connection survey	
3117	PARKVIEW COURT			C	N	1"		C	3/4"		MF						Installed after lead ban	Y	1995	nsp during install o	Field inspection only	Y		Cross-connection survey	
3083	PARKVIEW COURT			C	N	1"		UNK-NOLG			MF						Installed after lead ban	Y	1995	nsp during install o	Installed after lead ban	N			
3081	PARKVIEW COURT			C	N	1"		UNK-NOLG			MF						Installed after lead ban	Y	1995	nsp during install o	Installed after lead ban	N			
751	PARKVIEW ROAD			C	N	1"		C	3/4"		SF						Installation record	Y	1982	nsp during install o	Field inspection only	Y		Cross-connection survey	
741	PARKVIEW ROAD			C	N	1"		UNK-NOLG			SF						Installation record	Y	1982	nsp during install o	Installation record	N			
715	PARKVIEW ROAD			C	N	1"		P	1 1/2"		MF						Installation record	Y	1982	nsp during install o	Field inspection only	Y		Cross-connection survey	
713	PARKVIEW ROAD			C	N	1"		C	1"		MF						Installation record	Y	1982	nsp during install o	Field inspection only	Y		Cross-connection survey	
709	PARKVIEW ROAD			C	N	1"		UNK-NOLG			MF						Installation record	Y	1982	nsp during install o	Installation record	N			
707	PARKVIEW ROAD			C	N	1"		P	3/4"		MF						Installation record	Y	1982	nsp during install o	Field inspection only	Y		Cross-connection survey	
703	PARKVIEW ROAD			C	N	1"		C	1"		MF						Installation record	Y	1982	nsp during install o	Field inspection only	Y		Cross-connection survey	
701	PARKVIEW ROAD			C	N	1"		C	1"		MF						Installation record	Y	1982	nsp during install o	Installation record	N			
700	PARKVIEW ROAD			C	N	1"		UNK-NOLG			MF						Installation record	Y	1982	nsp during install o	Installation record	N			
702	PARKVIEW ROAD			C	N	1"		UNK-NOLG			MF						Installation record	Y	1982	nsp during install o	Installation record	N			
706	PARKVIEW ROAD			C	N	1"		UNK-NOLG			MF						Installation record	Y	1982	nsp during install o	Installation record	N			
708	PARKVIEW ROAD			C	N	1"		UNK-NOLG			MF						Installation record	Y	1982	nsp during install o	Installation record	N			
712	PARKVIEW ROAD			C	N	1"		UNK-NOLG			MF						Installation record	Y	1982	nsp during install o	Installation record	N			
714	PARKVIEW ROAD			C	N	1"		UNK-NOLG			MF						Installation record	Y	1982	nsp during install o	Installation record	N			
724	PARKVIEW ROAD			C	N	1"		UNK-NOLG			SF						Installation record	Y	1982	nsp during install o	Installation record	N			
1479	PARKWAY DRIVE			C	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1991	nsp during install o	Installed after lead ban	N			
1498	PARKWAY DRIVE			C	N	1"		C	1"		SF						Installed after lead ban	Y	1991	nsp during install o	Field inspection only	Y		Cross-connection survey	
1494	PARKWAY DRIVE			C	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1991	nsp during install o	Installed after lead ban	N			
1490	PARKWAY DRIVE			C	N	1"		C	1"		SF						Installed after lead ban	Y	1991	nsp during install o	Field inspection only	Y		Cross-connection survey	
1486	PARKWAY DRIVE			C	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1991	nsp during install o	Installed after lead ban	N			
1482	PARKWAY DRIVE			C	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1991	nsp during install o	Installed after lead ban	N			
1478	PARKWAY DRIVE			C	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1991	nsp during install o	Installed after lead ban	N			
1474	PARKWAY DRIVE			C	N	1"		P	1"		SF						Installed after lead ban	Y	1991	nsp during install o	Field inspection only	Y		Cross-connection survey	
1470	PARKWAY DRIVE			C	N	1"		C			SF						Installed after lead ban	Y	1991	nsp during install o	Installed after lead ban	N			
1465	PARKWAY DRIVE			C	N	1"		C	3/4"		SF						Installed after lead ban	Y	1991	nsp during install o	Field inspection only	Y		Cross-connection survey	
1467	PARKWAY DRIVE			C	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1991	nsp during install o	Installed after lead ban	N			
1471	PARKWAY DRIVE			C	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1991	nsp during install o	Installed after lead ban	N			
1475	PARKWAY DRIVE			C	N	1"		C	1"		SF						Installed after lead ban	Y	1991	nsp during install o	Field inspection only	Y		Cross-connection survey	
1483	PARKWAY DRIVE			C	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1991	nsp during install o	Installed after lead ban	N			
1110	PASTEL DOVE CIRCLE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1102	PASTEL DOVE CIRCLE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1109	PASTEL DOVE CIRCLE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1101	PASTEL DOVE CIRCLE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1118	PASTEL DOVE CIRCLE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1117	PASTEL DOVE CIRCLE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
2202	PATTY LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1966	nsp during install o	Installation record	N			
2199	PATTY LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1966	nsp during install o	Field inspection only	Y		Cross-connection survey	
2167	PATTY LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1966	nsp during install o	Field inspection only	Y		Cross-connection survey	
2153	PATTY LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1966	nsp during install o	Installation record	N			
2205	PATTY LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1966	nsp during install o	Installation record	N			
2221	PATTY LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1966	nsp during install o	Installation record	N			
2213	PATTY LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1966	nsp during install o	Installation record	N			
2193	PATTY LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1966	nsp during install o	Installation record	N			
2187	PATTY LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1966	nsp during install o	Installation record	N			
2181	PATTY LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1966	nsp during install o	Installation record	N			
2173	PATTY LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1966	nsp during install o	Installation record	N			
2161	PATTY LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1966	nsp during install o	Field inspection only	Y		Cross-connection survey	

LOCATIONAL IDENTIFIER ADDRESS	LOCATIONAL IDENTIFIER STREET NAME	LOCATIONAL IDENTIFIER UNIT OR SUITE #	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
2147	PATTY LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1966	nsp during install o	Installation record	N			
2148	PATTY LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1966	nsp during install o	Installation record	N			
2154	PATTY LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1966	nsp during install o	Installation record	N			
2160	PATTY LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1966	nsp during install o	Installation record	N			
2168	PATTY LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1966	nsp during install o	Field inspection only	Y		Cross-connection survey	
2174	PATTY LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1966	nsp during install o	Installation record	N			
2182	PATTY LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1966	nsp during install o	Installation record	N			
2188	PATTY LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1966	nsp during install o	Installation record	N			
2196	PATTY LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1966	nsp during install o	Field inspection only	Y		Cross-connection survey	
2210	PATTY LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1966	nsp during install o	Installation record	N			
2218	PATTY LANE			C	N	3/4"		C	1"		SF						Installation record	Y	1966	nsp during install o	Field inspection only	Y		Cross-connection survey	
2138	PATTY LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1966	nsp during install o	Field inspection only	Y		Cross-connection survey	
2140	PATTY LANE			C	N	3/4"		C	1"		SF						Installation record	Y	1966	nsp during install o	Field inspection only	Y		Cross-connection survey	
2141	PATTY LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1966	nsp during install o	Installation record	N			
1590	W PAULSON ROAD			C	N	3/4"		C	1"		SF						Installation record	Y	1973	nsp during install o	Field inspection only	Y		Cross-connection survey	
1502	W PAULSON ROAD			C	N	3/4"		C	3/4"		SF						Installation record	Y	1973	nsp during install o	Field inspection only	Y		Cross-connection survey	
1680	W PAULSON ROAD			C	N	3/4"		C	3/4"		SF						Installation record	Y	1973	nsp during install o	Field inspection only	Y		Cross-connection survey	
1677	W PAULSON ROAD			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1973	nsp during install o	Installation record	N			
1589	W PAULSON ROAD			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1973	nsp during install o	Installation record	N			
1560	W PAULSON ROAD			C	N	3/4"		C	1"		SF						Installation record	Y	1973	nsp during install o	Field inspection only	Y		Cross-connection survey	
1510	W PAULSON ROAD			C	N	3/4"		C	3/4"		SF						Installation record	Y	1973	nsp during install o	Field inspection only	Y		Cross-connection survey	
1628	W PAULSON ROAD			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1973	nsp during install o	Installation record	N			
1634	W PAULSON ROAD			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1973	nsp during install o	Installation record	N			
1640	W PAULSON ROAD			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1973	nsp during install o	Installation record	N			
1646	W PAULSON ROAD			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1973	nsp during install o	Installation record	N			
1654	W PAULSON ROAD			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1973	nsp during install o	Installation record	N			
1660	W PAULSON ROAD			C	N	1"		UNK-NOLG			MF						Installation record	Y	1973	nsp during install o	Installation record	N			
1662	W PAULSON ROAD			C	N	1"		UNK-NOLG			MF						Installation record	Y	1973	nsp during install o	Installation record	N			
1666	W PAULSON ROAD			C	N	1"		C	1"		MF						Installation record	Y	1973	nsp during install o	Field inspection only	Y		Cross-connection survey	
1668	W PAULSON ROAD			C	N	1"		C	3/4"		MF						Installation record	Y	1973	nsp during install o	Field inspection only	Y		Cross-connection survey	
1674	W PAULSON ROAD			C	N	1"		UNK-NOLG			MF						Installation record	Y	1973	nsp during install o	Installation record	N			
1676	W PAULSON ROAD			C	N	1"		UNK-NOLG			MF						Installation record	Y	1973	nsp during install o	Installation record	N			
1673	W PAULSON ROAD			C	N	1"		C	3/4"		MF						Installation record	Y	1973	nsp during install o	Field inspection only	Y		Cross-connection survey	
1671	W PAULSON ROAD			C	N	1"		C	1"		MF						Installation record	Y	1973	nsp during install o	Field inspection only	Y		Cross-connection survey	
1667	W PAULSON ROAD			C	N	1"		UNK-NOLG			MF						Installation record	Y	1973	nsp during install o	Installation record	N			
1665	W PAULSON ROAD			C	N	1"		UNK-NOLG			MF						Installation record	Y	1973	nsp during install o	Installation record	N			
1659	W PAULSON ROAD			C	N	1"		C	3/4"		MF						Installation record	Y	1973	nsp during install o	Field inspection only	Y		Cross-connection survey	
1657	W PAULSON ROAD			C	N	1"		C	3/4"		MF						Installation record	Y	1973	nsp during install o	Field inspection only	Y		Cross-connection survey	
1649	W PAULSON ROAD			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1973	nsp during install o	Installation record	N			
1643	W PAULSON ROAD			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1973	nsp during install o	Installation record	N			
1635	W PAULSON ROAD			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1973	nsp during install o	Installation record	N			
1629	W PAULSON ROAD			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1973	nsp during install o	Installation record	N			
1541	W PAULSON ROAD			C	N	3/4"		C	3/4"		SF						Installation record	Y	1973	nsp during install o	Field inspection only	Y		Cross-connection survey	
1533	W PAULSON ROAD			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1973	nsp during install o	Installation record	N			
1527	W PAULSON ROAD			C	N	3/4"		C	1"		SF						Installation record	Y	1973	nsp during install o	Installation record	N			
1519	W PAULSON ROAD			C	N	3/4"		C	1"		SF						Installation record	Y	1973	nsp during install o	Field inspection only	Y		Cross-connection survey	
1513	W PAULSON ROAD			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1973	nsp during install o	Installation record	N			
1503	W PAULSON ROAD			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1973	nsp during install o	Installation record	N			
1501	W PAULSON ROAD			C	N	3/4"		C	3/4"		SF						Installation record	Y	1973	nsp during install o	Field inspection only	Y		Cross-connection survey	
1518	W PAULSON ROAD			C	N	3/4"		C	3/4"		SF						Installation record	Y	1973	nsp during install o	Field inspection only	Y		Cross-connection survey	
1526	W PAULSON ROAD			C	N	3/4"		C	1"		SF						Installation record	Y	1973	nsp during install o	Installation record	N			
1532	W PAULSON ROAD			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1973	nsp during install o	Installation record	N			
1540	W PAULSON ROAD			C	N	3/4"		C	3/4"		SF						Installation record	Y	1973	nsp during install o	Field inspection only	Y		Cross-connection survey	
1552	W PAULSON ROAD			C	N	3/4"		UNK-NOLG			MF						Installation record	Y	1973	nsp during install o	Installation record	N			
1554	W PAULSON ROAD			C	N	3/4"		UNK-NOLG			MF						Installation record	Y	1973	nsp during install o	Installation record	N			
1568	W PAULSON ROAD			C	N	3/4"		C	3/4"		SF						Installation record	Y	1973	nsp during install o	Field inspection only	Y		Cross-connection survey	
1574	W PAULSON ROAD			C	N	3/4"		C	1"		SF						Installation record	Y	1973	nsp during install o	Field inspection only	Y		Cross-connection survey	
1580	W PAULSON ROAD			C	N	3/4"		C	3/4"		SF						Installation record	Y	1973	nsp during install o	Field inspection only	Y		Cross-connection survey	
1604	W PAULSON ROAD			C	N	3/4"		C	3/4"		SF						Installation record	Y	1973	nsp during install o	Field inspection only	Y		Cross-connection survey	
1603	W PAULSON ROAD			C	N	3/4"		C	3/4"		SF						Installation record	Y	1973	nsp during install o	Field inspection only	Y		Cross-connection survey	
1595	W PAULSON ROAD			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1973	nsp during install o	Installation record	N			
1583	W PAULSON ROAD			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1973	nsp during install o	Installation record	N			
1577	W PAULSON ROAD			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1973	nsp during install o	Installation record	N			
1571	W PAULSON ROAD			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1973	nsp during install o	Installation record	N			
1565	W PAULSON ROAD			C	N	3/4"		C	3/4"		SF						Installation record	Y	1973	nsp during install o	Installation record	N			
978	PEONIES DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
962	PEONIES DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
958	PEONIES DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
947	PEONIES DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
984	PEONIES DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1009	PEONIES DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
951	PEONIES DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
952	PEONIES DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
939	PEONIES DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
944	PEONIES DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
974	PEONIES DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
955	PEONIES DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
943	PEONIES DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
983	PEONIES DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
968	PEONIES DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
977	PEONIES DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
973	PEONIES DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1092	PEONIES DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1051	PEONIES DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
996	PEONIES DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	

LOCATIONAL IDENTIFIER ADDRESS	LOCATIONAL IDENTIFIER STREET NAME	LOCATIONAL IDENTIFIER UNIT OR SUITE #	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
1036	PEONIES DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
988	PEONIES DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1035	PEONIES DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1060	PEONIES DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1028	PEONIES DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1020	PEONIES DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1004	PEONIES DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1059	PEONIES DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1012	PEONIES DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1067	PEONIES DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1084	PEONIES DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1068	PEONIES DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1017	PEONIES DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1025	PEONIES DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1083	PEONIES DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1075	PEONIES DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1091	PEONIES DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1095	PEONIES DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1076	PEONIES DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1107	PEONIES DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
995	PEONIES DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
2461	PESHTIGO STREET			C	N	3/4"		C	3/4"		SF						Installation record	Y	1968	nsp during install o	Field inspection only	Y		Cross-connection survey	
2445	PESHTIGO STREET			C	N	3/4"		C	3/4"		SF						Installation record	Y	1968	nsp during install o	Field inspection only	Y		Cross-connection survey	
2452	PESHTIGO STREET			C	N	3/4"		C	3/4"		SF						Installation record	Y	1968	nsp during install o	Field inspection only	Y		Cross-connection survey	
2436	PESHTIGO STREET			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	nsp during install o	Installation record	N			
2444	PESHTIGO STREET			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	nsp during install o	Installation record	N			
2458	PESHTIGO STREET			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	nsp during install o	Installation record	N			
2466	PESHTIGO STREET			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	nsp during install o	Installation record	N			
2467	PESHTIGO STREET			C	N	3/4"		C	1"		SF						Installation record	Y	1968	nsp during install o	Installation record	N			
2453	PESHTIGO STREET			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	nsp during install o	Installation record	N			
2437	PESHTIGO STREET			C	N	3/4"		C	3/4"		SF						Installation record	Y	1968	nsp during install o	Field inspection only	Y		Cross-connection survey	
966	PILGRIM WAY			C	N	1"		UNK-NOLG			MF						Installation record	Y	1981	nsp during install o	Installation record	N			
968	PILGRIM WAY			C	N	1"		UNK-NOLG			MF						Installation record	Y	1981	nsp during install o	Installation record	N			
948	PILGRIM WAY			C	N	1"		UNK-NOLG			MF						Installation record	Y	1981	nsp during install o	Installation record	N			
950	PILGRIM WAY			C	N	1"		UNK-NOLG			MF						Installation record	Y	1981	nsp during install o	Installation record	N			
958	PILGRIM WAY			C	N	1"		C	1"		MF						Installation record	Y	1981	nsp during install o	Field inspection only	Y		Cross-connection survey	
960	PILGRIM WAY			C	N	1"		C	1"		MF						Installation record	Y	1981	nsp during install o	Field inspection only	Y		Cross-connection survey	
974	PILGRIM WAY			C	N	1"		C	1"		MF						Installation record	Y	1981	nsp during install o	Field inspection only	Y		Cross-connection survey	
976	PILGRIM WAY			C	N	1"		C	1"		MF						Installation record	Y	1981	nsp during install o	Field inspection only	Y		Cross-connection survey	
2737	PIONEER DRIVE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	nsp during install o	Installation record	N			
2866	PIONEER DRIVE			C	N	3/4"		P	1"		SF						Installation record	Y	1968	nsp during install o	Field inspection only	Y		Cross-connection survey	
2842	PIONEER DRIVE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	nsp during install o	Installation record	N			
2697	PIONEER DRIVE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	nsp during install o	Installation record	N			
2734	PIONEER DRIVE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	nsp during install o	Installation record	N			
2829	PIONEER DRIVE			C	N	3/4"		C	1"		SF						Installation record	Y	1968	nsp during install o	Field inspection only	Y		Cross-connection survey	
2622	PIONEER DRIVE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	nsp during install o	Installation record	N			
2747	PIONEER DRIVE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	nsp during install o	Installation record	N			
2634	PIONEER DRIVE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	nsp during install o	Installation record	N			
2784	PIONEER DRIVE			C	N	3/4"		P	1"		SF						Installation record	Y	1968	nsp during install o	Field inspection only	Y		Cross-connection survey	
2790	PIONEER DRIVE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	nsp during install o	Installation record	N			
2826	PIONEER DRIVE			C	N	3/4"		C	1"		SF						Installation record	Y	1968	nsp during install o	Field inspection only	N		Cross-connection survey	
2834	PIONEER DRIVE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	nsp during install o	Installation record	N			
2850	PIONEER DRIVE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	nsp during install o	Installation record	N			
2860	PIONEER DRIVE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	nsp during install o	Installation record	N			
2548	PIONEER DRIVE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	nsp during install o	Installation record	N			
2572	PIONEER DRIVE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1968	nsp during install o	Field inspection only	Y		Cross-connection survey	
2582	PIONEER DRIVE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1968	nsp during install o	Field inspection only	Y		Cross-connection survey	
2633	PIONEER DRIVE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	nsp during install o	Installation record	N			
2704	PIONEER DRIVE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	nsp during install o	Installation record	N			
2755	PIONEER DRIVE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	nsp during install o	Installation record	N			
2750	PIONEER DRIVE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	nsp during install o	Installation record	N			
2600	PIONEER DRIVE			C	N	3/4"		C	1"		SF						Installation record	Y	1968	nsp during install o	Field inspection only	Y		Cross-connection survey	
2610	PIONEER DRIVE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	nsp during install o	Installation record	N			
2623	PIONEER DRIVE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	nsp during install o	Installation record	N			
2657	PIONEER DRIVE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1968	nsp during install o	Field inspection only	Y		Cross-connection survey	
2654	PIONEER DRIVE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	nsp during install o	Installation record	N			
2674	PIONEER DRIVE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1968	nsp during install o	Field inspection only	Y		Cross-connection survey	
2673	PIONEER DRIVE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	nsp during install o	Installation record	N			
2689	PIONEER DRIVE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	nsp during install o	Installation record	N			
2681	PIONEER DRIVE			C	N	3/4"		C	1"		SF						Installation record	Y	1968	nsp during install o	Field inspection only	Y		Cross-connection survey	
2686	PIONEER DRIVE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	nsp during install o	Installation record	N			
2779	PIONEER DRIVE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	nsp during install o	Installation record	N			
2847	PIONEER DRIVE			C	N	3/4"		C	1"		SF						Installation record	Y	1968	nsp during install o	Field inspection only	Y		Cross-connection survey	
2301	South Point Rd			P	N	1"		P	1"		SF						Installed after lead ban	Y	2016	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1580	POLO RUN TERRACE			C	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1993	nsp during install o	Installed after lead ban	N			
1571	POLO RUN TERRACE			C	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1993	nsp during install o	Installed after lead ban	N			
1551	POLO RUN TERRACE			C	N	1"		C	3/4"		SF						Installed after lead ban	Y	1993	nsp during install o	Field inspection only	Y		Cross-connection survey	
1534	POLO RUN TERRACE			C	N	1"		C	3/4"		SF						Installed after lead ban	Y	1993	nsp during install o	Field inspection only	Y		Cross-connection survey	
1540	POLO RUN TERRACE			C	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1993	nsp during install o	Installed after lead ban	N			
1515	POLO RUN TERRACE			C	N	1"		C	1"		SF						Installed after lead ban	Y	1993	nsp during install o	Field inspection only	Y		Cross-connection survey	
1590	POLO RUN TERRACE			C	N	1"		P	3/4"		SF						Installed after lead ban	Y	1993	nsp during install o	Field inspection only	Y		Cross-connection survey	
1570	POLO RUN TERRACE			C	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1993	nsp during install o	Installed after lead ban	N			
1581	POLO RUN TERRACE			C	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1993	nsp during install o	Installed after lead ban	N			
1591	POLO RUN TERRACE			C	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1993	nsp during install o	Installed after lead ban	N			
1520	POLO RUN TERRACE			C	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1993	nsp during install o	Installed after lead ban	N			

LOCATIONAL IDENTIFIER ADDRESS	LOCATIONAL IDENTIFIER STREET NAME	LOCATIONAL IDENTIFIER UNIT OR SUITE #	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
1561	POLO RUN TERRACE			C	N	1"		P	1"		SF						Installed after lead ban	Y	1993	ısp during install o	Field inspection only	Y		Cross-connection survey	
1560	POLO RUN TERRACE			C	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1993	ısp during install o	Installed after lead ban	N			
1511	POLO RUN TERRACE			C	N	1"		P	1"		SF						Installed after lead ban	Y	1993	ısp during install o	Field inspection only	Y		Cross-connection survey	
1521	POLO RUN TERRACE			C	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1993	ısp during install o	Installed after lead ban	N			
1541	POLO RUN TERRACE			C	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1993	ısp during install o	Installed after lead ban	N			
1526	POLO RUN TERRACE			C	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1993	ısp during install o	Installed after lead ban	N			
1531	POLO RUN TERRACE			C	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1993	ısp during install o	Installed after lead ban	N			
1498	PONDEROSA AVENUE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	ısp during install o	Installation record	N			
1263	PONDEROSA AVENUE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	ısp during install o	Installation record	N			
1524	PONDEROSA AVENUE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	ısp during install o	Installation record	N			
1274	PONDEROSA AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1968	ısp during install o	Field inspection only	Y		Cross-connection survey	
1275	PONDEROSA AVENUE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	ısp during install o	Installation record	N			
1365	PONDEROSA AVENUE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	ısp during install o	Installation record	N			
1282	PONDEROSA AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1968	ısp during install o	Field inspection only	Y		Cross-connection survey	
1397	PONDEROSA AVENUE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	ısp during install o	Installation record	N			
1565	PONDEROSA AVENUE			C	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1991	ısp during install o	Installed after lead ban	N			
1294	PONDEROSA AVENUE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	ısp during install o	Installation record	N			
1570	PONDEROSA AVENUE			C	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1991	ısp during install o	Installed after lead ban	N			
1371	PONDEROSA AVENUE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	ısp during install o	Installation record	N			
1490	PONDEROSA AVENUE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	ısp during install o	Installation record	N			
1564	PONDEROSA AVENUE			C	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1991	ısp during install o	Installed after lead ban	N			
1325	PONDEROSA AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1968	ısp during install o	Installation record	N			
1289	PONDEROSA AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1968	ısp during install o	Field inspection only	Y		Cross-connection survey	
1596	PONDEROSA AVENUE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	ısp during install o	Installation record	N			
1251	PONDEROSA AVENUE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	ısp during install o	Installation record	N			
1525	PONDEROSA AVENUE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	ısp during install o	Installation record	N			
1511	PONDEROSA AVENUE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	ısp during install o	Installation record	N			
1550	PONDEROSA AVENUE			C	N	1"		P	1"		SF						Installed after lead ban	Y	1991	ısp during install o	Field inspection only	Y		Cross-connection survey	
1555	PONDEROSA AVENUE			C	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1991	ısp during install o	Installed after lead ban	N			
1561	PONDEROSA AVENUE			C	N	1"		P	1"		SF						Installed after lead ban	Y	1991	ısp during install o	Field inspection only	Y		Cross-connection survey	
1571	PONDEROSA AVENUE			C	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1991	ısp during install o	Installed after lead ban	N			
1585	PONDEROSA AVENUE			C	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1991	ısp during install o	Installed after lead ban	N			
1591	PONDEROSA AVENUE			C	N	1"		P	1"		SF						Installed after lead ban	Y	1991	ısp during install o	Field inspection only	Y		Cross-connection survey	
1599	PONDEROSA AVENUE			C	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1991	ısp during install o	Installed after lead ban	N			
1609	PONDEROSA AVENUE			C	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1991	ısp during install o	Installed after lead ban	N			
1621	PONDEROSA AVENUE			C	N	1"		C	3/4"		SF						Installed after lead ban	Y	1991	ısp during install o	Field inspection only	Y		Cross-connection survey	
1623	PONDEROSA AVENUE			C	N	1"		C	1"		SF						Installed after lead ban	Y	1991	ısp during install o	Field inspection only	Y		Cross-connection survey	
1625	PONDEROSA AVENUE			C	N	1"		C	1"		SF						Installed after lead ban	Y	1991	ısp during install o	Field inspection only	Y		Cross-connection survey	
1629	PONDEROSA AVENUE			C	N	1"		P	1"		SF						Installed after lead ban	Y	1991	ısp during install o	Field inspection only	Y		Cross-connection survey	
1631	PONDEROSA AVENUE			C	N	1"		P	1"		SF						Installed after lead ban	Y	1991	ısp during install o	Field inspection only	Y		Cross-connection survey	
1633	PONDEROSA AVENUE			C	N	1"		C	3/4"		SF						Installed after lead ban	Y	1991	ısp during install o	Field inspection only	Y		Cross-connection survey	
1635	PONDEROSA AVENUE			C	N	1"		C	1"		SF						Installed after lead ban	Y	1991	ısp during install o	Field inspection only	Y		Cross-connection survey	
1640	PONDEROSA AVENUE			C	N	1"		C	1"		SF						Installed after lead ban	Y	1991	ısp during install o	Field inspection only	Y		Cross-connection survey	
1642	PONDEROSA AVENUE			C	N	1"		C	1"		SF						Installed after lead ban	Y	1991	ısp during install o	Field inspection only	Y		Cross-connection survey	
1630	PONDEROSA AVENUE			C	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1991	ısp during install o	Installed after lead ban	N			
1632	PONDEROSA AVENUE			C	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1991	ısp during install o	Installed after lead ban	N			
1624	PONDEROSA AVENUE			C	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1991	ısp during install o	Installed after lead ban	N			
1622	PONDEROSA AVENUE			C	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1991	ısp during install o	Installed after lead ban	N			
1620	PONDEROSA AVENUE			C	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1991	ısp during install o	Installed after lead ban	N			
1590	PONDEROSA AVENUE			C	N	1"		C	3/4"		SF						Installed after lead ban	Y	1991	ısp during install o	Field inspection only	Y		Cross-connection survey	
1582	PONDEROSA AVENUE			C	N	1"		P	3/4"		SF						Installed after lead ban	Y	1991	ısp during install o	Field inspection only	Y		Cross-connection survey	
1576	PONDEROSA AVENUE			C	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1991	ısp during install o	Installed after lead ban	N			
1556	PONDEROSA AVENUE			C	N	1"		P	1"		SF						Installed after lead ban	Y	1991	ısp during install o	Field inspection only	Y		Cross-connection survey	
1396	PONDEROSA AVENUE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	ısp during install o	Installation record	N			
1404	PONDEROSA AVENUE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	ısp during install o	Installation record	N			
1410	PONDEROSA AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1968	ısp during install o	Field inspection only	Y		Cross-connection survey	
1416	PONDEROSA AVENUE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	ısp during install o	Installation record	N			
1424	PONDEROSA AVENUE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	ısp during install o	Installation record	N			
1430	PONDEROSA AVENUE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	ısp during install o	Installation record	N			
1438	PONDEROSA AVENUE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	ısp during install o	Installation record	N			
1444	PONDEROSA AVENUE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	ısp during install o	Installation record	N			
1450	PONDEROSA AVENUE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	ısp during install o	Installation record	N			
1474	PONDEROSA AVENUE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	ısp during install o	Installation record	N			
1484	PONDEROSA AVENUE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	ısp during install o	Installation record	N			
1504	PONDEROSA AVENUE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	ısp during install o	Installation record	N			
1510	PONDEROSA AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1968	ısp during install o	Field inspection only	Y		Cross-connection survey	
1518	PONDEROSA AVENUE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	ısp during install o	Installation record	N			
1529	PONDEROSA AVENUE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	ısp during install o	Installation record	N			
1519	PONDEROSA AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1968	ısp during install o	Field inspection only	Y		Cross-connection survey	
1503	PONDEROSA AVENUE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	ısp during install o	Installation record	N			
1495	PONDEROSA AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1968	ısp during install o	Field inspection only	Y		Cross-connection survey	
1489	PONDEROSA AVENUE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	ısp during install o	Installation record	N			
1483	PONDEROSA AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1968	ısp during install o	Field inspection only	Y		Cross-connection survey	
1475	PONDEROSA AVENUE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	ısp during install o	Installation record	N			
1451	PONDEROSA AVENUE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	ısp during install o	Installation record	N			
1447	PONDEROSA AVENUE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	ısp during install o	Installation record	N			
1439	PONDEROSA AVENUE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	ısp during install o	Installation record	N			
1431	PONDEROSA AVENUE			C	N	3/4"		C	1"		SF						Installation record	Y	1968	ısp during install o	Field inspection only	Y		Cross-connection survey	
1425	PONDEROSA AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1968	ısp during install o	Field inspection only	Y		Cross-connection survey	
1417	PONDEROSA AVENUE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	ısp during install o	Installation record	N			
1411	PONDEROSA AVENUE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	ısp during install o	Installation record	N			
1403	PONDEROSA AVENUE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	ısp during install o	Installation record	N			
1357	PONDEROSA AVENUE			C	N	3/4"		C	1"		SF						Installation record	Y	1968	ısp during install o	Field inspection only	Y		Cross-connection survey	
1351	PONDEROSA AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1968	ısp during install o	Field inspection only	Y		Cross-connection survey	
1345	PONDEROSA AVENUE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	ısp during install o	Installation record	N			

LOCATIONAL IDENTIFIER ADDRESS	LOCATIONAL IDENTIFIER STREET NAME	LOCATIONAL IDENTIFIER UNIT OR SUITE #	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
1335	PONDEROSA AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1968	nsp during install o	Field inspection only	Y		Cross-connection survey	
1331	PONDEROSA AVENUE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	nsp during install o	Installation record	N			
1315	PONDEROSA AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1968	nsp during install o	Field inspection only	Y		Cross-connection survey	
1309	PONDEROSA AVENUE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	nsp during install o	Installation record	N			
1250	PONDEROSA AVENUE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	nsp during install o	Installation record	N			
1256	PONDEROSA AVENUE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	nsp during install o	Installation record	N			
1262	PONDEROSA AVENUE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	nsp during install o	Installation record	N			
1268	PONDEROSA AVENUE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	nsp during install o	Installation record	N			
1288	PONDEROSA AVENUE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	nsp during install o	Installation record	N			
1295	PONDEROSA AVENUE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	nsp during install o	Installation record	N			
1283	PONDEROSA AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1968	nsp during install o	Field inspection only	Y		Cross-connection survey	
1269	PONDEROSA AVENUE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	nsp during install o	Installation record	N			
1257	PONDEROSA AVENUE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	nsp during install o	Installation record	N			
1577	PONDEROSA AVENUE			C	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1991	nsp during install o	Installed after lead ban	Y			
3670	PONDS EDGE COURT			P	N	1"		C	1"		SF						Installed after lead ban	Y	2014	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3669	PONDS EDGE COURT			P	N	1"		C	1"		SF						Installed after lead ban	Y	2014	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3687	PONDS EDGE COURT			P	N	1"		C	1"		SF						Installed after lead ban	Y	2014	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3660	PONDS EDGE COURT			P	N	1"		C	1"		SF						Installed after lead ban	Y	2014	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3663	PONDS EDGE COURT			P	N	1"		C	1"		SF						Installed after lead ban	Y	2014	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3666	PONDS EDGE COURT			P	N	1"		C	1"		SF						Installed after lead ban	Y	2014	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3680	PONDS EDGE COURT			P	N	1"		C	1"		SF						Installed after lead ban	Y	2014	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3699	PONDS EDGE COURT			P	N	1"		C	1"		SF						Installed after lead ban	Y	2014	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3691	PONDS EDGE COURT			P	N	1"		C	1"		SF						Installed after lead ban	Y	2014	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3695	PONDS EDGE COURT			P	N	1"		C	1"		SF						Installed after lead ban	Y	2014	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3677	PONDS EDGE COURT			P	N	1"		C	1"		SF						Installed after lead ban	Y	2014	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3683	PONDS EDGE WAY			P	N	1"		C	1"		SF						Installed after lead ban	Y	2014	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1590	PORT STREET			C	N	1"		C	1"		SF						Installation record	Y	1975	nsp during install o	Field inspection only	Y		Cross-connection survey	
1601	PORT STREET			C	N	1"		UNK-NOLG			SF						Installation record	Y	1975	nsp during install o	Installation record	N			
1582	PORT STREET			C	N	1"		UNK-NOLG			SF						Installation record	Y	1975	nsp during install o	Installation record	N			
1596	PORT STREET			C	N	1"		UNK-NOLG			SF						Installation record	Y	1975	nsp during install o	Installation record	N			
1602	PORT STREET			C	N	1"		C	1"		SF						Installation record	Y	1975	nsp during install o	Field inspection only	Y		Cross-connection survey	
1608	PORT STREET			C	N	1"		C	1"		SF						Installation record	Y	1975	nsp during install o	Field inspection only	Y		Cross-connection survey	
1609	PORT STREET			C	N	1"		C	1"		SF						Installation record	Y	1975	nsp during install o	Installation record	N			
1126	PRINCESS DOVE CIRCLE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1114	PRINCESS DOVE CIRCLE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1116	PRINCESS DOVE CIRCLE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1128	PRINCESS DOVE CIRCLE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1113	PRINCESS DOVE CIRCLE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1115	PRINCESS DOVE CIRCLE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1125	PRINCESS DOVE CIRCLE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1127	PRINCESS DOVE CIRCLE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
948	RASMUSSEN PLACE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1964	nsp during install o	Installation record	N			
962	RASMUSSEN PLACE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1964	nsp during install o	Field inspection only	Y		Cross-connection survey	
2194	RASMUSSEN PLACE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1964	nsp during install o	Installation record	N			
963	RASMUSSEN PLACE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1964	nsp during install o	Field inspection only	Y		Cross-connection survey	
921	RASMUSSEN PLACE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1964	nsp during install o	Field inspection only	Y		Cross-connection survey	
920	RASMUSSEN PLACE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1964	nsp during install o	Field inspection only	Y		Cross-connection survey	
2216	RASMUSSEN PLACE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1964	nsp during install o	Field inspection only	Y		Cross-connection survey	
934	RASMUSSEN PLACE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1964	nsp during install o	Installation record	N			
941	RASMUSSEN PLACE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1964	nsp during install o	Installation record	N			
913	RASMUSSEN PLACE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1964	nsp during install o	Installation record	N			
940	RASMUSSEN PLACE			C	N	3/4"		C	1"		SF						Installation record	Y	1964	nsp during install o	Field inspection only	Y		Cross-connection survey	
949	RASMUSSEN PLACE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1964	nsp during install o	Field inspection only	Y		Cross-connection survey	
2210	RASMUSSEN PLACE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1964	nsp during install o	Installation record	N			
2205	RASMUSSEN PLACE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1964	nsp during install o	Installation record	N			
977	RASMUSSEN PLACE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1964	nsp during install o	Installation record	N			
2200	RASMUSSEN PLACE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1964	nsp during install o	Field inspection only	Y		Cross-connection survey	
927	RASMUSSEN PLACE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1964	nsp during install o	Installation record	N			
954	RASMUSSEN PLACE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1964	nsp during install o	Field inspection only	Y		Cross-connection survey	
935	RASMUSSEN PLACE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1964	nsp during install o	Field inspection only	Y		Cross-connection survey	
914	RASMUSSEN PLACE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1964	nsp during install o	Field inspection only	Y		Cross-connection survey	
928	RASMUSSEN PLACE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1964	nsp during install o	Installation record	N			
971	RASMUSSEN PLACE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1964	nsp during install o	Installation record	N			
955	RASMUSSEN PLACE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1964	nsp during install o	Installation record	N			
981	RASMUSSEN PLACE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1964	nsp during install o	Field inspection only	Y		Cross-connection survey	
2197	RASMUSSEN PLACE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1964	nsp during install o	Installation record	N			
2366	S RIDGE ROAD			C	N	3/4"		C	1"		SF						Installation record	Y	1964	nsp during install o	Field inspection only	Y		Cross-connection survey	
2062	S RIDGE ROAD			C	N	3/4"		C	3/4"		SF						Installation record	Y	1964	nsp during install o	Field inspection only	Y		Cross-connection survey	
3502	S RIDGE ROAD			P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
2054	S RIDGE ROAD			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1964	nsp during install o	Installation record	N			
3508	S RIDGE ROAD			P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3612	S RIDGE ROAD			P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
2860	S RIDGE ROAD			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1964	nsp during install o	Installation record	N			
3676	S RIDGE ROAD			P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
2235	S RIDGE ROAD			C	N	3/4"		C	3/4"		SF						Installation record	Y	1964	nsp during install o	Field inspection only	Y		Cross-connection survey	
2018	S RIDGE ROAD			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1964	nsp during install o	Installation record	N			
3677	S RIDGE ROAD			P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
2247	S RIDGE ROAD			C	N	3/4"		C	1"		MF						Installation record	Y	1964	nsp during install o	Field inspection only	Y		Cross-connection survey	
2245	S RIDGE ROAD			C	N	3/4"		C	1"		MF						Installation record	Y	1964	nsp during install o	Field inspection only	Y		Cross-connection survey	
3661	S RIDGE ROAD			P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
2882	S RIDGE ROAD			C	N	1"		C	3/4"		SF						Installation record	Y	1964	nsp during install o	Field inspection only	Y		Cross-connection survey	
2080	S RIDGE ROAD			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1964	nsp during install o	Installation record	N			
2273	S RIDGE ROAD			C	N	3/4"		UNK-NOLG			MF						Installation record	Y	1964	nsp during install o	Installation record	N			
2271	S RIDGE ROAD			C	N	3/4"		UNK-NOLG			MF						Installation record	Y	1964	nsp during install o	Installation record	N			
3564	S RIDGE ROAD			P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	

LOCATIONAL IDENTIFIER ADDRESS	LOCATIONAL IDENTIFIER STREET NAME	LOCATIONAL IDENTIFIER UNIT OR SUITE #	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
2097	S RIDGE ROAD			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1964	nsp during install o	Installation record	N			
2151	S RIDGE ROAD			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1964	nsp during install o	Installation record	N			
2169	S RIDGE ROAD			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1964	nsp during install o	Installation record	N			
3653	S RIDGE ROAD			P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
2265	S RIDGE ROAD			C	N	1"		UNK-NOLG			MF						Installation record	Y	1964	nsp during install o	Installation record	N			
2263	S RIDGE ROAD			C	N	1"		UNK-NOLG			MF						Installation record	Y	1964	nsp during install o	Installation record	N			
2257	S RIDGE ROAD			C	N	1"		C	3/4"		MF						Installation record	Y	1964	nsp during install o	Field inspection only	Y		Cross-connection survey	
2255	S RIDGE ROAD			C	N	1"		C	1"		MF						Installation record	Y	1964	nsp during install o	Field inspection only	Y		Cross-connection survey	
3621	S RIDGE ROAD			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3645	S RIDGE ROAD			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3669	S RIDGE ROAD			P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
2147	S RIDGE ROAD			C	N	3/4"		C	3/4"		SF						Installation record	Y	1964	nsp during install o	Field inspection only	Y		Cross-connection survey	
3629	S RIDGE ROAD			P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3637	S RIDGE ROAD			P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
2153	S RIDGE ROAD			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1964	nsp during install o	Installation record	N			
2117	S RIDGE ROAD			C	N	3/4"		C	3/4"		SF						Installation record	Y	1964	nsp during install o	Installation record	N			
3509	S RIDGE ROAD			P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
2958	S RIDGE ROAD			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1964	nsp during install o	Installation record	N			
2069	S RIDGE ROAD			C	N	3/4"		C	3/4"		SF						Installation record	Y	1964	nsp during install o	Installation record	N			
2050	S RIDGE ROAD			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1964	nsp during install o	Installation record	N			
2070	S RIDGE ROAD			C	N	3/4"		C	3/4"		SF						Installation record	Y	1964	nsp during install o	Installation record	N			
2736	S RIDGE ROAD			C	N	1"		UNK-NOLG			SF						Installation record	Y	1967	nsp during install o	Installation record	N			
2750	S RIDGE ROAD			C	N	1"		UNK-NOLG			SF						Installation record	Y	1967	nsp during install o	Installation record	N			
2766	S RIDGE ROAD			C	N	1"		UNK-NOLG			SF						Installation record	Y	1967	nsp during install o	Installation record	N			
2780	S RIDGE ROAD			C	N	1"		UNK-NOLG			SF						Installation record	Y	1967	nsp during install o	Installation record	N			
2790	S RIDGE ROAD			C	N	1"		UNK-NOLG			SF						Installation record	Y	1967	nsp during install o	Installation record	N			
2798	S RIDGE ROAD			C	N	1"		C	1"		SF						Installation record	Y	1967	nsp during install o	Field inspection only	Y		Cross-connection survey	
2806	S RIDGE ROAD			C	N	1"		UNK-NOLG			SF						Installation record	Y	1967	nsp during install o	Installation record	N			
2812	S RIDGE ROAD			C	N	1"		C	1"		SF						Installation record	Y	1967	nsp during install o	Field inspection only	Y		Cross-connection survey	
2828	S RIDGE ROAD			C	N	1"		UNK-NOLG			SF						Installation record	Y	1967	nsp during install o	Installation record	N			
2836	S RIDGE ROAD			C	N	1"		UNK-NOLG			SF						Installation record	Y	1967	nsp during install o	Installation record	N			
2842	S RIDGE ROAD			C	N	1"		UNK-NOLG			SF						Installation record	Y	1967	nsp during install o	Installation record	N			
2848	S RIDGE ROAD			C	N	1"		C	3/4"		SF						Installation record	Y	1967	nsp during install o	Field inspection only	Y		Cross-connection survey	
2854	S RIDGE ROAD			C	N	1"		UNK-NOLG			SF						Installation record	Y	1967	nsp during install o	Installation record	N			
2340	S RIDGE ROAD			C	N	3/4"		C	3/4"		MF						Installation record	Y	1964	nsp during install o	Field inspection only	Y		Cross-connection survey	
2342	S RIDGE ROAD			C	N	3/4"		C	3/4"		MF						Installation record	Y	1964	nsp during install o	Field inspection only	Y		Cross-connection survey	
2346	S RIDGE ROAD			C	N	3/4"		C	1"		MF						Installation record	Y	1964	nsp during install o	Field inspection only	Y		Cross-connection survey	
2348	S RIDGE ROAD			C	N	3/4"		C	1"		MF						Installation record	Y	1964	nsp during install o	Field inspection only	Y		Cross-connection survey	
2354	S RIDGE ROAD			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1964	nsp during install o	Installation record	N			
2374	S RIDGE ROAD			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1964	nsp during install o	Installation record	N			
2400	S RIDGE ROAD			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1964	nsp during install o	Installation record	N			
2404	S RIDGE ROAD			C	N	3/4"		C	3/4"		SF						Installation record	Y	1964	nsp during install o	Field inspection only	Y		Cross-connection survey	
2410	S RIDGE ROAD			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1964	nsp during install o	Installation record	N			
2416	S RIDGE ROAD			C	N	1"		C	3/4"		SF						Installation record	Y	1964	nsp during install o	Field inspection only	Y		Cross-connection survey	
2906	S RIDGE ROAD			C	N	1"		C	3/4"		SF						Installation record	Y	1967	nsp during install o	Installation record	N			
2924	S RIDGE ROAD			C	N	1"		UNK-NOLG			SF						Installation record	Y	1967	nsp during install o	Installation record	N			
2946	S RIDGE ROAD			C	N	1"		UNK-NOLG			SF						Installation record	Y	1967	nsp during install o	Installation record	N			
2950	S RIDGE ROAD			C	N	1"		UNK-NOLG			SF						Installation record	Y	1967	nsp during install o	Installation record	N			
2966	S RIDGE ROAD			C	N	1"		UNK-NOLG			SF						Installation record	Y	1967	nsp during install o	Installation record	N			
2982	S RIDGE ROAD			C	N	1"		UNK-NOLG			SF						Installation record	Y	1967	nsp during install o	Installation record	N			
3012	S RIDGE ROAD			C	N	1"		UNK-NOLG			SF						Installation record	Y	1967	nsp during install o	Installation record	N			
2283	S RIDGE ROAD			C	N	3/4"		C	3/4"		SF						Installation record	Y	1964	nsp during install o	Field inspection only	Y		Cross-connection survey	
2281	S RIDGE ROAD			C	N	3/4"		C	3/4"		SF						Installation record	Y	1964	nsp during install o	Field inspection only	Y		Cross-connection survey	
2231	S RIDGE ROAD			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1964	nsp during install o	Installation record	N			
2223	S RIDGE ROAD			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1964	nsp during install o	Installation record	N			
2211	S RIDGE ROAD			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1964	nsp during install o	Installation record	N			
2175	S RIDGE ROAD			C	N	3/4"		C	3/4"		SF						Installation record	Y	1964	nsp during install o	Field inspection only	Y		Cross-connection survey	
2159	S RIDGE ROAD			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1964	nsp during install o	Installation record	N			
2131	S RIDGE ROAD			C	N	3/4"		C	3/4"		SF						Installation record	Y	1964	nsp during install o	Field inspection only	Y		Cross-connection survey	
2127	S RIDGE ROAD			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1964	nsp during install o	Installation record	N			
2107	S RIDGE ROAD			C	N	3/4"		C	3/4"		SF						Installation record	Y	1964	nsp during install o	Field inspection only	Y		Cross-connection survey	
2095	S RIDGE ROAD			C	N	3/4"		C	3/4"		MF						Installation record	Y	1964	nsp during install o	Field inspection only	Y		Cross-connection survey	
2093	S RIDGE ROAD			C	N	3/4"		C	3/4"		MF						Installation record	Y	1964	nsp during install o	Field inspection only	Y		Cross-connection survey	
2077	S RIDGE ROAD			C	N	3/4"		C	3/4"		SF						Installation record	Y	1964	nsp during install o	Field inspection only	Y		Cross-connection survey	
2063	S RIDGE ROAD			C	N	3/4"		C	3/4"		SF						Installation record	Y	1964	nsp during install o	Field inspection only	Y		Cross-connection survey	
2076	S RIDGE ROAD			C	N	3/4"		C			SF						Installation record	Y	1964	nsp during install o	Installation record	N			
2150	S RIDGE ROAD			C	N	3/4"		C	3/4"		SF						Installation record	Y	1964	nsp during install o	Installation record	N			
3501	S RIDGE ROAD			P	N	1"		P	1"		MF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3503	S RIDGE ROAD			P	N	1"		P	1"		MF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3500	S RIDGE ROAD			P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3565	S RIDGE ROAD			P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3540	S RIDGE ROAD			P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3548	S RIDGE ROAD			P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3556	S RIDGE ROAD			P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3620	S RIDGE ROAD			P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3572	S RIDGE ROAD			P	N	1"		C	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3588	S RIDGE ROAD			P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3604	S RIDGE ROAD			P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3580	S RIDGE ROAD			P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3596	S RIDGE ROAD			P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3652	S RIDGE ROAD			P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3660	S RIDGE ROAD			P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3628	S RIDGE ROAD			P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3636	S RIDGE ROAD			P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
2420	S RIDGE ROAD			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1964	nsp during install o	Installation record	N			

LOCATIONAL IDENTIFIER ADDRESS	LOCATIONAL IDENTIFIER STREET NAME	LOCATIONAL IDENTIFIER UNIT OR SUITE #	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
2426	S RIDGE ROAD			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1964	nsp during install o	Installation record	N			
2430	S RIDGE ROAD			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1964	nsp during install o	Installation record	N			
2436	S RIDGE ROAD			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1964	nsp during install o	Installation record	N			
2440	S RIDGE ROAD			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1964	nsp during install o	Installation record	N			
2446	S RIDGE ROAD			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1964	nsp during install o	Installation record	N			
2450	S RIDGE ROAD			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1964	nsp during install o	Installation record	N			
2456	S RIDGE ROAD			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1964	nsp during install o	Installation record	N			
2460	S RIDGE ROAD			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1964	nsp during install o	Installation record	N			
3557	S RIDGE ROAD			P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
2160	RIDGECREST TRAIL			C	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1988	nsp during install o	Installed after lead ban	N			
2146	RIDGECREST TRAIL			C	N	1"		C	3/4"		SF						Installed after lead ban	Y	1988	nsp during install o	Field inspection only	Y		Cross-connection survey	
2152	RIDGECREST TRAIL			C	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1988	nsp during install o	Installed after lead ban	N			
2157	RIDGECREST TRAIL			C	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1988	nsp during install o	Installed after lead ban	N			
2149	RIDGECREST TRAIL			C	N	1"		C	3/4"		SF						Installed after lead ban	Y	1988	nsp during install o	Field inspection only	Y		Cross-connection survey	
1386	RIDGECREST TRAIL			C	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1988	nsp during install o	Installed after lead ban	N			
1377	RIDGECREST TRAIL			C	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1988	nsp during install o	Installed after lead ban	N			
1411	RIDGECREST TRAIL			C	N	1"		C	1"		MF						Installed after lead ban	Y	1988	nsp during install o	Field inspection only	Y		Cross-connection survey	
1409	RIDGECREST TRAIL			C	N	1"		C	1"		MF						Installed after lead ban	Y	1988	nsp during install o	Field inspection only	Y		Cross-connection survey	
1397	RIDGECREST TRAIL			C	N	1"		UNK-NOLG			MF						Installed after lead ban	Y	1988	nsp during install o	Installed after lead ban	N			
1395	RIDGECREST TRAIL			C	N	1"		UNK-NOLG			MF						Installed after lead ban	Y	1988	nsp during install o	Installed after lead ban	N			
1388	RIDGECREST TRAIL			C	N	1"		UNK-NOLG			MF						Installed after lead ban	Y	1988	nsp during install o	Installed after lead ban	N			
1390	RIDGECREST TRAIL			C	N	1"		UNK-NOLG			MF						Installed after lead ban	Y	1988	nsp during install o	Installed after lead ban	N			
1372	RIDGECREST TRAIL			C	N	1 1/2"		C	1 1/2"		MF						Installed after lead ban	Y	1988	nsp during install o	Field inspection only	Y		Cross-connection survey	
1374	RIDGECREST TRAIL			C	N			C			MF						Installed after lead ban	Y	1988	nsp during install o	Field inspection only	Y		Cross-connection survey	
1376	RIDGECREST TRAIL			C	N			C			MF						Installed after lead ban	Y	1988	nsp during install o	Field inspection only	Y		Cross-connection survey	
1378	RIDGECREST TRAIL			C	N			C			MF						Installed after lead ban	Y	1988	nsp during install o	Field inspection only	Y		Cross-connection survey	
1392	RIDGECREST TRAIL			C	N	1"		UNK-NOLG			MF						Installed after lead ban	Y	1988	nsp during install o	Installed after lead ban	N			
1394	RIDGECREST TRAIL			C	N	1"		UNK-NOLG			MF						Installed after lead ban	Y	1988	nsp during install o	Installed after lead ban	N			
1396	RIDGECREST TRAIL			C	N	1"		C	3/4"		MF						Installed after lead ban	Y	1988	nsp during install o	Installed after lead ban	N			
1398	RIDGECREST TRAIL			C	N	1"		C	3/4"		MF						Installed after lead ban	Y	1988	nsp during install o	Field inspection only	Y		Cross-connection survey	
1400	RIDGECREST TRAIL			C	N	1"		UNK-NOLG			MF						Installed after lead ban	Y	1988	nsp during install o	Field inspection only	Y		Cross-connection survey	
1402	RIDGECREST TRAIL			C	N	2"		C	2"		MF						Installed after lead ban	Y	1988	nsp during install o	Installed after lead ban	N			
1404	RIDGECREST TRAIL			C	N			C	3/4"		MF						Installed after lead ban	Y	1988	nsp during install o	Field inspection only	Y		Cross-connection survey	
1406	RIDGECREST TRAIL			C	N			C			MF						Installed after lead ban	Y	1988	nsp during install o	Field inspection only	Y		Cross-connection survey	
1408	RIDGECREST TRAIL			C	N			C			MF						Installed after lead ban	Y	1988	nsp during install o	Installed after lead ban	N			
1410	RIDGECREST TRAIL			C	N			C			MF						Installed after lead ban	Y	1988	nsp during install o	Installed after lead ban	N			
1412	RIDGECREST TRAIL			C	N			C	3/4"		MF						Installed after lead ban	Y	1988	nsp during install o	Installed after lead ban	N			
1414	RIDGECREST TRAIL			C	N			C			MF						Installed after lead ban	Y	1988	nsp during install o	Installed after lead ban	N			
1420	RIDGECREST TRAIL			C	N	1"		C	3/4"		SF						Installed after lead ban	Y	1988	nsp during install o	Installed after lead ban	N			
3416	RIVERSTONE COURT			P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3412	RIVERSTONE COURT			P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3425	RIVERSTONE COURT			P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3420	RIVERSTONE COURT			P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3408	RIVERSTONE COURT			P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3421	RIVERSTONE COURT			P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3424	RIVERSTONE COURT			P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3404	RIVERSTONE COURT			P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3405	RIVERSTONE COURT			P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3401	RIVERSTONE COURT			P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3433	RIVERSTONE COURT			P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3400	RIVERSTONE COURT			P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3428	RIVERSTONE COURT			P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3429	RIVERSTONE COURT			P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3440	RIVERSTONE COURT			P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3437	RIVERSTONE COURT			P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3432	RIVERSTONE COURT			P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3436	RIVERSTONE COURT			P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3441	RIVERSTONE COURT			P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
2445	ROSEDALE STREET			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	nsp during install o	Installation record	N			
2459	ROSEDALE STREET			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	nsp during install o	Installation record	N			
2466	ROSEDALE STREET			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	nsp during install o	Installation record	N			
2467	ROSEDALE STREET			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	nsp during install o	Installation record	N			
2453	ROSEDALE STREET			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	nsp during install o	Installation record	N			
2437	ROSEDALE STREET			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	nsp during install o	Installation record	N			
2436	ROSEDALE STREET			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	nsp during install o	Installation record	N			
2444	ROSEDALE STREET			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	nsp during install o	Installation record	N			
2452	ROSEDALE STREET			C	N	3/4"		C	3/4"		SF						Installation record	Y	1968	nsp during install o	Field inspection only	Y		Cross-connection survey	
2458	ROSEDALE STREET			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	nsp during install o	Installation record	N			
1592	RUSTIC WAY			P	N	1"		P	1"		SF						Installed after lead ban	Y	1993	nsp during install o	Field inspection only	Y		Cross-connection survey	
1567	RUSTIC WAY			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1993	nsp during install o	Installed after lead ban	N			
1585	RUSTIC WAY			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1993	nsp during install o	Installed after lead ban	N			
1605	RUSTIC WAY			P	N	1"		P	1"		SF						Installed after lead ban	Y	1993	nsp during install o	Field inspection only	Y		Cross-connection survey	
1601	RUSTIC WAY			P	N	1"		C	3/4"		SF						Installed after lead ban	Y	1993	nsp during install o	Field inspection only	Y		Cross-connection survey	
1525	RUSTIC WAY			P	N	1"		P	1"		SF						Installed after lead ban	Y	1993	nsp during install o	Field inspection only	Y		Cross-connection survey	
1575	RUSTIC WAY			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1993	nsp during install o	Installed after lead ban	N			
1593	RUSTIC WAY			P	N	1"		C	3/4"		SF						Installed after lead ban	Y	1993	nsp during install o	Field inspection only	Y		Cross-connection survey	
1540	RUSTIC WAY			P	N	1"		P	1"		SF						Installed after lead ban	Y	1993	nsp during install o	Field inspection only	Y		Cross-connection survey	
1560	RUSTIC WAY			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1993	nsp during install o	Installed after lead ban	N			
1566	RUSTIC WAY			P	N	1"		P	1"		SF						Installed after lead ban	Y	1993	nsp during install o	Installed after lead ban	N			
1574	RUSTIC WAY			P	N	1"		P	1"		SF						Installed after lead ban	Y	1993	nsp during install o	Field inspection only	Y		Cross-connection survey	
1580	RUSTIC WAY			P	N	1"		C	3/4"		SF						Installed after lead ban	Y	1993	nsp during install o	Field inspection only	Y		Cross-connection survey	
1586	RUSTIC WAY			P	N	1"		P	1"		SF						Installed after lead ban	Y	1993	nsp during install o	Field inspection only	Y		Cross-connection survey	
1600	RUSTIC WAY			P	N	1"		C	1"		SF						Installed after lead ban	Y	1993	nsp during install o	Field inspection only	Y		Cross-connection survey	
1606	RUSTIC WAY			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1993	nsp during install o	Installed after lead ban	N			
1535	RUSTIC WAY			P	N	1"		P	1"		SF						Installed after lead ban	Y	1993	nsp during install o	Field inspection only	Y		Cross-connection survey	

LOCATIONAL IDENTIFIER ADDRESS	LOCATIONAL IDENTIFIER STREET NAME	LOCATIONAL IDENTIFIER UNIT OR SUITE #	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
2252	SAN LUIS PLACE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1961	nsp during install o	Field inspection only	Y		Cross-connection survey	
2278	SAN LUIS PLACE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1961	nsp during install o	Installation record	N			
3630	SAND ACRES DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2014	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3758	SAND ACRES DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2014	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3746	SAND ACRES DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2014	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3633	SAND ACRES DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2014	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3623	SAND ACRES DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2014	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3615	SAND ACRES DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2014	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3766	SAND ACRES DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2014	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3795	SAND ACRES DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2014	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3774	SAND ACRES DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2014	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3550	SAND ACRES DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2014	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3534	SAND ACRES DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2014	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3510	SAND ACRES DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2014	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3500	SAND ACRES DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2014	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3490	SAND ACRES DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2014	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3431	SAND ACRES DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2014	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3461	SAND ACRES DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2014	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3590	SAND ACRES DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2014	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3571	SAND ACRES DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2014	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3601	SAND ACRES DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2014	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3618	SAND ACRES DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2014	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3620	SAND ACRES DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2014	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3600	SAND ACRES DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2014	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3780	SAND ACRES DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2014	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3790	SAND ACRES DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2014	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3800	SAND ACRES DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2014	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3816	SAND ACRES DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2014	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3591	SAND ACRES DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2014	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3522	SAND ACRES DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2014	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1134	SANDRA LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1964	nsp during install o	Installation record	N			
1101	SANDRA LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1964	nsp during install o	Installation record	N			
1170	SANDRA LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1964	nsp during install o	Installation record	N			
1096	SANDRA LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1964	nsp during install o	Installation record	N			
1104	SANDRA LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1964	nsp during install o	Installation record	N			
1112	SANDRA LANE			C	N	1"		C	1"		SF						Installation record	Y	1974	nsp during install o	Field inspection only	Y		Cross-connection survey	
1120	SANDRA LANE			C	N	1"		UNK-NOLG			SF						Installation record	Y	1974	nsp during install o	Installation record	N			
1128	SANDRA LANE			C	N	1"		UNK-NOLG			SF						Installation record	Y	1974	nsp during install o	Installation record	N			
1142	SANDRA LANE			C	N	1"		UNK-NOLG			SF						Installation record	Y	1974	nsp during install o	Installation record	N			
1148	SANDRA LANE			C	N	1"		UNK-NOLG			SF						Installation record	Y	1974	nsp during install o	Installation record	N			
1154	SANDRA LANE			C	N	1"		UNK-NOLG			SF						Installation record	Y	1974	nsp during install o	Installation record	N			
1160	SANDRA LANE			C	N	1"		UNK-NOLG			SF						Installation record	Y	1974	nsp during install o	Installation record	N			
1161	SANDRA LANE			C	N	1"		UNK-NOLG			SF						Installation record	Y	1974	nsp during install o	Installation record	N			
1153	SANDRA LANE			C	N	1"		UNK-NOLG			SF						Installation record	Y	1974	nsp during install o	Installation record	N			
1145	SANDRA LANE			C	N	1"		UNK-NOLG			SF						Installation record	Y	1974	nsp during install o	Installation record	N			
1139	SANDRA LANE			C	N	1"		UNK-NOLG			SF						Installation record	Y	1974	nsp during install o	Installation record	N			
1111	SANDRA LANE			C	N	1"		UNK-NOLG			SF						Installation record	Y	1974	nsp during install o	Installation record	N			
2404	SANTA BARBARA DRIVE			C	N	1"		UNK-NOLG			SF						Installation record	N	1964		Installation record	N			
2350	SANTA BARBARA DRIVE			C	N	1"		C	1"		SF						Installation record	N	1979		Field inspection only	Y		Cross-connection survey	
2277	SANTA BARBARA DRIVE			C	N	1"		C	1"		SF						Installation record	N	1964		Installation record	N			
2244	SANTA BARBARA DRIVE			C	N	1"		UNK-NOLG			SF						Installation record	N	1964		Installation record	N			
2445	SANTA BARBARA DRIVE			C	N	1"		UNK-NOLG			SF						Installation record	N	1964		Installation record	N			
2271	SANTA BARBARA DRIVE			C	N	1"		UNK-NOLG			SF						Installation record	N	1964		Installation record	N			
2360	SANTA BARBARA DRIVE			C	N	1"		C	1"		SF						Installation record	N	1979		Field inspection only	Y		Cross-connection survey	
2418	SANTA BARBARA DRIVE			C	N	1"		C	3/4"		SF						Installation record	N	1964		Field inspection only	Y		Cross-connection survey	
2243	SANTA BARBARA DRIVE			C	N	1"		UNK-NOLG			SF						Installation record	N	1964		Installation record	N			
2270	SANTA BARBARA DRIVE			C	N	1"		C	3/4"		SF						Installation record	N	1964		Field inspection only	Y		Cross-connection survey	
2276	SANTA BARBARA DRIVE			C	N	1"		UNK-NOLG			SF						Installation record	N	1964		Installation record	N			
2321	SANTA BARBARA DRIVE			C	N	1"		UNK-NOLG			SF						Installation record	N	1964		Installation record	N			
2309	SANTA BARBARA DRIVE			C	N	1"		C	1"		SF						Installation record	N	1979		Field inspection only	Y		Cross-connection survey	
2310	SANTA BARBARA DRIVE			C	N	1"		UNK-NOLG			SF						Installation record	N	1979		Installation record	N			
2300	SANTA BARBARA DRIVE			C	N	1"		UNK-NOLG			SF						Installation record	N	1979		Installation record	N			
2301	SANTA BARBARA DRIVE			C	N	1"		C	3/4"		SF						Installation record	N	1979		Field inspection only	Y		Cross-connection survey	
2234	SANTA BARBARA DRIVE			C	N	1"		C	3/4"		SF						Installation record	N	1964		Field inspection only	Y		Cross-connection survey	
2235	SANTA BARBARA DRIVE			C	N	1"		UNK-NOLG			SF						Installation record	N	1964		Installation record	N			
2229	SANTA BARBARA DRIVE			C	N	1"		UNK-NOLG			SF						Installation record	N	1964		Installation record	N			
2225	SANTA BARBARA DRIVE			C	N	1"		C	3/4"		MF						Installation record	N	1964		Field inspection only	Y		Cross-connection survey	
2223	SANTA BARBARA DRIVE			C	N	1"		C	1"		MF						Installation record	N	1964		Field inspection only	Y		Cross-connection survey	
2221	SANTA BARBARA DRIVE			C	N	1"		C	1"		SF						Installation record	N	1964		Field inspection only	Y		Cross-connection survey	
2219	SANTA BARBARA DRIVE			C	N	1"		C	3/4"		SF						Installation record	N	1964		Field inspection only	Y		Cross-connection survey	
2217	SANTA BARBARA DRIVE			C	N	1"		C	3/4"		SF						Installation record	N	1964		Field inspection only	Y		Cross-connection survey	
2215	SANTA BARBARA DRIVE			C	N	1"		C	3/4"		MF						Installation record	N	1964		Field inspection only	Y		Cross-connection survey	
2213	SANTA BARBARA DRIVE			C	N	1"		C	3/4"		MF						Installation record	N	1964		Field inspection only	Y		Cross-connection survey	
2211	SANTA BARBARA DRIVE			C	N	1"		C	3/4"		SF						Installation record	N	1964		Field inspection only	Y		Cross-connection survey	
2216	SANTA BARBARA DRIVE			C	N	1"		C	1"		SF						Installation record	N	1964		Field inspection only	Y		Cross-connection survey	
2209	SANTA BARBARA DRIVE			C	N	1"		C	3/4"		SF						Installation record	N	1964		Field inspection only	Y		Cross-connection survey	
2207	SANTA BARBARA DRIVE			C	N	1"		C	3/4"		MF						Installation record	N	1964		Field inspection only	Y		Cross-connection survey	
2205	SANTA BARBARA DRIVE			C	N	1"		C	3/4"		SF						Installation record	N	1964		Field inspection only	Y		Cross-connection survey	
2203	SANTA BARBARA DRIVE			C	N	1"		C	3/4"		SF						Installation record	N	1964		Field inspection only	Y		Cross-connection survey	
2201	SANTA BARBARA DRIVE			C	N	1"		C	3/4"		MF						Installation record	N	1964		Field inspection only	Y		Cross-connection survey	
2199	SANTA BARBARA DRIVE			C	N	1"		C	3/4"		MF						Installation record	N	1964		Field inspection only	Y		Cross-connection survey	
2197	SANTA BARBARA DRIVE			C	N	1"		C	3/4"		MF						Installation record	N	1964		Field inspection only	Y		Cross-connection survey	
2195	SANTA BARBARA DRIVE			C	N	1"		C	3/4"		MF						Installation record	N	1964		Field inspection only	Y		Cross-connection survey	
2441	SANTA BARBARA DRIVE			C	N	1"		UNK-NOLG			SF						Installation record	N	1979		Installation record	N			
2437	SANTA BARBARA DRIVE			C	N	1"		C	3/4"		SF						Installation record	N	1979		Field inspection only	Y		Cross-connection survey	

LOCATIONAL IDENTIFIER ADDRESS	LOCATIONAL IDENTIFIER STREET NAME	LOCATIONAL IDENTIFIER UNIT OR SUITE #	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
2429	SANTA BARBARA DRIVE			C	N	1"		UNK-NOLG			SF						Installation record	N	1979		Installation record	N			
2421	SANTA BARBARA DRIVE			C	N	1"		C	1"		SF						Installation record	N	1979		Field inspection only	Y		Cross-connection survey	
2415	SANTA BARBARA DRIVE			C	N	1"		C	1"		SF						Installation record	N	1979		Field inspection only	Y		Cross-connection survey	
2410	SANTA BARBARA DRIVE			C	N	1"		UNK-NOLG			SF						Installation record	N	1979		Installation record	N			
2405	SANTA BARBARA DRIVE			C	N	1"		UNK-NOLG			SF						Installation record	N	1979		Installation record	N			
2381	SANTA BARBARA DRIVE			C	N	1"		UNK-NOLG			SF						Installation record	N	1979		Installation record	N			
2371	SANTA BARBARA DRIVE			C	N	1"		UNK-NOLG			SF						Installation record	N	1979		Installation record	N			
2361	SANTA BARBARA DRIVE			C	N	1"		UNK-NOLG			SF						Installation record	N	1979		Installation record	N			
2351	SANTA BARBARA DRIVE			C	N	1"		C	1"		SF						Installation record	N	1979		Field inspection only	Y		Cross-connection survey	
2331	SANTA BARBARA DRIVE			C	N	1"		C	1"		SF						Installation record	N	1979		Field inspection only	Y		Cross-connection survey	
1171	SCHAUER LANE			C	N	1"		UNK-NOLG			SF						Installation record	Y	1977	ısp during install o	Installation record	N			
1139	SCHAUER LANE			C	N	1"		UNK-NOLG			SF						Installation record	Y	1977	ısp during install o	Installation record	N			
1151	SCHAUER LANE			C	N	1"		UNK-NOLG			SF						Installation record	Y	1977	ısp during install o	Installation record	N			
1125	SCHAUER LANE			C	N	1"		UNK-NOLG			SF						Installation record	Y	1977	ısp during install o	Installation record	N			
1119	SCHAUER LANE			C	N	1"		UNK-NOLG			SF						Installation record	Y	1977	ısp during install o	Installation record	N			
1111	SCHAUER LANE			C	N	1"		C	1"		SF						Installation record	Y	1977	ısp during install o	Field inspection only	Y		Cross-connection survey	
1105	SCHAUER LANE			C	N	1"		P	1"		SF						Installation record	Y	1977	ısp during install o	Field inspection only	Y		Cross-connection survey	
1104	SCHAUER LANE			C	N	1"		UNK-NOLG			SF						Installation record	Y	1977	ısp during install o	Installation record	N			
1112	SCHAUER LANE			C	N	1"		C	3/4"		SF						Installation record	Y	1977	ısp during install o	Field inspection only	Y		Cross-connection survey	
1118	SCHAUER LANE			C	N	1"		UNK-NOLG			SF						Installation record	Y	1977	ısp during install o	Installation record	N			
1124	SCHAUER LANE			C	N	1"		UNK-NOLG			SF						Installation record	Y	1977	ısp during install o	Installation record	N			
1130	SCHAUER LANE			C	N	1"		C	1"		SF						Installation record	Y	1977	ısp during install o	Field inspection only	Y		Cross-connection survey	
1138	SCHAUER LANE			C	N	1"		UNK-NOLG			SF						Installation record	Y	1977	ısp during install o	Installation record	N			
1144	SCHAUER LANE			C	N	1"		UNK-NOLG			SF						Installation record	Y	1977	ısp during install o	Installation record	N			
1150	SCHAUER LANE			C	N	1"		UNK-NOLG			SF						Installation record	Y	1977	ısp during install o	Installation record	N			
1156	SCHAUER LANE			C	N	1"		UNK-NOLG			SF						Installation record	Y	1977	ısp during install o	Installation record	N			
1162	SCHAUER LANE			C	N	1"		UNK-NOLG			SF						Installation record	Y	1977	ısp during install o	Installation record	N			
1170	SCHAUER LANE			C	N	1"		C	1"		SF						Installation record	Y	1977	ısp during install o	Field inspection only	Y		Cross-connection survey	
1163	SCHAUER LANE			C	N	1"		UNK-NOLG			SF						Installation record	Y	1977	ısp during install o	Installation record	N			
1157	SCHAUER LANE			C	N	1"		UNK-NOLG			SF						Installation record	Y	1977	ısp during install o	Installation record	N			
1145	SCHAUER LANE			C	N	1"		UNK-NOLG			SF						Installation record	Y	1977	ısp during install o	Installation record	N			
1131	SCHAUER LANE			C	N	1"		UNK-NOLG			SF						Installation record	Y	1977	ısp during install o	Installation record	N			
2377	SHADY LANE			C	N	1"		C	3/4"		SF						Installation record	Y	1967	ısp during install o	Field inspection only	Y		Cross-connection survey	
2115	SHADY LANE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1991	ısp during install o	Installed after lead ban	N			
2437	SHADY LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1967	ısp during install o	Installation record	N			
2043	SHADY LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1967	ısp during install o	Installation record	N			
2408	SHADY LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1967	ısp during install o	Installation record	N			
2372	SHADY LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1967	ısp during install o	Field inspection only	Y		Cross-connection survey	
2121	SHADY LANE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1991	ısp during install o	Installed after lead ban	N			
2101	SHADY LANE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1991	ısp during install o	Installed after lead ban	N			
2181	SHADY LANE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1991	ısp during install o	Installed after lead ban	N			
2461	SHADY LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1967	ısp during install o	Installation record	N			
2071	SHADY LANE			P	N	1"		C	1"		SF						Installed after lead ban	Y	1991	ısp during install o	Installed after lead ban	N			
2460	SHADY LANE			C	N	1"		UNK-NOLG			SF						Installation record	Y	1967	ısp during install o	Installation record	N			
2276	SHADY LANE			C	N	1"		C	3/4"		SF						Installation record	Y	1967	ısp during install o	Field inspection only	Y		Cross-connection survey	
2430	SHADY LANE			C	N	1"		UNK-NOLG			SF						Installation record	Y	1967	ısp during install o	Installation record	N			
2251	SHADY LANE			C	N	1"		C	1"		SF						Installation record	Y	1967	ısp during install o	Field inspection only	Y		Cross-connection survey	
2027	SHADY LANE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1991	ısp during install o	Installed after lead ban	N			
2079	SHADY LANE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1991	ısp during install o	Installed after lead ban	N			
2110	SHADY LANE			P	N	1"		C	1"		SF						Installed after lead ban	Y	1991	ısp during install o	Field inspection only	Y		Cross-connection survey	
2488	SHADY LANE			P	N	1"		C	3/4"		SF						Installation record	Y	1967	ısp during install o	Field inspection only	Y		Cross-connection survey	
2021	SHADY LANE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1991	ısp during install o	Installed after lead ban	N			
2170	SHADY LANE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1991	ısp during install o	Installed after lead ban	N			
2111	SHADY LANE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1991	ısp during install o	Installed after lead ban	N			
2180	SHADY LANE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1991	ısp during install o	Installed after lead ban	N			
2171	SHADY LANE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1991	ısp during install o	Installed after lead ban	N			
2356	SHADY LANE			C	N	1"		C	1"		SF						Installation record	Y	1967	ısp during install o	Field inspection only	Y		Cross-connection survey	
2494	SHADY LANE			C	N	1"		UNK-NOLG			SF						Installation record	Y	1967	ısp during install o	Installation record	N			
2175	SHADY LANE			P	N	1"		UNK-NOLG			SF						Installation record	Y	1967	ısp during install o	Installation record	N			
2176	SHADY LANE			P	N	1"		C	3/4"		SF						Installation record	Y	1967	ısp during install o	Field inspection only	Y		Cross-connection survey	
2277	SHADY LANE			P	N	1"		C	3/4"		SF						Installation record	Y	1967	ısp during install o	Field inspection only	Y		Cross-connection survey	
2404	SHADY LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1967	ısp during install o	Installation record	N			
2053	SHADY LANE			P	N	1"		C	1"		SF						Installed after lead ban	Y	1991	ısp during install o	Installed after lead ban	N			
2382	SHADY LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1967	ısp during install o	Installation record	N			
2035	SHADY LANE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1991	ısp during install o	Installation record	N			
2161	SHADY LANE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1991	ısp during install o	Installation record	N			
2160	SHADY LANE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1991	ısp during install o	Installation record	N			
2481	SHADY LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1967	ısp during install o	Installation record	N			
2250	SHADY LANE			C	N	3/4"		C	1"		SF						Installation record	Y	1967	ısp during install o	Field inspection only	Y		Cross-connection survey	
2122	SHADY LANE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1991	ısp during install o	Installation record	N			
2445	SHADY LANE			P	N	3/4"		C	3/4"		SF						Installation record	Y	1967	ısp during install o	Field inspection only	Y		Cross-connection survey	
2438	SHADY LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1967	ısp during install o	Field inspection only	Y		Cross-connection survey	
2444	SHADY LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1967	ısp during install o	Installation record	N			
2244	SHADY LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1967	ısp during install o	Installation record	N			
2150	SHADY LANE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1991	ısp during install o	Installation record	N			
2034	SHADY LANE			P	N	1"		C	1"		SF						Installed after lead ban	Y	1991	ısp during install o	Field inspection only	Y		Cross-connection survey	
2482	SHADY LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1967	ısp during install o	Installation record	N			
2346	SHADY LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1967	ısp during install o	Installation record	N			
2487	SHADY LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1967	ısp during install o	Field inspection only	Y		Cross-connection survey	
2498	SHADY LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1967	ısp during install o	Field inspection only	Y		Cross-connection survey	
2453	SHADY LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1967	ısp during install o	Installation record	N			
2096	SHADY LANE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1991	ısp during install o	Installation record	N			
2061	SHADY LANE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1991	ısp during install o	Installation record	N			
2245	SHADY LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1967	ısp during install o	Installation record	N			
2085	SHADY LANE			P	N	1"		C	3/4"		SF						Installed after lead ban	Y	1991	ısp during install o	Field inspection only	Y		Cross-connection survey	

LOCATIONAL IDENTIFIER ADDRESS	LOCATIONAL IDENTIFIER STREET NAME	LOCATIONAL IDENTIFIER UNIT OR SUITE #	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
2010	SHADY LANE			P	N	1"		C	1"		SF						Installed after lead ban	Y	1991	nsp during install o	Field inspection only	Y		Cross-connection survey	
2424	SHADY LANE			C	N	3/4"		C	1"		SF						Installation record	Y	1967	nsp during install o	Field inspection only	Y		Cross-connection survey	
2450	SHADY LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1967	nsp during install o	Installation record	N			
2347	SHADY LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1967	nsp during install o	Field inspection only	Y		Cross-connection survey	
2151	SHADY LANE			P	N	1"		C	3/4"		SF						Installed after lead ban	Y	1991	nsp during install o	Field inspection only	Y		Cross-connection survey	
2322	SHADY LANE			C	N	3/4"		C	1"		SF						Installation record	Y	1967	nsp during install o	Field inspection only	Y		Cross-connection survey	
2330	SHADY LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1967	nsp during install o	Installation record	N			
2080	SHADY LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1967	nsp during install o	Installation record	N			
2114	SHADY LANE			P	N	1"		C	3/4"		SF						Installed after lead ban	Y	1991	nsp during install o	Field inspection only	Y		Cross-connection survey	
2088	SHADY LANE			P	N	1"		P	1"		SF						Installed after lead ban	Y	1991	nsp during install o	Field inspection only	Y		Cross-connection survey	
2468	SHADY LANE			C	N	3/4"		P	1"		SF						Installation record	Y	1967	nsp during install o	Installation record	N			
1099	SHARIE LANE			C	N	1"		C	1"		SF						Installation record	Y	1976	nsp during install o	Field inspection only	Y		Cross-connection survey	
1155	SHARIE LANE			C	N	1"		UNK-NOLG			SF						Installation record	Y	1976	nsp during install o	Installation record	N			
1144	SHARIE LANE			C	N	1"		UNK-NOLG			SF						Installation record	Y	1976	nsp during install o	Installation record	N			
1141	SHARIE LANE			C	N	1"		UNK-NOLG			SF						Installation record	Y	1976	nsp during install o	Installation record	N			
1129	SHARIE LANE			C	N	1"		UNK-NOLG			SF						Installation record	Y	1976	nsp during install o	Installation record	N			
1112	SHARIE LANE			C	N	1"		UNK-NOLG			SF						Installation record	Y	1976	nsp during install o	Installation record	N			
1161	SHARIE LANE			C	N	1"		UNK-NOLG			SF						Installation record	Y	1976	nsp during install o	Installation record	N			
1104	SHARIE LANE			C	N	1"		UNK-NOLG			SF						Installation record	Y	1976	nsp during install o	Installation record	N			
1118	SHARIE LANE			C	N	1"		UNK-NOLG			SF						Installation record	Y	1976	nsp during install o	Installation record	N			
1124	SHARIE LANE			C	N	1"		UNK-NOLG			SF						Installation record	Y	1976	nsp during install o	Installation record	N			
1130	SHARIE LANE			C	N	1"		UNK-NOLG			SF						Installation record	Y	1976	nsp during install o	Installation record	N			
1138	SHARIE LANE			C	N	1"		UNK-NOLG			SF						Installation record	Y	1976	nsp during install o	Installation record	N			
1150	SHARIE LANE			C	N	1"		UNK-NOLG			SF						Installation record	Y	1976	nsp during install o	Installation record	N			
1156	SHARIE LANE			C	N	1"		UNK-NOLG			SF						Installation record	Y	1976	nsp during install o	Installation record	N			
1162	SHARIE LANE			C	N	1"		UNK-NOLG			SF						Installation record	Y	1976	nsp during install o	Installation record	N			
1170	SHARIE LANE			C	N	1"		UNK-NOLG			SF						Installation record	Y	1976	nsp during install o	Installation record	N			
1175	SHARIE LANE			C	N	1"		UNK-NOLG			SF						Installation record	Y	1976	nsp during install o	Installation record	N			
1167	SHARIE LANE			C	N	1"		UNK-NOLG			SF						Installation record	Y	1976	nsp during install o	Installation record	N			
1149	SHARIE LANE			C	N	1"		UNK-NOLG			SF						Installation record	Y	1976	nsp during install o	Installation record	N			
1135	SHARIE LANE			C	N	1"		UNK-NOLG			SF						Installation record	Y	1976	nsp during install o	Installation record	N			
1123	SHARIE LANE			C	N	1"		UNK-NOLG			SF						Installation record	Y	1976	nsp during install o	Installation record	N			
1115	SHARIE LANE			C	N	1"		UNK-NOLG			SF						Installation record	Y	1976	nsp during install o	Installation record	N			
1109	SHARIE LANE			C	N	1"		C	3/4"		SF						Installation record	Y	1976	nsp during install o	Field inspection only	Y		Cross-connection survey	
1103	SHARIE LANE			C	N	1"		UNK-NOLG			SF						Installation record	Y	1976	nsp during install o	Installation record	N			
1513	SHERWOOD DRIVE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1967	nsp during install o	Installation record	N			
1526	SHERWOOD DRIVE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1967	nsp during install o	Field inspection only	Y		Cross-connection survey	
1498	SHERWOOD DRIVE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1967	nsp during install o	Installation record	N			
1487	SHERWOOD DRIVE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1967	nsp during install o	Installation record	N			
1505	SHERWOOD DRIVE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1967	nsp during install o	Installation record	N			
1512	SHERWOOD DRIVE			C	N	3/4"		C	1"		SF						Installation record	Y	1967	nsp during install o	Field inspection only	Y		Cross-connection survey	
1492	SHERWOOD DRIVE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1967	nsp during install o	Installation record	N			
1601	SHERWOOD DRIVE			C	N	1"		UNK-NOLG			SF						Installation record	Y	1975	nsp during install o	Installation record	N			
1556	SHERWOOD DRIVE			C	N	1"		C	1"		SF						Installation record	Y	1975	nsp during install o	Field inspection only	Y		Cross-connection survey	
1570	SHERWOOD DRIVE			C	N	1"		UNK-NOLG			SF						Installation record	Y	1975	nsp during install o	Installation record	N			
1518	SHERWOOD DRIVE			C	N	1"		UNK-NOLG			SF						Installation record	Y	1975	nsp during install o	Installation record	N			
1470	SHERWOOD DRIVE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1967	nsp during install o	Field inspection only	Y		Cross-connection survey	
1478	SHERWOOD DRIVE			C	N	3/4"		C	1"		SF						Installation record	Y	1967	nsp during install o	Field inspection only	Y		Cross-connection survey	
1486	SHERWOOD DRIVE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1967	nsp during install o	Installation record	N			
1504	SHERWOOD DRIVE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1967	nsp during install o	Installation record	N			
1542	SHERWOOD DRIVE			C	N	1"		UNK-NOLG			SF						Installation record	Y	1975	nsp during install o	Installation record	N			
1543	SHERWOOD DRIVE			C	N	1"		UNK-NOLG			SF						Installation record	Y	1975	nsp during install o	Installation record	N			
1527	SHERWOOD DRIVE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1967	nsp during install o	Installation record	N			
1519	SHERWOOD DRIVE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1967	nsp during install o	Installation record	N			
1499	SHERWOOD DRIVE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1967	nsp during install o	Field inspection only	Y		Cross-connection survey	
1493	SHERWOOD DRIVE			C	N	3/4"		C	1"		SF						Installation record	Y	1967	nsp during install o	Field inspection only	Y		Cross-connection survey	
1481	SHERWOOD DRIVE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1967	nsp during install o	Installation record	N			
1473	SHERWOOD DRIVE			C	N	3/4"		C	1"		SF						Installation record	Y	1967	nsp during install o	Field inspection only	Y		Cross-connection survey	
1595	SHERWOOD DRIVE			C	N	1"		C	1"		SF						Installation record	Y	1975	nsp during install o	Field inspection only	Y		Cross-connection survey	
1587	SHERWOOD DRIVE			C	N	1"		UNK-NOLG			SF						Installation record	Y	1975	nsp during install o	Installation record	N			
1581	SHERWOOD DRIVE			C	N	1"		UNK-NOLG			SF						Installation record	Y	1975	nsp during install o	Installation record	N			
1573	SHERWOOD DRIVE			C	N	1"		C	1"		SF						Installation record	Y	1975	nsp during install o	Field inspection only	Y		Cross-connection survey	
1565	SHERWOOD DRIVE			C	N	1"		UNK-NOLG			SF						Installation record	Y	1975	nsp during install o	Installation record	N			
1559	SHERWOOD DRIVE			C	N	1"		C	1"		SF						Installation record	Y	1975	nsp during install o	Field inspection only	Y		Cross-connection survey	
1551	SHERWOOD DRIVE			C	N	1"		C	1"		SF						Installation record	Y	1975	nsp during install o	Field inspection only	Y		Cross-connection survey	
1550	SHERWOOD DRIVE			C	N	1"		C	1"		SF						Installation record	Y	1975	nsp during install o	Field inspection only	Y		Cross-connection survey	
1562	SHERWOOD DRIVE			C	N	1"		UNK-NOLG			SF						Installation record	Y	1975	nsp during install o	Installation record	N			
1576	SHERWOOD DRIVE			C	N	1"		C	3/4"		SF						Installation record	Y	1975	nsp during install o	Field inspection only	Y		Cross-connection survey	
1582	SHERWOOD DRIVE			C	N	1"		C	1"		SF						Installation record	Y	1975	nsp during install o	Field inspection only	Y		Cross-connection survey	
1588	SHERWOOD DRIVE			C	N	1"		UNK-NOLG			SF						Installation record	Y	1975	nsp during install o	Installation record	N			
1596	SHERWOOD DRIVE			C	N	1"		UNK-NOLG			SF						Installation record	Y	1975	nsp during install o	Installation record	N			
1600	SHERWOOD DRIVE			C	N	1"		UNK-NOLG			SF						Installation record	Y	1975	nsp during install o	Installation record	N			
1466	SILVERADO COURT			P	N	1"		P	1"		SF						Installed after lead ban	Y	2011	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1434	SILVERADO COURT			P	N	1"		P	1"		SF						Installed after lead ban	Y	2011	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1442	SILVERADO COURT			P	N	1"		P	1"		SF						Installed after lead ban	Y	2011	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1433	SILVERADO COURT			P	N	1"		P	1"		SF						Installed after lead ban	Y	2011	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3538	SILVERADO COURT			P	N	1"		P	1"		SF						Installed after lead ban	Y	2011	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1458	SILVERADO COURT			P	N	1"		P	1"		SF						Installed after lead ban	Y	2011	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1452	SILVERADO COURT			P	N	1"		P	1"		SF						Installed after lead ban	Y	2011	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1449	SILVERADO COURT			P	N	1"		P	1"		SF						Installed after lead ban	Y	2011	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1441	SILVERADO COURT			P	N	1"		P	1"		SF						Installed after lead ban	Y	2011	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1449	SILVERADO COURT	WOM		P	N	1"		P	1"		SF						Installed after lead ban	Y	2011	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3561	SILVERADO TRAIL			P	N	1"		P	1"		SF						Installed after lead ban	Y	2011	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3549	SILVERADO TRAIL			P	N	1"		P	1"		SF						Installed after lead ban	Y	2011	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3555	SILVERADO TRAIL			P	N	1"		P	1"		SF						Installed after lead ban	Y	2011	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	

LOCATIONAL IDENTIFIER ADDRESS	LOCATIONAL IDENTIFIER STREET NAME	LOCATIONAL IDENTIFIER UNIT OR SUITE #	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
3554	SILVERADO TRAIL			P	N	1"		P	1"		SF						Installed after lead ban	Y	2011	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3546	SILVERADO TRAIL			P	N	1"		P	1"		SF						Installed after lead ban	Y	2011	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3562	SILVERADO TRAIL			P	N	1"		P	1"		SF						Installed after lead ban	Y	2011	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3570	SILVERADO TRAIL			P	N	1"		P	1"		SF						Installed after lead ban	Y	2011	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1287	SKYLARK LANE			P	N	1"		C	3/4"		SF						Installed after lead ban	Y	1991	nsp during install o	Installed after lead ban	N			
1334	SKYLARK LANE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1991	nsp during install o	Installed after lead ban	N			
1294	SKYLARK LANE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1991	nsp during install o	Installed after lead ban	N			
1299	SKYLARK LANE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1991	nsp during install o	Installed after lead ban	N			
1272	SKYLARK LANE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1991	nsp during install o	Installed after lead ban	N			
1335	SKYLARK LANE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1991	nsp during install o	Installed after lead ban	N			
1275	SKYLARK LANE			P	N	1"		C	1"		SF						Installed after lead ban	Y	1991	nsp during install o	Field inspection only	Y		Cross-connection survey	
1506	SKYLARK LANE			P	N	1"		P	2"		SF						Installed after lead ban	Y	1995	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1460	SKYLARK LANE			P	N	1"		P	1"		SF						Installed after lead ban	Y	1991	nsp during install o	Field inspection only	Y		Cross-connection survey	
1441	SKYLARK LANE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1991	nsp during install o	Installed after lead ban	N			
1281	SKYLARK LANE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1991	nsp during install o	Installed after lead ban	N			
1510	SKYLARK LANE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1995	nsp during install o	Installed after lead ban	N			
1327	SKYLARK LANE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1991	nsp during install o	Installed after lead ban	N			
1471	SKYLARK LANE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1991	nsp during install o	Installed after lead ban	N			
1450	SKYLARK LANE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1991	nsp during install o	Installed after lead ban	N			
1385	SKYLARK LANE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1991	nsp during install o	Installed after lead ban	N			
1278	SKYLARK LANE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1991	nsp during install o	Installed after lead ban	N			
1470	SKYLARK LANE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1991	nsp during install o	Installed after lead ban	N			
1319	SKYLARK LANE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1991	nsp during install o	Installed after lead ban	N			
1266	SKYLARK LANE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1991	nsp during install o	Installed after lead ban	N			
1444	SKYLARK LANE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1991	nsp during install o	Installed after lead ban	N			
1466	SKYLARK LANE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1991	nsp during install o	Installed after lead ban	N			
1440	SKYLARK LANE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1991	nsp during install o	Installed after lead ban	N			
1342	SKYLARK LANE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1991	nsp during install o	Installed after lead ban	N			
1487	SKYLARK LANE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1991	nsp during install o	Installed after lead ban	N			
1293	SKYLARK LANE			P	N	1"		C	1"		SF						Installed after lead ban	Y	1991	nsp during install o	Field inspection only	Y		Cross-connection survey	
1503	SKYLARK LANE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1991	nsp during install o	Installed after lead ban	N			
1430	SKYLARK LANE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1991	nsp during install o	Installed after lead ban	N			
1480	SKYLARK LANE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1991	nsp during install o	Installed after lead ban	N			
1488	SKYLARK LANE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1991	nsp during install o	Installed after lead ban	N			
1490	SKYLARK LANE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1991	nsp during install o	Installed after lead ban	N			
1500	SKYLARK LANE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1991	nsp during install o	Installed after lead ban	N			
1475	SKYLARK LANE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1991	nsp during install o	Installed after lead ban	N			
1461	SKYLARK LANE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1991	nsp during install o	Installed after lead ban	N			
1451	SKYLARK LANE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1991	nsp during install o	Installed after lead ban	N			
1435	SKYLARK LANE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1991	nsp during install o	Installed after lead ban	N			
1431	SKYLARK LANE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1991	nsp during install o	Installed after lead ban	N			
1401	SKYLARK LANE			P	N	1"		P	1"		SF						Installed after lead ban	Y	1991	nsp during install o	Field inspection only	Y		Cross-connection survey	
1260	SKYLARK LANE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1991	nsp during install o	Installed after lead ban	N			
1284	SKYLARK LANE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1991	nsp during install o	Installed after lead ban	N			
1292	SKYLARK LANE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1991	nsp during install o	Installed after lead ban	N			
1318	SKYLARK LANE			P	N	1"		C	3/4"		SF						Installed after lead ban	Y	1991	nsp during install o	Field inspection only	Y		Cross-connection survey	
1326	SKYLARK LANE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1991	nsp during install o	Installed after lead ban	N			
1352	SKYLARK LANE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1991	nsp during install o	Installed after lead ban	N			
1360	SKYLARK LANE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1991	nsp during install o	Installed after lead ban	N			
1366	SKYLARK LANE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1991	nsp during install o	Installed after lead ban	N			
1374	SKYLARK LANE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1991	nsp during install o	Installed after lead ban	N			
1375	SKYLARK LANE			P	N	1"		C	3/4"		SF						Installed after lead ban	Y	1991	nsp during install o	Field inspection only	Y		Cross-connection survey	
1363	SKYLARK LANE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1991	nsp during install o	Installed after lead ban	N			
1361	SKYLARK LANE			P	N	1"		C	3/4"		SF						Installed after lead ban	Y	1991	nsp during install o	Field inspection only	Y		Cross-connection survey	
1351	SKYLARK LANE			P	N	1"		C	3/4"		SF						Installed after lead ban	Y	1991	nsp during install o	Field inspection only	Y		Cross-connection survey	
1345	SKYLARK LANE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1991	nsp during install o	Installed after lead ban	N			
1269	SKYLARK LANE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1991	nsp during install o	Installed after lead ban	N			
1261	SKYLARK LANE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1991	nsp during install o	Installed after lead ban	N			
2257	SMITHVILLE ROAD			C	N	1"		UNK-NOLG			SF						Installation record	Y	1976	nsp during install o	Installation record	N			
2269	SMITHVILLE ROAD			C	N	1"		UNK-NOLG			SF						Installation record	Y	1976	nsp during install o	Installation record	N			
2247	SMITHVILLE ROAD			C	N	1"		UNK-NOLG			SF						Installation record	Y	1976	nsp during install o	Installation record	N			
2244	SMITHVILLE ROAD			C	N	1"		C	3/4"		SF						Installation record	Y	1976	nsp during install o	Field inspection only	Y		Cross-connection survey	
2270	SMITHVILLE ROAD			C	N	1"		C	1"		SF						Installation record	Y	1976	nsp during install o	Field inspection only	Y		Cross-connection survey	
2276	SMITHVILLE ROAD			C	N	1"		C	3/4"		SF						Installation record	Y	1976	nsp during install o	Field inspection only	Y			
1055	SPRINGFIELD DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2003	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1088	SPRINGFIELD DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2003	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1104	SPRINGFIELD DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2003	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1096	SPRINGFIELD DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2003	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1080	SPRINGFIELD DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2003	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1072	SPRINGFIELD DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2003	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1064	SPRINGFIELD DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2003	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1056	SPRINGFIELD DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2003	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1047	SPRINGFIELD DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2003	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1063	SPRINGFIELD DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2003	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1079	SPRINGFIELD DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2003	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1087	SPRINGFIELD DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2003	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1095	SPRINGFIELD DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2003	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1103	SPRINGFIELD DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2003	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1111	SPRINGFIELD DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2003	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1039	SPRINGFIELD DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2003	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1031	SPRINGFIELD DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2003	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
2475	ST JOHNS DRIVE			C	N	1"		UNK-NOLG			SF						Installation record	Y	1973	nsp during install o	Installation record	N			
2467	ST JOHNS DRIVE			C	N	1"		UNK-NOLG			SF						Installation record	Y	1973	nsp during install o	Installation record	N			
2461	ST JOHNS DRIVE			C	N	1"		UNK-NOLG			SF						Installation record	Y	1973	nsp during install o	Installation record	N			
2453	ST JOHNS DRIVE			C	N	1"		UNK-NOLG			SF						Installation record	Y	1973	nsp during install o	Installation record	N			

LOCATIONAL IDENTIFIER ADDRESS	LOCATIONAL IDENTIFIER STREET NAME	LOCATIONAL IDENTIFIER UNIT OR SUITE #	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
2447	ST JOHNS DRIVE			C	N	1"		UNK-NOLG			SF						Installation record	Y	1973	nsp during install o	Installation record	N			
2441	ST JOHNS DRIVE			C	N	1"		UNK-NOLG			SF						Installation record	Y	1973	nsp during install o	Installation record	N			
2452	ST JOHNS DRIVE			C	N	1"		C	1"		SF						Installation record	Y	1973	nsp during install o	Field inspection only	Y		Cross-connection survey	
2460	ST JOHNS DRIVE			C	N	1"		C	1"		SF						Installation record	Y	1973	nsp during install o	Field inspection only	Y		Cross-connection survey	
2499	ST JOHNS DRIVE			C	N	1"		UNK-NOLG			SF						Installation record	Y	1973	nsp during install o	Installation record	N			
2495	ST JOHNS DRIVE			C	N	1"		UNK-NOLG			SF						Installation record	Y	1973	nsp during install o	Installation record	N			
2489	ST JOHNS DRIVE			C	N	1"		UNK-NOLG			SF						Installation record	Y	1973	nsp during install o	Installation record	N			
893	STADIUM DRIVE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1962	nsp during install o	Field inspection only	Y		Cross-connection survey	
901	STADIUM DRIVE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1962	nsp during install o	Installation record	N			
914	STADIUM DRIVE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1962	nsp during install o	Installation record	N			
890	STADIUM DRIVE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1962	nsp during install o	Field inspection only	Y		Cross-connection survey	
896	STADIUM DRIVE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1962	nsp during install o	Field inspection only	Y		Cross-connection survey	
910	STADIUM DRIVE			C	N	3/4"		C	1"		SF						Installation record	Y	1962	nsp during install o	Field inspection only	Y		Cross-connection survey	
935	STADIUM DRIVE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1962	nsp during install o	Field inspection only	Y		Cross-connection survey	
927	STADIUM DRIVE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1962	nsp during install o	Field inspection only	Y		Cross-connection survey	
921	STADIUM DRIVE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1962	nsp during install o	Field inspection only	Y		Cross-connection survey	
915	STADIUM DRIVE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1962	nsp during install o	Field inspection only	Y		Cross-connection survey	
897	STADIUM DRIVE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1962	nsp during install o	Installation record	N			
889	STADIUM DRIVE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1962	nsp during install o	Field inspection only	Y		Cross-connection survey	
880	STADIUM DRIVE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1962	nsp during install o	Field inspection only	Y		Cross-connection survey	
884	STADIUM DRIVE			P	N	2"		P	2"		SF						Installation record	Y	1962	nsp during install o	Installed after lead ban	Y	2023	Visual insp during install or repair	
900	STADIUM DRIVE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1962	nsp during install o	Field inspection only	Y		Cross-connection survey	
2467	SUN VALLEY COURT			C	N	1"		C	1"		SF						Installation record	N	1966		Field inspection only	Y		Cross-connection survey	
2455	SUN VALLEY COURT			C	N	1"		C	3/4"		SF						Installation record	N	1966		Field inspection only	Y		Cross-connection survey	
2454	SUN VALLEY COURT			C	N	1"		C	3/4"		SF						Installation record	N	1966		Field inspection only	Y		Cross-connection survey	
2460	SUN VALLEY COURT			C	N	1"		C	3/4"		SF						Installation record	N	1966		Field inspection only	Y		Cross-connection survey	
2466	SUN VALLEY COURT			C	N	1"		C	1"		SF						Installation record	N	1966		Field inspection only	Y		Cross-connection survey	
2474	SUN VALLEY COURT			C	N	1"		C	3/4"		SF						Installation record	N	1966		Field inspection only	Y		Cross-connection survey	
2480	SUN VALLEY COURT			C	N	1"		C	1"		MF						Installation record	N	1966		Field inspection only	Y		Cross-connection survey	
2482	SUN VALLEY COURT			C	N	1"		C	3/4"		MF						Installation record	N	1966		Field inspection only	Y		Cross-connection survey	
2490	SUN VALLEY COURT			C	N	1"		C	1"		MF						Installation record	N	1966		Field inspection only	Y		Cross-connection survey	
2492	SUN VALLEY COURT			C	N	1"		C	1"		MF						Installation record	N	1966		Field inspection only	Y		Cross-connection survey	
2494	SUN VALLEY COURT			C	N	1"		C	3/4"		SF						Installation record	N	1966		Field inspection only	Y		Cross-connection survey	
2495	SUN VALLEY COURT			C	N	1"		C	3/4"		SF						Installation record	N	1966		Field inspection only	Y		Cross-connection survey	
2491	SUN VALLEY COURT			C	N	1"		C	3/4"		MF						Installation record	N	1966		Field inspection only	Y		Cross-connection survey	
2489	SUN VALLEY COURT			C	N	1"		C	3/4"		MF						Installation record	N	1966		Field inspection only	Y		Cross-connection survey	
2485	SUN VALLEY COURT			C	N	1"		C	3/4"		MF						Installation record	N	1966		Field inspection only	Y		Cross-connection survey	
2483	SUN VALLEY COURT			C	N	1"		C	3/4"		MF						Installation record	N	1966		Field inspection only	Y		Cross-connection survey	
2475	SUN VALLEY COURT			C	N	1"		C	3/4"		MF						Installation record	N	1966		Field inspection only	Y		Cross-connection survey	
2473	SUN VALLEY COURT			C	N	1"		C	3/4"		MF						Installation record	N	1966		Field inspection only	Y		Cross-connection survey	
2461	SUN VALLEY COURT			P	N	1"		C	3/4"		SF						Installation record	N	1966		Field inspection only	Y		Cross-connection survey	
1243	SUNNY CREEK DRIVE			C	N	1"		C	1"		SF						Installed after lead ban	Y	1987	nsp during install o	Field inspection only	Y		Cross-connection survey	
1303	SUNNY CREEK DRIVE			C	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1987	nsp during install o	Installed after lead ban	N			
1228	SUNNY CREEK DRIVE			C	N	1"		C	1"		SF						Installed after lead ban	Y	1987	nsp during install o	Installed after lead ban	N			
1209	SUNNY CREEK DRIVE			C	N	1"		C	1"		SF						Installed after lead ban	Y	1987	nsp during install o	Installed after lead ban	N			
1213	SUNNY CREEK DRIVE			C	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1987	nsp during install o	Installed after lead ban	N			
1221	SUNNY CREEK DRIVE			C	N	1"		C	1"		SF						Installed after lead ban	Y	1987	nsp during install o	Installed after lead ban	N			
1229	SUNNY CREEK DRIVE			C	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1987	nsp during install o	Installed after lead ban	N			
1237	SUNNY CREEK DRIVE			C	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1987	nsp during install o	Installed after lead ban	N			
1251	SUNNY CREEK DRIVE			C	N	1"		C	1"		SF						Installed after lead ban	Y	1987	nsp during install o	Field inspection only	Y		Cross-connection survey	
1259	SUNNY CREEK DRIVE			C	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1987	nsp during install o	Installed after lead ban	N			
1265	SUNNY CREEK DRIVE			C	N	1"		C	1"		SF						Installed after lead ban	Y	1987	nsp during install o	Field inspection only	Y		Cross-connection survey	
1273	SUNNY CREEK DRIVE			C	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1987	nsp during install o	Installed after lead ban	N			
1279	SUNNY CREEK DRIVE			C	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1987	nsp during install o	Installed after lead ban	N			
1285	SUNNY CREEK DRIVE			C	N	1"		C	3/4"		SF						Installed after lead ban	Y	1987	nsp during install o	Field inspection only	Y		Cross-connection survey	
1293	SUNNY CREEK DRIVE			C	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1987	nsp during install o	Installed after lead ban	N			
1307	SUNNY CREEK DRIVE			C	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1987	nsp during install o	Installed after lead ban	N			
1311	SUNNY CREEK DRIVE			C	N	1"		C	1"		SF						Installed after lead ban	Y	1987	nsp during install o	Field inspection only	Y		Cross-connection survey	
1304	SUNNY CREEK DRIVE			C	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1987	nsp during install o	Installed after lead ban	N			
1292	SUNNY CREEK DRIVE			C	N	1"		C	1"		SF						Installed after lead ban	Y	1987	nsp during install o	Field inspection only	Y		Cross-connection survey	
1274	SUNNY CREEK DRIVE			C	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1987	nsp during install o	Installed after lead ban	N			
1264	SUNNY CREEK DRIVE			C	N	1"		C	3/4"		SF						Installed after lead ban	Y	1987	nsp during install o	Field inspection only	Y		Cross-connection survey	
1258	SUNNY CREEK DRIVE			C	N	1"		C	1"		SF						Installed after lead ban	Y	1987	nsp during install o	Installed after lead ban	N			
1250	SUNNY CREEK DRIVE			C	N	1"		C	1"		SF						Installed after lead ban	Y	1987	nsp during install o	Field inspection only	Y		Cross-connection survey	
1244	SUNNY CREEK DRIVE			C	N	1"		C	3/4"		SF						Installed after lead ban	Y	1987	nsp during install o	Field inspection only	Y		Cross-connection survey	
1236	SUNNY CREEK DRIVE			C	N	1"		C	1"		SF						Installed after lead ban	Y	1987	nsp during install o	Field inspection only	Y		Cross-connection survey	
1135	SUNNY HILL COURT			C	N	1"		C	3/4"		SF						Installed after lead ban	Y	1987	nsp during install o	Field inspection only	Y		Cross-connection survey	
1110	SUNNY HILL COURT			C	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1987	nsp during install o	Installed after lead ban	N			
1114	SUNNY HILL COURT			C	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1987	nsp during install o	Installed after lead ban	N			
1122	SUNNY HILL COURT			C	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1987	nsp during install o	Installed after lead ban	N			
1130	SUNNY HILL COURT			C	N	1"		C	3/4"		SF						Installed after lead ban	Y	1987	nsp during install o	Field inspection only	Y		Cross-connection survey	
1134	SUNNY HILL COURT			C	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1987	nsp during install o	Installed after lead ban	N			
1131	SUNNY HILL COURT			C	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1987	nsp during install o	Installed after lead ban	N			
1123	SUNNY HILL COURT			C	N	1"		C	1"		SF						Installed after lead ban	Y	1987	nsp during install o	Field inspection only	Y		Cross-connection survey	
1115	SUNNY HILL COURT			C	N	1"		C	1"		SF						Installed after lead ban	Y	1987	nsp during install o	Field inspection only	Y		Cross-connection survey	
1109	SUNNY HILL COURT			C	N	1"		C	3/4"		SF						Installed after lead ban	Y	1987	nsp during install o	Field inspection only	Y		Cross-connection survey	
1211	SWAN COURT			C	N	1"		C	3/4"		SF						Installation record	Y	1975	nsp during install o	Field inspection only	Y		Cross-connection survey	
1236	SWAN COURT			C	N	1"		UNK-NOLG			SF						Installation record	Y	1975	nsp during install o	Installation record	N			
1259	SWAN COURT			C	N	1"		C	3/4"		SF						Installation record	Y	1975	nsp during install o	Field inspection only	Y		Cross-connection survey	
1251	SWAN COURT			C	N	1"		UNK-NOLG			SF						Installation record	Y	1975	nsp during install o	Installation record	N			
1243	SWAN COURT			C	N	1"		UNK-NOLG			SF						Installation record	Y	1975	nsp during install o	Installation record	N			
1237	SWAN COURT			C	N	1"		C	3/4"		SF						Installation record	Y	1975	nsp during install o	Field inspection only	Y		Cross-connection survey	
1231	SWAN COURT			C	N	1"		UNK-NOLG			SF						Installation record	Y	1975	nsp during install o	Installation record	N			
1223	SWAN COURT			C	N	1"		UNK-NOLG			SF						Installation record	Y	1975	nsp during install o	Installation record	N			
1219	SWAN COURT			C	N	1"		UNK-NOLG			SF						Installation record	Y	1975	nsp during install o	Installation record	N			

LOCATIONAL IDENTIFIER ADDRESS	LOCATIONAL IDENTIFIER STREET NAME	LOCATIONAL IDENTIFIER UNIT OR SUITE #	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
1212	SWAN COURT			C	N	1"		C	1"		SF						Installation record	Y	1975	nsp during install o	Installation record	N			
1216	SWAN COURT			C	N	1"		C	1"		SF						Installation record	Y	1975	nsp during install o	Field inspection only	Y		Cross-connection survey	
1224	SWAN COURT			C	N	1"		UNK-NOLG			SF						Installation record	Y	1975	nsp during install o	Installation record	N			
1230	SWAN COURT			C	N	1"		C	3/4"		SF						Installation record	Y	1975	nsp during install o	Field inspection only	Y		Cross-connection survey	
1242	SWAN COURT			C	N	1"		P	1"		SF						Installation record	Y	1975	nsp during install o	Field inspection only	Y		Cross-connection survey	
1250	SWAN COURT			C	N	1"		UNK-NOLG			SF						Installation record	Y	1975	nsp during install o	Installation record	N			
2110	SWEETWATER COURT			C	N	1"		C	1"		SF						Installed after lead ban	Y	1993	nsp during install o	Field inspection only	Y		Cross-connection survey	
2130	SWEETWATER COURT			C	N	1"		C	1"		SF						Installed after lead ban	Y	1993	nsp during install o	Field inspection only	Y		Cross-connection survey	
2131	SWEETWATER COURT			C	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1993	nsp during install o	Installed after lead ban	N			
2131	SWEETWATER COURT			C	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1993	nsp during install o	Installed after lead ban	N			
2121	SWEETWATER COURT			C	N	1"		P	1"		SF						Installed after lead ban	Y	1993	nsp during install o	Field inspection only	Y		Cross-connection survey	
2120	SWEETWATER COURT			C	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1993	nsp during install o	Installed after lead ban	N			
2691	TAMARACK CIRCLE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1971	nsp during install o	Installation record	N			
2690	TAMARACK CIRCLE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1971	nsp during install o	Field inspection only	Y		Cross-connection survey	
2685	TAMARACK CIRCLE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1971	nsp during install o	Installation record	N			
2684	TAMARACK CIRCLE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1971	nsp during install o	Field inspection only	Y		Cross-connection survey	
1818	TAS SHA COURT			P	N	1"		P	1"		SF						Installed after lead ban	Y	1999	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1861	TAS SHA COURT			P	N	1"		P	1"		SF						Installed after lead ban	Y	1999	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1860	TAS SHA COURT			P	N	1"		P	1"		SF						Installed after lead ban	Y	1999	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1789	TAS SHA COURT			P	N	1"		P	1"		SF						Installed after lead ban	Y	1999	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1823	TAS SHA COURT			P	N	1"		P	1"		SF						Installed after lead ban	Y	1999	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1869	TAS SHA COURT			P	N	1"		P	1"		SF						Installed after lead ban	Y	1999	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1530	TEMPLE MORE LANE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1996	nsp during install o	Installed after lead ban	N			
1535	TEMPLE MORE LANE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1996	nsp during install o	Installed after lead ban	N			
1500	TEMPLE MORE LANE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1996	nsp during install o	Installed after lead ban	N			
1510	TEMPLE MORE LANE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1996	nsp during install o	Installed after lead ban	N			
1514	TEMPLE MORE LANE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1996	nsp during install o	Installed after lead ban	N			
1520	TEMPLE MORE LANE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1996	nsp during install o	Installed after lead ban	N			
1525	TEMPLE MORE LANE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1996	nsp during install o	Installed after lead ban	N			
1521	TEMPLE MORE LANE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1996	nsp during install o	Installed after lead ban	N			
1511	TEMPLE MORE LANE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1996	nsp during install o	Installed after lead ban	N			
1507	TEMPLE MORE LANE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1996	nsp during install o	Installed after lead ban	N			
1166	THUNDERBYRD COURT			P	N	1"		C	1"		SF						Installation record	Y	1976		Field inspection only	Y		Cross-connection survey	
1170	THUNDERBYRD COURT			P	N	1"		C	1"		SF						Installation record	Y	1976		Field inspection only	Y		Cross-connection survey	
1171	THUNDERBYRD COURT			P	N	1"		UNK-NOLG			SF						Installation record	Y	1976		Installation record	N			
1165	THUNDERBYRD COURT			P	N	1"		UNK-NOLG			SF						Installation record	Y	1976		Installation record	N			
1159	THUNDERBYRD COURT			P	N	1"		C	1"		SF						Installation record	Y	1976		Field inspection only	Y			
2907	THUNDERBYRD TRAIL			P	N	1"		C	1"		SF						Installation record	Y	1976		Field inspection only	Y			
2941	THUNDERBYRD TRAIL			P	N	1"		C	1"		SF						Installed after lead ban	Y	1988		Installed after lead ban	N			
2974	THUNDERBYRD TRAIL			P	N	1"		C	3/4"		SF						Installed after lead ban	Y	1988		Field inspection only	Y		Cross-connection survey	
2906	THUNDERBYRD TRAIL			P	N	1"		UNK-NOLG			SF						Installation record	Y	1976		Installation record	N			
2910	THUNDERBYRD TRAIL			P	N	1"		UNK-NOLG			SF						Installation record	Y	1976		Installation record	N			
2969	THUNDERBYRD TRAIL			C	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1988		Installed after lead ban	N			
2961	THUNDERBYRD TRAIL			C	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1988		Installed after lead ban	N			
2955	THUNDERBYRD TRAIL			C	N	1"		C	1"		SF						Installed after lead ban	Y	1988		Field inspection only	Y		Cross-connection survey	
2947	THUNDERBYRD TRAIL			C	N	1"		C	3/4"		SF						Installed after lead ban	Y	1988		Field inspection only	Y		Cross-connection survey	
2933	THUNDERBYRD TRAIL			C	N	1"		C	1"		SF						Installed after lead ban	Y	1988		Installed after lead ban	N			
2923	THUNDERBYRD TRAIL			C	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1988	nsp during install o	Installed after lead ban	N			
2920	THUNDERBYRD TRAIL			C	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1988	nsp during install o	Installed after lead ban	N			
2940	THUNDERBYRD TRAIL			C	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1988	nsp during install o	Installed after lead ban	N			
2960	THUNDERBYRD TRAIL			C	N	1"		C	1"		SF						Installed after lead ban	Y	1988	nsp during install o	Field inspection only	Y		Cross-connection survey	
2968	THUNDERBYRD TRAIL			C	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1988	nsp during install o	Installed after lead ban	N			
2980	THUNDERBYRD TRAIL			C	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1988	nsp during install o	Installed after lead ban	N			
2811	TIMBER LANE			C	N	1"		C	3/4"		SF						Installation record	Y	1969	nsp during install o	Field inspection only	Y		Cross-connection survey	
2909	TIMBER LANE			C	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1988	nsp during install o	Installed after lead ban	N			
2727	TIMBER LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1966	nsp during install o	Installation record	N			
2692	TIMBER LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1966	nsp during install o	Installation record	N			
2663	TIMBER LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1966	nsp during install o	Installation record	N			
2853	TIMBER LANE			C	N	1"		C	1"		SF						Installation record	Y	1966	nsp during install o	Field inspection only	Y		Cross-connection survey	
2759	TIMBER LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1966	nsp during install o	Installation record	N			
2777	TIMBER LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1966	nsp during install o	Installation record	N			
2787	TIMBER LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1966	nsp during install o	Installation record	N			
2817	TIMBER LANE			C	N	1"		UNK-NOLG			SF						Installation record	Y	1966	nsp during install o	Installation record	N			
2825	TIMBER LANE			C	N	1"		C	3/4"		SF						Installation record	Y	1966	nsp during install o	Field inspection only	Y		Cross-connection survey	
2831	TIMBER LANE			C	N	1"		C	3/4"		SF						Installation record	Y	1966	nsp during install o	Field inspection only	Y		Cross-connection survey	
2839	TIMBER LANE			C	N	1"		UNK-NOLG			SF						Installation record	Y	1966	nsp during install o	Installation record	N			
2847	TIMBER LANE			C	N	1"		C	1"		SF						Installation record	Y	1966	nsp during install o	Field inspection only	Y		Cross-connection survey	
2861	TIMBER LANE			C	N	1"		UNK-NOLG			SF						Installation record	Y	1966	nsp during install o	Installation record	N			
2654	TIMBER LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1966	nsp during install o	Field inspection only	Y		Cross-connection survey	
2662	TIMBER LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1966	nsp during install o	Installation record	N			
2670	TIMBER LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1966	nsp during install o	Installation record	N			
2678	TIMBER LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1966	nsp during install o	Field inspection only	Y		Cross-connection survey	
2684	TIMBER LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1966	nsp during install o	Installation record	N			
2700	TIMBER LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1966	nsp during install o	Installation record	N			
2710	TIMBER LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1966	nsp during install o	Installation record	N			
2720	TIMBER LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1966	nsp during install o	Field inspection only	Y		Cross-connection survey	
2780	TIMBER LANE			C	N	3/4"		C	1"		SF						Installation record	Y	1966	nsp during install o	Field inspection only	Y		Cross-connection survey	
2790	TIMBER LANE			C	N	3/4"		C	1"		SF						Installation record	Y	1966	nsp during install o	Field inspection only	Y		Cross-connection survey	
2941	TIMBER LANE			C	N	1"		UNK-NOLG			SF						Installation record	Y	1966	nsp during install o	Installation record	N			
2824	TIMBER LANE			C	N	1"		UNK-NOLG			SF						Installation record	Y	1966	nsp during install o	Installation record	N			
2830	TIMBER LANE			C	N	1"		C	1"		SF						Installation record	Y	1966	nsp during install o	Field inspection only	Y		Cross-connection survey	
2850	TIMBER LANE			C	N	1"		UNK-NOLG			SF						Installation record	Y	1966	nsp during install o	Installation record	N			
2723	TIMBER LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1966	nsp during install o	Installation record	N			
2715	TIMBER LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1966	nsp during install o	Installation record	N			
2703	TIMBER LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1966	nsp during install o	Installation record	N			

LOCATIONAL IDENTIFIER ADDRESS	LOCATIONAL IDENTIFIER STREET NAME	LOCATIONAL IDENTIFIER UNIT OR SUITE #	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
2693	TIMBER LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1966	nsp during install o	Installation record	N			
2687	TIMBER LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1966	nsp during install o	Installation record	N			
2675	TIMBER LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1966	nsp during install o	Installation record	N			
2671	TIMBER LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1966	nsp during install o	Field inspection only	Y		Cross-connection survey	
2655	TIMBER LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1966	nsp during install o	Installation record	N			
2951	TIMBER LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1966	nsp during install o	Field inspection only	Y		Cross-connection survey	
2957	TIMBER LANE			C	N	3/4"		C	3/4"		SF						Installed after lead ban	Y	1988	nsp during install o	Field inspection only	Y		Cross-connection survey	
2891	TIMBER LANE			C	N	1"		UNK-NOLG			SF						Installation record	Y	1966	nsp during install o	Installation record	N			
2070	TRISSINO WAY			C	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1987	nsp during install o	Installed after lead ban	N			
2051	TRISSINO WAY			C	N	1"		C	1"		SF						Installed after lead ban	Y	1987	nsp during install o	Field inspection only	Y		Cross-connection survey	
2106	TRISSINO WAY			C	N	1"		C	3/4"		SF						Installed after lead ban	Y	1987	nsp during install o	Field inspection only	Y		Cross-connection survey	
2101	TRISSINO WAY			C	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1987	nsp during install o	Installed after lead ban	N			
2131	TRISSINO WAY			C	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1987	nsp during install o	Installed after lead ban	N			
2100	TRISSINO WAY			C	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1987	nsp during install o	Installed after lead ban	N			
2020	TRISSINO WAY			C	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1987	nsp during install o	Installed after lead ban	N			
2024	TRISSINO WAY			C	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1987	nsp during install o	Installed after lead ban	N			
2036	TRISSINO WAY			C	N	1"		C	1"		SF						Installed after lead ban	Y	1987	nsp during install o	Field inspection only	Y		Cross-connection survey	
2044	TRISSINO WAY			C	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1987	nsp during install o	Installed after lead ban	N			
2050	TRISSINO WAY			C	N	1"		C	1"		SF						Installed after lead ban	Y	1987	nsp during install o	Installed after lead ban	N			
2060	TRISSINO WAY			C	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1987	nsp during install o	Installed after lead ban	N			
2080	TRISSINO WAY			C	N	1"		C	3/4"		SF						Installed after lead ban	Y	1987	nsp during install o	Field inspection only	Y		Cross-connection survey	
2090	TRISSINO WAY			C	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1987	nsp during install o	Installed after lead ban	N			
2120	TRISSINO WAY			C	N	1"		P	1"		SF						Installed after lead ban	Y	1987	nsp during install o	Field inspection only	Y		Cross-connection survey	
2115	TRISSINO WAY			C	N	1"		P	1"		SF						Installed after lead ban	Y	1987	nsp during install o	Field inspection only	Y		Cross-connection survey	
2109	TRISSINO WAY			C	N	1"		C	1"		SF						Installed after lead ban	Y	1987	nsp during install o	Installed after lead ban	N			
2085	TRISSINO WAY			C	N	1"		C	1"		SF						Installed after lead ban	Y	1987	nsp during install o	Field inspection only	Y		Cross-connection survey	
2079	TRISSINO WAY			C	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1987	nsp during install o	Installed after lead ban	N			
2071	TRISSINO WAY			C	N	1"		C	1"		SF						Installed after lead ban	Y	1987	nsp during install o	Field inspection only	Y		Cross-connection survey	
2065	TRISSINO WAY			C	N	1"		C	3/4"		SF						Installed after lead ban	Y	1987	nsp during install o	Field inspection only	Y		Cross-connection survey	
2059	TRISSINO WAY			C	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1987	nsp during install o	Installed after lead ban	N			
2043	TRISSINO WAY			C	N	1"		C	3/4"		SF						Installed after lead ban	Y	1987	nsp during install o	Field inspection only	Y		Cross-connection survey	
2035	TRISSINO WAY			C	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1987	nsp during install o	Installed after lead ban	N			
2029	TRISSINO WAY			C	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1987	nsp during install o	Installed after lead ban	N			
2017	TRISSINO WAY			C	N	1"		C	1"		SF						Installed after lead ban	Y	1987	nsp during install o	Field inspection only	Y		Cross-connection survey	
2055	TRUE LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1962	nsp during install o	Installation record	N			
2090	TRUE LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1962	nsp during install o	Installation record	N			
2066	TRUE LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1962	nsp during install o	Installation record	N			
2061	TRUE LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1962	nsp during install o	Installation record	N			
2067	TRUE LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1962	nsp during install o	Installation record	N			
2077	TRUE LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1962	nsp during install o	Installation record	N			
2076	TRUE LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1962	nsp during install o	Installation record	N			
2098	TRUE LANE			C	N	3/4"		C	5/8"		SF						Installation record	Y	1962	nsp during install o	Field inspection only	Y		Cross-connection survey	
2116	TRUE LANE			C	N	1"		C	3/4"		MF						Installation record	Y	1962	nsp during install o	Field inspection only	Y		Cross-connection survey	
2118	TRUE LANE			C	N	1"		C	3/4"		MF						Installation record	Y	1962	nsp during install o	Field inspection only	Y		Cross-connection survey	
2126	TRUE LANE			C	N	1"		C	1"		MF						Installation record	Y	1962	nsp during install o	Field inspection only	Y		Cross-connection survey	
2128	TRUE LANE			C	N	1"		C	1"		MF						Installation record	Y	1962	nsp during install o	Field inspection only	Y		Cross-connection survey	
2140	TRUE LANE			C	N	1"		UNK-NOLG			MF						Installation record	Y	1962	nsp during install o	Installation record	N			
2142	TRUE LANE			C	N	1"		UNK-NOLG			MF						Installation record	Y	1962	nsp during install o	Installation record	N			
2150	TRUE LANE			C	N	1"		C	3/4"		MF						Installation record	Y	1962	nsp during install o	Field inspection only	Y		Cross-connection survey	
2152	TRUE LANE			C	N	1"		C	3/4"		MF						Installation record	Y	1962	nsp during install o	Field inspection only	Y		Cross-connection survey	
2168	TRUE LANE			C	N	1"		C	1"		MF						Installation record	Y	1962	nsp during install o	Field inspection only	Y		Cross-connection survey	
2170	TRUE LANE			C	N	1"		C	3/4"		MF						Installation record	Y	1962	nsp during install o	Field inspection only	Y		Cross-connection survey	
2149	TRUE LANE			C	N	1"		UNK-NOLG			MF						Installation record	Y	1962	nsp during install o	Installation record	N			
2147	TRUE LANE			C	N	1"		UNK-NOLG			MF						Installation record	Y	1962	nsp during install o	Installation record	N			
2145	TRUE LANE			C	N	1"		UNK-NOLG			MF						Installation record	Y	1962	nsp during install o	Installation record	N			
2143	TRUE LANE			C	N	1"		UNK-NOLG			MF						Installation record	Y	1962	nsp during install o	Installation record	N			
2153	TRUE LANE			C	N	1"		C	3/4"		MF						Installation record	Y	1962	nsp during install o	Field inspection only	Y		Cross-connection survey	
2155	TRUE LANE			C	N	1"		C	1"		MF						Installation record	Y	1962	nsp during install o	Field inspection only	Y		Cross-connection survey	
2163	TRUE LANE			C	N	1"		UNK-NOLG			MF						Installation record	Y	1962	nsp during install o	Installation record	N			
2165	TRUE LANE			C	N	1"		UNK-NOLG			MF						Installation record	Y	1962	nsp during install o	Installation record	N			
2173	TRUE LANE			C	N	1"		C	3/4"		MF						Installation record	Y	1962	nsp during install o	Field inspection only	Y		Cross-connection survey	
2175	TRUE LANE			C	N	1"		C	3/4"		MF						Installation record	Y	1962	nsp during install o	Field inspection only	Y		Cross-connection survey	
2178	TRUE LANE			C	N	1"		UNK-NOLG			MF						Installation record	Y	1962	nsp during install o	Installation record	N			
1990	TRUE LANE			C	N	1"		UNK-NOLG			MF						Installation record	Y	1962	nsp during install o	Installation record	N			
1992	TRUE LANE			C	N	1"		UNK-NOLG			MF						Installation record	Y	1962	nsp during install o	Installation record	N			
1996	TRUE LANE			C	N	3/4"		C	1"		SF						Installation record	Y	1962	nsp during install o	Field inspection only	Y		Cross-connection survey	
2016	TRUE LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1962	nsp during install o	Field inspection only	Y		Cross-connection survey	
2014	TRUE LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1962	nsp during install o	Field inspection only	Y		Cross-connection survey	
2017	TRUE LANE				N	3/4"		UNK-NOLG			SF						Installation record	Y	1962	nsp during install o	Installation record	N			
2021	TRUE LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1962	nsp during install o	Field inspection only	Y		Cross-connection survey	
2040	TRUE LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1962	nsp during install o	Field inspection only	Y		Cross-connection survey	
2029	TRUE LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1962	nsp during install o	Field inspection only	Y		Cross-connection survey	
2035	TRUE LANE			C	N	3/4"		C	1"		SF						Installation record	Y	1962	nsp during install o	Field inspection only	Y		Cross-connection survey	
2043	TRUE LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1962	nsp during install o	Field inspection only	Y		Cross-connection survey	
2053	TRUE LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1962	nsp during install o	Field inspection only	Y		Cross-connection survey	
2050	TRUE LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1962	nsp during install o	Field inspection only	Y		Cross-connection survey	
1082	VALLEY VIEW ROAD			C	N	3/4"		C	3/4"		SF						Installation record	Y	1966	nsp during install o	Field inspection only	Y		Cross-connection survey	
1281	VALLEY VIEW ROAD			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1966	nsp during install o	Installation record	N			
1061	VALLEY VIEW ROAD			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1966	nsp during install o	Installation record	N			
1107	VALLEY VIEW ROAD			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1966	nsp during install o	Installation record	N			
1320	VALLEY VIEW ROAD			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1966	nsp during install o	Installation record	N			
1134	VALLEY VIEW ROAD			C	N	3/4"		C	1"		SF						Installation record	Y	1966	nsp during install o	Field inspection only	Y		Cross-connection survey	
1210	VALLEY VIEW ROAD			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1966	nsp during install o	Installation record	N			
1315	VALLEY VIEW ROAD			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1966	nsp during install o	Installation record	N			
1280	VALLEY VIEW ROAD			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1966	nsp during install o	Installation record	N			

LOCATIONAL IDENTIFIER ADDRESS	LOCATIONAL IDENTIFIER STREET NAME	LOCATIONAL IDENTIFIER UNIT OR SUITE #	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
1306	VALLEY VIEW ROAD			C	N	3/4"		C	3/4"		SF						Installation record	Y	1966	ısp during install o	Field inspection only	Y		Cross-connection survey	
1188	VALLEY VIEW ROAD			C	N	3/4"		C	3/4"		SF						Installation record	Y	1966	ısp during install o	Field inspection only	Y		Cross-connection survey	
1243	VALLEY VIEW ROAD			C	N	3/4"		C	1"		SF						Installation record	Y	1966	ısp during install o	Field inspection only	Y		Cross-connection survey	
1128	VALLEY VIEW ROAD			C	N	3/4"		C	3/4"		SF						Installation record	Y	1966	ısp during install o	Field inspection only	Y		Cross-connection survey	
1255	VALLEY VIEW ROAD			C	N	3/4"		C	1"		SF						Installation record	Y	1966	ısp during install o	Field inspection only	Y		Cross-connection survey	
1064	VALLEY VIEW ROAD			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1966	ısp during install o	Installation record	N			
1070	VALLEY VIEW ROAD			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1966	ısp during install o	Installation record	N			
1076	VALLEY VIEW ROAD			C	N	3/4"		C	1"		SF						Installation record	Y	1966	ısp during install o	Field inspection only	Y		Cross-connection survey	
1090	VALLEY VIEW ROAD			C	N	3/4"		C	3/4"		SF						Installation record	Y	1966	ısp during install o	Field inspection only	Y		Cross-connection survey	
1096	VALLEY VIEW ROAD			C	N	3/4"		C	3/4"		SF						Installation record	Y	1966	ısp during install o	Field inspection only	Y		Cross-connection survey	
1102	VALLEY VIEW ROAD			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1966	ısp during install o	Installation record	N			
1108	VALLEY VIEW ROAD			C	N	3/4"		C	3/4"		SF						Installation record	Y	1966	ısp during install o	Field inspection only	Y		Cross-connection survey	
1116	VALLEY VIEW ROAD			C	N	3/4"		C	3/4"		SF						Installation record	Y	1966	ısp during install o	Field inspection only	Y		Cross-connection survey	
1122	VALLEY VIEW ROAD			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1966	ısp during install o	Installation record	N			
1135	VALLEY VIEW ROAD			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1966	ısp during install o	Installation record	N			
1127	VALLEY VIEW ROAD			C	N	3/4"		C	3/4"		SF						Installation record	Y	1966	ısp during install o	Installation record	N			
1121	VALLEY VIEW ROAD			C	N	3/4"		C	3/4"		SF						Installation record	Y	1966	ısp during install o	Field inspection only	Y		Cross-connection survey	
1113	VALLEY VIEW ROAD			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1966	ısp during install o	Installation record	N			
1101	VALLEY VIEW ROAD			C	N	3/4"		C	3/4"		SF						Installation record	Y	1966	ısp during install o	Field inspection only	Y		Cross-connection survey	
1093	VALLEY VIEW ROAD			C	N	3/4"		C	3/4"		SF						Installation record	Y	1966	ısp during install o	Field inspection only	Y		Cross-connection survey	
1087	VALLEY VIEW ROAD			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1966	ısp during install o	Installation record	N			
1081	VALLEY VIEW ROAD			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1966	ısp during install o	Installation record	N			
1075	VALLEY VIEW ROAD			C	N	3/4"		C	1"		SF						Installation record	Y	1966	ısp during install o	Field inspection only	Y		Cross-connection survey	
1065	VALLEY VIEW ROAD			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1966	ısp during install o	Installation record	N			
1160	VALLEY VIEW ROAD			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1966	ısp during install o	Installation record	N			
1166	VALLEY VIEW ROAD			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1966	ısp during install o	Installation record	N			
1174	VALLEY VIEW ROAD			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1966	ısp during install o	Installation record	N			
1180	VALLEY VIEW ROAD			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1966	ısp during install o	Installation record	N			
1194	VALLEY VIEW ROAD			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1966	ısp during install o	Installation record	N			
1202	VALLEY VIEW ROAD			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1966	ısp during install o	Installation record	N			
1216	VALLEY VIEW ROAD			C	N	3/4"		C	3/4"		SF						Installation record	Y	1966	ısp during install o	Field inspection only	Y		Cross-connection survey	
1242	VALLEY VIEW ROAD			C	N	3/4"		C	3/4"		SF						Installation record	Y	1966	ısp during install o	Field inspection only	Y		Cross-connection survey	
1248	VALLEY VIEW ROAD			C	N	3/4"		C	3/4"		SF						Installation record	Y	1966	ısp during install o	Field inspection only	Y		Cross-connection survey	
1254	VALLEY VIEW ROAD			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1966	ısp during install o	Installation record	N			
1260	VALLEY VIEW ROAD			C	N	3/4"		C	3/4"		SF						Installation record	Y	1966	ısp during install o	Field inspection only	Y		Cross-connection survey	
1268	VALLEY VIEW ROAD			C	N	3/4"		C	3/4"		SF						Installation record	Y	1966	ısp during install o	Field inspection only	Y		Cross-connection survey	
1274	VALLEY VIEW ROAD			C	N	3/4"		C	3/4"		SF						Installation record	Y	1966	ısp during install o	Installation record	N			
1286	VALLEY VIEW ROAD			C	N	3/4"		C	3/4"		SF						Installation record	Y	1966	ısp during install o	Field inspection only	Y		Cross-connection survey	
1294	VALLEY VIEW ROAD			C	N	3/4"		C	3/4"		SF						Installation record	Y	1966	ısp during install o	Field inspection only	Y		Cross-connection survey	
1300	VALLEY VIEW ROAD			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1966	ısp during install o	Installation record	N			
1312	VALLEY VIEW ROAD			C	N	3/4"		C	1"		SF						Installation record	Y	1966	ısp during install o	Field inspection only	Y		Cross-connection survey	
1325	VALLEY VIEW ROAD			C	N	3/4"		C	3/4"		SF						Installation record	Y	1966	ısp during install o	Field inspection only	Y		Cross-connection survey	
1321	VALLEY VIEW ROAD			C	N	3/4"		C	3/4"		SF						Installation record	Y	1966	ısp during install o	Field inspection only	Y		Cross-connection survey	
1307	VALLEY VIEW ROAD			C	N	3/4"		C	3/4"		SF						Installation record	Y	1966	ısp during install o	Field inspection only	Y		Cross-connection survey	
1301	VALLEY VIEW ROAD			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1966	ısp during install o	Installation record	N			
1295	VALLEY VIEW ROAD			C	N	3/4"		C	3/4"		SF						Installation record	Y	1966	ısp during install o	Field inspection only	Y		Cross-connection survey	
1289	VALLEY VIEW ROAD			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1966	ısp during install o	Installation record	N			
1275	VALLEY VIEW ROAD			C	N	3/4"		C	3/4"		SF						Installation record	Y	1966	ısp during install o	Field inspection only	Y		Cross-connection survey	
1269	VALLEY VIEW ROAD			C	N	3/4"		C	1"		SF						Installation record	Y	1966	ısp during install o	Field inspection only	Y		Cross-connection survey	
1261	VALLEY VIEW ROAD			C	N	3/4"		C	3/4"		SF						Installation record	Y	1966	ısp during install o	Field inspection only	Y		Cross-connection survey	
1249	VALLEY VIEW ROAD			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1966	ısp during install o	Installation record	N			
1217	VALLEY VIEW ROAD			C	N	3/4"		C	3/4"		SF						Installation record	Y	1966	ısp during install o	Field inspection only	Y		Cross-connection survey	
1211	VALLEY VIEW ROAD			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1966	ısp during install o	Installation record	N			
1203	VALLEY VIEW ROAD			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1966	ısp during install o	Installation record	N			
1195	VALLEY VIEW ROAD			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1966	ısp during install o	Installation record	N			
1189	VALLEY VIEW ROAD			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1966	ısp during install o	Installation record	N			
1181	VALLEY VIEW ROAD			C	N	3/4"		C	3/4"		SF						Installation record	Y	1966	ısp during install o	Field inspection only	Y		Cross-connection survey	
1175	VALLEY VIEW ROAD			C	N	3/4"		C	3/4"		SF						Installation record	Y	1966	ısp during install o	Field inspection only	Y		Cross-connection survey	
1167	VALLEY VIEW ROAD			C	N	3/4"		C	3/4"		SF						Installation record	Y	1966	ısp during install o	Field inspection only	Y		Cross-connection survey	
1161	VALLEY VIEW ROAD			C	N	3/4"		C	3/4"		SF						Installation record	Y	1966	ısp during install o	Field inspection only	Y		Cross-connection survey	
2444	VALLIER COURT			C	N	1"		C	1"		SF						Installation record	Y	1980	ısp during install o	Field inspection only	Y		Cross-connection survey	
2447	VALLIER COURT			C	N	1"		C	1"		SF						Installation record	Y	1980	ısp during install o	Field inspection only	Y		Cross-connection survey	
2439	VALLIER COURT			C	N	1"		C	1"		SF						Installation record	Y	1980	ısp during install o	Field inspection only	Y		Cross-connection survey	
2432	VALLIER COURT			C	N	1"		UNK-NOLG			SF						Installation record	Y	1980	ısp during install o	Installation record	N			
2438	VALLIER COURT			C	N	1"		UNK-NOLG			SF						Installation record	Y	1980	ısp during install o	Installation record	N			
478	VAN ROSSUM AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1982	ısp during install o	Field inspection only	Y		Cross-connection survey	
474	VAN ROSSUM AVENUE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1982	ısp during install o	Installation record	N			
466	VAN ROSSUM AVENUE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1982	ısp during install o	Installation record	N			
433	VAN ROSSUM AVENUE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1982	ısp during install o	Installation record	N			
428	VAN ROSSUM AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1982	ısp during install o	Field inspection only	Y		Cross-connection survey	
436	VAN ROSSUM AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1982	ısp during install o	Field inspection only	Y		Cross-connection survey	
463	VAN ROSSUM AVENUE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1982	ısp during install o	Installation record	N			
462	VAN ROSSUM AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1982	ısp during install o	Field inspection only	Y		Cross-connection survey	
3010	VERCAUTEREN DRIVE			C	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1988	ısp during install o	Installed after lead ban	N			
2995	VERCAUTEREN DRIVE			C	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1988	ısp during install o	Installed after lead ban	N			
2892	VERCAUTEREN DRIVE			C	N	1"		UNK-NOLG			SF						Installation record	Y	1977	ısp during install o	Installation record	N			
2882	VERCAUTEREN DRIVE			C	N	1"		UNK-NOLG			SF						Installation record	Y	1977	ısp during install o	Installation record	N			
2910	VERCAUTEREN DRIVE			C	N	1"		UNK-NOLG			SF						Installation record	Y	1977	ısp during install o	Installation record	N			
2911	VERCAUTEREN DRIVE			C	N	1"		UNK-NOLG			SF						Installation record	Y	1977	ısp during install o	Installation record	N			
2905	VERCAUTEREN DRIVE			C	N	1"		UNK-NOLG			SF						Installation record	Y	1977	ısp during install o	Installation record	N			
2895	VERCAUTEREN DRIVE			C	N	1"		C	1"		SF						Installation record	Y	1977	ısp during install o	Field inspection only	Y		Cross-connection survey	
2889	VERCAUTEREN DRIVE			C	N	1"		C	1"		SF						Installation record	Y	1977	ısp during install o	Field inspection only	Y		Cross-connection survey	
3015	VERCAUTEREN DRIVE			C	N	1"		C	1"		SF						Installed after lead ban	Y	1988	ısp during install o	Field inspection only	Y		Cross-connection survey	
3009	VERCAUTEREN DRIVE			C	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1988	ısp during install o	Installed after lead ban	N			
3001	VERCAUTEREN DRIVE			C	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1988	ısp during install o	Installed after lead ban	N			

LOCATIONAL IDENTIFIER ADDRESS	LOCATIONAL IDENTIFIER STREET NAME	LOCATIONAL IDENTIFIER UNIT OR SUITE #	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
2987	VERCAUTEREN DRIVE			C	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1988	nsp during install o	Installed after lead ban	N			
2981	VERCAUTEREN DRIVE			C	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1988	nsp during install o	Installed after lead ban	N			
2973	VERCAUTEREN DRIVE			C	N	1"		C	1"		SF						Installed after lead ban	Y	1988	nsp during install o	Installed after lead ban	N			
2967	VERCAUTEREN DRIVE			C	N	1"		P	1"		SF						Installed after lead ban	Y	1988	nsp during install o	Field inspection only	Y		Cross-connection survey	
2961	VERCAUTEREN DRIVE			C	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1988	nsp during install o	Installed after lead ban	N			
2951	VERCAUTEREN DRIVE			C	N	1"		P	1"		SF						Installed after lead ban	Y	1988	nsp during install o	Field inspection only	Y		Cross-connection survey	
2945	VERCAUTEREN DRIVE			C	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1988	nsp during install o	Installed after lead ban	N			
2935	VERCAUTEREN DRIVE			C	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1988	nsp during install o	Installed after lead ban	N			
2933	VERCAUTEREN DRIVE			C	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1988	nsp during install o	Installed after lead ban	N			
2929	VERCAUTEREN DRIVE			C	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1988	nsp during install o	Installed after lead ban	N			
2922	VERCAUTEREN DRIVE			C	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1988	nsp during install o	Installed after lead ban	N			
2930	VERCAUTEREN DRIVE			C	N	1"		C	1"		SF						Installed after lead ban	Y	1988	nsp during install o	Field inspection only	Y		Cross-connection survey	
2934	VERCAUTEREN DRIVE			C	N	1"		C	1"		SF						Installed after lead ban	Y	1988	nsp during install o	Field inspection only	Y		Cross-connection survey	
2940	VERCAUTEREN DRIVE			C	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1988	nsp during install o	Installed after lead ban	N			
2950	VERCAUTEREN DRIVE			C	N	1"		C	1"		SF						Installed after lead ban	Y	1988	nsp during install o	Field inspection only	Y		Cross-connection survey	
3014	VERCAUTEREN DRIVE			C	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1988	nsp during install o	Installed after lead ban	N			
3016	VERCAUTEREN DRIVE			C	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1988	nsp during install o	Installed after lead ban	N			
1700	VIEW LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1964	nsp during install o	Installation record	N			
1741	VIEW LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1964	nsp during install o	Installation record	N			
1630	VIEW LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1964	nsp during install o	Installation record	N			
1493	VIEW LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1968	nsp during install o	Field inspection only	Y		Cross-connection survey	
1701	VIEW LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1964	nsp during install o	Installation record	N			
1311	VIEW LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	nsp during install o	Installation record	N			
1425	VIEW LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	nsp during install o	Installation record	N			
1308	VIEW LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1968	nsp during install o	Field inspection only	Y		Cross-connection survey	
1651	VIEW LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1964	nsp during install o	Installation record	N			
1280	VIEW LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	nsp during install o	Installation record	N			
1481	VIEW LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	nsp during install o	Installation record	N			
1291	VIEW LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	nsp during install o	Installation record	N			
1610	VIEW LANE			C	N	3/4"		C	1"		SF						Installation record	Y	1964	nsp during install o	Installation record	N			
1760	VIEW LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1964	nsp during install o	Field inspection only	Y		Cross-connection survey	
1487	VIEW LANE			C	N	3/4"		C	1"		SF						Installation record	Y	1968	nsp during install o	Field inspection only	Y		Cross-connection survey	
1691	VIEW LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1964	nsp during install o	Installation record	N			
1317	VIEW LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	nsp during install o	Installation record	N			
1302	VIEW LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	nsp during install o	Installation record	N			
1546	VIEW LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1964	nsp during install o	Installation record	N			
1359	VIEW LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	nsp during install o	Installation record	N			
1486	VIEW LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	nsp during install o	Installation record	N			
1351	VIEW LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	nsp during install o	Installation record	N			
1320	VIEW LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	nsp during install o	Installation record	N			
1736	VIEW LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1964	nsp during install o	Field inspection only	Y		Cross-connection survey	
1618	VIEW LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1964	nsp during install o	Installation record	N			
1621	VIEW LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1964	nsp during install o	Installation record	N			
1292	VIEW LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1968	nsp during install o	Field inspection only	Y		Cross-connection survey	
1560	VIEW LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1964	nsp during install o	Installation record	N			
1730	VIEW LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1964	nsp during install o	Installation record	N			
1617	VIEW LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1964	nsp during install o	Installation record	N			
1296	VIEW LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	nsp during install o	Installation record	N			
1698	VIEW LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1964	nsp during install o	Installation record	N			
1571	VIEW LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1964	nsp during install o	Field inspection only	Y		Cross-connection survey	
1624	VIEW LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1964	nsp during install o	Installation record	N			
1391	VIEW LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	nsp during install o	Installation record	N			
1362	VIEW LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	nsp during install o	Installation record	N			
1376	VIEW LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	nsp during install o	Installation record	N			
1390	VIEW LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	nsp during install o	Installation record	N			
1480	VIEW LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	nsp during install o	Installation record	N			
1574	VIEW LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1964	nsp during install o	Installation record	N			
1600	VIEW LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1964	nsp during install o	Field inspection only	Y		Cross-connection survey	
1587	VIEW LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1964	nsp during install o	Installation record	N			
1433	VIEW LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1968	nsp during install o	Field inspection only	Y		Cross-connection survey	
1405	VIEW LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	nsp during install o	Installation record	N			
1430	VIEW LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	nsp during install o	Installation record	N			
1385	VIEW LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	nsp during install o	Installation record	N			
1552	VIEW LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1964	nsp during install o	Installation record	N			
1559	VIEW LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1964	nsp during install o	Installation record	N			
1648	VIEW LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1964	nsp during install o	Installation record	N			
1752	VIEW LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1964	nsp during install o	Installation record	N			
1377	VIEW LANE			C	N	3/4"		C	1"		SF						Installation record	Y	1968	nsp during install o	Field inspection only	Y		Cross-connection survey	
1344	VIEW LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	nsp during install o	Installation record	N			
1350	VIEW LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	nsp during install o	Installation record	N			
1345	VIEW LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	nsp during install o	Installation record	N			
1416	VIEW LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	nsp during install o	Installation record	N			
1438	VIEW LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	nsp during install o	Installation record	N			
1640	VIEW LANE			C	N	3/4"		C	1"		SF						Installation record	Y	1968	nsp during install o	Field inspection only	Y		Cross-connection survey	
1603	VIEW LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	nsp during install o	Installation record	N			
1337	VIEW LANE			C	N	3/4"		C	1"		SF						Installation record	Y	1968	nsp during install o	Field inspection only	Y		Cross-connection survey	
1305	VIEW LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	nsp during install o	Installation record	N			
1297	VIEW LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1968	nsp during install o	Field inspection only	Y		Cross-connection survey	
1370	VIEW LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	nsp during install o	Installation record	N			
1419	VIEW LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	nsp during install o	Installation record	N			
1399	VIEW LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	nsp during install o	Installation record	N			
1657	VIEW LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1964	nsp during install o	Installation record	N			
1439	VIEW LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	nsp during install o	Installation record	N			
1281	VIEW LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1968	nsp during install o	Field inspection only	Y		Cross-connection survey	
1404	VIEW LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	nsp during install o	Installation record	N			

LOCATIONAL IDENTIFIER ADDRESS	LOCATIONAL IDENTIFIER STREET NAME	LOCATIONAL IDENTIFIER UNIT OR SUITE #	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
1410	VIEW LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	nsp during install o	Installation record	N			
1566	VIEW LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1964	nsp during install o	Installation record	N			
1584	VIEW LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1964	nsp during install o	Installation record	N			
1744	VIEW LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1964	nsp during install o	Installation record	N			
1749	VIEW LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1964	nsp during install o	Installation record	N			
1693	VIEW LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1964	nsp during install o	Installation record	N			
1656	VIEW LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1964	nsp during install o	Field inspection only	Y		Cross-connection survey	
1453	VIEW LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	nsp during install o	Installation record	N			
1314	VIEW LANE			C	N	3/4"		C	1"		SF						Installation record	Y	1968	nsp during install o	Field inspection only	Y		Cross-connection survey	
1627	VIEW LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1964	nsp during install o	Installation record	N			
1413	VIEW LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	nsp during install o	Installation record	N			
1581	VIEW LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1964	nsp during install o	Installation record	N			
1759	VIEW LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1964	nsp during install o	Installation record	N			
1735	VIEW LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1964	nsp during install o	Field inspection only	Y		Cross-connection survey	
1371	VIEW LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1968	nsp during install o	Field inspection only	Y		Cross-connection survey	
1444	VIEW LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	nsp during install o	Installation record	N			
1555	VIEW LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1964	nsp during install o	Installation record	N			
1450	VIEW LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	nsp during install o	Installation record	N			
1396	VIEW LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	nsp during install o	Installation record	N			
1445	VIEW LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	nsp during install o	Installation record	N			
1601	VIEW LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1964	nsp during install o	Installation record	N			
1276	VIEW LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	nsp during install o	Installation record	N			
1602	VIEW LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1964	nsp during install o	Installation record	N			
1365	VIEW LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	nsp during install o	Installation record	N			
1358	VIEW LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	nsp during install o	Installation record	N			
1384	VIEW LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	nsp during install o	Installation record	N			
1424	VIEW LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	nsp during install o	Installation record	N			
1492	VIEW LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1968	nsp during install o	Installation record	N			
1670	VIEW LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1964	nsp during install o	Installation record	N			
1724	VIEW LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1964	nsp during install o	Field inspection only	Y		Cross-connection survey	
1671	VIEW LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1964	nsp during install o	Installation record	N			
2801	VIKING DRIVE				N	8"		C	1"		MF					This development is served by a pı	Installed after lead ban	Y		Visual insp during install o	Installed after lead ban	Y		Visual insp at meter	
2803	VIKING DRIVE				N			C	1"		MF						Installed after lead ban	Y			Installed after lead ban	Y		Visual insp at meter	
2805	VIKING DRIVE				N			C	1"		MF						Installed after lead ban	Y			Installed after lead ban	Y		Visual insp at meter	
2807	VIKING DRIVE				N			C	1"		MF						Installed after lead ban	Y			Installed after lead ban	Y		Visual insp at meter	
2837	VIKING DRIVE				N			C	1"		MF						Installed after lead ban	Y			Installed after lead ban	Y		Visual insp at meter	
2849	VIKING DRIVE				N			C	1"		MF						Installed after lead ban	Y			Installed after lead ban	Y		Visual insp at meter	
2855	VIKING DRIVE				N			C	1"		MF						Installed after lead ban	Y			Installed after lead ban	Y		Visual insp at meter	
2857	VIKING DRIVE				N			C	1"		MF						Installed after lead ban	Y			Installed after lead ban	Y		Visual insp at meter	
2847	VIKING DRIVE				N			C	1"		MF						Installed after lead ban	Y			Installed after lead ban	Y		Visual insp at meter	
2851	VIKING DRIVE				N			C	1"		MF						Installed after lead ban	Y			Installed after lead ban	Y		Visual insp at meter	
2853	VIKING DRIVE				N			C	1"		MF						Installed after lead ban	Y			Installed after lead ban	Y		Visual insp at meter	
2861	VIKING DRIVE				N			C	1"		MF						Installed after lead ban	Y			Installed after lead ban	Y		Visual insp at meter	
2867	VIKING DRIVE				N			C	1"		MF						Installed after lead ban	Y			Installed after lead ban	Y		Visual insp at meter	
2869	VIKING DRIVE				N			C	1"		MF						Installed after lead ban	Y			Installed after lead ban	Y		Visual insp at meter	
2859	VIKING DRIVE				N			C	1"		MF						Installed after lead ban	Y			Installed after lead ban	Y		Visual insp at meter	
2863	VIKING DRIVE				N			C	1"		MF						Installed after lead ban	Y			Installed after lead ban	Y		Visual insp at meter	
2865	VIKING DRIVE				N			C	1"		MF						Installed after lead ban	Y			Installed after lead ban	Y		Visual insp at meter	
2873	VIKING DRIVE				N			C	1"		MF						Installed after lead ban	Y			Installed after lead ban	Y		Visual insp at meter	
2871	VIKING DRIVE				N			C	1"		MF						Installed after lead ban	Y			Installed after lead ban	Y		Visual insp at meter	
2875	VIKING DRIVE				N			C	1"		MF						Installed after lead ban	Y			Installed after lead ban	Y		Visual insp at meter	
2873	VIKING DRIVE				N			C	1"		MF						Installed after lead ban	Y			Installed after lead ban	Y		Visual insp at meter	
2877	VIKING DRIVE				N			C	1"		MF						Installed after lead ban	Y			Installed after lead ban	Y		Visual insp at meter	
2845	VIKING DRIVE				N			C	1"		MF						Installed after lead ban	Y			Installed after lead ban	Y		Visual insp at meter	
2839	VIKING DRIVE				N			C	1"		MF						Installed after lead ban	Y			Installed after lead ban	Y		Visual insp at meter	
2841	VIKING DRIVE				N			C	1"		MF						Installed after lead ban	Y			Installed after lead ban	Y		Visual insp at meter	
2843	VIKING DRIVE				N			C	1"		MF						Installed after lead ban	Y			Installed after lead ban	Y		Visual insp at meter	
2829	VIKING DRIVE				N			C	1"		MF						Installed after lead ban	Y			Installed after lead ban	Y		Visual insp at meter	
2831	VIKING DRIVE				N			C	1"		MF						Installed after lead ban	Y			Installed after lead ban	Y		Visual insp at meter	
2835	VIKING DRIVE				N			C	1"		MF						Installed after lead ban	Y			Installed after lead ban	Y		Visual insp at meter	
2833	VIKING DRIVE				N			C	1"		MF						Installed after lead ban	Y			Installed after lead ban	Y		Visual insp at meter	
2813	VIKING DRIVE				N			C	1"		MF						Installed after lead ban	Y			Installed after lead ban	Y		Visual insp at meter	
2811	VIKING DRIVE				N			C	1"		MF						Installed after lead ban	Y			Installed after lead ban	Y		Visual insp at meter	
2809	VIKING DRIVE				N			C	1"		MF						Installed after lead ban	Y			Installed after lead ban	Y		Visual insp at meter	
2815	VIKING DRIVE				N			C	1"		MF						Installed after lead ban	Y			Installed after lead ban	Y		Visual insp at meter	
2821	VIKING DRIVE				N			C	1"		MF						Installed after lead ban	Y			Installed after lead ban	Y		Visual insp at meter	
2823	VIKING DRIVE				N			C	1"		MF						Installed after lead ban	Y			Installed after lead ban	Y		Visual insp at meter	
2817	VIKING DRIVE				N			C	1"		MF						Installed after lead ban	Y			Installed after lead ban	Y		Visual insp at meter	
2827	VIKING DRIVE				N			C	1"		MF						Installed after lead ban	Y			Installed after lead ban	Y		Visual insp at meter	
2819	VIKING DRIVE				N			C	1"		MF						Installed after lead ban	Y			Installed after lead ban	Y		Visual insp at meter	
2825	VIKING DRIVE				N			C	1"		MF						Installed after lead ban	Y			Installed after lead ban	Y		Visual insp at meter	
2837	VIKING DRIVE	Clubhouse			N			C	1"		NONRES						Installed after lead ban	Y			Installed after lead ban	Y		Visual insp at meter	
2702	VIOLET LANE			C	N	1"		UNK-NOLG			MF						Installation record	Y	1973	nsp during install o	Installation record	N			
2700	VIOLET LANE			C	N	1"		UNK-NOLG			MF						Installation record	Y	1973	nsp during install o	Installation record	N			
2664	VIOLET LANE			C	N	1"		C	3/4"		MF						Installation record	Y	1973	nsp during install o	Field inspection only	Y		Cross-connection survey	
2666	VIOLET LANE			C	N	1"		C	3/4"		MF						Installation record	Y	1973	nsp during install o	Field inspection only	Y		Cross-connection survey	
2672	VIOLET LANE			C	N	1"		C	3/4"		MF						Installation record	Y	1973	nsp during install o	Field inspection only	Y		Cross-connection survey	
2674	VIOLET LANE			C	N	1"		C	3/4"		MF						Installation record	Y	1973	nsp during install o	Field inspection only	Y		Cross-connection survey	
2680	VIOLET LANE			C	N	1"		C	1"		MF						Installation record	Y	1973	nsp during install o	Field inspection only	Y		Cross-connection survey	
2682	VIOLET LANE			C	N	1"		C	3/4"		MF						Installation record	Y	1973	nsp during install o	Field inspection only	Y		Cross-connection survey	
2686	VIOLET LANE			C	N	1"		UNK-NOLG			MF						Installation record	Y	1973	nsp during install o	Installation record	N			
2688	VIOLET LANE			C	N	1"		UNK-NOLG			MF						Installation record	Y	1973	nsp during install o	Installation record	N			
2694	VIOLET LANE			C	N	1"		C	1"		MF						Installation record	Y	1973	nsp during install o	Field inspection only	Y		Cross-connection survey	
2696	VIOLET LANE			C	N	1"		UNK-NOLG			MF						Installation record	Y	1973	nsp during install o	Installation record	N			
2691	VIOLET LANE			C	N	1"		C	3/4"		MF						Installation record	Y	1973	nsp during install o	Field inspection only	Y		Cross-connection survey	

LOCATIONAL IDENTIFIER ADDRESS	LOCATIONAL IDENTIFIER STREET NAME	LOCATIONAL IDENTIFIER UNIT OR SUITE #	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
2681	VIOLET LANE			C	N	1"		UNK-NOLG			MF						Installation record	Y	1973	nsp during install o	Installation record	N			
2652	VISSERS COURT			C	N	1"		C	1"		SF						Installation record	Y	1975	nsp during install o	Field inspection only	Y		Cross-connection survey	
2681	VISSERS COURT			C	N	1"		UNK-NOLG			SF						Installation record	Y	1975	nsp during install o	Installation record	N			
2655	VISSERS COURT			C	N	1"		UNK-NOLG			SF						Installation record	Y	1975	nsp during install o	Installation record	N			
2660	VISSERS COURT			C	N	1"		UNK-NOLG			SF						Installation record	Y	1975	nsp during install o	Installation record	N			
2666	VISSERS COURT			C	N	1"		C	1"		SF						Installation record	Y	1975	nsp during install o	Field inspection only	Y		Cross-connection survey	
2678	VISSERS COURT			C	N	1"		UNK-NOLG			SF						Installation record	Y	1975	nsp during install o	Installation record	N			
2684	VISSERS COURT			C	N	1"		C	1"		SF						Installation record	Y	1975	nsp during install o	Field inspection only	Y		Cross-connection survey	
2688	VISSERS COURT			C	N	1"		C	3/4"		SF						Installation record	Y	1975	nsp during install o	Field inspection only	Y		Cross-connection survey	
2691	VISSERS COURT			C	N	1"		UNK-NOLG			SF						Installation record	Y	1975	nsp during install o	Installation record	N			
2687	VISSERS COURT			C	N	1"		UNK-NOLG			SF						Installation record	Y	1975	nsp during install o	Installation record	N			
1580	WATERFORD COURT			P	N	1"		P	1"		SF						Installed after lead ban	Y	1993	nsp during install o	Field inspection only	Y		Cross-connection survey	
1567	WATERFORD COURT			P	N	1"		C	1"		SF						Installed after lead ban	Y	1993	nsp during install o	Field inspection only	Y		Cross-connection survey	
1560	WATERFORD COURT			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1993	nsp during install o	Installed after lead ban	N			
1525	WATERFORD COURT			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1993	nsp during install o	Installed after lead ban	N			
1540	WATERFORD COURT			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1993	nsp during install o	Installed after lead ban	N			
1570	WATERFORD COURT			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1993	nsp during install o	Installed after lead ban	N			
1530	WATERFORD COURT			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1993	nsp during install o	Installed after lead ban	N			
1550	WATERFORD COURT			P	N	1"		C	1"		SF						Installed after lead ban	Y	1993	nsp during install o	Field inspection only	Y		Cross-connection survey	
1520	WATERFORD COURT			P	N	1"		P	1"		SF						Installed after lead ban	Y	1993	nsp during install o	Field inspection only	Y		Cross-connection survey	
1561	WATERFORD COURT			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1993	nsp during install o	Installed after lead ban	N			
1554	WATERFORD COURT			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1993	nsp during install o	Installed after lead ban	N			
1431	WATERFORD DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	1993	nsp during install o	Field inspection only	Y		Cross-connection survey	
1445	WATERFORD DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	1993	nsp during install o	Field inspection only	Y		Cross-connection survey	
1481	WATERFORD DRIVE			P	N	1"		C	1"		SF						Installed after lead ban	Y	1993	nsp during install o	Field inspection only	Y		Cross-connection survey	
1505	WATERFORD DRIVE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1993	nsp during install o	Installed after lead ban	N			
1495	WATERFORD DRIVE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1993	nsp during install o	Installed after lead ban	N			
1421	WATERFORD DRIVE			P	N	1"		C	3/4"		SF						Installed after lead ban	Y	1993	nsp during install o	Field inspection only	Y		Cross-connection survey	
1461	WATERFORD DRIVE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1993	nsp during install o	Installed after lead ban	N			
1451	WATERFORD DRIVE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1993	nsp during install o	Installed after lead ban	N			
1475	WATERFORD DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	1993	nsp during install o	Field inspection only	Y		Cross-connection survey	
1467	WATERFORD DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	1993	nsp during install o	Field inspection only	Y		Cross-connection survey	
1474	WATERFORD DRIVE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1993	nsp during install o	Installed after lead ban	N			
1460	WATERFORD DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	1993	nsp during install o	Field inspection only	Y		Cross-connection survey	
1390	WATERFORD DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	1993	nsp during install o	Field inspection only	Y		Cross-connection survey	
1391	WATERFORD DRIVE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1993	nsp during install o	Installed after lead ban	N			
1430	WATERFORD DRIVE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1993	nsp during install o	Installed after lead ban	N			
1436	WATERFORD DRIVE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1993	nsp during install o	Installed after lead ban	N			
1444	WATERFORD DRIVE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1993	nsp during install o	Installed after lead ban	N			
1450	WATERFORD DRIVE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1993	nsp during install o	Installed after lead ban	N			
1466	WATERFORD DRIVE			P	N	1"		C	1"		SF						Installed after lead ban	Y	1993	nsp during install o	Field inspection only	Y		Cross-connection survey	
1480	WATERFORD DRIVE			P	N	1"		C	3/4"		SF						Installed after lead ban	Y	1993	nsp during install o	Field inspection only	Y		Cross-connection survey	
1484	WATERFORD DRIVE			P	N	1"		C	3/4"		SF						Installed after lead ban	Y	1993	nsp during install o	Field inspection only	Y		Cross-connection survey	
1488	WATERFORD DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	1993	nsp during install o	Field inspection only	Y		Cross-connection survey	
1500	WATERFORD DRIVE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1993	nsp during install o	Installed after lead ban	N			
1435	WATERFORD DRIVE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1993	nsp during install o	Installed after lead ban	N			
961	WATERMOLEN AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1959	nsp during install o	Field inspection only	Y		Cross-connection survey	
923	WATERMOLEN AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1959	nsp during install o	Field inspection only	Y		Cross-connection survey	
937	WATERMOLEN AVENUE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1959	nsp during install o	Installation record	N			
951	WATERMOLEN AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1959	nsp during install o	Field inspection only	Y		Cross-connection survey	
943	WATERMOLEN AVENUE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1959	nsp during install o	Installation record	N			
915	WATERMOLEN AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1959	nsp during install o	Field inspection only	Y		Cross-connection survey	
931	WATERMOLEN AVENUE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1959	nsp during install o	Installation record	N			
967	WATERMOLEN AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1959	nsp during install o	Field inspection only	Y		Cross-connection survey	
973	WATERMOLEN AVENUE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1959	nsp during install o	Installation record	N			
981	WATERMOLEN AVENUE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1959	nsp during install o	Installation record	N			
989	WATERMOLEN AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1959	nsp during install o	Field inspection only	Y		Cross-connection survey	
984	WATERMOLEN AVENUE			C	N	3/4"		C	1"		SF						Installation record	Y	1959	nsp during install o	Field inspection only	Y		Cross-connection survey	
976	WATERMOLEN AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1959	nsp during install o	Field inspection only	Y		Cross-connection survey	
970	WATERMOLEN AVENUE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1959	nsp during install o	Installation record	N			
960	WATERMOLEN AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1959	nsp during install o	Field inspection only	Y		Cross-connection survey	
956	WATERMOLEN AVENUE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1959	nsp during install o	Installation record	N			
950	WATERMOLEN AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1959	nsp during install o	Field inspection only	Y		Cross-connection survey	
940	WATERMOLEN AVENUE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1959	nsp during install o	Installation record	N			
930	WATERMOLEN AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1959	nsp during install o	Field inspection only	Y		Cross-connection survey	
922	WATERMOLEN AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1959	nsp during install o	Field inspection only	Y		Cross-connection survey	
916	WATERMOLEN AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1959	nsp during install o	Field inspection only	Y		Cross-connection survey	
906	WATERMOLEN AVENUE			C	N	3/4"		C	1"		SF						Installation record	Y	1959	nsp during install o	Field inspection only	Y		Cross-connection survey	
1360	WAUBE LANE			C	N	1"		P	1"		SF						Installation record	Y	1981	nsp during install o	Field inspection only	Y		Cross-connection survey	
1140	WAUBE LANE			C	N	1"		UNK-NOLG			SF						Installation record	Y	1981	nsp during install o	Installation record	N			
1346	WAUBE LANE			C	N	1"		UNK-NOLG			SF						Installation record	Y	1981	nsp during install o	Installation record	N			
1440	WAUBE LANE			C	N	1"		UNK-NOLG			SF						Installation record	Y	1981	nsp during install o	Installation record	N			
1334	WAUBE LANE			C	N	1"		C	1"		SF						Installation record	Y	1981	nsp during install o	Field inspection only	Y		Cross-connection survey	
1370	WAUBE LANE			C	N	1"		UNK-NOLG			SF						Installation record	Y	1981	nsp during install o	Installation record	N			
1428	WAUBE LANE			C	N	1"		UNK-NOLG			SF						Installation record	Y	1981	nsp during install o	Installation record	N			
1450	WAUBE LANE			C	N	1"		P	1"		SF						Installation record	Y	1981	nsp during install o	Field inspection only	Y		Cross-connection survey	
1460	WAUBE LANE			C	N	1"		UNK-NOLG			SF						Installation record	Y	1981	nsp during install o	Installation record	N			
1096	WAUBE LANE			C	N	1"		C	1"		SF						Installation record	Y	1981	nsp during install o	Field inspection only	Y		Cross-connection survey	
1116	WAUBE LANE			C	N	1"		UNK-NOLG			SF						Installation record	Y	1981	nsp during install o	Installation record	N			
1118	WAUBE LANE			C	N	1"		UNK-NOLG			SF						Installation record	Y	1981	nsp during install o	Installation record	N			
1126	WAUBE LANE			C	N	1"		C	1"		SF						Installation record	Y	1981	nsp during install o	Field inspection only	Y		Cross-connection survey	
1128	WAUBE LANE			C	N	1"		C	1"		SF						Installation record	Y	1981	nsp during install o	Field inspection only	Y		Cross-connection survey	
1132	WAUBE LANE			C	N	1"		UNK-NOLG			SF						Installation record	Y	1981	nsp during install o	Installation record	N			
1134	WAUBE LANE			C	N	1"		UNK-NOLG			SF						Installation record	Y	1981	nsp during install o	Installation record	N			
1138	WAUBE LANE			C	N	1"		UNK-NOLG			SF						Installation record	Y	1981	nsp during install o	Installation record	N			

LOCATIONAL IDENTIFIER ADDRESS	LOCATIONAL IDENTIFIER STREET NAME	LOCATIONAL IDENTIFIER UNIT OR SUITE #	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
1144	WAUBE LANE			C	N	1"		C	1"		SF						Installation record	Y	1981	nsp during install o	Field inspection only	Y		Cross-connection survey	
1146	WAUBE LANE			C	N	1"		C	1"		SF						Installation record	Y	1981	nsp during install o	Field inspection only	Y		Cross-connection survey	
1158	WAUBE LANE			C	N	1"		UNK-NOLG			SF						Installation record	Y	1981	nsp during install o	Installation record	N			
1160	WAUBE LANE	A		C	N	1"		C	1"		SF						Installation record	Y	1981	nsp during install o	Field inspection only	Y		Cross-connection survey	
1481	WESTMEATH AVENUE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1996	nsp during install o	Installed after lead ban	N			
1420	WESTMEATH AVENUE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1996	nsp during install o	Installed after lead ban	N			
1466	WESTMEATH AVENUE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1996	nsp during install o	Installed after lead ban	N			
1436	WESTMEATH AVENUE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1996	nsp during install o	Installed after lead ban	N			
1511	WESTMEATH AVENUE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1996	nsp during install o	Installed after lead ban	N			
1494	WESTMEATH AVENUE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1996	nsp during install o	Installed after lead ban	N			
1445	WESTMEATH AVENUE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1996	nsp during install o	Installed after lead ban	N			
1469	WESTMEATH AVENUE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1996	nsp during install o	Installed after lead ban	N			
1461	WESTMEATH AVENUE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1996	nsp during install o	Installed after lead ban	N			
1426	WESTMEATH AVENUE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1996	nsp during install o	Installed after lead ban	N			
1460	WESTMEATH AVENUE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1996	nsp during install o	Installed after lead ban	N			
1530	WESTMEATH AVENUE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1996	nsp during install o	Installed after lead ban	N			
1500	WESTMEATH AVENUE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1996	nsp during install o	Installed after lead ban	N			
1510	WESTMEATH AVENUE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1996	nsp during install o	Installed after lead ban	N			
1520	WESTMEATH AVENUE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1996	nsp during install o	Installed after lead ban	N			
1515	WESTMEATH AVENUE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1996	nsp during install o	Installed after lead ban	N			
1501	WESTMEATH AVENUE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1996	nsp during install o	Installed after lead ban	N			
1495	WESTMEATH AVENUE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1996	nsp during install o	Installed after lead ban	N			
1491	WESTMEATH AVENUE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1996	nsp during install o	Installed after lead ban	N			
1475	WESTMEATH AVENUE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1996	nsp during install o	Installed after lead ban	N			
1451	WESTMEATH AVENUE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1996	nsp during install o	Installed after lead ban	N			
1441	WESTMEATH AVENUE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1996	nsp during install o	Installed after lead ban	N			
1431	WESTMEATH AVENUE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1996	nsp during install o	Installed after lead ban	N			
1425	WEXFORD LANE			P	N	1"		P	1"		SF						Installed after lead ban	Y	1997	nsp during install o	Field inspection only	Y		Cross-connection survey	
1485	WEXFORD LANE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1997	nsp during install o	Installed after lead ban	N			
1432	WEXFORD LANE			P	N	1"		C	3/4"		SF						Installed after lead ban	Y	1997	nsp during install o	Field inspection only	Y		Cross-connection survey	
1435	WEXFORD LANE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1997	nsp during install o	Installed after lead ban	N			
1454	WEXFORD LANE			P	N	1"		P	1"		SF						Installed after lead ban	Y	1997	nsp during install o	Field inspection only	Y		Cross-connection survey	
1460	WEXFORD LANE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1997	nsp during install o	Installed after lead ban	N			
1445	WEXFORD LANE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1997	nsp during install o	Installed after lead ban	N			
1461	WEXFORD LANE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1997	nsp during install o	Installed after lead ban	N			
1444	WEXFORD LANE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1997	nsp during install o	Installed after lead ban	N			
1441	WEXFORD LANE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1997	nsp during install o	Installed after lead ban	N			
1471	WEXFORD LANE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1997	nsp during install o	Installed after lead ban	N			
1421	WEXFORD LANE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1997	nsp during install o	Installed after lead ban	N			
1470	WEXFORD LANE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1997	nsp during install o	Installed after lead ban	N			
1477	WEXFORD LANE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1997	nsp during install o	Installed after lead ban	N			
1440	WEXFORD LANE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1997	nsp during install o	Installed after lead ban	N			
1426	WEXFORD LANE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1997	nsp during install o	Installed after lead ban	N			
1455	WEXFORD LANE			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1997	nsp during install o	Installed after lead ban	N			
2850	WEXFORD WAY			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1997	nsp during install o	Installed after lead ban	N			
2860	WEXFORD WAY			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1997	nsp during install o	Installed after lead ban	N			
2851	WEXFORD WAY			P	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1997	nsp during install o	Installed after lead ban	N			
3513	WHITE DOVE LANE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3568	WHITE DOVE LANE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3537	WHITE DOVE LANE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3536	WHITE DOVE LANE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3544	WHITE DOVE LANE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3545	WHITE DOVE LANE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3481	WHITE DOVE LANE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3483	WHITE DOVE LANE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3529	WHITE DOVE LANE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3521	WHITE DOVE LANE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3480	WHITE DOVE LANE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3482	WHITE DOVE LANE			P	N	1"		P	1"		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3505	WHITE DOVE LANE			P	N	1"		P	1'		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3553	WHITE DOVE LANE			P	N	1"		P	1'		SF						Installed after lead ban	Y	2006	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
2077	WILDWOOD LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1961	nsp during install o	Installation record	N			
2074	WILDWOOD LANE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1961	nsp during install o	Installation record	N			
2068	WILDWOOD LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1961	nsp during install o	Field inspection only	Y		Cross-connection survey	
1505	WOODMONT WAY			C	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1987	nsp during install o	Installed after lead ban	N			
1486	WOODMONT WAY			C	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1987	nsp during install o	Installed after lead ban	N			
1487	WOODMONT WAY			C	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1987	nsp during install o	Installed after lead ban	N			
1450	WOODMONT WAY			C	N	1"		C	3/4"		SF						Installed after lead ban	Y	1987	nsp during install o	Field inspection only	Y		Cross-connection survey	
1496	WOODMONT WAY			C	N	1"		C	1"		SF						Installed after lead ban	Y	1987	nsp during install o	Field inspection only	Y		Cross-connection survey	
1480	WOODMONT WAY			C	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1987	nsp during install o	Installed after lead ban	N			
1470	WOODMONT WAY			C	N	1"		P	1"		SF						Installed after lead ban	Y	1987	nsp during install o	Field inspection only	Y		Cross-connection survey	
1460	WOODMONT WAY			C	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1987	nsp during install o	Installed after lead ban	N			
1455	WOODMONT WAY			C	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1987	nsp during install o	Installed after lead ban	N			
1497	WOODMONT WAY			C	N	1"		C	1"		SF						Installed after lead ban	Y	1987	nsp during install o	Field inspection only	Y		Cross-connection survey	
1515	WOODMONT WAY			C	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1987	nsp during install o	Installed after lead ban	N			
1525	WOODMONT WAY			C	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1987	nsp during install o	Installed after lead ban	N			
1537	WOODMONT WAY			C	N	1"		C	1"		SF						Installed after lead ban	Y	1987	nsp during install o	Field inspection only	Y		Cross-connection survey	
1545	WOODMONT WAY			C	N	1"		C	1"		SF						Installed after lead ban	Y	1987	nsp during install o	Installed after lead ban	N			
3710	WOODS EDGE WAY			P	N	1"		P	1"		SF						Installation record	Y	2013	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3717	WOODS EDGE WAY			P	N	1"		P	1"		SF						Installation record	Y	2013	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3721	WOODS EDGE WAY			P	N	1"		P	1"		SF						Installation record	Y	2013	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3703	WOODS EDGE WAY			P	N	1"		P	1"		SF						Installation record	Y	2013	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3675	WOODS EDGE WAY			P	N	1"		P	1"		SF						Installation record	Y	2013	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3647	WOODS EDGE WAY			P	N	1"		P	1"		SF						Installation record	Y	2013	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3709	WOODS EDGE WAY			P	N	1"		P	1"		SF						Installation record	Y	2013	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	

LOCATIONAL IDENTIFIER ADDRESS	LOCATIONAL IDENTIFIER STREET NAME	LOCATIONAL IDENTIFIER UNIT OR SUITE #	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
3725	WOODS EDGE WAY			P	N	1"		P	1"		SF						Installation record	Y	2013	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3706	WOODS EDGE WAY			P	N	1"		P	1"		SF						Installation record	Y	2013	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3655	WOODS EDGE WAY			P	N	1"		P	1"		SF						Installation record	Y	2013	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3681	WOODS EDGE WAY			P	N	1"		P	1"		SF						Installation record	Y	2013	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3627	WOODS EDGE WAY			P	N	1"		P	1"		SF						Installation record	Y	2013	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3689	WOODS EDGE WAY			P	N	1"		P	1"		SF						Installation record	Y	2013	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3619	WOODS EDGE WAY			P	N	1"		P	1"		SF						Installation record	Y	2013	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3635	WOODS EDGE WAY			P	N	1"		P	1"		SF						Installation record	Y	2013	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3641	WOODS EDGE WAY			P	N	1"		P	1"		SF						Installation record	Y	2013	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3702	WOODS EDGE WAY			P	N	1"		P	1"		SF						Installation record	Y	2013	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3698	WOODS EDGE WAY			P	N	1"		P	1"		SF						Installation record	Y	2013	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3729	WOODS EDGE WAY			P	N	1"		P	1"		SF						Installation record	Y	2013	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3697	WOODS EDGE WAY			P	N	1"		P	1"		SF						Installation record	Y	2013	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3661	WOODS EDGE WAY			P	N	1"		P	1"		SF						Installation record	Y	2013	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3667	WOODS EDGE WAY			P	N	1"		P	1"		SF						Installation record	Y	2013	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3745	WOODS EDGE WAY			P	N	1"		P	1"		SF						Installation record	Y	2013	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3739	WOODS EDGE WAY			P	N	1"		P	1"		SF						Installation record	Y	2013	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3733	WOODS EDGE WAY			P	N	1"		P	1"		SF						Installation record	Y	2013	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3713	WOODS EDGE WAY			P	N	1"		P	1"		SF						Installation record	Y	2013	nsp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1340	WREN LANE			C	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1988	nsp during install o	Installed after lead ban	N			
1310	WREN LANE			C	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1988	nsp during install o	Installed after lead ban	N			
1321	WREN LANE			C	N	1"		C	3/4"		SF						Installed after lead ban	Y	1988	nsp during install o	Field inspection only	Y		Cross-connection survey	
1331	WREN LANE			C	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1988	nsp during install o	Installed after lead ban	N			
1341	WREN LANE			C	N	1"		C	3/4"		SF						Installed after lead ban	Y	1988	nsp during install o	Field inspection only	Y		Cross-connection survey	
1345	WREN LANE			C	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1988	nsp during install o	Installed after lead ban	N			
1346	WREN LANE			C	N	1"		C	1"		SF						Installed after lead ban	Y	1988	nsp during install o	Field inspection only	Y		Cross-connection survey	
1330	WREN LANE			C	N	1"		C	1"		SF						Installed after lead ban	Y	1988	nsp during install o	Field inspection only	Y		Cross-connection survey	
1320	WREN LANE			C	N	1"		C	1"		SF						Installed after lead ban	Y	1988	nsp during install o	Field inspection only	Y		Cross-connection survey	
1951	AIRPORT DRIVE			P	N			P	2"		NONRES						Installation record	Y	1978	nsp during install o	Field inspection only	Y		Cross-connection survey	
1801	AIRPORT DRIVE			C	N			P	2"		NONRES						Installation record	Y	1978	nsp during install o	Field inspection only	Y		Cross-connection survey	
2077	AIRPORT DRIVE	5		C	N			C	2"		NONRES						Installation record	Y	1978	nsp during install o	Field inspection only	Y		Cross-connection survey	
1967	AIRPORT DRIVE			C	N			C	2"		NONRES						Installation record	Y	1978	nsp during install o	Field inspection only	Y		Cross-connection survey	
1965	AIRPORT DRIVE			C	N			C	1/2"		NONRES						Installation record	Y	1978	nsp during install o	Field inspection only	Y		Cross-connection survey	
1964	AIRPORT DRIVE			C	N			C	2"		NONRES						Installation record	Y	1978	nsp during install o	Field inspection only	Y		Cross-connection survey	
1921	AIRPORT DRIVE			C	N			C	1 1/2"		NONRES						Installation record	Y	1978	nsp during install o	Field inspection only	Y		Cross-connection survey	
1921	AIRPORT DRIVE			C	N			C	1 1/2"		NONRES						Installation record	Y	1978	nsp during install o	Field inspection only	Y		Cross-connection survey	
1921	AIRPORT DRIVE			C	N			C	1 1/2"		NONRES						Installation record	Y	1978	nsp during install o	Field inspection only	Y		Cross-connection survey	
2065	AIRPORT DRIVE			P	N			P	8"		NONRES					Riser is DI	Installation record	Y	1978	nsp during install o	Field inspection only	Y		Cross-connection survey	
2151	AIRPORT DRIVE			C	N			C	1"		NONRES						Installation record	Y	1978	nsp during install o	Field inspection only	Y		Cross-connection survey	
2131	AIRPORT DRIVE			C	N			C	1"		NONRES						Installation record	Y	1978	nsp during install o	Field inspection only	Y		Cross-connection survey	
2131	AIRPORT DRIVE			C	N			C	1"		NONRES						Installation record	Y	1978	nsp during install o	Field inspection only	Y		Cross-connection survey	
1931	AIRPORT DRIVE			P	N			C	1"		NONRES						Installation record	Y	1978	nsp during install o	Field inspection only	Y		Cross-connection survey	
2170	AIRPORT DRIVE			C	N			C	1"		NONRES						Installation record	Y	1978	nsp during install o	Field inspection only	Y		Cross-connection survey	
2100	AIRPORT DRIVE			C	N			C	1 1/2"		NONRES						Installation record	Y	1978	nsp during install o	Field inspection only	Y		Cross-connection survey	
2100	AIRPORT DRIVE			C	N			C	1 1/2"		NONRES						Installation record	Y	1978	nsp during install o	Field inspection only	Y		Cross-connection survey	
2020	AIRPORT DRIVE			P	N			C	3"		NONRES						Installation record	Y	1978	nsp during install o	Field inspection only	Y		Cross-connection survey	
2020	AIRPORT DRIVE			C	N			C	1"		NONRES						Installation record	Y	1978	nsp during install o	Field inspection only	Y		Cross-connection survey	
2020	AIRPORT DRIVE			P	N			C	4"		NONRES						Installation record	Y	1978	nsp during install o	Field inspection only	Y		Cross-connection survey	
2040	AIRPORT DRIVE			P	N			C	3"		NONRES						Installation record	Y	1978	nsp during install o	Field inspection only	Y		Cross-connection survey	
2040	AIRPORT DRIVE			C	N			C	1"		NONRES						Installation record	Y	1978	nsp during install o	Field inspection only	Y		Cross-connection survey	
2040	AIRPORT DRIVE			P	N			C	6"		NONRES						Installation record	Y	1978	nsp during install o	Field inspection only	Y		Cross-connection survey	
2040	AIRPORT DRIVE			P	N			C	3"		NONRES						Installation record	Y	1978	nsp during install o	Field inspection only	Y		Cross-connection survey	
2632	PACKERLAND DRIVE			C	N			C	1 1/2"		NONRES						Installation record	Y	1973	nsp during install o	Field inspection only	Y		Cross-connection survey	
2491	BABCOCK ROAD			P	N			C	1"		NONRES						Installed after lead ban	Y	2015	nsp during install o	Field inspection only	Y		Cross-connection survey	
3120	PACKERLAND DRIVE			P	N			C	1"		NONRES						Installed after lead ban	N	1993	nsp during install o	Field inspection only	Y		Cross-connection survey	
3120	PACKERLAND DRIVE	WOM		P	N			C	1"		NONRES						Installed after lead ban	N	1993	nsp during install o	Field inspection only	Y		Cross-connection survey	
3120	PACKERLAND DRIVE			P	N			C	1 1/2"		NONRES						Installed after lead ban	N	1993	nsp during install o	Field inspection only	Y		Cross-connection survey	
2555	PACKERLAND DRIVE			P	N			P	3"		NONRES						Diameter > 2 inches	N	1993	nsp during install o	Field inspection only	Y		Cross-connection survey	
2615	PACKERLAND DRIVE			P	N			C	1"		NONRES						Installed after lead ban	N	1993	nsp during install o	Field inspection only	Y		Cross-connection survey	
2077	AIRPORT DRIVE			P	N			C	1"		NONRES					Comes off 8" that goes to	Diameter > 2 inches	N			Field inspection only	Y		Cross-connection survey	
2077	AIRPORT DRIVE			P	N			C	1"		NONRES					Comes off 8" that goes to property		N			Field inspection only	Y		Cross-connection survey	
2077	AIRPORT DRIVE			P	N			C	1 1/2"		NONRES					Comes off 8" that goes to property		N			Field inspection only	Y		Cross-connection survey	
2077	AIRPORT DRIVE			P	N			C	1"		NONRES					Comes off 8" that goes to property		N			Field inspection only	Y		Cross-connection survey	
2077	AIRPORT DRIVE			P	N			C	1"		NONRES					Comes off 8" that goes to property		N			Field inspection only	Y		Cross-connection survey	
2077	AIRPORT DRIVE			P	N			C	1"		NONRES					Comes off 8" that goes to property		N			Field inspection only	Y		Cross-connection survey	
2077	AIRPORT DRIVE			P	N			C	2"		NONRES					Comes off 8" that goes to property		N			Field inspection only	Y		Cross-connection survey	
2077	AIRPORT DRIVE			P	N			C	1"		NONRES					Comes off 8" that goes to property		N			Field inspection only	Y		Cross-connection survey	
2021	AIRPORT DRIVE			P	N			C	1"		NONRES						Installed after lead ban	N	1993	nss-connection sur	Field inspection only	Y		Cross-connection survey	
417	Aldon Cl	201		P	N	8"		P	3/4"		MF					8" lateral that feeds pr	Diameter > 2 inches	Y	2021	nsp during install o	Installation record	Y		Visual insp during install or repair	
417	Aldon Cl	202		P	N			P	3/4"		MF						Installed after lead ban	Y	2021	nsp during install o	Installation record	Y		Visual insp during install or repair	
417	Aldon Cl	203		P	N			P	3/4"		MF						Installed after lead ban	Y	2021	nsp during install o	Installation record	Y		Visual insp during install or repair	
417	Aldon Cl	204		P	N			P	3/4"		MF						Installed after lead ban	Y	2021	nsp during install o	Installation record	Y		Visual insp during install or repair	
417	Aldon Cl	205		P	N			P	3/4"		MF						Installed after lead ban	Y	2021	nsp during install o	Installation record	Y		Visual insp during install or repair	
417	Aldon Cl	301		P	N			P	3/4"		MF						Installed after lead ban	Y	2021	nsp during install o	Installation record	Y		Visual insp during install or repair	
417	Aldon Cl	302		P	N			P	3/4"		MF						Installed after lead ban	Y	2021	nsp during install o	Installation record	Y		Visual insp during install or repair	
417	Aldon Cl	303		P	N			P	3/4"		MF						Installed after lead ban	Y	2021	nsp during install o	Installation record	Y		Visual insp during install or repair	
417	Aldon Cl	304		P	N			P	3/4"		MF						Installed after lead ban	Y	2021	nsp during install o	Installation record	Y		Visual insp during install or repair	
417	Aldon Cl	305		P	N			P	3/4"		MF						Installed after lead ban	Y	2021	nsp during install o	Installation record	Y		Visual insp during install or repair	
417	Aldon Cl	401		P	N			P	3/4"		MF						Installed after lead ban	Y	2021	nsp during install o	Installation record	Y		Visual insp during install or repair	
417	Aldon Cl	402		P	N			P	3/4"		MF						Installed after lead ban	Y	2021	nsp during install o	Installation record	Y		Visual insp during install or repair	
417	Aldon Cl	403		P	N			P	3/4"		MF						Installed after lead ban	Y	2021	nsp during install o	Installation record	Y		Visual insp during install or repair	
417	Aldon Cl	404		P	N			P	3/4"		MF						Installed after lead ban	Y	2021	nsp during install o	Installation record	Y		Visual insp during install or repair	
417	Aldon Cl	405		P	N			P	3/4"		MF						Installed after lead ban	Y	2021	nsp during install o	Installation record	Y		Visual insp during install or repair	
417	Aldon Cl	501		P	N			P	3/4"		MF						Installed after lead ban	Y	2021	nsp during install o	Installation record	Y		Visual insp during install or repair	
417	Aldon Cl	502		P	N			P	3/4"		MF						Installed after lead ban	Y	2021	nsp during install o	Installation record	Y		Visual insp during install or repair	

LOCATIONAL IDENTIFIER ADDRESS	LOCATIONAL IDENTIFIER STREET NAME	LOCATIONAL IDENTIFIER UNIT OR SUITE #	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
417	Aldon Cl	Whole		P	N			P	3/4"		MF						Installed after lead ban	Y	2021	nsp during install o	Installation record	Y		Visual insp during install or repair	
1314	ALICE DRIVE			C	N	2"		C	2"		MF						Installation record	Y	1967	nsp during install o	Field inspection only	Y		Cross-connection survey	
1308	ALICE DRIVE			C	N	2"		C	1"		MF						Installation record	Y	1967	nsp during install o	Field inspection only	Y		Cross-connection survey	
1302	ALICE DRIVE			C	N	2"		C	1"		MF						Installation record	Y	1967	nsp during install o	Field inspection only	Y		Cross-connection survey	
1301	ALICE DRIVE			C	N	2"		C	1"		MF						Installation record	Y	1967	nsp during install o	Field inspection only	Y		Cross-connection survey	
2979	ALLIED STREET	D		C	N			C	1"		NONRES						Installation record	N	1973		Field inspection only	Y		Cross-connection survey	
2979	ALLIED STREET	A		C	N	2"		C	1"		NONRES						Installation record	Y	1973		Field inspection only	Y		Cross-connection survey	
2979	ALLIED STREET	B		C	N			C	1"		NONRES						Installation record	N	1973		Field inspection only	Y		Cross-connection survey	
2831	ALLIED STREET			C	N			C	1"		NONRES						Installation record	N	1973		Field inspection only	Y		Cross-connection survey	
2841	ALLIED STREET	A		C	N	1 1/2"		C	1 1/2"		NONRES						Installation record	Y	1973		Field inspection only	Y		Cross-connection survey	
2841	ALLIED STREET	B		C	N			C	1"		NONRES						Installation record	N	1973		Field inspection only	Y		Cross-connection survey	
2834	ALLIED STREET	A		C	N			C	1"		NONRES						Installation record	N	1973		Field inspection only	Y		Cross-connection survey	
2834	ALLIED STREET	C		C	N			C	1"		NONRES						Installation record	N	1973		Field inspection only	Y		Cross-connection survey	
2811	ALLIED STREET			C	N			C	1"		NONRES						Installation record	N	1973		Field inspection only	Y		Cross-connection survey	
3040	ALLIED STREET			P	N	2"		P	1 1/2"		NONRES						Installation record	Y	1973		Field inspection only	Y		Cross-connection survey	
2799	ALLIED STREET			C	N			C	1"		NONRES						Installation record	N	1973		Field inspection only	Y		Cross-connection survey	
2863	ALLIED STREET	A & B		C	N			C	1"		NONRES						Installation record	N	1973		Field inspection only	Y		Cross-connection survey	
2865	ALLIED STREET			C	N			C	1 1/2"		NONRES						Installation record	N	1973		Field inspection only	Y		Cross-connection survey	
2789	ALLIED STREET			C	N	1 1/2"		C	1 1/2"		NONRES						Installation record	Y	1973		Field inspection only	Y		Cross-connection survey	
2789	ALLIED STREET			C	N			C	3/4"		NONRES						Installation record	N	1973		Field inspection only	Y		Cross-connection survey	
2929	ALLIED STREET			C	N			C	1"		NONRES						Installation record	N	1973		Field inspection only	Y		Cross-connection survey	
2929	ALLIED STREET			C	N			C	1"		NONRES						Installation record	N	1973		Field inspection only	Y		Cross-connection survey	
2777	ALLIED STREET			C	N			C	1"		NONRES						Installation record	N	1973		Field inspection only	Y		Cross-connection survey	
2945	ALLIED STREET			C	N			P	4"		NONRES						Diameter > 2 inches	N	1973		Field inspection only	Y		Cross-connection survey	
2930	ALLIED STREET			C	N			C	1 1/2"		NONRES						Installation record	N	1973		Field inspection only	Y		Cross-connection survey	
2960	ALLIED STREET			C	N			C	1"		NONRES						Installation record	N	1973		Field inspection only	Y		Cross-connection survey	
3061	ALLIED STREET	A		C	N			C	1"		NONRES						Installation record	N	1973		Field inspection only	Y		Cross-connection survey	
3061	ALLIED STREET	B		C	N			C	1"		NONRES						Installation record	N	1973		Field inspection only	Y		Cross-connection survey	
2844	ALLIED STREET	1		C	N			C	1"		NONRES						Installation record	N	1973		Field inspection only	Y		Cross-connection survey	
2761	ALLIED STREET			C	N			C	1 1/2"		NONRES						Installation record	N	1973		Field inspection only	Y		Cross-connection survey	
2821	ALLIED STREET			C	N			C	1"		NONRES						Installation record	N	1973		Field inspection only	Y		Cross-connection survey	
933	ANDERSON DRIVE	H		C	N			C	1"		NONRES				6" plastic was ran to tl		Diameter > 2 inches	Y	1973		Field inspection only	Y		Cross-connection survey	
933	ANDERSON DRIVE	L		C	N			C	3/4"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
933	ANDERSON DRIVE	E		C	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
933	ANDERSON DRIVE	J		C	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
933	ANDERSON DRIVE	K		C	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
933	ANDERSON DRIVE	A		C	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
933	ANDERSON DRIVE	F		C	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
933	ANDERSON DRIVE	D		C	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
933	ANDERSON DRIVE	C		C	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
933	ANDERSON DRIVE	G		C	N			C	3/4"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
933	ANDERSON DRIVE	I		C	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
901	ANDERSON DRIVE	A		P	N			P	1"		NONRES						Installation record	Y		Visual insp during install o	Field inspection only	Y		Cross-connection survey	
1107	ANDERSON DRIVE			P	N	8"		C	1 1/2"		MF				8" Private lateral feeds thes		Installation record	Y			Field inspection only	Y		Cross-connection survey	
1103	ANDERSON DRIVE			UNK-NOLG	N			C	1 1/2"		MF						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1099	ANDERSON DRIVE			UNK-NOLG	N			C	1 1/2"		MF						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1031	ANDERSON DRIVE			UNK-NOLG	N			C	3"		NONRES						Diameter > 2 inches	N			Field inspection only	Y		Cross-connection survey	
1051	ANDERSON DRIVE			UNK-NOLG	N			C	3"		NONRES						Diameter > 2 inches	N			Field inspection only	Y		Cross-connection survey	
2480	BAY AREA PLACE			C	N	2"		C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
1040	PILGRIM WAY			UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
1050	PILGRIM WAY			UNK-NOLG	N			C	3"		NONRES						Diameter > 2 inches	N			Field inspection only	Y		Cross-connection survey	
1060	PILGRIM WAY			UNK-NOLG	N			C	3"		NONRES						Diameter > 2 inches	N			Field inspection only	Y		Cross-connection survey	
1044	PILGRIM WAY			UNK-NOLG	N			P	4"		NONRES						Diameter > 2 inches	N			Field inspection only	Y		Cross-connection survey	
1111	ANDERSON DRIVE			UNK-NOLG	N			C	1 1/2"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
1087	ANDERSON DRIVE			UNK-NOLG	N			C	1 1/2"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
1079	ANDERSON DRIVE			UNK-NOLG	N			C	1 1/2"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
1071	ANDERSON DRIVE			UNK-NOLG	N			C	1 1/2"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1241	APACHE AVENUE			C	N	1"		C	3/4"		MF						Installation record	Y		Visual insp during install o	Field inspection only	Y		Cross-connection survey	
1240	APACHE AVENUE			C	N	1"		C	3/4"		MF						Installation record	Y		Visual insp during install o	Field inspection only	Y		Cross-connection survey	
1240	PONDEROSA AVENUE			C	N	1"		C	3/4"		MF						Installation record	Y		Visual insp during install o	Field inspection only	Y		Cross-connection survey	
1945	Argonne St			P	N	2"		P	1 1/2"		NONRES						Installation record	Y		Visual insp during install o	Field inspection only	Y		Cross-connection survey	
840	ARMED FORCES DRIVE			P	N			P	2"		NONRES						Installed after lead ban	Y	1999	nsp during install o	Field inspection only	Y		Cross-connection survey	
811	ARMED FORCES DRIVE			P	N			P	1"		NONRES						Installed after lead ban	Y	1999	nsp during install o	Field inspection only	Y		Cross-connection survey	
811	ARMED FORCES DRIVE	WOM		P	N			P	2"		NONRES						Installed after lead ban	Y	1999	nsp during install o	Field inspection only	Y		Cross-connection survey	
789	ARMED FORCES DRIVE			P	N			P	1"		NONRES						Installed after lead ban	Y	1999	nsp during install o	Field inspection only	Y		Cross-connection survey	
789	ARMED FORCES DRIVE			P	N			P	1"		NONRES						Installed after lead ban	Y	1999	nsp during install o	Field inspection only	Y		Cross-connection survey	
780	ARMED FORCES DRIVE			P	N			C	1 1/2"		NONRES						Installed after lead ban	Y	1999	nsp during install o	Field inspection only	Y		Cross-connection survey	
780	ARMED FORCES DRIVE			P	N			P	4"		NONRES						Diameter > 2 inches	Y	1999	nsp during install o	Field inspection only	Y		Cross-connection survey	
2740	S ASHLAND AVENUE			C	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
2280	S ASHLAND AVENUE			UNK-NOLG	N			C	2"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
2200	S ASHLAND AVENUE			UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
2230	S ASHLAND AVENUE	101		UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
2170	S ASHLAND AVENUE			UNK-NOLG	N			C	1 1/2"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
2770	S ASHLAND AVENUE			UNK-NOLG	N			C	3/4"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
2500	S ASHLAND AVENUE			UNK-NOLG	N			P	1 1/2"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
2502	S ASHLAND AVENUE			UNK-NOLG	N			C	1 1/2"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
2190	S ASHLAND AVENUE	A		UNK-NOLG	N			C	3/4"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
2190	S ASHLAND AVENUE	B		UNK-NOLG	N			P	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
2190	S ASHLAND AVENUE	C		UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
2290	S ASHLAND AVENUE			UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
2290	S ASHLAND AVENUE			UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
3221	MARKET STREET			UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
2700	S ASHLAND AVENUE			P	N			P	3"		NONRES						Diameter > 2 inches	Y		Visual insp during install o	Field inspection only	Y		Cross-connection survey	
2700	S ASHLAND AVENUE	WOM		P	N			P	1"		NONRES						Installation record	Y		Visual insp during install o	Field inspection only	Y		Cross-connection survey	
2650	S ASHLAND AVENUE			UNK-NOLG	N			P	2"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	

LOCATIONAL IDENTIFIER ADDRESS	LOCATIONAL IDENTIFIER STREET NAME	LOCATIONAL IDENTIFIER UNIT OR SUITE #	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
2700	S ASHLAND AVENUE			P	N			P	1 1/2"		NONRES						Installation record	Y		Visual insp during install o	Field inspection only	Y		Cross-connection survey	
2600	S ASHLAND AVENUE	B		UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
2600	S ASHLAND AVENUE	A		UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
2670	S ASHLAND AVENUE			UNK-NOLG	N			C	1 1/2"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
999	ASHWAUBENON STREET			UNK-NOLG	N	2"		C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
1286	ASHWAUBENON STREET			UNK-NOLG	N	2"		C	1 1/2"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
1260	ASHWAUBENON STREET			UNK-NOLG	N	2"		C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
1201	ASHWAUBENON STREET			UNK-NOLG	N	2"		C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
970	ASHWAUBENON STREET			UNK-NOLG	N	2"		C	1 1/4"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
1170	ASHWAUBENON STREET			UNK-NOLG	N	2"		C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
1172	ASHWAUBENON STREET			UNK-NOLG	N	2"		C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
1168	ASHWAUBENON STREET			UNK-NOLG	N	2"		C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
1164	ASHWAUBENON STREET			UNK-NOLG	N	2"		C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
1166	ASHWAUBENON STREET			UNK-NOLG	N	2"		C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
1162	ASHWAUBENON STREET			UNK-NOLG	N	2"		C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
1161	ASHWAUBENON STREET			UNK-NOLG	N	2"		C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
1180	ASHWAUBENON STREET			UNK-NOLG	N	2"		C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
1144	ASHWAUBENON STREET			UNK-NOLG	N	2"		C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
1140	ASHWAUBENON STREET			UNK-NOLG	N	2"		C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
1132	ASHWAUBENON STREET			UNK-NOLG	N	2"		C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
1107	ASHWAUBENON STREET			UNK-NOLG	N	2"		C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
1101	ASHWAUBENON STREET			UNK-NOLG	N	2"		C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
1103	ASHWAUBENON STREET			UNK-NOLG	N	2"		C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
1109	ASHWAUBENON STREET			UNK-NOLG	N	2"		C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
1111	ASHWAUBENON STREET			UNK-NOLG	N	2"		C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
1113	ASHWAUBENON STREET			UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
1115	ASHWAUBENON STREET			UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
1117	ASHWAUBENON STREET			UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
1119	ASHWAUBENON STREET			UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
1105	ASHWAUBENON STREET			UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
1200	ASHWAUBENON STREET			UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
941	ASHWAUBENON STREET	AW		DI	N			C	1"		NONRES					8" servining this proj	Installation record	Y			Field inspection only	Y		Cross-connection survey	
941	ASHWAUBENON STREET	AE		DI	N			C	1"		NONRES					8" servining this proj	Installation record	Y			Field inspection only	Y		Cross-connection survey	
941	ASHWAUBENON STREET	B		DI	N			C	1"		NONRES					8" servining this proj	Installation record	Y			Field inspection only	Y		Cross-connection survey	
941	ASHWAUBENON STREET	C		DI	N			C	1"		NONRES					8" servining this proj	Installation record	Y			Field inspection only	Y		Cross-connection survey	
941	ASHWAUBENON STREET	E		DI	N			C	1"		NONRES					8" servining this proj	Installation record	Y			Field inspection only	Y		Cross-connection survey	
941	ASHWAUBENON STREET	D		DI	N			C	1"		NONRES					8" servining this proj	Installation record	Y			Field inspection only	Y		Cross-connection survey	
941	ASHWAUBENON STREET	F		DI	N			C	1"		NONRES					8" servining this proj	Installation record	Y			Field inspection only	Y		Cross-connection survey	
941	ASHWAUBENON STREET	G		DI	N			C	1"		NONRES					8" servining this proj	Installation record	Y			Field inspection only	Y		Cross-connection survey	
951	ASHWAUBENON STREET	A		DI	N			C	1"		NONRES					8" servining this proj	Installation record	Y			Field inspection only	Y		Cross-connection survey	
951	ASHWAUBENON STREET	B		DI	N			C	1"		NONRES					8" servining this proj	Installation record	Y			Field inspection only	Y		Cross-connection survey	
951	ASHWAUBENON STREET	C		DI	N			C	1"		NONRES					8" servining this proj	Installation record	Y			Field inspection only	Y		Cross-connection survey	
951	ASHWAUBENON STREET	D		DI	N			C	1"		NONRES					8" servining this proj	Installation record	Y			Field inspection only	Y		Cross-connection survey	
963	ASHWAUBENON STREET			UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
965	ASHWAUBENON STREET			UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
1021	ASHWAUBENON STREET			UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
1023	ASHWAUBENON STREET			UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
1011	ASHWAUBENON STREET			UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
1051	ASHWAUBENON STREET			UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
1048	ASHWAUBENON STREET			UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
1037	ASHWAUBENON STREET			UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
1049	ASHWAUBENON STREET			UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
1000	ASHWAUBENON STREET			DI	N	6"		DI	6"		NONRES						Diameter > 2 inches	Y			Field inspection only	Y		Cross-connection survey	
2700	BABCOCK ROAD			C	N			C	1 1/2"		NONRES						Installation record	Y	1978		Field inspection only	Y		Cross-connection survey	
2543	BABCOCK ROAD			C	N			P	1"		NONRES						Installation record	Y	1978		Field inspection only	Y		Cross-connection survey	
2535	BABCOCK ROAD			C	N			P	1"		NONRES						Installation record	Y	1978		Field inspection only	Y		Cross-connection survey	
2482	BABCOCK ROAD			C	N			C	3/4"		NONRES						Installation record	Y	1978		Field inspection only	Y		Cross-connection survey	
2486	BABCOCK ROAD			C	N			C	3/4"		NONRES						Installation record	Y	1978		Field inspection only	Y		Cross-connection survey	
2488	BABCOCK ROAD			C	N			C	3/4"		NONRES						Installation record	Y	1978		Field inspection only	Y		Cross-connection survey	
2480	BABCOCK ROAD			C	N			C	3/4"		NONRES						Installation record	Y	1978		Field inspection only	Y		Cross-connection survey	
2530	BABCOCK ROAD			C	N	2"		P	1"		NONRES						Field inspection only	Y		Visual insp during install o	Field inspection only	Y		Cross-connection survey	
2530	BABCOCK ROAD			C	N	2"		C	2"		NONRES						Field inspection only	Y		Visual insp during install o	Field inspection only	Y		Cross-connection survey	
677	BAETEN ROAD			C	N	2"		P	1 1/2"		NONRES						Field inspection only	Y			Field inspection only	Y		Cross-connection survey	
681	BAETEN ROAD			C	N	2"		C	1 1/2"		NONRES						Field inspection only	Y			Field inspection only	Y		Cross-connection survey	
641	BAETEN ROAD			C	N	2"		C	1"		NONRES						Field inspection only	Y			Field inspection only	Y		Cross-connection survey	
595	BAETEN ROAD			C	N	2"		C	1"		NONRES						Field inspection only	Y			Field inspection only	Y		Cross-connection survey	
389	BAY PARK SQUARE			DI	N	8"		C	1"		NONRES					this property is served by a	Installation record	Y			Field inspection only	Y		Cross-connection survey	
323	BAY PARK SQUARE	B		DI	N			C	1"		NONRES					this property is served by a	Installation record	Y			Field inspection only	Y		Cross-connection survey	
323	BAY PARK SQUARE	A		DI	N			C	1"		NONRES					this property is served by a	Installation record	Y			Field inspection only	Y		Cross-connection survey	
303	BAY PARK SQUARE	WOM		DI	N			C	1"		NONRES					this property is served by a	Installation record	Y			Field inspection only	Y		Cross-connection survey	
303	BAY PARK SQUARE	WOM		DI	N			C	1"		NONRES					this property is served by a	Installation record	Y			Field inspection only	Y		Cross-connection survey	
303	BAY PARK SQUARE			DI	N			C	1"		NONRES					this property is served by a	Installation record	Y			Field inspection only	Y		Cross-connection survey	
304	BAY PARK SQUARE			DI	N			C	1 1/2"		NONRES					this property is served by a	Installation record	Y			Field inspection only	Y		Cross-connection survey	
303	BAY PARK SQUARE			DI	N			C	2"		NONRES					this property is served by a	Installation record	Y			Field inspection only	Y		Cross-connection survey	
431	BAY PARK SQUARE			DI	N			C	1"		NONRES					this property is served by a	Installation record	Y			Field inspection only	Y		Cross-connection survey	
2401	S ONEIDA STREET	FCI		P	N	6"		C	1"		NONRES						Installed after lead ban	Y	2011	nsp during install o	Field inspection only	Y		Cross-connection survey	
2401	S ONEIDA STREET	WOM		P	N	6"		C	1"		NONRES						Installed after lead ban	Y	2011	nsp during install o	Field inspection only	Y		Cross-connection survey	
2481	S ONEIDA STREET			P	N	12"		C	1"		NONRES						Installation record	Y	2011	nsp during install o	Field inspection only	Y		Cross-connection survey	
2481	S ONEIDA STREET	WOM		P	N	12"		C	1"		NONRES						Installation record	Y	2011	nsp during install o	Field inspection only	Y		Cross-connection survey	
357	BAY PARK SQUARE	B		DI	N			C	1"		NONRES					this proprty is served by a	Installation record	Y			Field inspection only	Y		Cross-connection survey	
345	BAY PARK SQUARE			DI	N			C	1"		NONRES					this proprty is served by a	Installation record	Y			Field inspection only	Y		Cross-connection survey	
922	BAY PARK SQUARE	A		DI	N			C	1"		NONRES					this proprty is served by a	Installation record	Y			Field inspection only	Y		Cross-connection survey	
101	BAY PARK SQUARE			DI	N			C	3"		NONRES					this proprty is served by a	Installation record	Y			Field inspection only	Y		Cross-connection survey	
275	BAY PARK SQUARE			DI	N			C	1"		NONRES					this proprty is served by a	Installation record	Y			Field inspection only	Y		Cross-connection survey	
269	BAY PARK SQUARE			DI	N			C	1"		NONRES					this proprty is served by a	Installation record	Y			Field inspection only	Y		Cross-connection survey	

LOCATIONAL IDENTIFIER ADDRESS	LOCATIONAL IDENTIFIER STREET NAME	LOCATIONAL IDENTIFIER UNIT OR SUITE #	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
251	BAY PARK SQUARE			DI	N			C	1"		NONRES				this proprty is served by a		Installation record	Y			Field inspection only	Y		Cross-connection survey	
241	BAY PARK SQUARE			DI	N			C	1"		NONRES				this proprty is served by a		Installation record	Y			Field inspection only	Y		Cross-connection survey	
219	BAY PARK SQUARE			DI	N			C	1"		NONRES				this proprty is served by a		Installation record	Y			Field inspection only	Y		Cross-connection survey	
211	BAY PARK SQUARE			DI	N			C	1"		NONRES				this proprty is served by a		Installation record	Y			Field inspection only	Y		Cross-connection survey	
169	BAY PARK SQUARE			DI	N			C	1"		NONRES				this proprty is served by a		Installation record	Y			Field inspection only	Y		Cross-connection survey	
151	BAY PARK SQUARE			DI	N			C	1"		NONRES				this proprty is served by a		Installation record	Y			Field inspection only	Y		Cross-connection survey	
110	BAY PARK SQUARE	A		DI	N			C	1"		NONRES				this proprty is served by a		Installation record	Y			Field inspection only	Y		Cross-connection survey	
299	BAY PARK SQUARE			DI	N			C	1"		NONRES				this proprty is served by a		Installation record	Y			Field inspection only	Y		Cross-connection survey	
233	BAY PARK SQUARE			DI	N			C	1"		NONRES				this proprty is served by a		Installation record	Y			Field inspection only	Y		Cross-connection survey	
283	BAY PARK SQUARE			DI	N			C	1"		NONRES				this proprty is served by a		Installation record	Y			Field inspection only	Y		Cross-connection survey	
317	BAY PARK SQUARE			DI	N			C	1"		NONRES				this proprty is served by a		Installation record	Y			Field inspection only	Y		Cross-connection survey	
203	BAY PARK SQUARE			DI	N			C	1"		NONRES				this proprty is served by a		Installation record	Y			Field inspection only	Y		Cross-connection survey	
197	BAY PARK SQUARE	A		DI	N			C	1"		NONRES				this proprty is served by a		Installation record	Y			Field inspection only	Y		Cross-connection survey	
165	BAY PARK SQUARE			DI	N			C	1"		NONRES				this proprty is served by a		Installation record	Y			Field inspection only	Y		Cross-connection survey	
110	BAY PARK SQUARE	B		DI	N			C	1"		NONRES				this proprty is served by a		Installation record	Y			Field inspection only	Y		Cross-connection survey	
227	BAY PARK SQUARE			DI	N			C	1"		NONRES				this proprty is served by a		Installation record	Y			Field inspection only	Y		Cross-connection survey	
191	BAY PARK SQUARE	A		DI	N			C	1"		NONRES				this proprty is served by a		Installation record	Y			Field inspection only	Y		Cross-connection survey	
669	BAY PARK SQUARE			DI	N			C	1"		NONRES				this proprty is served by a		Installation record	Y			Field inspection only	Y		Cross-connection survey	
411	BAY PARK SQUARE			DI	N			C	1"		NONRES				this proprty is served by a		Installation record	Y			Field inspection only	Y		Cross-connection survey	
683	BAY PARK SQUARE			DI	N			C	1"		NONRES				this proprty is served by a		Installation record	Y			Field inspection only	Y		Cross-connection survey	
905	BAY PARK SQUARE			DI	N			C	1"		NONRES				this proprty is served by a		Installation record	Y			Field inspection only	Y		Cross-connection survey	
383	BAY PARK SQUARE			DI	N			C	1"		NONRES				this proprty is served by a		Installation record	Y			Field inspection only	Y		Cross-connection survey	
305	BAY PARK SQUARE			DI	N			C	1"		NONRES				this proprty is served by a		Installation record	Y			Field inspection only	Y		Cross-connection survey	
651	BAY PARK SQUARE			DI	N			C	1"		NONRES				this proprty is served by a		Installation record	Y			Field inspection only	Y		Cross-connection survey	
217	BAY PARK SQUARE			DI	N			C	1"		NONRES				this proprty is served by a		Installation record	Y			Field inspection only	Y		Cross-connection survey	
215	BAY PARK SQUARE			DI	N			C	1"		NONRES				this proprty is served by a		Installation record	Y			Field inspection only	Y		Cross-connection survey	
210	BAY PARK SQUARE			DI	N			C	1"		NONRES				this proprty is served by a		Installation record	Y			Field inspection only	Y		Cross-connection survey	
207	BAY PARK SQUARE			DI	N			C	1"		NONRES				this proprty is served by a		Installation record	Y			Field inspection only	Y		Cross-connection survey	
185	BAY PARK SQUARE			DI	N			C	1"		NONRES				this proprty is served by a		Installation record	Y			Field inspection only	Y		Cross-connection survey	
0	BAY PARK SQUARE	KI15		DI	N			C	1"		NONRES				this proprty is served by a		Installation record	Y			Field inspection only	Y		Cross-connection survey	
221	BAY PARK SQUARE			DI	N			C	1"		NONRES				this proprty is served by a		Installation record	Y			Field inspection only	Y		Cross-connection survey	
205	BAY PARK SQUARE			DI	N			C	3/4"		NONRES				this proprty is served by a		Installation record	Y			Field inspection only	Y		Cross-connection survey	
209	BAY PARK SQUARE			DI	N			C	1"		NONRES				this proprty is served by a		Installation record	Y			Field inspection only	Y		Cross-connection survey	
677	BAY PARK SQUARE			DI	N			C	1"		NONRES				this proprty is served by a		Installation record	Y			Field inspection only	Y		Cross-connection survey	
669	BAY PARK SQUARE	WOM		DI	N			C	1"		NONRES				this proprty is served by a		Installation record	Y			Field inspection only	Y		Cross-connection survey	
613	BAY PARK SQUARE			DI	N			C	1"		NONRES				this proprty is served by a		Installation record	Y			Field inspection only	Y		Cross-connection survey	
500	BAY PARK SQUARE			DI	N			C	2"		NONRES				this proprty is served by a		Installation record	Y			Field inspection only	Y		Cross-connection survey	
976	BAY PARK SQUARE			DI	N			C	1 1/2"		NONRES				this proprty is served by a		Installation record	Y			Field inspection only	Y		Cross-connection survey	
311	BAY PARK SQUARE	B		DI	N			C	1 1/2"		NONRES				this proprty is served by a		Installation record	Y			Field inspection only	Y		Cross-connection survey	
1040	BAY PARK SQUARE			DI	N			C	1"		NONRES				this proprty is served by a		Installation record	Y			Field inspection only	Y		Cross-connection survey	
201	BAY PARK SQUARE			DI	N			C	1"		NONRES				this proprty is served by a		Installation record	Y			Field inspection only	Y		Cross-connection survey	
201 C	BAY PARK SQUARE			DI	N			C	1"		NONRES				this proprty is served by a		Installation record	Y			Field inspection only	Y		Cross-connection survey	
201 D	BAY PARK SQUARE			DI	N			C	1"		NONRES				this proprty is served by a		Installation record	Y			Field inspection only	Y		Cross-connection survey	
990	BAY PARK SQUARE			DI	N			C	1"		NONRES				this proprty is served by a		Installation record	Y			Field inspection only	Y		Cross-connection survey	
985	BAY PARK SQUARE			DI	N			C	1"		NONRES				this proprty is served by a		Installation record	Y			Field inspection only	Y		Cross-connection survey	
980	BAY PARK SQUARE			DI	N			C	1"		NONRES				this proprty is served by a		Installation record	Y			Field inspection only	Y		Cross-connection survey	
978	BAY PARK SQUARE			DI	N			C	1"		NONRES				this proprty is served by a		Installation record	Y			Field inspection only	Y		Cross-connection survey	
977	BAY PARK SQUARE	C		DI	N			C	1"		NONRES				this proprty is served by a		Installation record	Y			Field inspection only	Y		Cross-connection survey	
977	BAY PARK SQUARE	B		DI	N			C	1"		NONRES				this proprty is served by a		Installation record	Y			Field inspection only	Y		Cross-connection survey	
975	BAY PARK SQUARE			DI	N			C	1"		NONRES				this proprty is served by a		Installation record	Y			Field inspection only	Y		Cross-connection survey	
973	BAY PARK SQUARE			DI	N			C	1"		NONRES				this proprty is served by a		Installation record	Y			Field inspection only	Y		Cross-connection survey	
970	BAY PARK SQUARE			DI	N			C	1"		NONRES				this proprty is served by a		Installation record	Y			Field inspection only	Y		Cross-connection survey	
963	BAY PARK SQUARE			DI	N			C	1"		NONRES				this proprty is served by a		Installation record	Y			Field inspection only	Y		Cross-connection survey	
920	BAY PARK SQUARE			DI	N			C	1"		NONRES				this proprty is served by a		Installation record	Y			Field inspection only	Y		Cross-connection survey	
918	BAY PARK SQUARE			DI	N			C	1"		NONRES				this proprty is served by a		Installation record	Y			Field inspection only	Y		Cross-connection survey	
915	BAY PARK SQUARE			DI	N			C	1"		NONRES				this proprty is served by a		Installation record	Y			Field inspection only	Y		Cross-connection survey	
900	BAY PARK SQUARE			DI	N			C	1"		NONRES				this proprty is served by a		Installation record	Y			Field inspection only	Y		Cross-connection survey	
697	BAY PARK SQUARE	A B		DI	N			C	1"		NONRES				this proprty is served by a		Installation record	Y			Field inspection only	Y		Cross-connection survey	
689	BAY PARK SQUARE			DI	N			C	1"		NONRES				this proprty is served by a		Installation record	Y			Field inspection only	Y		Cross-connection survey	
661	BAY PARK SQUARE			DI	N			C	1"		NONRES				this proprty is served by a		Installation record	Y			Field inspection only	Y		Cross-connection survey	
645	BAY PARK SQUARE			DI	N			C	1"		NONRES				this proprty is served by a		Installation record	Y			Field inspection only	Y		Cross-connection survey	
639	BAY PARK SQUARE			DI	N			C	1"		NONRES				this proprty is served by a		Installation record	Y			Field inspection only	Y		Cross-connection survey	
635	BAY PARK SQUARE			DI	N			C	1"		NONRES				this proprty is served by a		Installation record	Y			Field inspection only	Y		Cross-connection survey	
628	BAY PARK SQUARE			DI	N			C	1"		NONRES				this proprty is served by a		Installation record	Y			Field inspection only	Y		Cross-connection survey	
619	BAY PARK SQUARE			DI	N			C	1"		NONRES				this proprty is served by a		Installation record	Y			Field inspection only	Y		Cross-connection survey	
607	BAY PARK SQUARE			DI	N			C	1"		NONRES				this proprty is served by a		Installation record	Y			Field inspection only	Y		Cross-connection survey	
551	BAY PARK SQUARE			DI	N			C	1"		NONRES				this proprty is served by a		Installation record	Y			Field inspection only	Y		Cross-connection survey	
521	BAY PARK SQUARE			DI	N			C	1"		NONRES				this proprty is served by a		Installation record	Y			Field inspection only	Y		Cross-connection survey	
511	BAY PARK SQUARE			DI	N			C	1"		NONRES				this proprty is served by a		Installation record	Y			Field inspection only	Y		Cross-connection survey	
375	BAY PARK SQUARE			DI	N			C	1"		NONRES				this proprty is served by a		Installation record	Y			Field inspection only	Y		Cross-connection survey	
363	BAY PARK SQUARE			DI	N			C	1"		NONRES				this proprty is served by a		Installation record	Y			Field inspection only	Y		Cross-connection survey	
339	BAY PARK SQUARE			DI	N			C	1"		NONRES				this proprty is served by a		Installation record	Y			Field inspection only	Y		Cross-connection survey	
333	BAY PARK SQUARE			DI	N			C	1"		NONRES				this proprty is served by a		Installation record	Y			Field inspection only	Y		Cross-connection survey	
311	BAY PARK SQUARE	A		DI	N			C	1"		NONRES				this proprty is served by a		Installation record	Y			Field inspection only	Y		Cross-connection survey	
263	BAY PARK SQUARE			DI	N			C	1"		NONRES				this proprty is served by a		Installation record	Y			Field inspection only	Y		Cross-connection survey	
930	BAY PARK SQUARE			DI	N			C	1"		NONRES				this proprty is served by a		Installation record	Y			Field inspection only	Y		Cross-connection survey	
281	BAY PARK SQUARE	A		DI	N			C	1"		NONRES				this proprty is served by a		Installation record	Y			Field inspection only	Y		Cross-connection survey	
780	BAYLAND COURT			C	N	2"		P	1"		NONRES						Installation record	Y	1980		Field inspection only	Y		Cross-connection survey	
808	BAYLAND COURT			C	N	2"		P	1 1/2"		NONRES						Installation record	Y	1980		Field inspection only	Y		Cross-connection survey	
2312	BEL AIRE COURT			C	N	3/4"		C	1"		NONRES						Installation record	Y	1965	nsp during install o	Field inspection only	Y		Cross-connection survey	
1052	BEL AIRE COURT			C	N	3/4"		C	1"		NONRES						Installation record	Y	1965	nsp during install o	Field inspection only	Y		Cross-connection survey	
1052	BEL AIRE COURT			C	N	3/4"		C	1"		NONRES						Installation record	Y	1965	nsp during install o	Field inspection only	Y		Cross-connection survey	
2304	BEL AIRE COURT			C	N	1"		C	1"		NONRES						Installation record	Y	1965	nsp during install o	Field inspection only	Y		Cross-connection survey	
786	BORVAN AVENUE			UNK-NOLG	N			C	1"		NONRES						Installation record	N	1969		Field inspection only	Y		Cross-connection survey	
790	BORVAN AVENUE			UNK-NOLG	N			C	2"		NONRES						Installation record	N	1969		Field inspection only	Y		Cross-connection survey	

LOCATIONAL IDENTIFIER ADDRESS	LOCATIONAL IDENTIFIER STREET NAME	LOCATIONAL IDENTIFIER UNIT OR SUITE #	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
732	BORVAN AVENUE			UNK-NOLG	N			C	1"		NONRES						Installation record	N	1969		Field inspection only	Y		Cross-connection survey	
742	BORVAN AVENUE			C	N	1"		C	1"		NONRES						Installation record	Y	1969		Field inspection only	Y		Cross-connection survey	
695	BORVAN AVENUE			UNK-NOLG	N			C	1"		NONRES						Installation record	N	1969		Field inspection only	Y		Cross-connection survey	
838	BORVAN AVENUE			UNK-NOLG	N			C	3/4"		NONRES						Installation record	N	1969		Field inspection only	Y		Cross-connection survey	
750	BORVAN AVENUE			UNK-NOLG	N			C	3/4"		NONRES						Installation record	N	1969		Field inspection only	Y		Cross-connection survey	
733	BORVAN AVENUE			UNK-NOLG	N			C	1"		NONRES						Installation record	N	1969		Field inspection only	Y		Cross-connection survey	
679	BORVAN AVENUE			UNK-NOLG	N			C	3/4"		NONRES						Installation record	N	1969		Field inspection only	Y		Cross-connection survey	
598	BORVAN AVENUE			UNK-NOLG	N			C	1"		NONRES						Installation record	N	1969		Field inspection only	Y		Cross-connection survey	
683	BORVAN AVENUE	C		UNK-NOLG	N			C	1"		NONRES						Installation record	N	1969		Field inspection only	Y		Cross-connection survey	
683	BORVAN AVENUE	A		UNK-NOLG	N			C	1"		NONRES						Installation record	N	1969		Field inspection only	Y		Cross-connection survey	
683	BORVAN AVENUE	B		UNK-NOLG	N			C	1"		NONRES						Installation record	N	1969		Field inspection only	Y		Cross-connection survey	
711	Borvan			UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
682	Borvan			UNK-NOLG	N			P	2"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
689	Mike McCarthy Way			P	N	8"		P	2"		MF						Installed after lead ban	Y	2018	ısp during install o	Installed after lead ban	Y		Cross-connection survey	
692	Borvan			UNK-NOLG	N			P	2"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2700	S BROADWAY			P	N	2"		C	1"		NONRES						Installed after lead ban	Y	1998	ısp during install o	Field inspection only	Y		Cross-connection survey	
2870	S BROADWAY			P	N			C	1"		NONRES						Installed after lead ban	Y	2004	ısp during install o	Field inspection only	Y		Cross-connection survey	
2870	S BROADWAY			P	N			C	1 1/2"		NONRES						Installed after lead ban	Y	2004	ısp during install o	Field inspection only	Y		Cross-connection survey	
2878	S BROADWAY			P	N			C	2"		NONRES						Installed after lead ban	Y	2004	ısp during install o	Field inspection only	Y		Cross-connection survey	
2285	S BROADWAY			P	N			DI	4"		NONRES					8" main feed this pro	Installed after lead ban	Y	2001	ısp during install o	Field inspection only	Y		Cross-connection survey	
2285	S BROADWAY			P	N			DI	4"		NONRES						Installed after lead ban	Y	2001	ısp during install o	Field inspection only	Y		Cross-connection survey	
2285	S BROADWAY			P	N			C	1"		NONRES						Installed after lead ban	Y	2001	ısp during install o	Field inspection only	Y		Cross-connection survey	
2538	S BROADWAY	WOM		P	N			C	1"		NONRES						Installed after lead ban	Y	1998	ısp during install o	Field inspection only	Y		Cross-connection survey	
2538	S BROADWAY			P	N			C	1 1/2"		NONRES						Installed after lead ban	Y	1998	ısp during install o	Field inspection only	Y		Cross-connection survey	
2538	S BROADWAY			P	N			C	1 1/2"		NONRES						Installed after lead ban	Y	1998	ısp during install o	Field inspection only	Y		Cross-connection survey	
2737	S RIDGE ROAD			C	N	2"		C	1"		NONRES						Installation record	Y	1969	ısp during install o	Field inspection only	Y		Cross-connection survey	
2777	S RIDGE ROAD			C	N			C	1"		NONRES						Installation record	Y	1969	ısp during install o	Field inspection only	Y		Cross-connection survey	
911	GLORY ROAD			UNK-NOLG	N			C	1"		NONRES						Installation record	N	1973		Field inspection only	Y		Cross-connection survey	
3101	PACKERLAND DRIVE			P	N	8"		P	4"		NONRES						Installed after lead ban	Y	1996	ısp during install o	Field inspection only	Y		Cross-connection survey	
3101	PACKERLAND DRIVE			P	N	8"		P	4"		NONRES						Installed after lead ban	Y	1996	ısp during install o	Field inspection only	Y		Cross-connection survey	
3171	Packerland Dr			P	N	2"		P	1 1/2"		NONRES						Installed after lead ban	Y	2020	ısp during install o	Field inspection only	Y		Cross-connection survey	
2490	S BROADWAY	WOM		P	N			P	1"		NONRES						Installed after lead ban	Y	1998	ısp during install o	Field inspection only	Y		Cross-connection survey	
2490	S BROADWAY	WOM		P	N			P	1"		NONRES						Installed after lead ban	Y	1998	ısp during install o	Field inspection only	Y		Cross-connection survey	
2490	S BROADWAY			P	N			P	1"		NONRES						Installed after lead ban	Y	1998	ısp during install o	Field inspection only	Y		Cross-connection survey	
2561	S BROADWAY			P	N	6"		DI	6"		NONRES						Installed after lead ban	Y	1998	ısp during install o	Field inspection only	Y		Cross-connection survey	
2561	S BROADWAY			P	N	6"		DI	6"		NONRES						Installed after lead ban	Y	1998	ısp during install o	Field inspection only	Y		Cross-connection survey	
1162	Brookwood			P	N	3"		P	3"		MF						Installed after lead ban	Y	2019	ısp during install o	Field inspection only	Y		Cross-connection survey	
1092	Brookwood			P	N	2"		P	3/4"		SF						Installed after lead ban	Y	2019	ısp during install o	Field inspection only	Y		Cross-connection survey	
1140	Brookwood			P	N	2"		P	3/4"		SF						Installed after lead ban	Y	2019	ısp during install o	Field inspection only	Y		Cross-connection survey	
1100	Brookwood			P	N	2"		P	3/4"		SF						Installed after lead ban	Y	2019	ısp during install o	Field inspection only	Y		Cross-connection survey	
1110	Brookwood			P	N	2"		P	3/4"		SF						Installed after lead ban	Y	2019	ısp during install o	Field inspection only	Y		Cross-connection survey	
1120	Brookwood			P	N	2"		P	3/4"		SF						Installed after lead ban	Y	2019	ısp during install o	Field inspection only	Y		Cross-connection survey	
1124	Brookwood			P	N	2"		P	3/4"		SF						Installed after lead ban	Y	2019	ısp during install o	Field inspection only	Y		Cross-connection survey	
1088	Brookwood			P	N	2"		P	3/4"		SF						Installed after lead ban	Y	2019	ısp during install o	Field inspection only	Y		Cross-connection survey	
1138	Brookwood			P	N	2"		P	3/4"		SF						Installed after lead ban	Y	2019	ısp during install o	Field inspection only	Y		Cross-connection survey	
1108	Brookwood			P	N	2"		P	3/4"		SF						Installed after lead ban	Y	2019	ısp during install o	Field inspection only	Y		Cross-connection survey	
1158	Brookwood			P	N	2"		P	3/4"		SF						Installed after lead ban	Y	2019	ısp during install o	Field inspection only	Y		Cross-connection survey	
1154	Brookwood			P	N	2"		P	3/4"		SF						Installed after lead ban	Y	2019	ısp during install o	Field inspection only	Y		Cross-connection survey	
1152	Brookwood			P	N	2"		P	3/4"		SF						Installed after lead ban	Y	2019	ısp during install o	Field inspection only	Y		Cross-connection survey	
1150	Brookwood			P	N	2"		P	3/4"		SF						Installed after lead ban	Y	2019	ısp during install o	Field inspection only	Y		Cross-connection survey	
1146	Brookwood			P	N	2"		P	3/4"		SF						Installed after lead ban	Y	2019	ısp during install o	Field inspection only	Y		Cross-connection survey	
1104	Brookwood			P	N	2"		P	3/4"		SF						Installed after lead ban	Y	2019	ısp during install o	Field inspection only	Y		Cross-connection survey	
1126	Brookwood			P	N	2"		P	3/4"		SF						Installed after lead ban	Y	2019	ısp during install o	Field inspection only	Y		Cross-connection survey	
1130	Brookwood			P	N	2"		P	3/4"		SF						Installed after lead ban	Y	2019	ısp during install o	Field inspection only	Y		Cross-connection survey	
1134	Brookwood			P	N	2"		P	3/4"		SF						Installed after lead ban	Y	2019	ısp during install o	Field inspection only	Y		Cross-connection survey	
1060	Brookwood			P	N	2"		P	3/4"		SF						Installed after lead ban	Y	2019	ısp during install o	Field inspection only	Y		Cross-connection survey	
1064	Brookwood			P	N	2"		P	3/4"		SF						Installed after lead ban	Y	2019	ısp during install o	Field inspection only	Y		Cross-connection survey	
1068	Brookwood			P	N	2"		P	3/4"		SF						Installed after lead ban	Y	2019	ısp during install o	Field inspection only	Y		Cross-connection survey	
1072	Brookwood			P	N	2"		P	3/4"		SF						Installed after lead ban	Y	2019	ısp during install o	Field inspection only	Y		Cross-connection survey	
1096	Brookwood			P	N	2"		P	3/4"		SF						Installed after lead ban	Y	2019	ısp during install o	Field inspection only	Y		Cross-connection survey	
1076	Brookwood			P	N	2"		P	3/4"		SF						Installed after lead ban	Y	2019	ısp during install o	Field inspection only	Y		Cross-connection survey	
1080	Brookwood			P	N	2"		P	3/4"		SF						Installed after lead ban	Y	2019	ısp during install o	Field inspection only	Y		Cross-connection survey	
1084	Brookwood			P	N	2"		P	3/4"		SF						Installed after lead ban	Y	2019	ısp during install o	Field inspection only	Y		Cross-connection survey	
1071	Brookwood			P	N	2"		P	3/4"		SF						Installed after lead ban	Y	2019	ısp during install o	Field inspection only	Y		Cross-connection survey	
1073	Brookwood			P	N	2"		P	3/4"		SF						Installed after lead ban	Y	2019	ısp during install o	Field inspection only	Y		Cross-connection survey	
1077	Brookwood			P	N	2"		P	3/4"		SF						Installed after lead ban	Y	2019	ısp during install o	Field inspection only	Y		Cross-connection survey	
1079	Brookwood			P	N	2"		P	3/4"		SF						Installed after lead ban	Y	2019	ısp during install o	Field inspection only	Y		Cross-connection survey	
1081	Brookwood			P	N	2"		P	3/4"		SF						Installed after lead ban	Y	2019	ısp during install o	Field inspection only	Y		Cross-connection survey	
1083	Brookwood			P	N	2"		P	3/4"		SF						Installed after lead ban	Y	2019	ısp during install o	Field inspection only	Y		Cross-connection survey	
1087	Brookwood			P	N	2"		P	3/4"		SF						Installed after lead ban	Y	2019	ısp during install o	Field inspection only	Y		Cross-connection survey	
1089	Brookwood			P	N	2"		P	3/4"		SF						Installed after lead ban	Y	2019	ısp during install o	Field inspection only	Y		Cross-connection survey	
1710	CALAWAY DRIVE			C	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
2691	CALAWAY DRIVE			C	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
2690	CALAWAY DRIVE			C	N	1 1/2"		C	1"		NONRES						Installation record	Y	1962	ısp during install o	Field inspection only	Y		Cross-connection survey	
2701	CALAWAY DRIVE			C	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
2711	CALAWAY DRIVE			C	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
2706	CALAWAY DRIVE			C	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
2712	CALAWAY DRIVE			C	N	1 1/2"		C	1 1/2"		NONRES						Installation record	Y	1962	ısp during install o	Field inspection only	Y		Cross-connection survey	
2717	CALAWAY DRIVE			C	N			C	2"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
2360	CANTER LANE			C	N			C	2"		MF						Installation record	N	1974		Field inspection only	Y		Cross-connection survey	
2320	CANTER LANE			C	N			C	2"		MF						Installation record	N	1974		Field inspection only	Y		Cross-connection survey	
2330	CANTER LANE			C	N			C	1 1/2"		MF						Installation record	N	1974		Field inspection only	Y		Cross-connection survey	
2340	CANTER LANE			C	N			C	1 1/2"		MF						Installation record	N	1974		Field inspection only	Y		Cross-connection survey	
2350	CANTER LANE			C	N			C	1 1/2"		MF						Installation record	N	1974		Field inspection only	Y		Cross-connection survey	
2370	CANTER LANE			C	N			C	1 1/2"		MF						Installation record	N	1974		Field inspection only	Y		Cross-connection survey	

LOCATIONAL IDENTIFIER ADDRESS	LOCATIONAL IDENTIFIER STREET NAME	LOCATIONAL IDENTIFIER UNIT OR SUITE #	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
2380	CANTER LANE			C	N			C	1 1/2"		MF						Installation record	N	1974		Field inspection only	Y		Cross-connection survey	
2390	CANTER LANE			C	N			C	1 1/2"		MF						Installation record	N	1974		Field inspection only	Y		Cross-connection survey	
2400	CANTER LANE			C	N			C	1"		MF						Installation record	N	1974		Field inspection only	Y		Cross-connection survey	
2408	CANTER LANE			C	N			C	1 1/2"		MF						Installation record	N	1974		Field inspection only	Y		Cross-connection survey	
2310	CANTER LANE			C	N			C	2"		MF						Installation record	N	1974		Field inspection only	Y		Cross-connection survey	
1680	CAROLE LANE			C	N			C	1 1/2"		MF						Installation record	N	1974		Field inspection only	Y		Cross-connection survey	
2108	CARSTENSEN LANE			C	N	1 1/2"		C	1 1/2"		MF						Installation record	Y	1970	ısp during install o	Field inspection only	Y		Cross-connection survey	
2126	CARSTENSEN LANE			C	N	1 1/2"		C	1"		MF						Installation record	Y	1970	ısp during install o	Field inspection only	Y		Cross-connection survey	
2240	CARSTENSEN LANE			C	N	1 1/2"		C	2"		MF						Installation record	Y	1970	ısp during install o	Field inspection only	Y		Cross-connection survey	
2116	CARSTENSEN LANE			C	N	1 1/2"		C	1"		MF						Installation record	Y	1970	ısp during install o	Field inspection only	Y		Cross-connection survey	
2182	CARSTENSEN LANE			C	N	1 1/2"		C	1"		MF						Installation record	Y	1970	ısp during install o	Field inspection only	Y		Cross-connection survey	
2146	CARSTENSEN LANE			C	N	1 1/2"		C	1"		NONRES						Installation record	Y	1970	ısp during install o	Field inspection only	Y		Cross-connection survey	
2176	CARSTENSEN LANE			C	N	1 1/2"		C	1"		MF						Installation record	Y	1970	ısp during install o	Field inspection only	Y		Cross-connection survey	
2150	CARSTENSEN LANE			C	N	1 1/2"		C	1"		NONRES						Installation record	Y	1970	ısp during install o	Field inspection only	Y		Cross-connection survey	
2339	CEDAR RIDGE			UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
985	CENTENNIAL STREET			UNK-NOLG	N			P	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
1010	CENTENNIAL STREET			UNK-NOLG	N			P	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
996	CENTENNIAL STREET			UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
1026	CENTENNIAL STREET			UNK-NOLG	N			P	3"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
990	CENTENNIAL STREET	C1		UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
991	CENTENNIAL STREET			UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
1040	CENTENNIAL STREET			UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
1000	CENTENNIAL STREET			UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
1050	CIRCLE DRIVE	D		UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
1050	CIRCLE DRIVE	A		UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
1050	CIRCLE DRIVE	C		UNK-NOLG	N			C	2"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
1050	CIRCLE DRIVE	B		UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
1040	CIRCLE DRIVE			P	N	2"		P	1"		NONRES						Installed after lead ban	Y	2008	ısp during install o	Field inspection only	Y		Cross-connection survey	
954	CIRCLE DRIVE			UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
956	CIRCLE DRIVE			UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
1000	CIRCLE DRIVE			UNK-NOLG	N			P	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
1018	CIRCLE DRIVE			UNK-NOLG	N			DI	8"		NONRES						Diameter > 2 inches	N			Field inspection only	Y		Cross-connection survey	
466	COLLETTE AVENUE			C	N	2"		P	1 1/4"		NONRES				this lateral comes off Br		Installation record	Y	2001	ısp during install o	Field inspection only	Y		Cross-connection survey	
1641	COMMANCHE AVENUE	G		UNK-NOLG	N	8"		C	1"		NONRES				this lateral comes off Pa		Installation record	N			Field inspection only	Y		Cross-connection survey	
1641	COMMANCHE AVENUE	G		UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
1641	COMMANCHE AVENUE	A		UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
1641	COMMANCHE AVENUE	F		UNK-NOLG	N			C	2"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
1641	COMMANCHE AVENUE	E		UNK-NOLG	N			C	3"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
1641	COMMANCHE AVENUE	H		UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
1641	COMMANCHE AVENUE	D		UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
1641	COMMANCHE AVENUE	C		UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
1641	COMMANCHE AVENUE	B		UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
1580	COMMANCHE AVENUE			P	N	8"		P	1"		NONRES						Diameter > 2 inches	Y	2008	ısp during install o	Field inspection only	Y		Cross-connection survey	
1630	COMMANCHE AVENUE			P	N	8"		C	1"		NONRES						Diameter > 2 inches	Y			Field inspection only	Y		Cross-connection survey	
1630	COMMANCHE AVENUE			P	N	8"		C	1"		NONRES						Diameter > 2 inches	Y			Field inspection only	Y		Cross-connection survey	
1639	COMMANCHE AVENUE			UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
3280	COMMODITY LANE	1		UNK-NOLG	N	6"		C	1"		NONRES				this complex is fed by 6		Installation record	N			Field inspection only	Y		Cross-connection survey	
3280	COMMODITY LANE	3		UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
3280	COMMODITY LANE	2		UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
3280	COMMODITY LANE	6		UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
3280	COMMODITY LANE	5		UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
3280	COMMODITY LANE	4		UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
3065	COMMODITY LANE	D		UNK-NOLG	N			P	1 1/2"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
3065	COMMODITY LANE	C		UNK-NOLG	N			P	1 1/2"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
3065	COMMODITY LANE	A		UNK-NOLG	N			P	1 1/2"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
3300	COMMODITY LANE			UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
3306	COMMODITY LANE			UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
3160	COMMODITY LANE			UNK-NOLG	N			C	1 1/2"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
3355	COMMODITY LANE			UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
3181	COMMODITY LANE			UNK-NOLG	N			C	2"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
3070	COMMODITY LANE			P	N	6"		P	1"		NONRES						Diameter > 2 inches	Y	2023	ısp during install o	Field inspection only	Y		Cross-connection survey	
3431	COMMODITY LANE			UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
3200	COMMODITY LANE			UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
3333	COMMODITY LANE	1		UNK-NOLG	N	6"		C	1"		NONRES				this is fed with 6" la		Installation record	Y			Field inspection only	Y		Cross-connection survey	
3333	COMMODITY LANE	2		UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
3333	COMMODITY LANE	3		UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
3350	COMMODITY LANE	C		C	N	2"		C	1"		NONRES				2" lateral feeds this cc		Field inspection only	Y		Visual insp at mete	Field inspection only	Y		Cross-connection survey	
3350	COMMODITY LANE	G		C	N			C	1"		NONRES						Field inspection only	Y		Visual insp at mete	Field inspection only	Y		Cross-connection survey	
3350	COMMODITY LANE	E		C	N			C	1"		NONRES						Field inspection only	Y		Visual insp at mete	Field inspection only	Y		Cross-connection survey	
3350	COMMODITY LANE	A		C	N			C	1"		NONRES						Field inspection only	Y		Visual insp at mete	Field inspection only	Y		Cross-connection survey	
3350	COMMODITY LANE	D		C	N			C	1"		NONRES						Field inspection only	Y		Visual insp at mete	Field inspection only	Y		Cross-connection survey	
3220	COMMODITY LANE			UNK-NOLG	N			P	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
3230	COMMODITY LANE			UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
3330	COMMODITY LANE			UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
1247	CONTRACT DRIVE			UNK-NOLG	N			C	3/4"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
1330	CONTRACT DRIVE			UNK-NOLG	N			C	2"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
1136	CONTRACT DRIVE			UNK-NOLG	N			P	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
1271	CONTRACT DRIVE			UNK-NOLG	N			C	1 1/2"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
1301	CONTRACT DRIVE			UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
1311	CONTRACT DRIVE			UNK-NOLG	N			C	2"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
1135	CONTRACT DRIVE			UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
1201	CONTRACT DRIVE			P	N	8"		P	1"		NONRES						Installed after lead ban	Y	2023	ısp during install o	Field inspection only	Y		Cross-connection survey	
1176	CONTRACT DRIVE			P	N			P	2"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1160	CONTRACT DRIVE			P	N			P	1 1/2"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1240	CONTRACT DRIVE			UNK-NOLG	N			C	1 1/2"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	

LOCATIONAL IDENTIFIER ADDRESS	LOCATIONAL IDENTIFIER STREET NAME	LOCATIONAL IDENTIFIER UNIT OR SUITE #	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
1207	CORMIER ROAD			UNK-NOLG	N			C	1 1/2"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
727	CORMIER ROAD	DOWN		P	N	2"		C	2"		NONRES						Installed after lead ban	Y	2018	nsp during install o	Field inspection only	Y		Cross-connection survey	
727	CORMIER ROAD	UP		P	N	2"		C	2"		NONRES						Installation record	Y	2018	nsp during install o	Field inspection only	Y		Cross-connection survey	
1055	CORMIER ROAD			UNK-NOLG	N			C	2"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
737	CORMIER ROAD			P	N	2"		C	1"		NONRES						Installed after lead ban				Field inspection only	Y		Cross-connection survey	
1071	CORMIER ROAD			P	N	2"		C	1"		NONRES						Installed after lead ban	Y	2018	nsp during install o	Field inspection only	Y		Cross-connection survey	
849	CORMIER ROAD			P	N	2"		C	1"		NONRES						Installed after lead ban	Y	2018	nsp during install o	Field inspection only	Y		Cross-connection survey	
845	CORMIER ROAD			P	N	2"		P	1"		NONRES						Installed after lead ban	Y	2018	nsp during install o	Field inspection only	Y		Cross-connection survey	
535	CORMIER ROAD			P	N	2"		C	1 1/2"		NONRES						Installed after lead ban	Y	2018	nsp during install o	Field inspection only	Y		Cross-connection survey	
812	CORMIER ROAD			P	N	2"		C	1 1/2"		NONRES						Installed after lead ban	Y	2018	nsp during install o	Field inspection only	Y		Cross-connection survey	
786	CORMIER ROAD			P	N	2"		C	2"		NONRES						Installed after lead ban	Y	2018	nsp during install o	Field inspection only	Y		Cross-connection survey	
822	CORMIER ROAD			P	N	2"		P	2"		NONRES						Installed after lead ban	Y	2018	nsp during install o	Field inspection only	Y		Cross-connection survey	
800	CORMIER ROAD			P	N	2"		C	1"		NONRES						Installed after lead ban	Y	2018	nsp during install o	Field inspection only	Y		Cross-connection survey	
580	CORMIER ROAD			P	N	2"		P	1"		NONRES						Installed after lead ban	Y	2018	nsp during install o	Field inspection only	Y		Cross-connection survey	
670	CORMIER ROAD	WOM		P	N	6"		DI	6"		NONRES						Installed after lead ban	Y	2018	nsp during install o	Field inspection only	Y		Cross-connection survey	
670	CORMIER ROAD			P	N	6"		DI	6"		NONRES						Installed after lead ban	Y	2018	nsp during install o	Field inspection only	Y		Cross-connection survey	
700	CORMIER ROAD			P	N	2"		P	1 1/2"		NONRES						Installed after lead ban	Y	2018	nsp during install o	Field inspection only	Y		Cross-connection survey	
680	CORMIER ROAD			P	N	2"		C	2"		SCH/CC						Installed after lead ban	Y	2018	nsp during install o	Field inspection only	Y		Cross-connection survey	
827	CORMIER ROAD			P	N	2"		P	1 1/2"		NONRES						Installed after lead ban	Y	2018	nsp during install o	Field inspection only	Y		Cross-connection survey	
1215	CORMIER ROAD	Multi		UNK-NOLG	N			C	1 1/2"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
1215	CORMIER ROAD	5		UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
1001	CORMIER ROAD			UNK-NOLG	N			C	2"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
821	CORMIER ROAD			P	N	2"		C	1 1/2"		NONRES						Installed after lead ban	Y	2018	nsp during install o	Field inspection only	Y		Cross-connection survey	
823	CORMIER ROAD			P	N	2"		C	1 1/2"		NONRES						Installed after lead ban	Y	2018	nsp during install o	Field inspection only	Y		Cross-connection survey	
825	CORMIER ROAD			P	N	2"		C	1 1/2"		NONRES						Installed after lead ban	Y	2018	nsp during install o	Field inspection only	Y		Cross-connection survey	
1189	CORMIER ROAD			UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
1199	CORMIER ROAD			UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
3190	CORONET WAY			UNK-NOLG	N			C	1"		NONRES						Installation record	N	1976		Field inspection only	Y		Cross-connection survey	
3190	CORONET WAY			UNK-NOLG	N			C	1"		NONRES						Installation record	N	1976		Field inspection only	Y		Cross-connection survey	
3161	CORONET WAY			UNK-NOLG	N			C	1"		NONRES						Installation record	N	1976		Field inspection only	Y		Cross-connection survey	
3173	CORONET WAY			UNK-NOLG	N			C	1"		NONRES						Installation record	N	1976		Field inspection only	Y		Cross-connection survey	
3146	CORONET WAY			UNK-NOLG	N			P	3/4"		NONRES						Installation record	N	1976		Field inspection only	Y		Cross-connection survey	
3180	CORONET WAY			UNK-NOLG	N			P	1"		NONRES						Installation record	N	1976		Field inspection only	Y		Cross-connection survey	
3164	CORONET WAY			C	N	1 1/2"		P	1"		NONRES						Installation record	Y	1976	nsp during install o	Field inspection only	Y		Cross-connection survey	
3136	CORONET WAY			UNK-NOLG	N			C	1"		NONRES						Installation record	N	1976		Field inspection only	Y		Cross-connection survey	
750	CORONIS CIRCLE			UNK-NOLG	N			C	1"		NONRES						Installation record	N	1976		Field inspection only	Y		Cross-connection survey	
735	CORONIS CIRCLE			UNK-NOLG	N			C	1"		NONRES						Installation record	N	1976		Field inspection only	Y		Cross-connection survey	
730	CORONIS CIRCLE			UNK-NOLG	N			C	1"		NONRES						Installation record	N	1976		Field inspection only	Y		Cross-connection survey	
700	CORONIS CIRCLE			UNK-NOLG	N			C	1"		NONRES						Installation record	N	1976		Field inspection only	Y		Cross-connection survey	
800	CORONIS WAY			UNK-NOLG	N			C	1"		NONRES						Installation record	N	1976		Field inspection only	Y		Cross-connection survey	
820	CORONIS WAY			UNK-NOLG	N			C	1"		NONRES						Installation record	N	1976		Field inspection only	Y		Cross-connection survey	
809	CORONIS WAY			UNK-NOLG	N			C	1"		NONRES						Installation record	N	1976		Field inspection only	Y		Cross-connection survey	
795	CORONIS WAY			UNK-NOLG	N			C	1"		NONRES						Installation record	N	1976		Field inspection only	Y		Cross-connection survey	
796	CORONIS WAY			UNK-NOLG	N			P	1 1/2"		NONRES						Installation record	N	1976		Field inspection only	Y		Cross-connection survey	
794	CORONIS WAY			UNK-NOLG	N			P	1 1/2"		NONRES						Installation record	N	1976		Field inspection only	Y		Cross-connection survey	
1587	CYPRESS ROAD			P	N	8"			1 1/2"		MF		8" plastic feeds these 4 ap	Installed after lead ban				Y	2006	nsp during install o	Field inspection only	Y		Cross-connection survey	
1583	CYPRESS ROAD			P	N				1 1/2"		MF		8" plastic feeds these 4 ap	Installed after lead ban				Y	2006	nsp during install o	Field inspection only	Y		Cross-connection survey	
1581	CYPRESS ROAD			P	N				1"		MF		8" plastic feeds these 4 ap	Installed after lead ban				Y	2006	nsp during install o	Field inspection only	Y		Cross-connection survey	
1585	CYPRESS ROAD			P	N				1"		MF		8" plastic feeds these 4 ap	Installed after lead ban				Y	2006	nsp during install o	Field inspection only	Y		Cross-connection survey	
2222	EARLY STREET			UNK-NOLG	N			C	1"		NONRES			Installation record				N			Field inspection only	Y		Cross-connection survey	
1311	ECHO LANE			UNK-NOLG	N			C	1 1/2"		MF			Installation record				N			Field inspection only	Y		Cross-connection survey	
1110	ECHO LANE			UNK-NOLG	N			P	2"		NONRES			Installation record				N			Field inspection only	Y		Cross-connection survey	
833	Element Way			P	N	8"		P	1"		MF			Installed after lead ban				Y	2019	nsp during install o	Field inspection only	Y		Cross-connection survey	
746	Element Way	Bldg 1		P	N	8"		P	3"		MF			Installed after lead ban				Y	2019	nsp during install o	Field inspection only	Y		Cross-connection survey	
798	Element Way	Bldg 3		P	N	8"		P	3"		MF			Installed after lead ban				Y	2019	nsp during install o	Field inspection only	Y		Cross-connection survey	
772	Element Way	Bldg 2		P	N	8"		p	3"		MF			Installed after lead ban				Y	2019	nsp during install o	Field inspection only	Y		Cross-connection survey	
840	Element Way	Bldg 4		P	N	8"		P	4"		MF			Installed after lead ban				Y	2019	nsp during install o	Field inspection only	Y		Cross-connection survey	
1340	EMINENCE STREET			C	N	2"		P	2"		MF			Installation record				Y	1980	nsp during install o	Field inspection only	Y		Cross-connection survey	
1340	EMINENCE STREET			C	N	2"		P	2"		MF			Installation record				Y	1980	nsp during install o	Field inspection only	Y		Cross-connection survey	
1361	MESA DR			UNK-NOLG	N			P	1 1/2"		MF			Installation record				N	1985		Field inspection only	Y		Cross-connection survey	
1365	MESA DR			UNK-NOLG	N			P	1 1/2"		MF			Installation record				N	1985		Field inspection only	Y		Cross-connection survey	
1363	MESA DR			UNK-NOLG	N			P	1 1/2"		MF			Installation record				N	1985		Field inspection only	Y		Cross-connection survey	
2710	EXECUTIVE DRIVE			P	N	6"		P	2"		NONRES			Installation record				Y	1986	nsp during install o	Field inspection only	Y		Cross-connection survey	
2701	EXECUTIVE DRIVE			P	N	6"		DI	6"		NONRES			Installation record				Y	1986	nsp during install o	Field inspection only	Y		Cross-connection survey	
1516	FERNANDO DRIVE			P	N	6"		DI	6"		NONRES			Installed after lead ban				Y	1999		Field inspection only	Y		Cross-connection survey	
1640	FERNANDO DRIVE			P	N	2"		P	1"		NONRES			Installed after lead ban				Y	1999		Field inspection only	Y		Cross-connection survey	
1640	FERNANDO DRIVE			P	N	2"		P	1"		NONRES			Installed after lead ban				Y	1999		Field inspection only	Y		Cross-connection survey	
2263	FOX HEIGHTS LANE			C	N	1"		C	1"		NONRES			Installation record				Y	1966	nsp during install o	Field inspection only	Y		Cross-connection survey	
2252	FOX HEIGHTS LANE			C	N	1"		C	1"		NONRES			Installation record				Y	1966	nsp during install o	Field inspection only	Y		Cross-connection survey	
2269	FOX HEIGHTS LANE			UNK-NOLG	N			C	1"		NONRES			Installation record				N	1966		Field inspection only	Y		Cross-connection survey	
2271	FOX HEIGHTS LANE			UNK-NOLG	N			C	1"		NONRES			Installation record				N	1966		Field inspection only	Y		Cross-connection survey	
2255	FOX HEIGHTS LANE			UNK-NOLG	N			P	4"		NONRES			Installation record				N	1966		Field inspection only	Y		Cross-connection survey	
2229	FOX HEIGHTS LANE			UNK-NOLG	N			C	1"		NONRES			Installation record				N	1966		Field inspection only	Y		Cross-connection survey	
2205	FOX HEIGHTS LANE			UNK-NOLG	N			C	1"		NONRES			Installation record				N	1966		Field inspection only	Y		Cross-connection survey	
2250	FOX HEIGHTS LANE			UNK-NOLG	N			C	1"		NONRES			Installation record				N	1966		Field inspection only	Y		Cross-connection survey	
2244	FOX HEIGHTS LANE	101		C	N	3/4"		C	1"		NONRES			Installation record				Y	1966	nsp during install o	Field inspection only	Y		Cross-connection survey	
2244	FOX HEIGHTS LANE	Upper		C	N	3/4"		C	1"		NONRES			Installation record				Y	1966	nsp during install o	Field inspection only	Y		Cross-connection survey	
2247	FOX HEIGHTS LANE	D		C	N	2"		C	1"		NONRES			Installation record				N	1966		Field inspection only	Y		Cross-connection survey	
2247	FOX HEIGHTS LANE	C		C	N	2"		C	1"		NONRES			Installation record				N	1966		Field inspection only	Y		Cross-connection survey	
2247	FOX HEIGHTS LANE	A		C	N	2"		C	1"		NONRES			Installation record				N	1966		Field inspection only	Y		Cross-connection survey	
1221	GLORY ROAD			UNK-NOLG	N			P	2"		NONRES			Installation record				N			Field inspection only	Y		Cross-connection survey	
1150	GLORY ROAD			UNK-NOLG	N			P	1"		NONRES			Installation record				N			Field inspection only	Y		Cross-connection survey	
1150	GLORY ROAD			UNK-NOLG	N			P	1"		NONRES			Installation record				N			Field inspection only	Y		Cross-connection survey	
975	ASHWAUBENON STREET			UNK-NOLG	N			C	1"		NONRES			Installation record				N			Field inspection only	Y		Cross-connection survey	
1515	GLORY ROAD	103		UNK-NOLG	N			P	2"		NONRES			Installed after lead ban				N	1991		Field inspection only	Y		Cross-connection survey	

LOCATIONAL IDENTIFIER ADDRESS	LOCATIONAL IDENTIFIER STREET NAME	LOCATIONAL IDENTIFIER UNIT OR SUITE #	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
1515	GLORY ROAD	101		UNK-NOLG	N			P	2"		NONRES						Installed after lead ban	N	1991		Field inspection only	Y		Cross-connection survey	
1275	GLORY ROAD			UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
1275	GLORY ROAD			UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
1370	GLORY ROAD			UNK-NOLG	N			C	1"		NONRES						Installed after lead ban	N	1991		Field inspection only	Y		Cross-connection survey	
954	GLORY ROAD	A		UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
954	GLORY ROAD	B		UNK-NOLG	N			P	1 1/4"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
998	GLORY ROAD			UNK-NOLG	N			C	3/4"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
1020	GLORY ROAD			UNK-NOLG	N			P	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
855	GLORY ROAD			UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
1361	GLORY ROAD			UNK-NOLG	N			C	1"		NONRES						Installed after lead ban	N	1991		Field inspection only	Y		Cross-connection survey	
1048	GLORY ROAD	A		UNK-NOLG	N			P	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
1048	GLORY ROAD	B		UNK-NOLG	N			P	2"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
1048	GLORY ROAD	C		UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
1048	GLORY ROAD	D		UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
1048	GLORY ROAD	E		UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
1048	GLORY ROAD	F		UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
1048	GLORY ROAD	G		UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
1050	GLORY ROAD	D		UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
1050	GLORY ROAD	C		UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
1050	GLORY ROAD	CC		UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
1050	GLORY ROAD	B		UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
1050	GLORY ROAD	A		UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
1142	GLORY ROAD			UNK-NOLG	N			P	2"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
1140	GLORY ROAD			UNK-NOLG	N			P	2"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
976	GLORY ROAD			UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
1555	GLORY ROAD			UNK-NOLG	N			C	1"		NONRES						Installed after lead ban	N	1991		Field inspection only	Y		Cross-connection survey	
1043	GRIFFITHS LANE			UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
858	HANSEN ROAD			UNK-NOLG	N			P	4"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
860	HANSEN ROAD			UNK-NOLG	N			P	3"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
600	HANSEN ROAD	WOM		UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
600	HANSEN ROAD			UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
940	HANSEN ROAD	101		P	N	8"		C	1"		NONRES				8" service feeds this cc		Installation record	Y		Visual insp during install o	Field inspection only	Y		Cross-connection survey	
940	HANSEN ROAD	F		P	N	8"		C	1"		NONRES				8" service feeds this cc		Installation record	Y		Visual insp during install o	Field inspection only	Y		Cross-connection survey	
940	HANSEN ROAD	E		P	N	8"		C	1"		NONRES				8" service feeds this cc		Installation record	Y		Visual insp during install o	Field inspection only	Y		Cross-connection survey	
940	HANSEN ROAD	G		P	N	8"		C	1"		NONRES				8" service feeds this cc		Installation record	Y		Visual insp during install o	Field inspection only	Y		Cross-connection survey	
940	HANSEN ROAD	B		P	N	8"		C	1 1/2"		NONRES				8" service feeds this cc		Installation record	Y		Visual insp during install o	Field inspection only	Y		Cross-connection survey	
940	HANSEN ROAD	C		P	N	8"		C	1"		NONRES				8" service feeds this cc		Installation record	Y		Visual insp during install o	Field inspection only	Y		Cross-connection survey	
940	HANSEN ROAD	D		P	N	8"		C	1"		NONRES				8" service feeds this cc		Installation record	Y		Visual insp during install o	Field inspection only	Y		Cross-connection survey	
940	HANSEN ROAD	A		P	N	8"		C	2"		NONRES				8" service feeds this cc		Installation record	Y		Visual insp during install o	Field inspection only	Y		Cross-connection survey	
1192	HANSEN ROAD	202		UNK-NOLG	N			C	2"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
1192	HANSEN ROAD	100		UNK-NOLG	N			C	2"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
1200	HANSEN ROAD			UNK-NOLG	N			C	2"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
1060	HANSEN ROAD			UNK-NOLG	N			C	2"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
1060	HANSEN ROAD			UNK-NOLG	N			C	2"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
790	HANSEN ROAD	A		P	N	8"		P	2"		NONRES				new service was installed because of bu		Installation record	Y	2015	nsp during install o	Field inspection only	Y		Cross-connection survey	
790	HANSEN ROAD	C		P	N	8"		P	2"		NONRES				new service was installed because of bu		Installation record	Y	2015	nsp during install o	Field inspection only	Y		Cross-connection survey	
790	HANSEN ROAD	D		P	N	8"		P	2"		NONRES				new service was installed because of bu		Installation record	Y	2015	nsp during install o	Field inspection only	Y		Cross-connection survey	
790	HANSEN ROAD	B		P	N	8"		P	2"		NONRES				new service was installed because of bu		Installation record	Y	2015	nsp during install o	Field inspection only	Y		Cross-connection survey	
790	HANSEN ROAD	E		P	N	8"		P	2"		NONRES				new service was installed because of bu		Installation record	Y	2015	nsp during install o	Field inspection only	Y		Cross-connection survey	
960	HANSEN ROAD			UNK-NOLG	N			P	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
909	HANSEN ROAD			UNK-NOLG	N			C	2"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
901	HANSEN ROAD			UNK-NOLG	N			C	2"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
855	HANSEN ROAD			UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
850	HANSEN ROAD			UNK-NOLG	N			P	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
975	HANSEN ROAD			UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
800	HANSEN ROAD			UNK-NOLG	N			C	2"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
906	HANSEN ROAD			UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
908	HANSEN ROAD			UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
910	HANSEN ROAD			UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
914	HANSEN ROAD			UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
912	HANSEN ROAD			UNK-NOLG	N			C	1 1/2"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
871	HANSEN ROAD			UNK-NOLG	N			P	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
862	HANSEN ROAD			UNK-NOLG	N			P	2"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
611	HANSEN ROAD			UNK-NOLG	N			C	2"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
900	HANSEN ROAD			UNK-NOLG	N			C	2"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
1181	HANSEN ROAD			UNK-NOLG	N			P	3"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
734	HANSEN ROAD	BACK		UNK-NOLG	N			C	1 1/2"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
734	HANSEN ROAD	FRONT		UNK-NOLG	N			C	1 1/2"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
750	HANSEN ROAD			UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
2071	HILLTOP DRIVE			C	N	2"		P	1 1/2"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2051	HILLTOP DRIVE			C	N	2"		C	1"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2061	HILLTOP DRIVE			C	N	2"		C	1"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2707	HOLMGREN WAY			UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
2666	HOLMGREN WAY			UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
3055	HOLMGREN WAY			UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
2301	HOLMGREN WAY	E		P	N	2"		C	1"		NONRES				2" plastic lateral feeds thi		Installed after lead ban	Y	1999		Field inspection only	Y		Cross-connection survey	
2301	HOLMGREN WAY	C		P	N	2"		C	1"		NONRES				2" plastic lateral feeds thi		Installed after lead ban	Y	1999		Field inspection only	Y		Cross-connection survey	
2301	HOLMGREN WAY	B		P	N	2"		C	1"		NONRES				2" plastic lateral feeds thi		Installed after lead ban	Y	1999		Field inspection only	Y		Cross-connection survey	
2301	HOLMGREN WAY	A		P	N	2"		C	1"		NONRES				2" plastic lateral feeds thi		Installed after lead ban	Y	1999		Field inspection only	Y		Cross-connection survey	
2301	HOLMGREN WAY	F		P	N	2"		C	1"		NONRES				2" plastic lateral feeds thi		Installed after lead ban	Y	1999		Field inspection only	Y		Cross-connection survey	
2301	HOLMGREN WAY	D		P	N	2"		C	1"		NONRES				2" plastic lateral feeds thi		Installed after lead ban	Y	1999		Field inspection only	Y		Cross-connection survey	
2775	HOLMGREN WAY			UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
2930	HOLMGREN WAY			UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
2270	HOLMGREN WAY	A		P	N	2"		P	1"		NONRES						Installed after lead ban	Y	2018	nsp during install o	Field inspection only	Y		Cross-connection survey	
2270	HOLMGREN WAY	B		P	N	2"		P	1"		NONRES						Installed after lead ban	Y	2018	nsp during install o	Field inspection only	Y		Cross-connection survey	

LOCATIONAL IDENTIFIER ADDRESS	LOCATIONAL IDENTIFIER STREET NAME	LOCATIONAL IDENTIFIER UNIT OR SUITE #	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
2385	HOLMGREN WAY	105		UNK-NOLG	N			P	1"		NONRES						Installed after lead ban	Y	1998		Field inspection only	Y		Cross-connection survey	
2385	HOLMGREN WAY	103		UNK-NOLG	N			P	1"		NONRES						Installed after lead ban	Y	1998		Field inspection only	Y		Cross-connection survey	
2385	HOLMGREN WAY	101		UNK-NOLG	N			P	2"		NONRES						Installed after lead ban	Y	1998		Field inspection only	Y		Cross-connection survey	
2080	HOLMGREN WAY			UNK-NOLG	N			C	1"		NONRES						Installed after lead ban	Y	1998		Field inspection only	Y		Cross-connection survey	
2240	HOLMGREN WAY			UNK-NOLG	N			C	1"		NONRES						Installed after lead ban	Y	1998		Field inspection only	Y		Cross-connection survey	
1929	HOLMGREN WAY			UNK-NOLG	N			C	1"		NONRES						Installed after lead ban	Y	1998		Field inspection only	Y		Cross-connection survey	
1919	HOLMGREN WAY			UNK-NOLG	N			C	1"		NONRES						Installed after lead ban	Y	1998		Field inspection only	Y		Cross-connection survey	
2461	HOLMGREN WAY			UNK-NOLG	N	8"		DI	8"		NONRES						Installed after lead ban	Y	2015	ısp during install o	Field inspection only	Y		Cross-connection survey	
2070	HOLMGREN WAY			UNK-NOLG	N			P	2"		NONRES						Installed after lead ban	Y	1998		Field inspection only	Y		Cross-connection survey	
2401	HOLMGREN WAY			UNK-NOLG	N			C	1"		NONRES						Installed after lead ban	Y	1998		Field inspection only	Y		Cross-connection survey	
2363	HOLMGREN WAY	B		UNK-NOLG	N			C	1"		NONRES						Installed after lead ban	Y	1998		Field inspection only	Y		Cross-connection survey	
2944	HOLMGREN WAY			UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
2351	HOLMGREN WAY			UNK-NOLG	N			C	1"		NONRES						Installed after lead ban	Y	1998		Field inspection only	Y		Cross-connection survey	
3014	HOLMGREN WAY			UNK-NOLG	N			C	1"		NONRES						Installed after lead ban	Y	1998		Field inspection only	Y		Cross-connection survey	
1931	HOLMGREN WAY			UNK-NOLG	N			C	1"		NONRES						Installed after lead ban	Y	1998		Field inspection only	Y		Cross-connection survey	
1941	HOLMGREN WAY			UNK-NOLG	N			C	3/4"		NONRES						Installed after lead ban	Y	1998		Field inspection only	Y		Cross-connection survey	
1941	HOLMGREN WAY			UNK-NOLG	N			C	3/4"		NONRES						Installed after lead ban	Y	1998		Field inspection only	Y		Cross-connection survey	
2280	HOLMGREN WAY			UNK-NOLG	N			C	1 1/2"		NONRES						Installed after lead ban	Y	1998		Field inspection only	Y		Cross-connection survey	
2325	HOLMGREN WAY	120		P	N			C	1"		NONRES						Installed after lead ban	Y	1998		Field inspection only	Y		Cross-connection survey	
2325	HOLMGREN WAY	110		P	N			C	1"		NONRES						Installed after lead ban	Y	1998		Field inspection only	Y		Cross-connection survey	
2689	HOLMGREN WAY			P	N			C	1"		NONRES						Installed after lead ban	Y	1998		Field inspection only	Y		Cross-connection survey	
3176	HOLMGREN WAY			P	N			C	1"		NONRES						Installed after lead ban	Y	1998		Field inspection only	Y		Cross-connection survey	
2042	HOLMGREN WAY			P	N			P	1"		NONRES						Installed after lead ban	Y	1998		Field inspection only	Y		Cross-connection survey	
2150	HOLMGREN WAY			P	N			C	1"		NONRES						Installed after lead ban	Y	1998		Field inspection only	Y		Cross-connection survey	
2150	HOLMGREN WAY			P	N			C	1"		NONRES						Installed after lead ban	Y	1998		Field inspection only	Y		Cross-connection survey	
3100	HOLMGREN WAY			P	N			C	1"		NONRES						Installed after lead ban	Y	1998		Field inspection only	Y		Cross-connection survey	
3120	HOLMGREN WAY			P	N			C	1"		NONRES						Installed after lead ban	Y	1998		Field inspection only	Y		Cross-connection survey	
3080	HOLMGREN WAY			P	N			C	1"		NONRES						Installed after lead ban	Y	1998		Field inspection only	Y		Cross-connection survey	
2220	HOLMGREN WAY			P	N			P	2"		NONRES						Installed after lead ban	Y	1998		Field inspection only	Y		Cross-connection survey	
2052	HOLMGREN WAY			P	N			C	1"		NONRES						Installed after lead ban	Y	1998		Field inspection only	Y		Cross-connection survey	
2132	HOLMGREN WAY			P	N			P	3"		MF						Installed after lead ban	Y	1998		Field inspection only	Y		Cross-connection survey	
2100	HOLMGREN WAY			P	N			P	2"		MF						Installed after lead ban	Y	1998		Field inspection only	Y		Cross-connection survey	
2411	HOLMGREN WAY			P	N			P	2"		NONRES						Installed after lead ban	Y	1998		Field inspection only	Y		Cross-connection survey	
2250	HOLMGREN WAY			P	N			P	1"		NONRES						Installed after lead ban	Y	1998		Field inspection only	Y		Cross-connection survey	
2083	HOLMGREN WAY			P	N			P	1"		NONRES						Installed after lead ban	Y	1998		Field inspection only	Y		Cross-connection survey	
2441	HOLMGREN WAY			P	N			P	1"		NONRES						Installed after lead ban	Y	1998		Field inspection only	Y		Cross-connection survey	
1992	HOLMGREN WAY			P	N			P	2"		NONRES						Installed after lead ban	Y	1998		Field inspection only	Y		Cross-connection survey	
1963	HOLMGREN WAY			P	N			P	1 1/2"		NONRES						Installed after lead ban	Y	1998		Field inspection only	Y		Cross-connection survey	
1963	HOLMGREN WAY			P	N			P	1 1/2"		NONRES						Installed after lead ban	Y	1998		Field inspection only	Y		Cross-connection survey	
2391	HOLMGREN WAY	A & B		P	N			P & C	2"		NONRES						Installed after lead ban	Y	1998		Field inspection only	Y		Cross-connection survey	
2870	HOLMGREN WAY			P	N			C	1"		NONRES						Installed after lead ban	Y	1998		Field inspection only	Y		Cross-connection survey	
2041	HOLMGREN WAY			P	N			C	2"		NONRES						Installed after lead ban	Y	1998		Field inspection only	Y		Cross-connection survey	
2611	HOLMGREN WAY			P	N			C	2"		NONRES						Installed after lead ban	Y	1998		Field inspection only	Y		Cross-connection survey	
3185	HOLMGREN WAY			P	N			C	1 1/2"		NONRES						Installed after lead ban	Y	1998		Field inspection only	Y		Cross-connection survey	
3161	HOLMGREN WAY			P	N			C	1"		NONRES						Installed after lead ban	Y	1998		Field inspection only	Y		Cross-connection survey	
2140	HOLMGREN WAY			P	N			P	2"		NONRES						Installed after lead ban	Y	1998		Field inspection only	Y		Cross-connection survey	
1978	HOLMGREN WAY			P	N			P	3"		NONRES						Installed after lead ban	Y	1998		Field inspection only	Y		Cross-connection survey	
3154	HOLMGREN WAY			P	N			P	2"		NONRES						Installed after lead ban	Y	1998		Field inspection only	Y		Cross-connection survey	
3171	HOLMGREN WAY			P	N			C	1"		NONRES						Installed after lead ban	Y	1998		Field inspection only	Y		Cross-connection survey	
3121	HOLMGREN WAY			P	N			C	1"		NONRES						Installed after lead ban	Y	1998		Field inspection only	Y		Cross-connection survey	
3135	HOLMGREN WAY			P	N			C	1"		NONRES						Installed after lead ban	Y	1998		Field inspection only	Y		Cross-connection survey	
3211	HOLMGREN WAY			P	N			C	1"		NONRES						Installed after lead ban	Y	1998		Field inspection only	Y		Cross-connection survey	
699	CORONIS CIRCLE			C	N			C	1"		NONRES						Installation record	N	1976		Field inspection only	Y		Cross-connection survey	
3134	HOLMGREN WAY			P	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
2590	HOLMGREN WAY			P	N			P	2"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
3101	HOLMGREN WAY	A		P	N			P	2"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
3101	HOLMGREN WAY	B		P	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
3136	HOLMGREN WAY			P	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
2610	HOLMGREN WAY	110		P	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
2600	HOLMGREN WAY	101		P	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
2995	HOLMGREN WAY			P	N	8"		P	1"		MF					8" plastic lateral feeds this grou	Installation record	Y			Field inspection only	Y		Cross-connection survey	
2987	HOLMGREN WAY			P	N	8"		P	3"		MF						Installation record	Y			Field inspection only	Y		Cross-connection survey	
2985	HOLMGREN WAY			P	N	8"		P	2"		MF						Installation record	Y			Field inspection only	Y		Cross-connection survey	
2993	HOLMGREN WAY			P	N	8"		P	2"		MF						Installation record	Y			Field inspection only	Y		Cross-connection survey	
2983	HOLMGREN WAY			P	N	8"		P	2"		MF						Installation record	Y			Field inspection only	Y		Cross-connection survey	
2991	HOLMGREN WAY			P	N	8"		P	2"		MF						Installation record	Y			Field inspection only	Y		Cross-connection survey	
2981	HOLMGREN WAY			P	N	8"		P	2"		MF						Installation record	Y			Field inspection only	Y		Cross-connection survey	
2989	HOLMGREN WAY			P	N	8"		P	2"		MF						Installation record	Y			Field inspection only	Y		Cross-connection survey	
3190	HOLMGREN WAY			P	N	2"		P	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
3019	HOLMGREN WAY			P	N	2"		C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
3021	HOLMGREN WAY			P	N	2"		C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
3021	HOLMGREN WAY	WOM		P	N	2"		C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
2200	HOLMGREN WAY			P	N	2"		C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
2067	HOLMGREN WAY			P	N	2"		C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
2160	HOLMGREN WAY			P	N	2"		P	1 1/4"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
3050	HOLMGREN WAY			P	N	2"		C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
3050	HOLMGREN WAY	WOM		P	N	2"		C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
3030	HOLMGREN WAY	A		P	N	8"		DI	8"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
3030	HOLMGREN WAY	B		P	N	8"		DI	8"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
3030	HOLMGREN WAY	C		P	N	8"		DI	8"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
2984	HOLMGREN WAY	2		P	N	2"		C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
2984	HOLMGREN WAY	1		P	N	2"		C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
2954	HOLMGREN WAY	1		P	N	2"		C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
3206	HOLMGREN WAY			P	N	2"		C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
2669	INDUSTRY COURT			P	N	6"		DI	4"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	

LOCATIONAL IDENTIFIER ADDRESS	LOCATIONAL IDENTIFIER STREET NAME	LOCATIONAL IDENTIFIER UNIT OR SUITE #	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
740	INDUSTRY COURT			P	N	2"		P	2"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
2666	INDUSTRY COURT			P	N	2"		P	2"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
2661	INDUSTRY COURT			P	N	2"		P	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
2625	INDUSTRY COURT			P	N	2"		P	2"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
451	JOANNES AVENUE			P	N	8"		P	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
451	JOANNES AVENUE			P	N	8"		P	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1291	LOMBARDI AVENUE			P	N			C	1"		NONRES						Installed after lead ban	Y	2016		Field inspection only	Y		Cross-connection survey	
1317	LOMBARDI ACCESS			P	N			P	1"		NONRES						Installed after lead ban	Y	2016		Field inspection only	Y		Cross-connection survey	
1241	LOMBARDI ACCESS	G		P	N			P	2"		NONRES						Installed after lead ban	Y	2016		Field inspection only	Y		Cross-connection survey	
1241	LOMBARDI ACCESS	J		P	N			P	1"		NONRES						Installed after lead ban	Y	2016		Field inspection only	Y		Cross-connection survey	
1241	LOMBARDI ACCESS	A		P	N			P	1"		NONRES						Installed after lead ban	Y	2016		Field inspection only	Y		Cross-connection survey	
1241	LOMBARDI ACCESS	B		P	N			P	1"		NONRES						Installed after lead ban	Y	2016		Field inspection only	Y		Cross-connection survey	
1241	LOMBARDI ACCESS	WOM		P	N			P	1"		NONRES						Installed after lead ban	Y	2016		Field inspection only	Y		Cross-connection survey	
1241	LOMBARDI ACCESS	D		P	N			P	1"		NONRES						Installed after lead ban	Y	2016		Field inspection only	Y		Cross-connection survey	
1241	LOMBARDI ACCESS	I		P	N			P	1"		NONRES						Installed after lead ban	Y	2016		Field inspection only	Y		Cross-connection survey	
1241	LOMBARDI ACCESS	H		P	N			P	1"		NONRES						Installed after lead ban	Y	2016		Field inspection only	Y		Cross-connection survey	
1241	LOMBARDI ACCESS	F		P	N			P	1"		NONRES						Installed after lead ban	Y	2016		Field inspection only	Y		Cross-connection survey	
1221	LOMBARDI ACCESS			P	N			P	2"		NONRES						Installed after lead ban	Y	2016		Field inspection only	Y		Cross-connection survey	
1065	LOMBARDI AVENUE			P	N			C	1"		NONRES						Installed after lead ban	Y	2016		Field inspection only	Y		Cross-connection survey	
1065	LOMBARDI AVENUE			P	N			C	2"		NONRES						Installed after lead ban	Y	2016		Field inspection only	Y		Cross-connection survey	
1065	LOMBARDI AVENUE			P	N			C	2"		NONRES						Installed after lead ban	Y	2016		Field inspection only	Y		Cross-connection survey	
1065	LOMBARDI AVENUE			P	N			C	1"		NONRES						Installed after lead ban	Y	2016		Field inspection only	Y		Cross-connection survey	
1065	LOMBARDI AVENUE			P	N			C	1 1/2"		NONRES						Installed after lead ban	Y	2016		Field inspection only	Y		Cross-connection survey	
1065	LOMBARDI AVENUE			P	N			C	2"		NONRES						Installed after lead ban	Y	2016		Field inspection only	Y		Cross-connection survey	
1155	LOMBARDI AVENUE			P	N						NONRES						Installed after lead ban	Y	2016		Field inspection only	Y		Cross-connection survey	
1265	LOMBARDI AVENUE	WOM		P	N	8"		C	3"		NONRES				Lambeau is fed by an 8" pri		Installation record	Y			Field inspection only	Y		Cross-connection survey	
1265	LOMBARDI AVENUE	WOM		P	N	8"		C	3"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1265	LOMBARDI AVENUE	WOM		P	N	8"		C	6"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1265	LOMBARDI AVENUE	WOM		P	N	8"		C	3"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1265	LOMBARDI AVENUE	WOM		P	N	8"		C	2"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1265	LOMBARDI AVENUE	WOM		P	N	8"		C	2"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1001	LOMBARDI AVENUE			P	N	6"		DI	6"		NONRES						Installed after lead ban	Y	2016		Field inspection only	Y		Cross-connection survey	
871	LOMBARDI AVENUE			P	N	2"		C	1 1/2"		NONRES						Installed after lead ban	Y	2016		Field inspection only	Y		Cross-connection survey	
787	LOMBARDI AVENUE			P	N	2"		C	1"		NONRES						Installed after lead ban	Y	2016		Field inspection only	Y		Cross-connection survey	
1251	LOMBARDI AVENUE			P	N	2"		C	2"		NONRES						Installed after lead ban	Y	2016		Field inspection only	Y		Cross-connection survey	
753	LOMBARDI AVENUE			P	N	2"		P	2"		NONRES						Installed after lead ban	Y	2016		Field inspection only	Y		Cross-connection survey	
1499	LOMBARDI AVENUE			P	N	2"		P	2"		NONRES						Installed after lead ban	Y	2016		Field inspection only	Y		Cross-connection survey	
1499	LOMBARDI AVENUE	WOM		P	N	2"		C	1"		NONRES						Installed after lead ban	Y	2016		Field inspection only	Y		Cross-connection survey	
1499	LOMBARDI AVENUE			P	N	2"		P	2"		NONRES						Installed after lead ban	Y	2016		Field inspection only	Y		Cross-connection survey	
3600	LOST LANE			C	N	2"		C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1145	W MAIN AVENUE			P	N			P	2"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1141	W MAIN AVENUE			P	N			P	2"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1101	W MAIN AVENUE			P	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1385	W MAIN AVENUE			P	N	6"		DI	6"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1450	W MAIN AVENUE			P	N	6"		DI	4"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1140	W MAIN AVENUE			P	N			P	2"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1151	W MAIN AVENUE			P	N			P	2"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1375	W MAIN AVENUE			P	N			C	2"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1420	W MAIN AVENUE			P	N			P	3"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1245	W MAIN AVENUE			P	N			P	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1121	W MAIN AVENUE			P	N			P	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1300	W MAIN AVENUE	100		P	N			P	2"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1300	W MAIN AVENUE	150		P	N			P	2"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1500	W MAIN AVENUE			P	N			P	2"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1652	W MAIN AVENUE			P	N	8"		P	1 1/2"		MF				8" private lateral feeds the:		Installed after lead ban	Y	2007	ısp during install o	Field inspection only	Y		Cross-connection survey	
1648	W MAIN AVENUE			P	N	8"		P	1 1/2"		MF						Installed after lead ban	Y	2007	ısp during install o	Field inspection only	Y		Cross-connection survey	
1644	W MAIN AVENUE			P	N	8"		P	1 1/2"		MF						Installed after lead ban	Y	2007	ısp during install o	Field inspection only	Y		Cross-connection survey	
1640	W MAIN AVENUE			P	N	8"		P	1 1/2"		MF						Installed after lead ban	Y	2007	ısp during install o	Field inspection only	Y		Cross-connection survey	
1636	W MAIN AVENUE			P	N	8"		P	1 1/2"		MF						Installed after lead ban	Y	2007	ısp during install o	Field inspection only	Y		Cross-connection survey	
1632	W MAIN AVENUE			P	N	8"		P	1 1/2"		MF						Installed after lead ban	Y	2007	ısp during install o	Field inspection only	Y		Cross-connection survey	
1628	W MAIN AVENUE			P	N	8"		P	1 1/2"		MF						Installed after lead ban	Y	2007	ısp during install o	Field inspection only	Y		Cross-connection survey	
1624	W MAIN AVENUE			P	N	8"		P	1"		MF						Installed after lead ban	Y	2007	ısp during install o	Field inspection only	Y		Cross-connection survey	
1620	W MAIN AVENUE			P	N	8"		P	1"		MF						Installed after lead ban	Y	2007	ısp during install o	Field inspection only	Y		Cross-connection survey	
1511	W MAIN AVENUE			P	N			P	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1511	W MAIN AVENUE			P	N			P	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1540	W MAIN AVENUE	A		P	N			P	2"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1540	W MAIN AVENUE	WOM		P	N			P	2"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1540	W MAIN AVENUE	C		P	N			P	2"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1540	W MAIN AVENUE	B		P	N			P	2"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1400	W MAIN AVENUE			P	N			P	2"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1260	W MAIN AVENUE			P	N			P	2"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1680	W MAIN CIRCLE			P	N	8"		P	1 1/2"		MF				8" lateral feeds these ac		Installed after lead ban	Y	2007	ısp during install o	Field inspection only	Y		Cross-connection survey	
1696	W MAIN CIRCLE			P	N	8"		P	1 1/2"		MF						Installed after lead ban	Y	2007	ısp during install o	Field inspection only	Y		Cross-connection survey	
1676	W MAIN CIRCLE			P	N	8"		P	1 1/2"		MF						Installed after lead ban	Y	2007	ısp during install o	Field inspection only	Y		Cross-connection survey	
1672	W MAIN CIRCLE			P	N	8"		P	1"		MF						Installed after lead ban	Y	2007	ısp during install o	Field inspection only	Y		Cross-connection survey	
1668	W MAIN CIRCLE			P	N	8"		P	1"		MF						Installed after lead ban	Y	2007	ısp during install o	Field inspection only	Y		Cross-connection survey	
1660	W MAIN CIRCLE			P	N	8"		P	3"		MF						Installed after lead ban	Y	2007	ısp during install o	Field inspection only	Y		Cross-connection survey	
1664	W MAIN CIRCLE			P	N	8"		P	3"		MF						Installed after lead ban	Y	2007	ısp during install o	Field inspection only	Y		Cross-connection survey	
2480	Marina Circle			P	N	2"		P	1 1/2"		MF						Installed after lead ban	Y	2003	ısp during install o	Field inspection only	Y		Cross-connection survey	
2465	Marina Circle			P	N	2"		P	1/2"		NONRES						Installed after lead ban	Y	2003	ısp during install o	Field inspection only	Y		Cross-connection survey	
470	MARINA LANE			P	N	2"		P	1"		NONRES						Installed after lead ban	Y	2003	ısp during install o	Field inspection only	Y		Cross-connection survey	
465	MARINA LANE			P	N	6"		DI	6"		NONRES						Installed after lead ban	Y	2003	ısp during install o	Field inspection only	Y		Cross-connection survey	
3110	MARKET STREET			C	N			P	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
3194	MARKET STREET	C		C	N			C	2"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
3194	MARKET STREET	D		C	N			C	2"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	

LOCATIONAL IDENTIFIER ADDRESS	LOCATIONAL IDENTIFIER STREET NAME	LOCATIONAL IDENTIFIER UNIT OR SUITE #	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
3194	MARKET STREET	F		C	N			C	2"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
3194	MARKET STREET	E		C	N			C	2"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
3194	MARKET STREET	A		C	N			C	2"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
3194	MARKET STREET	B		C	N			C	2"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
3146	MARKET STREET			C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
3158	MARKET STREET			C	N			C	1 1/2"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
3080	MARKET STREET			C	N			C	3/4"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
3100	MARKET STREET			C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
3090	MARKET STREET	A		C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
3131	MARKET STREET			C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
3111	MARKET STREET	A		C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
3111	MARKET STREET	B		C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
3111	MARKET STREET	D		C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
3224	MARKET STREET			C	N			C	1 1/4"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
3138	MARKET STREET			C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
3091	MARKET STREET			C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
3095	MARKET STREET			C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
3161	MARKET STREET			C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
3185	MARKET STREET			C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
3201	MARKET STREET	C		C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
3201	MARKET STREET	A		C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
3201	MARKET STREET	B		C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
827	MARQUIS WAY			C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
817	MARQUIS WAY			C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
812	MARQUIS WAY	A		C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
828	MARVELLE LANE			C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
822	MARVELLE LANE			C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
790	MARVELLE LANE	1		C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
790	MARVELLE LANE	2		C	N			P	3"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
790	MARVELLE LANE	3		C	N			P	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
801	MARVELLE LANE			C	N			C	2"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1372-1380	MESA DRIVE			C	N			P	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1370	MESA DRIVE			C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
686	MIKE MCCARTHY WAY			P	N	6"		P	4"		MF						Installed after lead ban	Y	2012-2018	ısp during install o	Field inspection only	Y		Cross-connection survey	
686	MIKE MCCARTHY WAY	100		P	N	6"		P	1"		NONRES						Installed after lead ban	Y	2012-2018	ısp during install o	Field inspection only	Y		Cross-connection survey	
686	MIKE MCCARTHY WAY	110		P	N	6"		P	4"		MF						Installed after lead ban	Y	2012-2018	ısp during install o	Field inspection only	Y		Cross-connection survey	
686	MIKE MCCARTHY WAY	120		P	N	6"		P	4"		NONRES						Installed after lead ban	Y	2012-2018	ısp during install o	Field inspection only	Y		Cross-connection survey	
705	MIKE MCCARTHY WAY			P	N	2"		C	2"		NONRES						Installed after lead ban	Y	2012-2018	ısp during install o	Field inspection only	Y		Cross-connection survey	
711	MIKE MCCARTHY WAY			P	N	2"		C	1"		NONRES						Installed after lead ban	Y	2012-2018	ısp during install o	Field inspection only	Y		Cross-connection survey	
838	MIKE MCCARTHY WAY			P	N	2"		P	1"		NONRES						Installed after lead ban	Y	2012-2018	ısp during install o	Field inspection only	Y		Cross-connection survey	
838	MIKE MCCARTHY WAY			P	N	2"		P	1"		NONRES						Installed after lead ban	Y	2012-2018	ısp during install o	Field inspection only	Y		Cross-connection survey	
790	MIKE MCCARTHY WAY			P	N	2"		P	1 1/2"		NONRES						Installed after lead ban	Y	2012-2018	ısp during install o	Field inspection only	Y		Cross-connection survey	
800	MIKE MCCARTHY WAY			P	N	2"		P	1"		NONRES						Installed after lead ban	Y	2012-2018	ısp during install o	Field inspection only	Y		Cross-connection survey	
851	MIKE MCCARTHY WAY			P	N	2"		P	1"		NONRES						Installed after lead ban	Y	2012-2018	ısp during install o	Field inspection only	Y		Cross-connection survey	
835	MIKE MCCARTHY WAY			P	N	2"		P	1 1/2"		NONRES						Installed after lead ban	Y	2012-2018	ısp during install o	Field inspection only	Y		Cross-connection survey	
781	MIKE MCCARTHY WAY			P	N	2"		C	1"		NONRES						Installed after lead ban	Y	2012-2018	ısp during install o	Field inspection only	Y		Cross-connection survey	
580	MIKE MCCARTHY WAY	SHOP		P	N	2"		C	1"		NONRES						Installed after lead ban	Y	2012-2018	ısp during install o	Field inspection only	Y		Cross-connection survey	
580	MIKE MCCARTHY WAY			P	N	2"		C	1"		NONRES						Installed after lead ban	Y	2012-2018	ısp during install o	Field inspection only	Y		Cross-connection survey	
842	MIKE MCCARTHY WAY			P	N	2"		C	1"		NONRES						Installed after lead ban	Y	2012-2018	ısp during install o	Field inspection only	Y		Cross-connection survey	
787	MIKE MCCARTHY WAY			P	N	2"		C	1"		NONRES						Installed after lead ban	Y	2012-2018	ısp during install o	Field inspection only	Y		Cross-connection survey	
787	MIKE MCCARTHY WAY			P	N	2"		C	3/4"		NONRES						Installed after lead ban	Y	2012-2018	ısp during install o	Field inspection only	Y		Cross-connection survey	
799	MIKE MCCARTHY WAY			P	N	2"		C	1"		NONRES						Installed after lead ban	Y	2012-2018	ısp during install o	Field inspection only	Y		Cross-connection survey	
825	MIKE MCCARTHY WAY			P	N	2"		P	1"		NONRES						Installed after lead ban	Y	2012-2018	ısp during install o	Field inspection only	Y		Cross-connection survey	
620	MIKE MCCARTHY WAY			P	N	2"		P	1"		NONRES						Installed after lead ban	Y	2012-2018	ısp during install o	Field inspection only	Y		Cross-connection survey	
757	MIKE MCCARTHY WAY			P	N	2"		C	3/4"		NONRES						Installed after lead ban	Y	2012-2018	ısp during install o	Field inspection only	Y		Cross-connection survey	
729	MIKE MCCARTHY WAY			P	N	2"		C	3/4"		NONRES						Installed after lead ban	Y	2012-2018	ısp during install o	Field inspection only	Y		Cross-connection survey	
651	MIKE MCCARTHY WAY			P	N	2"		C	1"		NONRES						Installed after lead ban	Y	2012-2018	ısp during install o	Field inspection only	Y		Cross-connection survey	
733	MIKE MCCARTHY WAY			P	N	2"		C	1"		NONRES						Installed after lead ban	Y	2012-2018	ısp during install o	Field inspection only	Y		Cross-connection survey	
645	MIKE MCCARTHY WAY			P	N	2"		P	1"		NONRES						Installed after lead ban	Y	2012-2018	ısp during install o	Field inspection only	Y		Cross-connection survey	
771	MIKE MCCARTHY WAY			P	N	2"		C	1"		NONRES						Installed after lead ban	Y	2012-2018	ısp during install o	Field inspection only	Y		Cross-connection survey	
773	MIKE MCCARTHY WAY			P	N	2"		C	1"		NONRES						Installed after lead ban	Y	2012-2018	ısp during install o	Field inspection only	Y		Cross-connection survey	
741	MIKE MCCARTHY WAY			P	N	2"		C	1"		NONRES						Installed after lead ban	Y	2012-2018	ısp during install o	Field inspection only	Y		Cross-connection survey	
753	MIKE MCCARTHY WAY			P	N	2"		C	1 1/2"		NONRES						Installed after lead ban	Y	2012-2018	ısp during install o	Field inspection only	Y		Cross-connection survey	
585	MIKE MCCARTHY WAY			P	N	2"		P	2"		NONRES						Installed after lead ban	Y	2012-2018	ısp during install o	Field inspection only	Y		Cross-connection survey	
755	MIKE MCCARTHY WAY			P	N	2"		C	1"		NONRES						Installed after lead ban	Y	2012-2018	ısp during install o	Field inspection only	Y		Cross-connection survey	
830	MORRIS AVENUE			P	N			P	4"		NONRES						Installed after lead ban	Y	2022	ısp during install o	Field inspection only	Y		Cross-connection survey	
1303	MORRIS AVENUE			C	N			P	1 1/2"		NONRES						Installed after lead ban	Y	2022	ısp during install o	Field inspection only	Y		Cross-connection survey	
426	MORRIS AVENUE			C	N			P	3"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
786	MORRIS AVENUE			P	N			P	1"		NONRES						Installed after lead ban	Y	2022	ısp during install o	Field inspection only	Y		Cross-connection survey	
810	MORRIS AVENUE			P	N			P	1 1/2"		NONRES						Installed after lead ban	Y	2022	ısp during install o	Field inspection only	Y		Cross-connection survey	
846	MORRIS AVENUE			P	N			C	1"		NONRES						Installed after lead ban	Y	2022	ısp during install o	Field inspection only	Y		Cross-connection survey	
1311	MORRIS AVENUE			C	N			C	1 1/2"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1319	MORRIS AVENUE			C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
751	MORRIS AVENUE			C	N			C	1 1/2"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
731	MORRIS AVENUE			C	N			P	1 1/2"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
720	MORRIS AVENUE			C	N			C	2"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
862	MORRIS AVENUE			P	N			P	1"		NONRES						Installed after lead ban	Y	2022	ısp during install o	Field inspection only	Y		Cross-connection survey	
732	MORRIS AVENUE			C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
825	MORRIS AVENUE			C	N			C	1"		NONRES						Installed after lead ban	Y	2022	ısp during install o	Field inspection only	Y		Cross-connection survey	
1325	MORRIS AVENUE			C	N			C	1 1/2"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1411	MORRIS AVENUE			C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1410	MORRIS AVENUE			C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
780	MORRIS AVENUE			P	N			C	1"		NONRES						Installed after lead ban	Y	2022	ısp during install o	Field inspection only	Y		Cross-connection survey	
1331	NORTH ROAD	300		C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1331	NORTH ROAD	100		C	N			P	2"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	

LOCATIONAL IDENTIFIER ADDRESS	LOCATIONAL IDENTIFIER STREET NAME	LOCATIONAL IDENTIFIER UNIT OR SUITE #	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
1331	NORTH ROAD	200		C	N			P	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1365	NORTH ROAD	G		P	N			P	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1365	NORTH ROAD	F		P	N			P	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1365	NORTH ROAD	D		P	N			P	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1365	NORTH ROAD	B		P	N			P	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1365	NORTH ROAD	A		P	N			P	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1391	NORTH ROAD			C	N			P	1 1/2"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1445	NORTH ROAD	2		C	N			C	1"		SCH/DC						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1445	NORTH ROAD	1		C	N			C	1"		SCH/DC						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1381	NORTH ROAD			C	N			C	1 1/2"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1375	NORTH ROAD			C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1345	NORTH ROAD	D		P	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1345	NORTH ROAD	C		P	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1345	NORTH ROAD	B		P	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1345	NORTH ROAD	A		P	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
2101	S ONEIDA STREET	300		P	N			P	1 1/2"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2101	S ONEIDA STREET	200		P	N			C	1"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2101	S ONEIDA STREET	100		P	N			P	2"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2101	S ONEIDA STREET	500		P	N			P	3"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2101	S ONEIDA STREET	400		P	N			C	1"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2237	S ONEIDA STREET			P	N				1 1/2"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2321	S ONEIDA STREET	10		P	N			C	1"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2321	S ONEIDA STREET	5		P	N			C	1 1/2"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2321	S ONEIDA STREET	3		P	N			C	1"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2321	S ONEIDA STREET	1		P	N			C	1"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2321	S ONEIDA STREET	8		P	N			C	1"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2321	S ONEIDA STREET	4		P	N			C	1"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2321	S ONEIDA STREET	WOM		P	N			C	1"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2321	S ONEIDA STREET	7		P	N			C	2"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2321	S ONEIDA STREET	9		P	N			C	1"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2621	S ONEIDA STREET	105		P	N			P	1"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2621	S ONEIDA STREET	102		P	N			P	1"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2621	S ONEIDA STREET	107		P	N			P	1"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2621	S ONEIDA STREET	108		P	N			P	1"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2621	S ONEIDA STREET	101		P	N			P	1"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2610	S ONEIDA STREET			P	N			P	1 1/2"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2456	S ONEIDA STREET			P	N			P	1 1/2"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2404	S ONEIDA STREET			P	N			P	1"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2893	S ONEIDA STREET			P	N				1"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2032	S ONEIDA STREET			P	N			P	1"		MF						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2615	S ONEIDA STREET			P	N			C	6"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2394	S ONEIDA STREET			P	N			C	1"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2253	S ONEIDA STREET			P	N			C	1"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2430	S ONEIDA STREET			P	N			C	2"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2475	S ONEIDA STREET			P	N			C	1"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2249	S ONEIDA STREET			P	N			C	1"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2215	S ONEIDA STREET			P	N			C	1"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2498	S ONEIDA STREET			P	N			DI	2"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2492	S ONEIDA STREET	WOM		P	N			DI	1"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2492	S ONEIDA STREET			P	N			DI	2"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2627	S ONEIDA STREET			P	N			DI	2"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2388	S ONEIDA STREET	300		P	N			DI	6"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2388	S ONEIDA STREET	200		P	N			DI	6"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2388	S ONEIDA STREET	100		P	N			DI	6"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2031	S ONEIDA STREET			P	N			C	1 1/2"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2700	S ONEIDA STREET			P	N			DI	4"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2403	S ONEIDA STREET			P	N			C	1"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2075	S ONEIDA STREET			P	N			P	1"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2075	S ONEIDA STREET	C		P	N			P	2"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2270	S ONEIDA STREET			P	N			DI	4"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2815	S ONEIDA STREET	C		P	N			C	1 1/4"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2815	S ONEIDA STREET			P	N			C	1 1/4"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2868	S ONEIDA STREET			P	N			P	3"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2330	S ONEIDA STREET	106		P	N			P	1"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2330	S ONEIDA STREET	101		P	N			P	1"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2330	S ONEIDA STREET	103		P	N			P	1 1/2"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2654	S ONEIDA STREET			P	N			P	2"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2654	S ONEIDA STREET			P	N			P	2"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2370	S ONEIDA STREET			P	N			C	3/4"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2357	S ONEIDA STREET			P	N			C	1"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2814	S ONEIDA STREET			P	N			C	1"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2301	S ONEIDA STREET			P	N			C	1 1/2"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2626	S ONEIDA STREET	B		P	N			P	2"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2626	S ONEIDA STREET	A		P	N			P	2"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2626	S ONEIDA STREET	WOM		P	N			P	2"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2626	S ONEIDA STREET	C		P	N			P	2"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2674	S ONEIDA STREET	101		P	N			P	1"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2674	S ONEIDA STREET	103		P	N			P	1"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2664	S ONEIDA STREET	101		P	N			P	2"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2664	S ONEIDA STREET	102		P	N			P	2"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2664	S ONEIDA STREET	103		P	N			P	2"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2664	S ONEIDA STREET	104		P	N			P	2"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2719	S ONEIDA STREET			P	N			C	1"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2161	S ONEIDA STREET			P	N			C	1 1/2"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2805	S Oneida Street			P	N			P	1"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	

LOCATIONAL IDENTIFIER ADDRESS	LOCATIONAL IDENTIFIER STREET NAME	LOCATIONAL IDENTIFIER UNIT OR SUITE #	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
2785	S ONEIDA STREET			P	N			P	1"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2779	S ONEIDA STREET			P	N			P	1 1/2"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2779	S ONEIDA STREET			P	N			P	1"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2763	S ONEIDA STREET			P	N			P	1"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2763	S ONEIDA STREET			P	N			P	1 1/2"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2783	S ONEIDA STREET			P	N			P	1"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2777	S Oneida Street			P	N			P	1"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2817	S ONEIDA STREET			P	N			P	1"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2767	S ONEIDA STREET			P	N			P	3"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2819	S ONEIDA STREET			P	N			P	6"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2279	S ONEIDA STREET	B		P	N			C	1 1/2"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2279	S ONEIDA STREET	A		P	N			C	1"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2281	S ONEIDA STREET			P	N			C	1"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2229	S ONEIDA STREET			P	N			C	1"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2231	S ONEIDA STREET			P	N			C	1"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2464	S ONEIDA STREET			P	N			C	1"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2435	S ONEIDA STREET			P	N			P	2"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2422	S ONEIDA STREET			P	N			P	2"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2350	S ONEIDA STREET			P	N			P	1"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2717	S ONEIDA STREET			P	N			P	1"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2053	S ONEIDA STREET			P	N			P	1 1/2"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2343	S ONEIDA STREET			P	N			C	1"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2340	S ONEIDA STREET			P	N			P	2"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2045	S ONEIDA STREET			P	N			C	1"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2821	S ONEIDA STREET			P	N			C	1"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2701	S ONEIDA STREET			P	N			C	2"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2415	S ONEIDA STREET			P	N			C	1"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2883	S ONEIDA STREET	100		P	N			P	4"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2883	S ONEIDA STREET	300		P	N			P	1"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2883	S ONEIDA STREET	200		P	N			P	1"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2883	S ONEIDA STREET	WOM		P	N			P	1"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2800	S ONEIDA STREET			P	N			C	2"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2495	S ONEIDA STREET			P	N			P	6"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2851	S ONEIDA STREET			P	N			P	2"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2594	S ONEIDA STREET			P	N			C	1"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2285	S ONEIDA STREET	1		P	N			C	2"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2840	S ONEIDA STREET			P	N			P	3"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2225	S ONEIDA STREET			P	N			C	1"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2201	S ONEIDA STREET	1		P	N			C	1"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2201	S ONEIDA STREET			P	N			C	1"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2609	S ONEIDA STREET			P	N			P	1"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2605	S ONEIDA STREET	117		P	N			P	1"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2605	S ONEIDA STREET	100		P	N			P	1"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2605	S ONEIDA STREET	128		P	N			P	1"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2605	S ONEIDA STREET	105		P	N			P	1 1/2"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2605	S ONEIDA STREET	120		P	N			P	1"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2605	S ONEIDA STREET	123		P	N			P	1 1/2"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2605	S ONEIDA STREET	125		P	N			P	1 1/2"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2605	S ONEIDA STREET	106		P	N			P	1"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2605	S ONEIDA STREET	WOM		P	N			P	1"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2605	S ONEIDA STREET	200		P	N			P	1"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2605	S ONEIDA STREET	104		P	N			C	3/4"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2605	S ONEIDA STREET	109		P	N			P	1"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2605	S ONEIDA STREET	Multi		P	N			P	1"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2605	S ONEIDA STREET	115		P	N			P	1"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2375	S ONEIDA STREET			P	N			P	1"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2550	S ONEIDA STREET			P	N			C	1"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2455	S ONEIDA STREET			P	N			P	1"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2850	S ONEIDA STREET			P	N			C	1"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2894	S ONEIDA STREET			P	N			C	1"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2476	S ONEIDA STREET	130		P	N			P	2"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2476	S ONEIDA STREET	140		P	N			P	2"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2476	S ONEIDA STREET	135		P	N			P	1"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2476	S ONEIDA STREET	150		P	N			P	1"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2476	S ONEIDA STREET	155		P	N			P	2"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2476	S ONEIDA STREET	110		P	N			P	1"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2476	S ONEIDA STREET	160		P	N			P	1"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2476	S ONEIDA STREET	100		P	N			P	1"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2476	S ONEIDA STREET	105		P	N			P	1 1/2"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2476	S ONEIDA STREET	115		P	N			P	1"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2476	S ONEIDA STREET			P	N			P	1"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2476	S ONEIDA STREET	120		P	N			P	1"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2065	S ONEIDA STREET			P	N			P	1"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2087	S ONEIDA STREET			P	N			P	1"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2081	S ONEIDA STREET			P	N			P	1"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2127	S ONEIDA STREET			P	N			C	1"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2129	S ONEIDA STREET			P	N			C	1"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2129	S ONEIDA STREET			P	N			C	1 1/2"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2113	S ONEIDA STREET			P	N			C	1"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2117	S ONEIDA STREET			P	N			C	1"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2121	S ONEIDA STREET	A		P	N			C	1"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2145	S ONEIDA STREET			P	N			C	1"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2181	S ONEIDA STREET			P	N			P	1 1/2"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2255	S ONEIDA STREET			P	N			C	1"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2257	S ONEIDA STREET			P	N			C	1"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	

LOCATIONAL IDENTIFIER ADDRESS	LOCATIONAL IDENTIFIER STREET NAME	LOCATIONAL IDENTIFIER UNIT OR SUITE #	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
2331	S ONEIDA STREET			P	N			C	1"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2337	S ONEIDA STREET			P	N			C	1"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2665	S ONEIDA STREET	F		P	N			P	1"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2665	S ONEIDA STREET	D		P	N			P	1"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2665	S ONEIDA STREET	B		P	N			P	1"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2665	S ONEIDA STREET	G		P	N			P	1"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2665	S ONEIDA STREET	E		P	N			P	2"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2665	S ONEIDA STREET	A		P	N			P	1"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2665	S ONEIDA STREET	C		P	N			P	1"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2450	S ONEIDA STREET			P	N			C	1"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2395	S Oneida Street	100		P	N			P	3"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2395	S ONEIDA STREET	120		P	N			P	3"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2418	S ONEIDA STREET			P	N			C	1"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2302	S Oneida St			P	N			P	2"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2308	S Oneida ST	100		P	N			P	2"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2308	S Oneida ST	110		P	N			P	2"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2308	S Oneida ST	120		P	N			P	2"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2314	S ONEIDA STREET			P	N			P	2"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
2740	S ONEIDA STREET			P	N			P	1"		NONRES						Installed after lead ban	Y	1998-2011	ısp during install o	Field inspection only	Y		Cross-connection survey	
1060	ORLANDO DRIVE			C	N			C	1 1/2"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
2571	PACKERLAND DRIVE			C	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
2581	PACKERLAND DRIVE			C	N			C	1 1/2"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
2707	PACKERLAND DRIVE			C	N			C	2"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
2670	PACKERLAND DRIVE			C	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
2642	PACKERLAND DRIVE			C	N			P	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
2662	PACKERLAND DRIVE			C	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
2631	PACKERLAND DRIVE	100		C	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
2631	PACKERLAND DRIVE	102		C	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
2631	PACKERLAND DRIVE	105		C	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
3377	PACKERLAND DRIVE	100		P	N			P	1 1/2"		NONRES						Installed after lead ban	Y	1994	ısp during install o	Field inspection only	Y		Cross-connection survey	
3377	PACKERLAND DRIVE	110		P	N			P	1 1/2"		NONRES						Installed after lead ban	Y	1994	ısp during install o	Field inspection only	Y		Cross-connection survey	
3377	PACKERLAND DRIVE	120		P	N			P	1 1/2"		NONRES						Installed after lead ban	Y	1994	ısp during install o	Field inspection only	Y		Cross-connection survey	
3377	PACKERLAND DRIVE	140		P	N			P	1 1/2"		NONRES						Installed after lead ban	Y	1994	ısp during install o	Field inspection only	Y		Cross-connection survey	
2688	PACKERLAND DRIVE			C	N			C	1 1/2"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
2600	PACKERLAND DRIVE			C	N			C	2"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
2710	PACKERLAND DRIVE	B		C	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
2710	PACKERLAND DRIVE	C		C	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
2710	PACKERLAND DRIVE	D		C	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
2696	PACKERLAND DRIVE	A		C	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
2696	PACKERLAND DRIVE	B		C	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
2625	PACKERLAND DRIVE			C	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
3879	PACKERLAND DRIVE			P	N			C	1"		NONRES						Installed after lead ban	Y	1994	ısp during install o	Field inspection only	Y		Cross-connection survey	
3879	PACKERLAND DRIVE			P	N			C	1"		NONRES						Installed after lead ban	Y	1994	ısp during install o	Field inspection only	Y		Cross-connection survey	
3879	PACKERLAND DRIVE			P	N			C	1 1/2"		NONRES						Installed after lead ban	Y	1994	ısp during install o	Field inspection only	Y		Cross-connection survey	
3500	PACKERLAND DRIVE			P	N			DI	4"		NONRES						Installed after lead ban	Y	1994	ısp during install o	Field inspection only	Y		Cross-connection survey	
2620	PACKERLAND DRIVE			C	N			P	2"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
2620	PACKERLAND DRIVE			C	N			P	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
3200	PACKERLAND DRIVE	A		P	N			C	1"		NONRES						Installed after lead ban	Y	1994	ısp during install o	Field inspection only	Y		Cross-connection survey	
3200	PACKERLAND DRIVE	B		P	N			C	1"		NONRES						Installed after lead ban	Y	1994	ısp during install o	Field inspection only	Y		Cross-connection survey	
3450	PACKERLAND DRIVE			P	N			P	1"		NONRES						Installed after lead ban	Y	1994	ısp during install o	Field inspection only	Y		Cross-connection survey	
3400	PACKERLAND DRIVE			P	N			DI	8"		NONRES						Installed after lead ban	Y	1994	ısp during install o	Field inspection only	Y		Cross-connection survey	
3376	PACKERLAND DRIVE			P	N			P	1 1/2"		NONRES						Installed after lead ban	Y	1994	ısp during install o	Field inspection only	Y		Cross-connection survey	
3297	PACKERLAND DRIVE			P	N			P	1 1/2"		SCH/CC						Installed after lead ban	Y	1994	ısp during install o	Field inspection only	Y		Cross-connection survey	
3301	PACKERLAND DRIVE	B		P	N			C	1"		NONRES						Installed after lead ban	Y	1994	ısp during install o	Field inspection only	Y		Cross-connection survey	
3301	PACKERLAND DRIVE	A		P	N			C	1"		NONRES						Installed after lead ban	Y	1994	ısp during install o	Field inspection only	Y		Cross-connection survey	
3311	PACKERLAND DRIVE			P	N			C	1"		NONRES						Installed after lead ban	Y	1994	ısp during install o	Field inspection only	Y		Cross-connection survey	
3313	PACKERLAND DRIVE	D		P	N			P	1"		NONRES						Installed after lead ban	Y	1994	ısp during install o	Field inspection only	Y		Cross-connection survey	
3313	PACKERLAND DRIVE	A1		P	N			C	1"		NONRES						Installed after lead ban	Y	1994	ısp during install o	Field inspection only	Y		Cross-connection survey	
3313	PACKERLAND DRIVE	A2		P	N			C	1"		NONRES						Installed after lead ban	Y	1994	ısp during install o	Field inspection only	Y		Cross-connection survey	
3313	PACKERLAND DRIVE	B		P	N			C	1"		NONRES						Installed after lead ban	Y	1994	ısp during install o	Field inspection only	Y		Cross-connection survey	
3313	PACKERLAND DRIVE	C		P	N			C	1"		NONRES						Installed after lead ban	Y	1994	ısp during install o	Field inspection only	Y		Cross-connection survey	
3313	PACKERLAND DRIVE	E		P	N			C	1"		NONRES						Installed after lead ban	Y	1994	ısp during install o	Field inspection only	Y		Cross-connection survey	
3321	PACKERLAND DRIVE	C		P	N			C	1"		NONRES						Installed after lead ban	Y	1994	ısp during install o	Field inspection only	Y		Cross-connection survey	
3321	PACKERLAND DRIVE	D		P	N			C	1"		NONRES						Installed after lead ban	Y	1994	ısp during install o	Field inspection only	Y		Cross-connection survey	
3321	PACKERLAND DRIVE	A		P	N			C	1"		NONRES						Installed after lead ban	Y	1994	ısp during install o	Field inspection only	Y		Cross-connection survey	
3321	PACKERLAND DRIVE	B		P	N			C	1"		NONRES						Installed after lead ban	Y	1994	ısp during install o	Field inspection only	Y		Cross-connection survey	
2650	PACKERLAND DRIVE			C	N			P	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
2648	PACKERLAND DRIVE			C	N			P	4"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
2720	PACKERLAND DRIVE			C	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
2740	PACKERLAND DRIVE	E		C	N			C	3/4"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
2740	PACKERLAND DRIVE	D		C	N			C	3/4"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
2740	PACKERLAND DRIVE	C		C	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
2740	PACKERLAND DRIVE	B		C	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
2740	PACKERLAND DRIVE	A		C	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
2740	PACKERLAND DRIVE	F		C	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
1543	PARK PLACE			P	N			C	2"		NONRES						Installed after lead ban	Y	1989	ısp during install o	Field inspection only	Y		Cross-connection survey	
1525	PARK PLACE	WOM		P	N			C	2"		NONRES						Installed after lead ban	Y	1989	ısp during install o	Field inspection only	Y		Cross-connection survey	
1525	PARK PLACE			P	N			C	2"		NONRES						Installed after lead ban	Y	1989	ısp during install o	Field inspection only	Y		Cross-connection survey	
1551	PARK PLACE			P	N			C	2"		NONRES						Installed after lead ban	Y	1989	ısp during install o	Field inspection only	Y		Cross-connection survey	
1537	PARK PLACE			P	N			C	2"		NONRES						Installed after lead ban	Y	1989	ısp during install o	Field inspection only	Y		Cross-connection survey	
1280	PARKVIEW ROAD	D		C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1280	PARKVIEW ROAD	B		C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1280	PARKVIEW ROAD	A		C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1280	PARKVIEW ROAD	C		C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
780	PARKVIEW ROAD			C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	

LOCATIONAL IDENTIFIER ADDRESS	LOCATIONAL IDENTIFIER STREET NAME	LOCATIONAL IDENTIFIER UNIT OR SUITE #	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
1067	PARKVIEW ROAD			C	N			P	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1260	PARKVIEW ROAD			C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1272	PARKVIEW ROAD	E		C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1272	PARKVIEW ROAD	A		C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
750	PARKVIEW ROAD			C	N			P	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1333	PARKVIEW ROAD			C	N			P	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1011	PARKVIEW ROAD			C	N			C	1 1/2"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1030	PARKVIEW ROAD			C	N			C	1 1/2"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1044	PARKVIEW ROAD			C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1332	PARKVIEW ROAD			C	N			P	1 1/2"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1201	PARKVIEW ROAD			C	N			C	1 1/2"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1281	PARKVIEW ROAD			C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1206	PARKVIEW ROAD			C	N			C	2"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1204	PARKVIEW ROAD			C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
974	PARKVIEW ROAD			C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
807	PARKVIEW ROAD			C	N			C	1 1/4"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
807	PARKVIEW ROAD	BACK		C	N			C	1 1/4"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
821	PARKVIEW ROAD			P	N			DI	4"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
821	PARKVIEW ROAD			C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
975	PARKVIEW ROAD	15		P	N			DI	4"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
975	PARKVIEW ROAD	12		P	N			DI	4"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
975	PARKVIEW ROAD	1		P	N			DI	4"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1292	PARKVIEW ROAD			C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1326	PARKVIEW ROAD			C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1272	PARKVIEW ROAD	H		C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1272	PARKVIEW ROAD	G		C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
885	PARKVIEW ROAD			C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1222	PARKVIEW ROAD			C	N			P	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
901	PARKVIEW ROAD			C	N			P	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1014	PARKVIEW ROAD	C		C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1014	PARKVIEW ROAD	C		C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1014	PARKVIEW ROAD	B		C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1014	PARKVIEW ROAD	A		C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
994	PARKVIEW ROAD			C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
984	PARKVIEW ROAD	C		C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
984	PARKVIEW ROAD	A		C	N			P	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1085	PARKVIEW ROAD			C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1085	PARKVIEW ROAD			C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1085	PARKVIEW ROAD			C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1235	PARKVIEW ROAD			C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1238	PARKVIEW ROAD			C	N			P	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1381	PARTNERSHIP DRIVE			P	N			P	1 1/2"		NONRES						Installed after lead ban	Y	1997	nsp during install o	Field inspection only	Y		Cross-connection survey	
1410	PARTNERSHIP DRIVE			P	N			P	1 1/2"		NONRES						Installed after lead ban	Y	1997	nsp during install o	Field inspection only	Y		Cross-connection survey	
1370	PARTNERSHIP DRIVE	C		P	N			P	2"		SCH/CC						Installed after lead ban	Y	1997	nsp during install o	Field inspection only	Y		Cross-connection survey	
1370	PARTNERSHIP DRIVE	B		P	N			P	2"		SCH/CC						Installed after lead ban	Y	1997	nsp during install o	Field inspection only	Y		Cross-connection survey	
1370	PARTNERSHIP DRIVE	A		P	N			P	2"		SCH/CC						Installed after lead ban	Y	1997	nsp during install o	Field inspection only	Y		Cross-connection survey	
1471	PARTNERSHIP DRIVE			P	N			P	2"		NONRES						Installed after lead ban	Y	1997	nsp during install o	Field inspection only	Y		Cross-connection survey	
1461	PARTNERSHIP DRIVE			P	N			P	1 1/2"		NONRES						Installed after lead ban	Y	1997	nsp during install o	Field inspection only	Y		Cross-connection survey	
1515	PARTNERSHIP DRIVE			P	N			C	1"		NONRES						Installed after lead ban	Y	1997	nsp during install o	Field inspection only	Y		Cross-connection survey	
1765	W PAULSON ROAD	2		C	N			P	1"		NONRES						Installation record	Y	1976	nsp during install o	Field inspection only	Y		Cross-connection survey	
1765	W PAULSON ROAD	1		C	N			P	1"		NONRES						Installation record	Y	1976	nsp during install o	Field inspection only	Y		Cross-connection survey	
1763	W PAULSON ROAD			C	N			P	1"		NONRES						Installation record	Y	1976	nsp during install o	Field inspection only	Y		Cross-connection survey	
1761	W PAULSON ROAD	A		C	N			P	1"		NONRES						Installation record	Y	1976	nsp during install o	Field inspection only	Y		Cross-connection survey	
1701	W PAULSON ROAD			C	N			C	1"		NONRES						Installation record	Y	1976	nsp during install o	Field inspection only	Y		Cross-connection survey	
1748	W PAULSON ROAD	A		C	N			P	1"		NONRES						Installation record	Y	1976	nsp during install o	Field inspection only	Y		Cross-connection survey	
1708	W PAULSON ROAD			C	N			C	1"		NONRES						Installation record	Y	1976	nsp during install o	Field inspection only	Y		Cross-connection survey	
1750	W PAULSON ROAD			C	N			P	1"		NONRES						Installation record	Y	1976	nsp during install o	Field inspection only	Y		Cross-connection survey	
1760	W PAULSON ROAD			C	N			C	1"		NONRES						Installation record	Y	1976	nsp during install o	Field inspection only	Y		Cross-connection survey	
1758	W PAULSON ROAD			C	N			C	1"		NONRES						Installation record	Y	1976	nsp during install o	Field inspection only	Y		Cross-connection survey	
1756	W PAULSON ROAD			C	N			C	1"		NONRES						Installation record	Y	1976	nsp during install o	Field inspection only	Y		Cross-connection survey	
1768	W PAULSON ROAD			C	N			C	1"		NONRES						Installation record	Y	1976	nsp during install o	Field inspection only	Y		Cross-connection survey	
1766	W PAULSON ROAD			C	N			C	1"		NONRES						Installation record	Y	1976	nsp during install o	Field inspection only	Y		Cross-connection survey	
1764	W PAULSON ROAD			C	N			C	1"		NONRES						Installation record	Y	1976	nsp during install o	Field inspection only	Y		Cross-connection survey	
1751	W PAULSON ROAD			C	N			C	1"		NONRES						Installation record	Y	1976	nsp during install o	Field inspection only	Y		Cross-connection survey	
909	PHOENIX WAY			P	N			P	1 1/4"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
761	PILGRIM WAY			P	N			C	1"		NONRES					8" lateral feeds this pr	Installed after lead ban	Y	2021	nsp during install o	Field inspection only	Y		Cross-connection survey	
811	PILGRIM WAY			P	N			P	1 1/2"		NONRES					8" plastic lateral feeds t	Installed after lead ban	Y	2007	nsp during install o	Field inspection only	Y		Cross-connection survey	
825	PILGRIM WAY	C		P	N			DI	8"		NONRES					8" plastic lateral feeds t	Installed after lead ban	Y	2007	nsp during install o	Field inspection only	Y		Cross-connection survey	
825	PILGRIM WAY	A		P	N			DI	8"		NONRES					8" plastic lateral feeds t	Installed after lead ban	Y	2007	nsp during install o	Field inspection only	Y		Cross-connection survey	
825	PILGRIM WAY	WOM		P	N			DI	8"		NONRES					8" plastic lateral feeds t	Installed after lead ban	Y	2007	nsp during install o	Field inspection only	Y		Cross-connection survey	
825	PILGRIM WAY	B		P	N			DI	8"		NONRES					8" plastic lateral feeds t	Installed after lead ban	Y	2007	nsp during install o	Field inspection only	Y		Cross-connection survey	
803	PILGRIM WAY	1		P	N			P	1 1/2"		NONRES					8" plastic lateral feeds t	Installed after lead ban	Y	2007	nsp during install o	Field inspection only	Y		Cross-connection survey	
803	PILGRIM WAY	5		P	N			P	1"		NONRES					8" plastic lateral feeds t	Installed after lead ban	Y	2007	nsp during install o	Field inspection only	Y		Cross-connection survey	
935	PILGRIM WAY			C	N			P	1 1/2"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
887	PILGRIM WAY			C	N			P	1 1/2"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
700	PILGRIM WAY			P	N			DI	4"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
465	PILGRIM WAY	WOM		P	N			P	1"		NONRES						Installed after lead ban	Y	2007	nsp during install o	Field inspection only	Y		Cross-connection survey	
465	PILGRIM WAY			P	N			P	2"		NONRES						Installed after lead ban	Y	2007	nsp during install o	Field inspection only	Y		Cross-connection survey	
480	PILGRIM WAY	1000		P	N			P	3"		NONRES						Installed after lead ban	Y	2007	nsp during install o	Field inspection only	Y		Cross-connection survey	
500	PILGRIM WAY			P	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
500	PILGRIM WAY	A		P	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1059	PILGRIM WAY			C	N			C	1"		MF						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1069	PILGRIM WAY			C	N			C	2"		MF						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1079	PILGRIM WAY			C	N			C	2"		MF						Installation record	Y			Field inspection only	Y		Cross-connection survey	
932	PILGRIM WAY			P	N			P	1 1/2"		MF					8" private lateral feeds thes	Installed after lead ban	Y	1991	nsp during install o	Field inspection only	Y		Cross-connection survey	

LOCATIONAL IDENTIFIER ADDRESS	LOCATIONAL IDENTIFIER STREET NAME	LOCATIONAL IDENTIFIER UNIT OR SUITE #	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
934	PILGRIM WAY			P	N			P	1 1/2"		MF				8" private lateral feeds thes		Installed after lead ban	Y	1991	nsp during install o	Field inspection only	Y		Cross-connection survey	
936	PILGRIM WAY			P	N			P	2"		MF				8" private lateral feeds thes		Installed after lead ban	Y	1991	nsp during install o	Field inspection only	Y		Cross-connection survey	
930	PILGRIM WAY			P	N			P	2"		MF				8" private lateral feeds thes		Installed after lead ban	Y	1991	nsp during install o	Field inspection only	Y		Cross-connection survey	
928	PILGRIM WAY			P	N			P	1 1/2"		MF				8" private lateral feeds thes		Installed after lead ban	Y	1991	nsp during install o	Field inspection only	Y		Cross-connection survey	
926	PILGRIM WAY			P	N			P	1 1/2"		MF				8" private lateral feeds thes		Installed after lead ban	Y	1991	nsp during install o	Field inspection only	Y		Cross-connection survey	
1106	PILGRIM WAY			C	N			C	2"		MF						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1096	PILGRIM WAY			C	N			C	2"		MF						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1086	PILGRIM WAY			C	N			C	2"		MF						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1116	PILGRIM WAY			C	N			C	1 1/2"		MF						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1126	PILGRIM WAY			C	N			C	1 1/2"		MF						Installation record	Y			Field inspection only	Y		Cross-connection survey	
991	PILGRIM WAY			C	N			P	1 1/2"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
991	PILGRIM WAY			C	N			P	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1091	PILGRIM WAY			C	N			P	1"		MF						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1101	PILGRIM WAY			C	N			P	2"		MF						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1113	PILGRIM WAY			C	N			P	2"		MF						Installation record	Y			Field inspection only	Y		Cross-connection survey	
565	PILGRIM WAY			C	N			P	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1241	PONDEROSA AVENUE			C	N			C	1"		MF						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1243	PONDEROSA AVENUE			C	N			C	1"		MF						Installation record	Y			Field inspection only	Y		Cross-connection survey	
2920	RAMADA WAY			C	N			P	1 1/2"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
2805	RAMADA WAY			C	N			P	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
2800	RAMADA WAY			C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
2750	RAMADA WAY	WOM		C	N			C	1 1/2"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
2750	RAMADA WAY			C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
2750	RAMADA WAY			C	N			P	3"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
2955	RAMADA WAY			C	N			C	1 1/4"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
2965	RAMADA WAY	A		C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
2965	RAMADA WAY	C		C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
2965	RAMADA WAY	B		C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
2815	RAMADA WAY			C	N			C	3"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
2840	RAMADA WAY			C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
2841	RAMADA WAY			C	N			P	3"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
2822	RAMADA WAY	100		C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
2822	RAMADA WAY	110		C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
2785	RAMADA WAY	WOM		UNK-NOLG	N			DI	1 1/2"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
2785	RAMADA WAY			UNK-NOLG	N			DI	3"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
2870	RAMADA WAY			C	N			P	3"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
2901	RAMADA WAY	100		C	N			P	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
2901	RAMADA WAY	101		C	N			P	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
2901	RAMADA WAY	101 A		C	N			P	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
2901	RAMADA WAY	103		C	N			P	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
2901	RAMADA WAY	104		C	N			P	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
2949	RAMADA WAY			C	N			C	2"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
2949	RAMADA WAY			P	N			C	3"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
2929	HOLMGREN WAY			C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
3001	RAMADA WAY	C		C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
3001	RAMADA WAY	D		C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
3001	RAMADA WAY	A		C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
3001	RAMADA WAY	B		C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
3049	RAMADA WAY			C	N			P	2"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
2830	RAMADA WAY			C	N			P	1 1/2"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
2771	RAMADA WAY			C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
2827	RAMADA WAY			C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
2240	S RIDGE ROAD			C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
2140	S RIDGE ROAD			C	N			P	1 1/2"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
2242	S RIDGE ROAD			C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1970	S RIDGE ROAD			C	N			DI	10"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1950	S RIDGE ROAD			C	N			P	2"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1950	S RIDGE ROAD			C	N			P	1 1/2"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
2160	S RIDGE ROAD			C	N			P	3"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
2158	S RIDGE ROAD			C	N			P	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
2164	S RIDGE ROAD			C	N			P	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
2162	S RIDGE ROAD			C	N			P	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
2154	S RIDGE ROAD			C	N			P	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
2156	S RIDGE ROAD			C	N			P	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
2300	S RIDGE ROAD			C	N			P	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
2282	S RIDGE ROAD			C	N			P	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
2282	S RIDGE ROAD			C	N			P	2"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
3330	S RIDGE ROAD			C	N			P	1 1/2"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
2337	S RIDGE ROAD			C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
2110	S RIDGE ROAD			C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
2248	S RIDGE ROAD			C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
2214	S RIDGE ROAD			C	N			P	1 1/2"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
2216	S RIDGE ROAD			C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
2218	S RIDGE ROAD			C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
2270	S RIDGE ROAD			C	N			P	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
2180	S RIDGE ROAD			C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
2985	S RIDGE ROAD			UNK-NOLG	N			DI	6"		NONRES						Diameter > 2 inches	Y			Field inspection only	Y		Cross-connection survey	
3130	S RIDGE ROAD			UNK-NOLG	N			DI	4"		NONRES						Diameter > 2 inches	Y			Field inspection only	Y		Cross-connection survey	
3130	S RIDGE ROAD			UNK-NOLG	N			DI	4"		NONRES						Diameter > 2 inches	Y			Field inspection only	Y		Cross-connection survey	
2733	S RIDGE ROAD			C	N			C	2"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
2202	S RIDGE ROAD			C	N			P	2"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
3195	S RIDGE ROAD			C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
2941	S RIDGE ROAD			C	N			P	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
3198	S RIDGE ROAD			C	N			P	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
3344	S RIDGE ROAD			C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	

LOCATIONAL IDENTIFIER ADDRESS	LOCATIONAL IDENTIFIER STREET NAME	LOCATIONAL IDENTIFIER UNIT OR SUITE #	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
3354	S RIDGE ROAD			C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
3230	S RIDGE ROAD			C	N			C	1 1/2"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
3142	S RIDGE ROAD			C	N			P	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
3142	S RIDGE ROAD			C	N			P	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
3168	S RIDGE ROAD			C	N			P	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
2929	S RIDGE ROAD			C	N			P	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
3215	S RIDGE RD			C	N			C	1 1/2"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1990	S Ridge Rd			C	N			C	1 1/2"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
2865	S RIDGE ROAD			C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
2445	S RIDGE ROAD			C	N			C	1 1/2"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
2439	S RIDGE ROAD			C	N			C	1 1/2"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
3355	S RIDGE ROAD	C		C	N			P	2"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
3400	S RIDGE ROAD			C	N			P	2"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
3060	S RIDGE ROAD			C	N			P	2"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
3061	S RIDGE ROAD	102		C	N			P	1 1/2"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
3061	S RIDGE ROAD	101		C	N			P	2"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
2861	S RIDGE ROAD			C	N			P	1 1/2"		SCH/CC						Installation record	Y			Field inspection only	Y		Cross-connection survey	
2353	S RIDGE ROAD			C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
2208	S RIDGE ROAD			C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
2120	S RIDGE ROAD			C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
2120	S RIDGE ROAD			C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
2023	S RIDGE ROAD			C	N			C	2"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
2321	SAN LUIS PLACE			C	N			C	2"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
2331	SAN LUIS PLACE			C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
3640	SAND ACRES DRIVE			C	N			P	1 1/4"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
3640	SAND ACRES DRIVE			C	N			P	1 1/4"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
2000	SHADY LANE			C	N			P	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
2407	SOUTH POINT ROAD			C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
2409	SOUTH POINT ROAD			C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1885	NORTH ROAD			C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
2485	SOUTH POINT ROAD			C	N			C	2"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
2499	SOUTH POINT ROAD			C	N			P	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
2499	SOUTH POINT ROAD	WOM		C	N			P	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
2499	SOUTH POINT ROAD			C	N			P	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
2499	SOUTH POINT ROAD			C	N			P	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
3383	SPIRIT WAY			P	N			P	2"		NONRES						Installed after lead ban	Y	1997	ısp during install o	Field inspection only	Y		Cross-connection survey	
3355	SPIRIT WAY			P	N			P	2"		NONRES						Installed after lead ban	Y	1997	ısp during install o	Field inspection only	Y		Cross-connection survey	
3360	SPIRIT WAY			P	N			DI	8"		NONRES						Installed after lead ban	Y	1997	ısp during install o	Field inspection only	Y		Cross-connection survey	
3303	SPIRIT WAY			P	N			P	1"		NONRES						Installed after lead ban	Y	1997	ısp during install o	Field inspection only	Y		Cross-connection survey	
3303	SPIRIT WAY			P	N			P	1"		NONRES						Installed after lead ban	Y	1997	ısp during install o	Field inspection only	Y		Cross-connection survey	
3430	SPIRIT WAY			P	N			P	3"		NONRES						Installed after lead ban	Y	1997	ısp during install o	Field inspection only	Y		Cross-connection survey	
3261	SPIRIT WAY			P	N			P	2"		NONRES						Installed after lead ban	Y	1997	ısp during install o	Field inspection only	Y		Cross-connection survey	
3281	SPIRIT WAY			P	N			P	2"		NONRES						Installed after lead ban	Y	1997	ısp during install o	Field inspection only	Y		Cross-connection survey	
1150	SPRINGHURST DRIVE			C	N			C	2"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1088	SPRINGHURST DRIVE			C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
922	STADIUM DRIVE			C	N			P	1 1/2"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
2271	TRUE LANE	B		UNK-NOLG	N			DI	6"		NONRES						Diameter > 2 inches	Y			Field inspection only	Y		Cross-connection survey	
2271	TRUE LANE	A		UNK-NOLG	N			DI	6"		NONRES						Diameter > 2 inches	Y			Field inspection only	Y		Cross-connection survey	
830	VANDERPERREN WAY			C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
741	VANDERPERREN WAY			C	N			C	1 1/2"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
741	VANDERPERREN WAY			C	N			C	1 1/2"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
840	VANDERPERREN WAY			C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
944	VANDERPERREN WAY			UNK-NOLG	N			DI	4"		NONRES						Diameter > 2 inches	Y			Field inspection only	Y		Cross-connection survey	
942	VANDERPERREN WAY			C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
2700	VERNON DRIVE			C	N			P	2"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
2680	VERNON DRIVE			C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
2760	VIKING DRIVE	Creekwood - Multi		C	N			C	2"		MF					8" private lateral feeds all the	Installation record	Y			Field inspection only	Y		Cross-connection survey	
2787	VIKING DRIVE	Creekwood - Multi		C	N			C	2"		MF					8" private lateral feeds all the	Installation record	Y			Field inspection only	Y		Cross-connection survey	
2784	VIKING DRIVE	Creekwood - Multi		C	N			C	2"		MF					8" private lateral feeds all the	Installation record	Y			Field inspection only	Y		Cross-connection survey	
2850	VIKING DRIVE	Creekwood - Multi		C	N			C	2"		MF					8" private lateral feeds all the	Installation record	Y			Field inspection only	Y		Cross-connection survey	
2820	VIKING DRIVE	Creekwood - Multi		C	N			C	2"		MF					8" private lateral feeds all the	Installation record	Y			Field inspection only	Y		Cross-connection survey	
2800	VIKING DRIVE	Creekwood - Multi		C	N			C	2"		MF					8" private lateral feeds all the	Installation record	Y			Field inspection only	Y		Cross-connection survey	
2806	VIKING DRIVE	Creekwood - Multi		C	N			C	2"		MF					8" private lateral feeds all the	Installation record	Y			Field inspection only	Y		Cross-connection survey	
2766	VIKING DRIVE	Creekwood - Multi		C	N			C	2"		MF					8" private lateral feeds all the	Installation record	Y			Field inspection only	Y		Cross-connection survey	
2748	VIKING DRIVE	Creekwood - Multi		C	N			C	2"		MF					8" private lateral feeds all the	Installation record	Y			Field inspection only	Y		Cross-connection survey	
2774	VIKING DRIVE	Creekwood - Multi		C	N			C	2"		MF					8" private lateral feeds all the	Installation record	Y			Field inspection only	Y		Cross-connection survey	
2740	VIKING DRIVE	Creekwood - Multi		C	N			C	2"		MF					8" private lateral feeds all the	Installation record	Y			Field inspection only	Y		Cross-connection survey	
2740	VIKING DRIVE	Creekwood - Multi		C	N			C	2"		MF					8" private lateral feeds all the	Installation record	Y			Field inspection only	Y		Cross-connection survey	
933	Waube Lane			P	N	8"		P	1"		NONRES						Installed after lead ban	Y	2022	ısp during install o	Field inspection only	Y		Cross-connection survey	
1017	WAUBE LANE			C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1017	WAUBE LANE			C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1019	WAUBE LANE			C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
940	WAUBE LANE	WOM		P	N	2"		C	1"		NONRES						Installed after lead ban	Y	2018	ısp during install o	Field inspection only	Y		Cross-connection survey	
940	WAUBE LANE			P	N	2"		C	1"		NONRES						Installed after lead ban	Y	2018	ısp during install o	Field inspection only	Y		Cross-connection survey	
980	WAUBE LANE	WOM		C	N			C	2"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
980	WAUBE LANE			C	N			C	2"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1331	WAUBE LANE			C	N			P	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1301	WAUBE LANE			C	N			P	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1179	PARKVIEW ROAD			C	N			P	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1361	WAUBE LANE			C	N			P	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1163	WAUBE LANE			C	N			P	1 1/2"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1053	WAUBE LANE			UNK-NOLG	N			DI	6"		NONRES						Diameter > 2 inches	Y			Field inspection only	Y		Cross-connection survey	
995	WAUBE LANE			C	N			P	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
969	WAUBE LANE	103		C	N			P	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
969	WAUBE LANE	102		C	N			P	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	

LOCATIONAL IDENTIFIER ADDRESS	LOCATIONAL IDENTIFIER STREET NAME	LOCATIONAL IDENTIFIER UNIT OR SUITE #	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
969	WAUBE LANE	101		C	N			P	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1201	WAUBE LANE			C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1235	WAUBE LANE			C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1245	WAUBE LANE			C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1263	WAUBE LANE			C	N			P	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1263	WAUBE LANE	C		C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1263	WAUBE LANE	A		C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
985	WAUBE LANE			C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1037	WAUBE LANE			C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1030	WAUBE LANE			C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1010	WAUBE LANE			C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
820	WILLARD DRIVE	224		C	N			P	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
820	WILLARD DRIVE	200		C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
820	WILLARD DRIVE	202		C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
820	WILLARD DRIVE	230		C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
820	WILLARD DRIVE	210		C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
755	WILLARD DRIVE			P	N			DI	6"		NONRES						Diameter > 2 inches	Y			Field inspection only	Y		Cross-connection survey	
784	WILLARD DRIVE	308		C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
784	WILLARD DRIVE	314		C	N			P	1"		MF						Installation record	Y			Field inspection only	Y		Cross-connection survey	
784	WILLARD DRIVE	310		C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
784	WILLARD DRIVE	312		C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
760	WILLARD DRIVE	400		C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
760	WILLARD DRIVE	416		C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
800	WILLARD DRIVE	112		C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
800	WILLARD DRIVE	102		C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
800	WILLARD DRIVE	100		C	N			P	3"		NONRES						Diameter > 2 inches	Y			Field inspection only	Y		Cross-connection survey	
781	WILLARD DRIVE			C	N			P	1 1/2"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
770	WILLARD DRIVE			C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
844	WILLARD DRIVE	Multi		C	N			C	1 1/2"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
844	WILLARD DRIVE	1		C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
601	WILLARD DRIVE			C	N			P	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
700	WILLARD DRIVE			C	N			P	1 1/2"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
840	WILLARD DRIVE			C	N			C	1 1/2"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1014	WILLARD DRIVE			C	N			C	1 1/2"		MF						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1008	WILLARD DRIVE			C	N			C	1 1/2"		MF						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1000	WILLARD DRIVE			C	N			C	1"		MF						Installation record	Y			Field inspection only	Y		Cross-connection survey	
994	WILLARD DRIVE			C	N			C	1"		MF						Installation record	Y			Field inspection only	Y		Cross-connection survey	
988	WILLARD DRIVE			C	N			C	1"		MF						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1020	WILLARD DRIVE			C	N			C	1 1/2"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
2332	SAN LUIS PLACE			UNK-NOLG	N			P	3"		MF						Diameter > 2 inches	Y			Field inspection only	Y		Cross-connection survey	
2338	SAN LUIS PLACE	Multi		C	N			C	1 1/2"		MF						Installation record	Y			Field inspection only	Y		Cross-connection survey	
978	WILLARD DRIVE			C	N			C	1 1/2"		MF						Installation record	Y			Field inspection only	Y		Cross-connection survey	
970	WILLARD DRIVE			C	N			C	1"		MF						Installation record	Y			Field inspection only	Y		Cross-connection survey	
968	WILLARD DRIVE			C	N			C	1 1/2"		MF						Installation record	Y			Field inspection only	Y		Cross-connection survey	
966	WILLARD DRIVE			C	N			C	1 1/2"		MF						Installation record	Y			Field inspection only	Y		Cross-connection survey	
956	WILLARD DRIVE			C	N			C	1"		MF						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1030	WILLARD DRIVE			C	N			C	1 1/2"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
980	WILLARD DRIVE			C	N			C	1"		SCH/CC						Installation record	Y			Field inspection only	Y		Cross-connection survey	
926	WILLARD DRIVE			C	N			P	1 1/2"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
916	WILLARD DRIVE			C	N			P	1 1/2"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
2280	S BROADWAY			C	N			C	2"		SCH/CC						Installation record	Y			Field inspection only	Y		Cross-connection survey	
955	WILLARD DRIVE			C	N			C	2"		SCH/CC						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1360	PONDEROSA AVENUE			UNK-NOLG	N			C	3"		SCH/CC						Diameter > 2 inches	Y			Field inspection only	Y		Cross-connection survey	
2200	TRUE LANE			UNK-NOLG	N			C	4"		SCH/CC						Diameter > 2 inches	Y			Field inspection only	Y		Cross-connection survey	
1055	GRIFFITHS LANE			C	N			C	1 1/2"		SCH/CC						Installation record	Y			Field inspection only	Y		Cross-connection survey	
2391	S RIDGE ROAD	Pool		C	N			C	2"		SCH/CC						Installation record	Y			Field inspection only	Y		Cross-connection survey	
2391	S Ridge RD	HS		C	N			C	2"		SCH/CC						Installation record	Y			Field inspection only	Y		Cross-connection survey	
2391	S Ridge Rd	Aud		C	N			C	2"		SCH/CC						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1919	S BROADWAY			C	N			P	2"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1930	S BROADWAY			C	N			P	2"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
500	PILGRIM WAY			C	N			C	2"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
2531	S BROADWAY			P	N			DI	4"		NONRES						Diameter > 2 inches	Y			Field inspection only	Y		Cross-connection survey	
516	GLOBE AVENUE			P	N			DI	4"		NONRES						Diameter > 2 inches	Y			Field inspection only	Y		Cross-connection survey	
486	GLOBE AVENUE			P	N			DI	6"		NONRES						Diameter > 2 inches	Y			Field inspection only	Y		Cross-connection survey	
486	GLOBE AVENUE			P	N			DI	6"		NONRES						Diameter > 2 inches	Y			Field inspection only	Y		Cross-connection survey	
486	GLOBE AVENUE			P	N			DI	6"		NONRES						Diameter > 2 inches	Y			Field inspection only	Y		Cross-connection survey	
516	GLOBE AVENUE			P	N			DI	4"		NONRES						Diameter > 2 inches	Y			Field inspection only	Y		Cross-connection survey	
2580	S BROADWAY			P	N			DI	8"		NONRES						Diameter > 2 inches	Y			Field inspection only	Y		Cross-connection survey	
2580	S BROADWAY			P	N			DI	8"		NONRES						Diameter > 2 inches	Y			Field inspection only	Y		Cross-connection survey	
2580	S BROADWAY			P	N			DI	8"		NONRES						Diameter > 2 inches	Y			Field inspection only	Y		Cross-connection survey	
2612	S BROADWAY			P	N			C	2"		NONRES						Diameter > 2 inches	Y			Field inspection only	Y		Cross-connection survey	
2612	S BROADWAY			P	N			C	4"		NONRES						Diameter > 2 inches	Y			Field inspection only	Y		Cross-connection survey	
2660	S BROADWAY			P	N			DI	4"		NONRES						Diameter > 2 inches	Y			Field inspection only	Y		Cross-connection survey	
2660	S BROADWAY			P	N			DI	4"		NONRES						Diameter > 2 inches	Y			Field inspection only	Y		Cross-connection survey	
2660	S BROADWAY			P	N			DI	4"		NONRES						Diameter > 2 inches	Y			Field inspection only	Y		Cross-connection survey	
2872	S BROADWAY			P	N			P	2"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
2876	S BROADWAY			P	N			P	2"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
610	BAETEN ROAD			C	N			P	2"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
2850	S ASHLAND AVENUE			UNK-NOLG	N			P	3"		NONRES						Diameter > 2 inches	Y			Field inspection only	Y		Cross-connection survey	
750	BAETEN ROAD			C	N			P	2"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
2830	S ASHLAND AVENUE			C	N			P	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
2799	HOLMGREN WAY			C	N			P	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
2800	S ASHLAND AVENUE			C	N			P	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
810	PARKVIEW ROAD			C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
810	PARKVIEW ROAD			C	N			P	2"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	

LOCATIONAL IDENTIFIER ADDRESS	LOCATIONAL IDENTIFIER STREET NAME	LOCATIONAL IDENTIFIER UNIT OR SUITE #	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
810	PARKVIEW ROAD			C	N			P	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
810	PARKVIEW ROAD			C	N			P	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
790	PARKVIEW ROAD			C	N			P	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
2300	S ASHLAND AVENUE			UNK-NOLG	N			DI	3"		NONRES						Diameter > 2 inches	Y			Field inspection only	Y		Cross-connection survey	
660	CORMIER ROAD			C	N			DI	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1163	GLORY ROAD			UNK-NOLG	N			DI	3"		NONRES						Diameter > 2 inches	Y			Field inspection only	Y		Cross-connection survey	
2885	ALLIED STREET	WOM		C	N			P	2"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
2885	ALLIED STREET			C	N			P	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
990	CIRCLE DRIVE			C	N			P	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
2851	ALLIED STREET			C	N			P	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1055	PARKVIEW ROAD			C	N			P	2"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1030	ASHWAUBENON STREET			P	N			P	2"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1050	ASHWAUBENON STREET			P	N			P	4"		NONRES						Diameter > 2 inches	Y			Field inspection only	Y		Cross-connection survey	
3161	S RIDGE ROAD			P	N			P	2"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
3120	COMMODITY LANE			P	N			P	3"		NONRES						Diameter > 2 inches	Y	1981		Field inspection only	Y		Cross-connection survey	
3120	COMMODITY LANE			P	N			P	3"		NONRES						Diameter > 2 inches	Y	1981		Field inspection only	Y		Cross-connection survey	
3155	COMMODITY LANE			P	N			C	1"		NONRES						Installation record	Y	1981		Field inspection only	Y		Cross-connection survey	
3142	COMMODITY LANE			P	N			C	1"		NONRES						Installation record	Y	1981		Field inspection only	Y		Cross-connection survey	
1250	GLORY ROAD			P	N			DI	8"		NONRES						Diameter > 2 inches	Y			Field inspection only	Y		Cross-connection survey	
1250	GLORY ROAD			P	N			P	2"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1330	GLORY ROAD			P	N			DI	8"		NONRES						Diameter > 2 inches	Y			Field inspection only	Y		Cross-connection survey	
1330	GLORY ROAD			P	N			DI	8"		NONRES						Diameter > 2 inches	Y			Field inspection only	Y		Cross-connection survey	
3250	S RIDGE ROAD			P	N			P	2"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
3250	S RIDGE ROAD			P	N			P	4"		NONRES						Diameter > 2 inches	Y			Field inspection only	Y		Cross-connection survey	
3291	S RIDGE ROAD			P	N			P	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
3251	S RIDGE ROAD			P	N			P	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
3399	S RIDGE ROAD			P	N			DI	6"		NONRES						Diameter > 2 inches	Y			Field inspection only	Y		Cross-connection survey	
3399	S RIDGE ROAD	WOM		P	N			DI	6"		NONRES						Diameter > 2 inches	Y			Field inspection only	Y		Cross-connection survey	
2060	S ASHLAND AVENUE			P	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
2050	S ASHLAND AVENUE			P	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
2074	S ASHLAND AVENUE			P	N			C	2"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
2074	S ASHLAND AVENUE			P	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
599	BORVAN AVENUE			P	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
599	BORVAN AVENUE			P	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
597	BORVAN AVENUE			P	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1015	CENTENNIAL STREET			P	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1015	CENTENNIAL STREET			P	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
1015	CENTENNIAL STREET			P	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
999	GLORY ROAD			P	N			P	1 1/2"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
975	GLORY ROAD			P	N			P	1 1/2"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
3166	MARKET STREET			P	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
975	PARKVIEW ROAD Ste 4			P	N			DI	4"		NONRES						Diameter > 2 inches	Y			Field inspection only	Y		Cross-connection survey	
975	PARKVIEW ROAD Ste 2			P	N			DI	4"		NONRES						Diameter > 2 inches	Y			Field inspection only	Y		Cross-connection survey	
975	PARKVIEW ROAD Ste 6			P	N			DI	4"		NONRES						Diameter > 2 inches	Y			Field inspection only	Y		Cross-connection survey	
1310	Ponderosa Ave			P	N			P	2"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
936	Anderson Drive			P	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
2881	S Broadway			P	N			CU	4"		NONRES						Diameter > 2 inches	Y			Field inspection only	Y		Cross-connection survey	
2570	Timber Ln			P	N			CU	4"		NONRES						Diameter > 2 inches	Y			Field inspection only	Y		Cross-connection survey	
2153	Holmgen Way			P	N			DI	6"		NONRES						Diameter > 2 inches	Y			Field inspection only	Y		Cross-connection survey	
2153	Holmgen Way			P	N			DI	6"		NONRES						Diameter > 2 inches	Y			Field inspection only	Y		Cross-connection survey	
2231	Holmgren Way			P	N			P	2"		NONRES						Diameter > 2 inches	Y			Field inspection only	Y		Cross-connection survey	
2155	Holmgren Way			P	N			P	3"		NONRES						Diameter > 2 inches	Y			Field inspection only	Y		Cross-connection survey	
900	Anderson Drive			P	N			DI	6"		NONRES						Diameter > 2 inches	Y			Field inspection only	Y		Cross-connection survey	
1327	GLORY ROAD			P	N			C	3"		NONRES						Diameter > 2 inches	Y			Field inspection only	Y		Cross-connection survey	

Click here to open USEPA 2022 Guidance for Developing and Maintaining a Service Line Inventory

Note: *Field names that are shaded* ***navy*** *are required for every service connection. Field names shaded* ***blue*** *are recommended, optional, or only required under certain conditions. See field descriptions for more information.*

	Column	Description
A	SITE ID	PWS that do not wish to report site addresses to the department in column B can use this column to "link" their materials inventory table to a separate service address table for their own use. ***This column is optional, however, it strongly recommended that PWS enter the site ID for locations that are lead and copper monitoring sites in this column.***
B	LOCATION IDENTIFIER	The location identifier can be the site address, however if there is more than one service connection at a given address, it must include additional detail. If the PWS does not wish to report addresses to the department it can be a block, intersection or landmark. This column is required per sub-subparagraph **§141.84 (a)(8)(i)** of the LCRR which requires that a location identifier be associated with each service line.

	Column	Description	Answer options	Answer Option Descriptions
C	GOOSENECK CURRENTLY PRESENT?	Is there a gooseneck, lead connector or pigtail present? ***PWS are required to track this information, if known. However, PWS are not required to conduct investigations to determine if a gooseneck is present.***	Y	YES - WITH CERTAINTY
			N	NO - WITH CERTAINTY
			UNK	NOT KNOWN WITH CERTAINTY
D	CURRENT STREET SIDE SERVICE LINE MATERIAL	Service line pipe material, from the water main to curb stop.	L	CONFIRMED LEAD
			C	CONFIRMED COPPER
			G	CONFIRMED GALVANIZED
			P	CONFIRMED PLASTIC
			DI	CONFIRMED DUCTILE IRON
			CI-L	CONFIRMED LINED CAST IRON
			CI-U	CONFIRMED UNLINED CAST IRON
			UNK-LG	UNKNOWN - MAY CONTAIN LEAD OR GALVANIZED
			UNK-NOLG	UNKNOWN - DEFINITELY DOES NOT CONTAIN LEAD OR GALVANIZED
E	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	Was the service line ever previously lead?	Y	YES – SERVICE LINE WAS PREVIOUSLY LEAD
			N	NO – KNOWS WITH CERTAINTY THAT SERVICE LINE MATERIAL WAS NEVER PREVIOUSLY LEAD
			UNK	NOT KNOWN WITH CERTAINTY IF MATERIAL WAS EVER PREVIOUSLY LEAD

	Column	Description
F	STREET SIDE SERVICE LINE SIZE	Service line pipe diameter in inches, from the water main to curb stop. This information is useful as a screening tool as most lead service lines are 2 inches or less in diameter. Furthermore, PWSs are required to report service line size to the PSC for their annual report. This column may also be used by PWS that wish to track information required by both agencies in a single document. ***Column F is optional.***
G	STREET SIDE SERVICE LINE INSTALL DATE	The four-digit year that the utility-side service was installed (i.e. 1974). If the exact year is not known, enter the decade (i.e. enter 1970 for any year in the 1970s) Althought this information is not required, it can be used as a screening tool to determine if the service line was installed before or after the lead ban (1986). ***Column G is optional.***
H	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	Service line pipe material, from the curb stop to water meter. See Row D for answer options.
I	PROPERTY SIDE SERVICE LINE SIZE[1]	Service line pipe diameter, in inches, from the curb stop to water meter. This information is useful as a screening tool as **most** lead service lines are 2 inches or less in diameter. Furthermore, PWS are required to report service line size to the PSC for their annual report. This column may also be used by PWS that wish to track information required by both agencies in a single document. ***Column I is optional.***
J	PROPERTY SIDE SERVICE LINE INSTALL DATE	If the exact year is not known, enter the decade (i.e. enter 1970 for any year in in the 1970s). This information it can be used as a screening tool to determine if the service line was installed before or after the lead ban (1986). ***Column J is optional.***

	Column	Description	Answer options	Answer Option Descriptions
K	BUILDING TYPE	The type of structure that is served water by the service connection. ***At a minimum, the PWS must identify the connection either SF, MF or NONRES .***	SF	SINGLE-FAMILY RESIDENTIAL
			MF	MULTI-FAMILY RESIDENTIAL
			SCH/CC	SCHOOL OR CHILD CARE *This category may be used by the PWSs to track locations that must be monitored under §141.92.*
			RES/CC	RESIDENTIAL & IN-HOME CHILD CARE *This category may be used by the PWSs to track locations that must be monitored under §141.92.*
			NONRES	NONRESIDENTIAL ONLY, NO SCHOOL OR CHILD CARE.
			MIX	MIXED RESIDENTIAL & NONRESIDENTIAL, NO SCHOOL OR CHILD CARE.
			O	OTHER
L	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	Is the cold-water kitchen tap treated by point-of-entry or point-of-use softening, filter or other treatment? ***Column L is optional.***	Y	YES - the sample tap is treated by a point of use or point of entry softener or filter
			N	NO - the sample tap is not treated by a point of use or point of entry softener or filter
			UNK	Presence or absence of POU and POE is UNKNOWN
M	BUILDING PLUMBING MATERIAL 1	The type of plumbing materials inside the structure that water is deliver to. If there is more than one known plumbing material type, select the second material type in column N. ***Columns M and N are optional.***	CLS	Copper with lead solder
			C	Copper, no lead solder
N	BUILDING PLUMBING MATERIAL 2		O	Other material that is not copper, or copper with lead solder
			UNK	Unknown

Column	Description

O	BUILDING PLUMBING MATERIAL INSTALL DATE	The four-digit year that the interior premise plumbing was installed. If the exact year is not known, you may enter the decade if the decade is not the 1980s. If the decade is the 1980s, you may enter one of the following: 1983-1984, <1983 or >1984. ***Column O is optional.***
P	COMMENTS	Use this column information to enter any other information that the PWS finds helpful to them or any information they wish to share with the department. ***Column P is optional.***

Column		Description	Answer options	Answer Option Descriptions *(Chapter 4 of EPA inventory guidance)*
Q	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	Use the drop-down menu to select the method used for materials classification. If the method you used is not one of the options, select other and describe the basis for classification in Column Y-Notes on materials classification.	**Previous eval**	Previous Materials Evaluation
			Installation record	Installation record (e.g., tap card)
			Installed after lead ban	Installation date after lead ban (1986)
			Diameter > 2 inches	Service line diameter is > 2 inches
			SL repair/replace record	Service line repair or replacement record
			Water sampling only	Water sampling only with no records
			Field inspection only	Field inspection only with no records
			Other - describe in notes	Other - if other is selected describe the basis for material classification in the Notes Column Y.

Column		Description
R	WAS STREET SIDE MATERIAL FIELD VERIFIED?	Was the street side material field verified? Select "Y" for "Yes" or "N" for "No".
S	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	If you selected "Yes" in column R, enter the date (DD/MM/YYYY) or four-digit year that the material was field verified. ***This field is only required if "Yes" was selected in Column R.***

Column		Description	Answer options	Answer Option Descriptions *(Chapter 5 of EPA inventory guidance)*
T	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	If PWS selected "Yes" in column R, select the method used for field verification. If the method you used is not one of the options, select other and describe the basis for classification in Column Y. ***This field is only required if "Yes" was selected in Column R.***	**Customer self id**	Customer self-identification
			CCTV - internal	CCTV investigation at curb stop - internal
			CCTV - external	CCTV investigation at curb stop - external
			Mech excav	Mechanical excavation at one location
			Visual insp at meter	Visual inspection at the meter pit
			Visual insp during install or repair	Visual inspection during construction or repair
			Cross connection survey	Cross Connection survey
			Other	Other - describe in Notes Column Y

Column		Description
U	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	Use the drop-down menu to select the method used for materials classification. If the method you used is not one of the options, select other and describe the basis for classification in Column Y. See Column Q for a description of and an explanation of answer options.
V	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	Was the street side material field verified? Select "Y" for "Yes" or "N" for "No".
W	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	If PWS selected "Yes" in column R, select the method used for field verification. If the method you used is not one of the options, select other and describe the basis for classification in Column Y. ***This field is only required if "Yes" was selected in Column V.***
X	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	If you selected "Yes" in column V, select the method used for field verification. See column T for an explanation of answer options. ***This field is only required if "Yes" was selected in Column V.***
Y	NOTES MATERIAL CLASSIFICATION	If PWS selected "other" in Columns Q, T, U or X, describe the basis for classification or field verification here. ***This field is only required if "other" was selected in column Q, T, U and/or X.***

Materials Inventory Template For Drinking Water Systems Under The Lead And Copper Rule Revisions



1. Why do Public Water Systems (PWSs) need to provide this information?

Under Section §**141.84** of the Lead and Copper Rule Revision (LCRR), all community Public Water Systems (PWS) "must develop an inventory to identify the materials of service lines connected to the public water distribution system. The inventory must include all service lines connected to the public water distribution system regardless of ownership status."

2. What specifically does the LCRR materials inventory require (columns D, E and H)?

Subparagraph §**141.84 (a) (4)** of the LCRR states that "each service line, or portion of the service line where ownership is split, must be categorized" as belonging to one of the following groups: lead; non-lead; lead status unknown; or galvanized requiring replacement. *The information provided in **columns D, E and H** of the materials spreadsheet will enable the department to correctly assign every service line or portion thereof to one of these four categories.*

3. What is the Site ID (column A)? Is this required?

The PWS can use this column to identify the site ID of lead and copper monitoring sites. For all other locations, the site ID is optional. PWSs that do not wish to report site addresses to the department in column B may want to use this column to "link" their materials inventory table to a separate service address table for their own use.

4. What is a locational identifier (column B)?

Sub-subparagraph §**141.84 (a)(8)(i)** of the LCRR requires a location identifier associated with each service line. The locational identifier can be the site address, or it can be a block, intersection or landmark.

The LCRR defines some categories of materials, such as 'lead status' and 'galvanized downstream of lead' differently in different sections of the rule. Thus, the spreadsheet is intended to be a simple and easy way for municipal PWSs to collect and report the information required now and in the future. The DNR will use the materials inventory data collected by the water system to categorize each of their service connections appropriately under each section of the LCRR.

Materials Inventory Template For Drinking Water Systems Under The Lead And Copper Rule Revisions

5. Why do PWSs need to indicate whether a gooseneck is present (column C)?

Paragraph §**141.86 (a)** of the LCRR directs every public water system to "identify a pool of targeted sampling sites based on the service line inventory." However, the materials information needed to categorize service lines in accordance with §**141.84** alone is insufficient to identify these targeted sampling sites. Specifically, as per LCRR sub-paragraph §**141.86 (a) (5),** Tier 3 sampling sites include both single-family structures served by galvanized lines located downstream of a lead service line (i.e. confirmed galvanized requiring replacement) or downstream of a lead gooseneck, pigtail or connector.

5. Why do PWSs need to indicate whether a service line that is not currently lead was ever previously lead (column E)?

The materials history of the upstream utility service line is needed to correctly categorize customer-side galvanized service lines as either non-lead or galvanized requiring replacement under the LCRR. Sub-subparagraph §**141.84 (a)(4)(ii)** of the LCRR requires that public water systems identify locations where a galvanized service line "is or was at any time downstream of a lead service line" or "lead status unknown" service line as "galvanized requiring replacement". If a water system knows with certainty that the utility side of a service line is not now, and never has previously been lead, then the downstream customer-side galvanized service line is identified as "non-lead". If a PWS does not know this with certainty, the material is categorized as "galvanized requiring replacement." However, as per paragraph §**141.86 (a)**, galvanized service lines currently or formerly downstream of a lead gooseneck, pigtail, or connector are *not* identified as galvanized requiring replacement.

5. Are PWSs required to track the interior premise plumbing materials and install date at every service location in their system (columns M, N and O)?

This information is only required for service locations that are potential compliance sampling sites. If the PWS has at least as many Tier 1, Tier 2 and/or Tier 3 sampling sites as their required number of monitoring sites, then they are not required to track this information at this time. However, the PWS will be required to collect this information in the future, once all of their lead service lines and galvanized lines requiring replacement are removed. It is recommended that PWS collect this information on an ongoing basis whenever they are inside structures, as part of their normal operations.

5. Are PWSs required to track whether there is a point-of-entry (POE) or point-of-use (POU) treatment device at every service location (column L)?

This information is only required for service connections that are potential monitoring sites. Sub-paragraph §**141.86 (1)** of the LCRR states that **"**Sampling sites may not include sites with installed point-of-entry (POE) treatment devices and taps used at sampling sites may not have point-of-use (POU) devices designed to remove inorganic contaminants…" However, the department recommends that PWSs collect this information concurrently with premise plumbing materials at a given residence, so that PWSs don"t need to revisit residences that become potential monitoring sites once their lead and galvanized lines are removed.

5. Are PWSs required to use the DNR template?

No, PWSs are *not* required to use the DNR template for their materials inventory. However, PWSs that track their drinking water distribution system materials using a different method should provide all of the information requested in the template.

5. Do Municipal PWSs have to report this information to the DNR and PSC both?

Due to differences in the frequency and timing of reporting and the type of information reported, municipal public water systems will continue to report service line information annually to the Public Service Commission (W-22 and W-29) for the foreseeable future. However, the DNR and PSC are in discussions about how they can collaborate to minimize the amount of similar reporting to multiple agencies after the LCRR compliance date.