



LOCATIONAL IDENTIFIER ADDRESS	LOCATIONAL IDENTIFIER STREET NAME	LOCATIONAL IDENTIFIER UNIT OR SUITE #	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
1210	ALICE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1211	ALICE DRIVE			C	N	3/4"		C	1"		SF						Installation record	N			Installation record	N			Cross-connection survey
1216	ALICE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1217	ALICE DRIVE			C	N	3/4"		C	3/4"		SF						Installation record	N			Installation record	N			Cross-connection survey
1242	ALICE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1243	ALICE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1248	ALICE DRIVE			C	N	3/4"		C	3/4"		SF						Installation record	N			Installation record	N			Cross-connection survey
1249	ALICE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1255	ALICE DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1256	ALICE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1262	ALICE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1263	ALICE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1268	ALICE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1269	ALICE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1274	ALICE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1275	ALICE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1280	ALICE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1281	ALICE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1286	ALICE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1287	ALICE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1293	ALICE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1294	ALICE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1301	ALICE DRIVE			C	N	2"		C	1"		MF						Installation record	Y	1967	isp during install o	Field inspection only	Y			Cross-connection survey
1302	ALICE DRIVE			C	N	2"		C	1"		MF						Installation record	Y	1967	isp during install o	Field inspection only	Y			Cross-connection survey
1308	ALICE DRIVE			C	N	2"		C	1"		MF						Installation record	Y	1967	isp during install o	Field inspection only	Y			Cross-connection survey
1314	ALICE DRIVE			C	N	2"		C	2"		MF						Installation record	Y	1967	isp during install o	Field inspection only	Y			Cross-connection survey
2761	ALLIED STREET			C	N			C	1 1/2"		NONRES						Installation record	N	1973		Field inspection only	Y			Cross-connection survey
2777	ALLIED STREET			C	N			C	1"		NONRES						Installation record	N	1973		Field inspection only	Y			Cross-connection survey
2789	ALLIED STREET			C	N	1 1/2"		C	1 1/2"		NONRES						Installation record	Y	1973		Field inspection only	Y			Cross-connection survey
2799	ALLIED STREET			C	N			C	1"		NONRES						Installation record	N	1973		Field inspection only	Y			Cross-connection survey
2811	ALLIED STREET			C	N			C	1"		NONRES						Installation record	N	1973		Field inspection only	Y			Cross-connection survey
2821	ALLIED STREET			C	N			C	1"		NONRES						Installation record	N	1973		Field inspection only	Y			Cross-connection survey
2831	ALLIED STREET			C	N			C	1"		NONRES						Installation record	N	1973		Field inspection only	Y			Cross-connection survey
2834	ALLIED STREET	A		C	N			C	1"		NONRES						Installation record	N	1973		Field inspection only	Y			Cross-connection survey
2841	ALLIED STREET	A		C	N	1 1/2"		C	1 1/2"		NONRES						Installation record	Y	1973		Field inspection only	Y			Cross-connection survey
2844	ALLIED STREET	1		C	N			C	1"		NONRES						Installation record	N	1973		Field inspection only	Y			Cross-connection survey
2851	ALLIED STREET			C	N			P	1"		NONRES						Installation record	Y			Field inspection only	Y			Cross-connection survey
2863	ALLIED STREET	A & B		C	N			C	1"		NONRES						Installation record	N	1973		Field inspection only	Y			Cross-connection survey
2865	ALLIED STREET			C	N			C	1 1/2"		NONRES						Installation record	N	1973		Field inspection only	Y			Cross-connection survey
2885	ALLIED STREET			C	N			P	1"		NONRES						Installation record	Y			Field inspection only	Y			Cross-connection survey
2929	ALLIED STREET			C	N			C	1"		NONRES						Installation record	N	1973		Field inspection only	Y			Cross-connection survey
2930	ALLIED STREET			C	N			C	1 1/2"		NONRES						Installation record	N	1973		Field inspection only	Y			Cross-connection survey
2945	ALLIED STREET			C	N			P	4"		NONRES						Diameter > 2 inches	N	1973		Field inspection only	Y			Cross-connection survey
2960	ALLIED STREET			C	N			C	1"		NONRES						Installation record	N	1973		Field inspection only	Y			Cross-connection survey
2979	ALLIED STREET	A		C	N	2"		C	1"		NONRES						Installation record	Y	1973		Field inspection only	Y			Cross-connection survey
3040	ALLIED STREET			P	N	2"		P	1 1/2"		NONRES						Installation record	Y	1973		Field inspection only	Y			Cross-connection survey
3061	ALLIED STREET	A		C	N			C	1"		NONRES						Installation record	N	1973		Field inspection only	Y			Cross-connection survey
900	Anderson Drive			P	N			DI	6"		NONRES						Diameter > 2 inches	Y			Field inspection only	Y			Cross-connection survey
901	ANDERSON DRIVE	A		P	N			P	1"		NONRES						Installation record	Y	Visual insp during install o		Field inspection only	Y			Cross-connection survey
933	ANDERSON DRIVE	A		C	N			C	1"		NONRES						Installation record	N			Field inspection only	Y			Cross-connection survey
936	Anderson Drive			P	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y			Cross-connection survey
949	ANDERSON DRIVE			C	N	1"		C			MF						Installation record	N			Installation record	N			
965	ANDERSON DRIVE			C	N	1"		C			MF						Installation record	N			Installation record	N			
973	ANDERSON DRIVE			C	N	1"		C			MF						Installation record	N			Installation record	N			
1031	ANDERSON DRIVE			UNK-NOLG	N			C	3"		NONRES						Diameter > 2 inches	N			Field inspection only	Y			Cross-connection survey
1051	ANDERSON DRIVE			UNK-NOLG	N			C	3"		NONRES						Diameter > 2 inches	N			Field inspection only	Y			Cross-connection survey
1071	ANDERSON DRIVE			UNK-NOLG	N			C	1 1/2"		MF						Installation record	N			Field inspection only	Y			Cross-connection survey
1079	ANDERSON DRIVE			UNK-NOLG	N			C	1 1/2"		MF						Installation record	N			Field inspection only	Y			Cross-connection survey
1087	ANDERSON DRIVE			UNK-NOLG	N			C	1 1/2"		MF						Installation record	N			Field inspection only	Y			Cross-connection survey
1099	ANDERSON DRIVE			UNK-NOLG	N			C	1 1/2"		MF						Installation record	Y			Field inspection only	Y			Cross-connection survey
1103	ANDERSON DRIVE			UNK-NOLG	N			C	1 1/2"		MF						Installation record	Y			Field inspection only	Y			Cross-connection survey
1107	ANDERSON DRIVE			P	N	8"		C	1 1/2"		MF				8" Private lateral feeds these add		Installation record	Y			Field inspection only	Y			Cross-connection survey
1111	ANDERSON DRIVE			UNK-NOLG	N			C	1 1/2"		MF						Installation record	N			Field inspection only	Y			Cross-connection survey
1241	APACHE AVENUE			C	N	1"		C	3/4"		MF						Installation record	Y	Visual insp during install o		Field inspection only	Y			Cross-connection survey
1248	APACHE AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1249	APACHE AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1254	APACHE AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installed after lead ban	N			
1255	APACHE AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installed after lead ban	N			
1260	APACHE AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1261	APACHE AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1266	APACHE AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1269	APACHE AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1274	APACHE AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1275	APACHE AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1280	APACHE AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1281	APACHE AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1286	APACHE AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1287	APACHE AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installed after lead ban	N			
1294	APACHE AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installed after lead ban	N			
1295	APACHE AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installed after lead ban	N			
1392	APACHE AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1397	APACHE AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1403	APACHE AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1404	APACHE AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			

LOCATIONAL IDENTIFIER ADDRESS	LOCATIONAL IDENTIFIER STREET NAME	LOCATIONAL IDENTIFIER UNIT OR SUITE #	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
1411	APACHE AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installed after lead ban	N			
1416	APACHE AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1417	APACHE AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1420	APACHE AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1425	APACHE AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1426	APACHE AVENUE			C	N	3/4"		C	1"		SF						Installation record	Y			Installed after lead ban	N			Cross-connection survey
1431	APACHE AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1432	APACHE AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1439	APACHE AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1442	APACHE AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1445	APACHE AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installed after lead ban	N			
1446	APACHE AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	Y			Installation record	N			Cross-connection survey
1451	APACHE AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1452	APACHE AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installed after lead ban	N			
1474	APACHE AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1475	APACHE AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installed after lead ban	N			
1482	APACHE AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1483	APACHE AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installed after lead ban	N			
1490	APACHE AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1491	APACHE AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1496	APACHE AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1497	APACHE AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installed after lead ban	N			
1502	APACHE AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1505	APACHE AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1508	APACHE AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installed after lead ban	N			
1509	APACHE AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1514	APACHE AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installed after lead ban	N			
1515	APACHE AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1520	APACHE AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1523	APACHE AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1526	APACHE AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1527	APACHE AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1540	APACHE AVENUE			C	N	1"		C			SF						Installation record	Y			Installed after lead ban	N			
1552	APACHE AVENUE			C	N	3/4"		P			SF						Installation record	Y			Installed after lead ban	N			
1556	APACHE AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installed after lead ban	N			
1560	APACHE AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installed after lead ban	N			
1561	APACHE AVENUE			C	N	1"		C			SF						Installation record	Y			Installed after lead ban	N			
1565	APACHE AVENUE			C	N	1"		C			SF						Installation record	Y			Installed after lead ban	N			
1570	APACHE AVENUE			P	N	1"		P			SF						SL repair/replace record	Y			Field inspection only	Y			
1571	APACHE AVENUE			C	N	1"		C			SF						Installation record	Y			Installed after lead ban	N			
1576	APACHE AVENUE			C	N	1"		C			SF						Installation record	Y			Installed after lead ban	N			
1579	APACHE AVENUE			C	N	1"		C			SF						Installation record	Y			Installed after lead ban	N			
1582	APACHE AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installed after lead ban	N			
1585	APACHE AVENUE			C	N	1"		C			SF						Installation record	Y			Installed after lead ban	N			
1590	APACHE AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installed after lead ban	N			
1591	APACHE AVENUE			C	N	1"		C			SF						Installation record	Y			Installed after lead ban	N			
1596	APACHE AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installed after lead ban	N			
1599	APACHE AVENUE			C	N	1"		P			SF						Installation record	Y			Installed after lead ban	N			
1602	APACHE AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installed after lead ban	N			
1605	APACHE AVENUE			C	N	1"		C			SF						Installation record	Y			Installed after lead ban	N			
1060	APRIL LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y			Field inspection only	Y			Cross-connection survey
1066	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1067	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1072	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Field inspection only	Y			Cross-connection survey
1073	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1080	APRIL LANE			C	N	3/4"		C	1"		SF						Installation record	Y			Installation record	N			Cross-connection survey
1081	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Field inspection only	Y			Cross-connection survey
1086	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1087	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1094	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1095	APRIL LANE			C	N	3/4"		C	1"		SF						Installation record	Y			Installation record	N			Cross-connection survey
1100	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1101	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1106	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1107	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1114	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1115	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1120	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1121	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1126	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1127	APRIL LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y			Installation record	N			Cross-connection survey
1134	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1135	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1160	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1166	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1167	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1173	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1174	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1179	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1180	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1185	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1188	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1193	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1194	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1199	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			

LOCATIONAL IDENTIFIER ADDRESS	LOCATIONAL IDENTIFIER STREET NAME	LOCATIONAL IDENTIFIER UNIT OR SUITE #	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
1202	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1205	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1210	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1211	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Field inspection only	Y			Cross-connection survey
1216	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1217	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1242	APRIL LANE			C	N	3/4"		C	1"		SF						Installation record	Y			Installation record	N			Cross-connection survey
1243	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1248	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1249	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1254	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1255	APRIL LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y			Installation record	N			Cross-connection survey
1260	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1261	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1268	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1269	APRIL LANE			C	N	3/4"		C	1"		SF						Installation record	Y			Installation record	N			Cross-connection survey
1274	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1275	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1280	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1281	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1288	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1289	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Field inspection only	Y			
1294	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1295	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1300	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1301	APRIL LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y			Field inspection only	Y			Cross-connection survey
1306	APRIL LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y			Installation record	N			Cross-connection survey
1307	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1314	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1315	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1320	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1321	APRIL LANE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1326	APRIL LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y			Field inspection only	Y			Cross-connection survey
1945	Argonne St			P	N	2"		P	1 1/2"		NONRES						Installation record	Y		Visual insp during install o	Field inspection only	Y			Cross-connection survey
1985	ARGONNE STREET			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1993	ARGONNE STREET			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2011	ARGONNE STREET			C	N	3/4"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2025	ARGONNE STREET			C	N	3/4"		C	3/4"		SF						Installation record	Y			Field inspection only	Y			Cross-connection survey
2039	ARGONNE STREET			C	N	3/4"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2049	ARGONNE STREET			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2073	ARGONNE STREET			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
780	ARMED FORCES DRIVE			P	N			P	4"		NONRES						Diameter > 2 inches	Y	1999	isp during install o	Field inspection only	Y			Cross-connection survey
789	ARMED FORCES DRIVE			P	N			P	1"		NONRES						Installed after lead ban	Y	1999	isp during install o	Field inspection only	Y			Cross-connection survey
811	ARMED FORCES DRIVE			P	N			P	1"		NONRES						Installed after lead ban	Y	1999	isp during install o	Field inspection only	Y			Cross-connection survey
840	ARMED FORCES DRIVE			P	N			P	2"		NONRES						Installed after lead ban	Y	1999	isp during install o	Field inspection only	Y			Cross-connection survey
3003	ASHBROOKE COURT			P	N	1"		P	1"		SF						Installation record	N			Installed after lead ban	Y			Visual insp during install or repair
3008	ASHBROOKE COURT			P	N	1"		P	1"		SF						Installation record	N			Installed after lead ban	Y			Visual insp during install or repair
3011	ASHBROOKE COURT			P	N	1"		P	1"		SF						Installation record	N			Installed after lead ban	Y			Visual insp during install or repair
3016	ASHBROOKE COURT			P	N	1"		P	1"		SF						Installation record	N			Installed after lead ban	Y			Visual insp during install or repair
1476	ASHLEY COURT			C	N	1"		C			SF						Installation record	N	1986		Installation record	N			
1477	ASHLEY COURT			C	N	1"		C			SF						Installation record	N	1986		Installation record	N			
1485	ASHLEY COURT			C	N	1"		C	1"		SF						Installation record	N	1986		Field inspection only	Y			Cross-connection survey
1486	ASHLEY COURT			C	N	1"		C			SF						Installation record	N	1986		Installation record	N			
1494	ASHLEY COURT			C	N	1"		C	1"		SF						Installation record	N	1986		Field inspection only	Y			Cross-connection survey
1495	ASHLEY COURT			C	N	1"		C			SF						Installation record	N	1986		Installation record	N			
1505	ASHLEY COURT			C	N	1"		C	1"		SF						Installation record	N	1986		Field inspection only	Y			Cross-connection survey
1508	ASHLEY COURT			C	N	1"		C	1"		SF						Installation record	N	1986		Field inspection only	Y			Cross-connection survey
1514	ASHLEY COURT			C	N	1"		C	1"		SF						Installation record	N	1986		Field inspection only	Y			Cross-connection survey
1515	ASHLEY COURT			C	N	1"		C			SF						Installation record	N	1986		Installation record	N			
1520	ASHLEY COURT			C	N	1"		C	1"		SF						Installation record	N	1986		Field inspection only	Y			Cross-connection survey
1525	ASHLEY COURT			C	N	1"		C			SF						Installation record	N	1986		Installation record	N			
1529	ASHLEY COURT			C	N	1"		C	1"		SF						Installation record	N	1986		Field inspection only	Y			Cross-connection survey
951	ASHWAUBENON STREET	A		DI	N			C	1"		NONRES					8" serving this property	Installation record	Y			Field inspection only	Y			Cross-connection survey
963	ASHWAUBENON STREET			UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y			Cross-connection survey
970	ASHWAUBENON STREET			UNK-NOLG	N	2"		C	1 1/4"		NONRES						Installation record	N			Field inspection only	Y			Cross-connection survey
975	ASHWAUBENON STREET			UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y			Cross-connection survey
999	ASHWAUBENON STREET			UNK-NOLG	N	2"		C	1"		NONRES						Installation record	N			Field inspection only	Y			Cross-connection survey
1000	ASHWAUBENON STREET			DI	N	6"		DI	6"		NONRES						Diameter > 2 inches	Y			Field inspection only	Y			Cross-connection survey
1011	ASHWAUBENON STREET			UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y			Cross-connection survey
1021	ASHWAUBENON STREET			UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y			Cross-connection survey
1030	ASHWAUBENON STREET			P	N			P	2"		NONRES						Installation record	Y			Field inspection only	Y			Cross-connection survey
1037	ASHWAUBENON STREET			UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y			Cross-connection survey
1048	ASHWAUBENON STREET			UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y			Cross-connection survey
1049	ASHWAUBENON STREET			UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y			Cross-connection survey
1050	ASHWAUBENON STREET			P	N			P	4"		NONRES						Diameter > 2 inches	Y			Field inspection only	Y			Cross-connection survey
1101	ASHWAUBENON STREET			UNK-NOLG	N	2"		C	1"		NONRES						Installation record	N			Field inspection only	Y			Cross-connection survey
1132	ASHWAUBENON STREET			UNK-NOLG	N	2"		C	1"		NONRES						Installation record	N			Field inspection only	Y			Cross-connection survey
1140	ASHWAUBENON STREET			UNK-NOLG	N	2"		C	1"		NONRES						Installation record	N			Field inspection only	Y			Cross-connection survey
1161	ASHWAUBENON STREET			UNK-NOLG	N	2"		C	1"		NONRES						Installation record	N			Field inspection only	Y			Cross-connection survey
1162	ASHWAUBENON STREET			UNK-NOLG	N	2"		C	1"		NONRES						Installation record	N			Field inspection only	Y			Cross-connection survey
1180	ASHWAUBENON STREET			UNK-NOLG	N	2"		C	1"		NONRES						Installation record	N			Field inspection only	Y			Cross-connection survey
1200	ASHWAUBENON STREET			UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y			Cross-connection survey
1201	ASHWAUBENON STREET			UNK-NOLG	N	2"		C	1"		NONRES						Installation record	N			Field inspection only	Y			Cross-connection survey



LOCATIONAL IDENTIFIER ADDRESS	LOCATIONAL IDENTIFIER STREET NAME	LOCATIONAL IDENTIFIER UNIT OR SUITE #	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
2491	BABCOCK ROAD			P	N			C	1"		NONRES						Installed after lead ban	Y	2015	Visual insp during install o	Field inspection only	Y		Cross-connection survey	
2530	BABCOCK ROAD			C	N	2"		C	2"		NONRES						Field inspection only	Y		Visual insp during install o	Field inspection only	Y		Cross-connection survey	
2535	BABCOCK ROAD			C	N			P	1"		NONRES						Installation record	Y	1978		Field inspection only	Y		Cross-connection survey	
2543	BABCOCK ROAD			C	N			P	1"		NONRES						Installation record	Y	1978		Field inspection only	Y		Cross-connection survey	
2549	BABCOCK ROAD			C	N	3/4"		C			MF						Installation record	N			Installation record	N			
2559	BABCOCK ROAD			C	N	1"		C	1"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2571	BABCOCK ROAD			C	N	3/4"		C			MF						Installation record	N			Installation record	N			
2574	BABCOCK ROAD			C	N	3/4"		C	3/4"		MF						Installation record	N			Installation record	N			Cross-connection survey
2580	BABCOCK ROAD			C	N	1"		P			SF						Installation record	N			SL repair/replace record	Y		Visual insp during install or repair	
2585	BABCOCK ROAD			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2601	BABCOCK ROAD			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2611	BABCOCK ROAD			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2620	BABCOCK ROAD			C	N	3/4"		C	3/4"		SF						Installation record	N			Installation record	N			Cross-connection survey
2650	BABCOCK ROAD			C	N	3/4"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2653	BABCOCK ROAD			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2658	BABCOCK ROAD			C	N	3/4"		C			MF						Installation record	N			Installation record	N			
2676	BABCOCK ROAD			C	N	3/4"		C			MF						Installation record	N			Installation record	N			
2679	BABCOCK ROAD			C	N	3/4"		C			MF						Installation record	N			Installation record	N			
2700	BABCOCK ROAD			C	N			C	1 1/2"		NONRES						Installation record	Y	1978		Field inspection only	Y		Cross-connection survey	
2715	BABCOCK ROAD			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2732	BABCOCK ROAD			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2744	BABCOCK ROAD			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
595	BAETEN ROAD			C	N	2"		C	1"		NONRES						Field inspection only	Y			Field inspection only	Y		Cross-connection survey	
610	BAETEN ROAD			C	N			P	2"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
615	BAETEN ROAD			C	N	1"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
641	BAETEN ROAD			C	N	2"		C	1"		NONRES						Field inspection only	Y			Field inspection only	Y		Cross-connection survey	
677	BAETEN ROAD			C	N	2"		P	1 1/2"		NONRES						Field inspection only	Y			Field inspection only	Y		Cross-connection survey	
681	BAETEN ROAD			C	N	2"		C	1 1/2"		NONRES						Field inspection only	Y			Field inspection only	Y		Cross-connection survey	
750	BAETEN ROAD			C	N			P	2"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
2091	BALSAM WAY			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2101	BALSAM WAY			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2107	BALSAM WAY			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2113	BALSAM WAY			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2114	BALSAM WAY			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2118	BALSAM WAY			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2119	BALSAM WAY			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2120	BALSAM WAY			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2140	BALSAM WAY			C	N	1"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2141	BALSAM WAY			C	N	1"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2144	BALSAM WAY			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2145	BALSAM WAY			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2152	BALSAM WAY			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2153	BALSAM WAY			C	N	1"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2160	BALSAM WAY			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2161	BALSAM WAY			C	N	1"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2168	BALSAM WAY			C	N	1"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2169	BALSAM WAY			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2174	BALSAM WAY			C	N	3/4"		C	1"		SF						Installation record	N			Installation record	N			Cross-connection survey
2175	BALSAM WAY			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2182	BALSAM WAY			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2183	BALSAM WAY			C	N	3/4"		C	1"		SF						Installation record	N			Installation record	N			Cross-connection survey
2190	BALSAM WAY			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2191	BALSAM WAY			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2196	BALSAM WAY			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2197	BALSAM WAY			C	N	1"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2203	BALSAM WAY			C	N	1"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2204	BALSAM WAY			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2210	BALSAM WAY			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2211	BALSAM WAY			C	N	1"		P			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2217	BALSAM WAY			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2218	BALSAM WAY			C	N	1"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2223	BALSAM WAY			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2224	BALSAM WAY			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2229	BALSAM WAY			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2232	BALSAM WAY			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2235	BALSAM WAY			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2245	BALSAM WAY			C	N	1"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2246	BALSAM WAY			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2251	BALSAM WAY			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2257	BALSAM WAY			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2263	BALSAM WAY			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2271	BALSAM WAY			C	N	3/4																			

LOCATIONAL IDENTIFIER ADDRESS	LOCATIONAL IDENTIFIER STREET NAME	LOCATIONAL IDENTIFIER UNIT OR SUITE #	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
2372	BALSAM WAY			C	N	3/4"		C			MF						Installation record	N			Installation record	N			
2373	BALSAM WAY			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2382	BALSAM WAY			C	N	1"		C			SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2383	BALSAM WAY			C	N	3/4"		C			MF						Installation record	N			Installation record	N			
2396	BALSAM WAY			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2397	BALSAM WAY			C	N	3/4"		C			MF						Installation record	N			Installation record	N			
2433	BALSAM WAY			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2434	BALSAM WAY			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2055	BARBERRY LANE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2062	BARBERRY LANE			P	N	3/4"		C			SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2063	BARBERRY LANE			P	N	3/4"		C			SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2068	BARBERRY LANE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2071	BARBERRY LANE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2076	BARBERRY LANE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2083	BARBERRY LANE			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2091	BARBERRY LANE			C	N	1"		P			SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2104	BARBERRY LANE			C	N	3/4"		C	3/4"		SF						Installation record	N			Installation record	N			Cross-connection survey
2107	BARBERRY LANE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2108	BARBERRY LANE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2112	BARBERRY LANE			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2116	BARBERRY LANE			P	N	3/4"		P			SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2119	BARBERRY LANE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2120	BARBERRY LANE			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2130	BARBERRY LANE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2133	BARBERRY LANE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2138	BARBERRY LANE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2144	BARBERRY LANE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2151	BARBERRY LANE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2152	BARBERRY LANE			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2158	BARBERRY LANE			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2166	BARBERRY LANE			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2171	BARBERRY LANE			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2174	BARBERRY LANE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2195	BARBERRY LANE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2203	BARBERRY LANE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2211	BARBERRY LANE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2217	BARBERRY LANE			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2218	BARBERRY LANE			C	N	1"		C			SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2220	BARBERRY LANE			P	N	1"		C			SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2222	BARBERRY LANE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2225	BARBERRY LANE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2230	BARBERRY LANE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2233	BARBERRY LANE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2236	BARBERRY LANE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2244	BARBERRY LANE			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2252	BARBERRY LANE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2253	BARBERRY LANE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2258	BARBERRY LANE			P	N	3/4"		C			SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2266	BARBERRY LANE			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2436	BASSWOOD STREET			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2437	BASSWOOD STREET			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2444	BASSWOOD STREET			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2445	BASSWOOD STREET			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2452	BASSWOOD STREET			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2453	BASSWOOD STREET			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2458	BASSWOOD STREET			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2459	BASSWOOD STREET			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2466	BASSWOOD STREET			C	N	1"		C			MF						Installation record	N			Field inspection only	Y			Cross-connection survey
2467	BASSWOOD STREET			C	N	1"		C			MF						Installation record	N			Installation record	N			
2455	BAY AREA PLACE			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2463	BAY AREA PLACE			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2469	BAY AREA PLACE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2475	BAY AREA PLACE			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2480	BAY AREA PLACE			C	N	2"		C	1"		NONRES						Installation record	N			Field inspection only	Y			Cross-connection survey
2485	BAY AREA PLACE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2491	BAY AREA PLACE			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2497	BAY AREA PLACE			C	N	1"		C			MF						Installation record	N			Installation record	N			
2580	BAY HARBOR CIRCLE	1		P	N	1"		P			SF						Installed after lead ban	N	2008		Installed after lead ban	Y			Visual insp during install or repair
2584	BAY HARBOR CIRCLE	1		P	N	1"		P			SF						Installed after lead ban	N	2008		Installed after lead ban	Y			Visual insp during install or repair
2588	BAY HARBOR CIRCLE	1		P	N	1"		P			SF						Installed after lead ban	N	2008		Installed after lead ban	Y			Visual insp during install or repair
2592	BAY HARBOR CIRCLE	1		P	N	1"		P			SF						Installed after lead ban	N	2008		Installed after lead ban	Y			Visual insp during install or repair
2601	Bay Harbor Circle	1		P	N	1"		P			SF						Installed after lead ban	N	2008		Installed after lead ban	Y			Visual insp during install or repair
2605	BAY HARBOR CIRCLE	1		P	N	1"		P			SF						Installed after lead ban	N	2008		Installed after lead ban	Y			Visual insp during install or repair
2609	BAY HARBOR CIRCLE	1		P	N	1"		P			SF						Installed after lead ban	N	2008		Installed after lead ban	Y			Visual insp during install or repair
2613	BAY HARBOR CIRCLE	1		P	N	1"		P			SF						Installed after lead ban	N	2008		Installed after lead ban	Y			Visual insp during install or repair
2617	BAY HARBOR CIRCLE	1		P	N	1"		P			SF						Installed after lead ban	N	2008		Installed after lead ban	Y			Visual insp during install or repair
2621	BAY HARBOR CIRCLE	1		P	N	1"		P			SF						Installed after lead ban	N	2008		Installed after lead ban	Y			Visual insp during install or repair
2625	BAY HARBOR CIRCLE	1		P	N	1"		P			SF						Installed after lead ban	N	2008		Installed after lead ban	Y			Visual insp during install or repair
303	BAY PARK SQUARE			DI	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y			Cross-connection survey
780	BAYLAND COURT			C	N	2"		P	1"		NONRES						Installation record	Y	1980		Field inspection only	Y			Cross-connection survey
808	BAYLAND COURT			C	N	2"		P	1 1/2"		NONRES						Installation record	Y	1980		Field inspection only	Y			Cross-connection survey
3608	Becker Ct			P	N	1"		P			SF						Installed after lead ban	Y	2008		Installed after lead ban	Y			Visual insp during install or repair
3613	Becker Ct			P	N	1"		P			SF						Installed after lead ban	Y	2008		Installed after lead ban	Y			Visual insp during install or repair
1052	BEL AIRE COURT			C	N	3/4"		C	1"		NONRES						Installation record	Y	1965	isp during install o	Field inspection only	Y			Cross-connection survey
2304	BEL AIRE COURT			C	N	1"		C	1"																

LOCATIONAL IDENTIFIER ADDRESS	LOCATIONAL IDENTIFIER STREET NAME	LOCATIONAL IDENTIFIER UNIT OR SUITE #	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
2312	BEL AIRE COURT			C	N	3/4"		C	1"		NONRES						Installation record	Y	1965	isp during install o	Field inspection only	Y		Cross-connection survey	
2736	BERKEN COURT			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2737	BERKEN COURT			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2740	BERKEN COURT			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2741	BERKEN COURT			C	N	3/4"		C	1"		SF						Installation record	N			Installation record	N			Cross-connection survey
2746	BERKEN COURT			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2749	BERKEN COURT			C	N	3/4"		C	1"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2754	BERKEN COURT			C	N	1"		C			SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2757	BERKEN COURT			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2760	BERKEN COURT			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2761	BERKEN COURT			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2766	BERKEN COURT			C	N	3/4"		C	1"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2767	BERKEN COURT			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2772	BERKEN COURT			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2773	BERKEN COURT			C	N	1"		P			MF						Installation record	N			Field inspection only	Y			Cross-connection survey
2778	BERKEN COURT			C	N	3/4"		C	1"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2781	BERKEN COURT			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2784	BERKEN COURT			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2792	BERKEN COURT			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2798	BERKEN COURT			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2799	BERKEN COURT			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2804	BERKEN COURT			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2805	BERKEN COURT			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2810	BERKEN COURT			C	N	3/4"		C	1"		SF						Installation record	N			Installation record	N			Cross-connection survey
2813	BERKEN COURT			C	N	3/4"		C	1"		SF						Installation record	N			Installation record	N			Cross-connection survey
2816	BERKEN COURT			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2824	BERKEN COURT			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2829	BERKEN COURT			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2830	BERKEN COURT			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2835	BERKEN COURT			C	N	3/4"		C	1"		SF						Installation record	N			Installation record	N			Cross-connection survey
2836	BERKEN COURT			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2842	BERKEN COURT			C	N	1"		C			SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2843	BERKEN COURT			C	N	1"		C			SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2848	BERKEN COURT			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2849	BERKEN COURT			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2855	BERKEN COURT			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2856	BERKEN COURT			C	N	1"		C			SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2861	BERKEN COURT			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2862	BERKEN COURT			C	N	3/4"		C	3/4"		SF						Installation record	N			Installation record	N			Cross-connection survey
1058	BETHANY PLACE			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y			Cross-connection survey
1064	BETHANY PLACE			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y			Cross-connection survey
1065	BETHANY PLACE			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y			Cross-connection survey
1070	BETHANY PLACE			C	N	3/4"		C	3/4"		SF						Installation record	N			Installation record	N			Cross-connection survey
1071	BETHANY PLACE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1076	BETHANY PLACE			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y			Cross-connection survey
1079	BETHANY PLACE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1084	BETHANY PLACE			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y			Cross-connection survey
1087	BETHANY PLACE			C	N	3/4"		C	3/4"		SF						Installation record	N			Installation record	N			Cross-connection survey
1092	BETHANY PLACE			C	N	3/4"		C	3/4"		SF						Installation record	N			Installation record	N			Cross-connection survey
2121	BETHANY PLACE			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y			Cross-connection survey
1050	BLACKBERRY WINTER LA			P	N	1"		P			SF						Installation record	Y			Installed after lead ban	Y			Visual insp during install or repair
1057	BLACKBERRY WINTER LA			P	N	1"		P			SF						Installation record	Y			Installed after lead ban	Y			Visual insp during install or repair
1058	BLACKBERRY WINTER LA			P	N	1"		P			SF						Installation record	Y			Installed after lead ban	Y			Visual insp during install or repair
1065	BLACKBERRY WINTER LA			P	N	1"		P			SF						Installation record	Y			Installed after lead ban	Y			Visual insp during install or repair
1066	BLACKBERRY WINTER LA			P	N	1"		P			SF						Installation record	Y			Installed after lead ban	Y			Visual insp during install or repair
1073	BLACKBERRY WINTER LA			P	N	1"		P			SF						Installation record	Y			Installed after lead ban	Y			Visual insp during install or repair
1074	BLACKBERRY WINTER LA			P	N	1"		P			SF						Installation record	Y			Installed after lead ban	Y			Visual insp during install or repair
1081	BLACKBERRY WINTER LA			P	N	1"		P			SF						Installation record	Y			Installed after lead ban	Y			Visual insp during install or repair
1082	BLACKBERRY WINTER LA			P	N	1"		P			SF						Installation record	Y			Installed after lead ban	Y			Visual insp during install or repair
1089	BLACKBERRY WINTER LA			P	N	1"		P			SF						Installation record	Y			Installed after lead ban	Y			Visual insp during install or repair
1090	BLACKBERRY WINTER LA			P	N	1"		P			SF						Installation record	Y			Installed after lead ban	Y			Visual insp during install or repair
1097	BLACKBERRY WINTER LA			P	N	1"		P			SF						Installation record	Y			Installed after lead ban	Y			Visual insp during install or repair
1098	BLACKBERRY WINTER LA			P	N	1"		P			SF						Installation record	Y			Installed after lead ban	Y			Visual insp during install or repair
1106	BLACKBERRY WINTER LA			P	N	1"		P			SF						Installation record	Y			Installed after lead ban	Y			Visual insp during install or repair
2851	BLUE JAY LANE			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2859	BLUE JAY LANE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2865	BLUE JAY LANE			C	N	1"		C			SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2866	BLUE JAY LANE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1063	BLUE RIDGE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1071	BLUE RIDGE DRIVE			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y			Cross-connection survey
1077	BLUE RIDGE DRIVE			C	N	3/4"		C			SF						Installation record								



LOCATIONAL IDENTIFIER ADDRESS	LOCATIONAL IDENTIFIER STREET NAME	LOCATIONAL IDENTIFIER UNIT OR SUITE #	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
1134	BLUE RIDGE DRIVE			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1135	BLUE RIDGE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1160	BLUE RIDGE DRIVE			C	N	1"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1161	BLUE RIDGE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1166	BLUE RIDGE DRIVE			C	N	1"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1167	BLUE RIDGE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1172	BLUE RIDGE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1175	BLUE RIDGE DRIVE			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1178	BLUE RIDGE DRIVE			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1181	BLUE RIDGE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1184	BLUE RIDGE DRIVE			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1189	BLUE RIDGE DRIVE			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1192	BLUE RIDGE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1197	BLUE RIDGE DRIVE			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1198	BLUE RIDGE DRIVE			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1203	BLUE RIDGE DRIVE			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1204	BLUE RIDGE DRIVE			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1210	BLUE RIDGE DRIVE			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1211	BLUE RIDGE DRIVE			C	N	3/4"		C	1"		SF						Installation record	N			Installation record	N		Cross-connection survey	
1216	BLUE RIDGE DRIVE			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1217	BLUE RIDGE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1238	BLUE RIDGE DRIVE			C	N	3/4"		C			MF						Installation record	N			Installation record	N			
1244	BLUE RIDGE DRIVE			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1245	BLUE RIDGE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1250	BLUE RIDGE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1251	BLUE RIDGE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1257	BLUE RIDGE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1260	BLUE RIDGE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1264	BLUE RIDGE DRIVE			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1265	BLUE RIDGE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1270	BLUE RIDGE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1271	BLUE RIDGE DRIVE			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1279	BLUE RIDGE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1280	BLUE RIDGE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1286	BLUE RIDGE DRIVE			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1287	BLUE RIDGE DRIVE			C	N	3/4"		C	3/4"		SF						Installation record	N			Installation record	N		Cross-connection survey	
1292	BLUE RIDGE DRIVE			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1293	BLUE RIDGE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1300	BLUE RIDGE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1301	BLUE RIDGE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1306	BLUE RIDGE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1307	BLUE RIDGE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1312	BLUE RIDGE DRIVE			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1313	BLUE RIDGE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1320	BLUE RIDGE DRIVE			C	N	3/4"		C			SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1321	BLUE RIDGE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1326	BLUE RIDGE DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1061	BLUEGRASS COURT			P	N	1"		P			SF						Installation record	Y			Installed after lead ban	Y		Visual insp during install or repair	
1062	BLUEGRASS COURT			P	N	1"		P			SF						Installation record	Y			Installed after lead ban	Y		Visual insp during install or repair	
682	Borvan			UNK-NOLG	N			P	2"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
692	Borvan			UNK-NOLG	N			P	2"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
711	Borvan			UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey	
597	BORVAN AVENUE			P	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
598	BORVAN AVENUE			UNK-NOLG	N			C	1"		NONRES						Installation record	N	1969		Field inspection only	Y		Cross-connection survey	
599	BORVAN AVENUE			P	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y		Cross-connection survey	
643	BORVAN AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
651	BORVAN AVENUE			C	N	1"		C			MF						Installation record	Y			Field inspection only	Y		Cross-connection survey	
661	BORVAN AVENUE			C	N	1"		P			MF						Installation record	Y			Field inspection only	Y		Cross-connection survey	
679	BORVAN AVENUE			UNK-NOLG	N			C	3/4"		NONRES						Installation record	N	1969		Field inspection only	Y		Cross-connection survey	
683	BORVAN AVENUE	A		UNK-NOLG	N			C	1"		NONRES						Installation record	N	1969		Field inspection only	Y		Cross-connection survey	
695	BORVAN AVENUE			UNK-NOLG	N			C	1"		NONRES						Installation record	N	1969		Field inspection only	Y		Cross-connection survey	
732	BORVAN AVENUE			UNK-NOLG	N			C	1"		NONRES						Installation record	N	1969		Field inspection only	Y		Cross-connection survey	
733	BORVAN AVENUE			UNK-NOLG	N			C	1"		NONRES						Installation record	N	1969		Field inspection only	Y		Cross-connection survey	
742	BORVAN AVENUE			C	N	1"		C	1"		NONRES						Installation record	Y	1969		Field inspection only	Y		Cross-connection survey	
750	BORVAN AVENUE			UNK-NOLG	N			C	3/4"		NONRES						Installation record	N	1969		Field inspection only	Y		Cross-connection survey	
786	BORVAN AVENUE			UNK-NOLG	N			C	1"		NONRES						Installation record	N	1969		Field inspection only	Y		Cross-connection survey	
790	BORVAN AVENUE			UNK-NOLG	N			C	2"		NONRES						Installation record	N	1969		Field inspection only	Y		Cross-connection survey	
838	BORVAN AVENUE			UNK-NOLG	N			C	3/4"		NONRES						Installation record	N	1969		Field inspection only	Y		Cross-connection survey	
845	BORVAN AVENUE			C	N	1"		C			SF						Installation record	Y			Field inspection only	Y		Cross-connection survey	
411	BOSAR AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
414	BOSAR AVENUE			C	N	1"		C			SF						Installation record	Y			Field inspection only	Y		Cross-connection survey	
428	BOSAR AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
433	BOSAR AVENUE			C	N	3/4"		C			SF						Installation record	Y			Field inspection only	Y		Cross-connection survey	
438	BOSAR AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
441	BOSAR AVENUE			C	N	3/4"		C			SF						Installation record	Y			Field inspection only	Y		Cross-connection survey	
444	BOSAR AVENUE			C	N	3/4"		C			SF						Installation record	Y			Field inspection only	Y		Cross-connection survey	
447	BOSAR AVENUE			C	N	3/4"		C			SF						Installation record	Y			Field inspection only	Y		Cross-connection survey	
450	BOSAR AVENUE			C	N	3/4"		C			SF						Installation record	Y			Field inspection only	Y		Cross-connection survey	
455	BOSAR AVENUE			C	N	3/4"		C			SF						Installation record	Y			Field inspection only	Y		Cross-connection survey	
458	BOSAR AVENUE			C	N	3/4"		C			SF						Installation record	Y			Field inspection only	Y		Cross-connection survey	
459	BOSAR AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	Y			Installation record	N		Cross-connection survey	
462	BOSAR AVENUE			C	N	3/4"		C			SF						Installation record	Y			Field inspection only	Y		Cross-connection survey	
471	BOSAR AVENUE			C	N	3/4"		C			SF						Installation record	Y			Installation record	N			
1464	BRADBURY COURT			P	N	1"		P			SF						Installed after lead ban	Y	1992		Installed after lead ban	Y			
1465	BRADBURY COURT			P	N	1"		P																	













LOCATIONAL IDENTIFIER ADDRESS	LOCATIONAL IDENTIFIER STREET NAME	LOCATIONAL IDENTIFIER UNIT OR SUITE #	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
1000	CIRCLE DRIVE			UNK-NOLG	N			P	1"		NONRES						Installation record	N			Field inspection only	Y			Cross-connection survey
1018	CIRCLE DRIVE			UNK-NOLG	N			DI	8"		NONRES						Diameter > 2 inches	N			Field inspection only	Y			Cross-connection survey
1040	CIRCLE DRIVE			P	N	2"		P	1"		NONRES						Installed after lead ban	Y	2008	isp during install o	Field inspection only	Y			Cross-connection survey
1050	CIRCLE DRIVE	A		UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y			Cross-connection survey
1080	CIRCLE DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1086	CIRCLE DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1091	CIRCLE DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1095	CIRCLE DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1104	CIRCLE DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1105	CIRCLE DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1125	CIRCLE DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1131	CIRCLE DRIVE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
1137	CIRCLE DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1143	CIRCLE DRIVE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
1147	CIRCLE DRIVE			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
1161	CIRCLE DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1183	CIRCLE DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1191	CIRCLE DRIVE			C	N	1"		P	1"		SF						Installation record	N			Installation record	N			Cross-connection survey
1211	CIRCLE DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1212	CIRCLE DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1221	CIRCLE DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1224	CIRCLE DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1233	CIRCLE DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1240	CIRCLE DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1250	CIRCLE DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1253	CIRCLE DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1258	CIRCLE DRIVE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
1261	CIRCLE DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1266	CIRCLE DRIVE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
1267	CIRCLE DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1273	CIRCLE DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1274	CIRCLE DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1279	CIRCLE DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1280	CIRCLE DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1285	CIRCLE DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1288	CIRCLE DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1291	CIRCLE DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1294	CIRCLE DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1297	CIRCLE DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1298	CIRCLE DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1299	CIRCLE DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1319	CIRCLE DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1320	CIRCLE DRIVE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
1327	CIRCLE DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1335	CIRCLE DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1336	CIRCLE DRIVE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
1343	CIRCLE DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1350	CIRCLE DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1353	CIRCLE DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1355	CIRCLE DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1360	CIRCLE DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1369	CIRCLE DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1374	CIRCLE DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1377	CIRCLE DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2920	CIRCLE OAKS LANE			P	N	1"		C			SF						Installed after lead ban	Y	1992		Installed after lead ban	N			
2930	CIRCLE OAKS LANE			P	N	1"		C	1"		SF						Installed after lead ban	Y	1992		Installed after lead ban	N			Cross-connection survey
2931	CIRCLE OAKS LANE			P	N	1"		C	1"		SF						Installed after lead ban	Y	1992		Field inspection only	Y			Cross-connection survey
2570	CLIVE STREET			C	N	1"		C			MF						Installation record	N			Installation record	N			
2582	CLIVE STREET			C	N	1"		C			MF						Installation record	N			Installation record	N			
2583	CLIVE STREET			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2590	CLIVE STREET			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2598	CLIVE STREET			C	N	1"		C	3/4"		MF						Installation record	N			Field inspection only	Y			Cross-connection survey
2601	CLIVE STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2609	CLIVE STREET			C	N	1"		C			MF						Installation record	N			Installation record	N			
2610	CLIVE STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2650	CLIVE STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2651	CLIVE STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2660	CLIVE STREET			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2661	CLIVE STREET			C	N	1"		C	1"		SF						Installation record	N			Installation record	N			Cross-connection survey
2678	CLIVE STREET			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2679	CLIVE STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2689	CLIVE STREET			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2690	CLIVE STREET			C	N	1"		C	1"		SF						Installation record	N			Installation record	N			Cross-connection survey
2697	CLIVE STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2705	CLIVE STREET			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2706	CLIVE STREET			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2711	CLIVE STREET			C	N	1"		C	3/4"		SF						Installation record	N			Installation record	N			Cross-connection survey
2716	CLIVE STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2717	CLIVE STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2732	CLIVE STREET			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2733	CLIVE STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2743	CLIVE STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2744	CLIVE STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
446	COLLETTE AVENUE			C	N	1"		C			MF						Installation record	N			Installation record	N			
454	COLLETTE AVENUE			C	N	1"		C	3/4"		MF						Installation record	N			Installation record	N			Cross-connection survey



LOCATIONAL IDENTIFIER ADDRESS	LOCATIONAL IDENTIFIER STREET NAME	LOCATIONAL IDENTIFIER UNIT OR SUITE #	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
455	COLLETTE AVENUE			C	N	1"		C	3/4"		MF						Installation record	N			Field inspection only	Y			Cross-connection survey
463	COLLETTE AVENUE			C	N	1"		C			MF						Installation record	N			Installation record	N			
466	COLLETTE AVENUE			C	N	2"		P	1 1/4"		NONRES					this lateral comes off Broadw	Installation record	Y	2001	isp during install o	Field inspection only	Y			Cross-connection survey
484	COLLETTE AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
490	COLLETTE AVENUE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
491	COLLETTE AVENUE			C	N	1"		C	3/4"		MF						Installation record	N			Field inspection only	Y			Cross-connection survey
495	COLLETTE AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
496	COLLETTE AVENUE			C	N	1"		C			MF						Installation record	N			Installation record	N			
501	COLLETTE AVENUE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
520	COLLETTE AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
524	COLLETTE AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
525	COLLETTE AVENUE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
528	COLLETTE AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
534	COLLETTE AVENUE			C	N	1"		C			MF						Installation record	N			Installation record	N			
538	COLLETTE AVENUE			C	N	1"		C	3/4"		MF						Installation record	N			Installation record	N			Cross-connection survey
539	COLLETTE AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
542	COLLETTE AVENUE			C	N	1"		C	3/4"		MF						Installation record	N			Field inspection only	Y			Cross-connection survey
551	COLLETTE AVENUE			C	N	1"		C	1"		MF						Installation record	N			Field inspection only	Y			Cross-connection survey
1247	COMMANCHE AVENUE			C	N	1"		C	1"		MF						Installation record	N			Field inspection only	Y			Cross-connection survey
1255	COMMANCHE AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1261	COMMANCHE AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1267	COMMANCHE AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1275	COMMANCHE AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1281	COMMANCHE AVENUE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
1289	COMMANCHE AVENUE			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
1295	COMMANCHE AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1390	COMMANCHE AVENUE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
1391	COMMANCHE AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1401	COMMANCHE AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1410	COMMANCHE AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1411	COMMANCHE AVENUE			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
1424	COMMANCHE AVENUE			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
1425	COMMANCHE AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1426	COMMANCHE AVENUE			C	N	1"		C			MF						Installation record	N			Installation record	N			
1427	COMMANCHE AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1428	COMMANCHE AVENUE			C	N	1"		C			MF						Installation record	N			Installation record	N			
1429	COMMANCHE AVENUE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
1432	COMMANCHE AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1433	COMMANCHE AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1439	COMMANCHE AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1440	COMMANCHE AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1445	COMMANCHE AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1446	COMMANCHE AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1451	COMMANCHE AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1452	COMMANCHE AVENUE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
1476	COMMANCHE AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1477	COMMANCHE AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1482	COMMANCHE AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1483	COMMANCHE AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1488	COMMANCHE AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1491	COMMANCHE AVENUE			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
1494	COMMANCHE AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1497	COMMANCHE AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1498	COMMANCHE AVENUE			C	N	1"		C	3/4"		SF						Installation record	N			Installation record	N			Cross-connection survey
1503	COMMANCHE AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1504	COMMANCHE AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1509	COMMANCHE AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1510	COMMANCHE AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1517	COMMANCHE AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1518	COMMANCHE AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1521	COMMANCHE AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1549	COMMANCHE AVENUE			C	N	1"		C	3/4"		MF						Installation record	N			Field inspection only	Y			Cross-connection survey
1557	COMMANCHE AVENUE			C	N	1"		C	1"		MF						Installation record	N			Field inspection only	Y			Cross-connection survey
1565	COMMANCHE AVENUE			C	N	1"		C	3/4"		MF						Installation record	N			Field inspection only	Y			Cross-connection survey
1571	COMMANCHE AVENUE			C	N	1"		C	3/4"		MF						Installation record	N			Field inspection only	Y			Cross-connection survey
1579	COMMANCHE AVENUE			C	N	1"		C	3/4"		MF						Installation record	N			Field inspection only	Y			Cross-connection survey
1580	COMMANCHE AVENUE			P	N	8"		P	1"		NONRES					Diameter > 2 inches	Y	2008	isp during install o	Field inspection only	Y			Cross-connection survey	
1581	COMMANCHE AVENUE			C	N	1"		C	3/4"		MF						Installation record	N			Field inspection only	Y			Cross-connection survey
1587	COMMANCHE AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1595	COMMANCHE AVENUE			C	N	1"		C			MF						Installation record	N			Installation record	N			
1597	COMMANCHE AVENUE			C	N	1"		C			MF						Installation record	N			Installation record	N			
1601	COMMANCHE AVENUE			C	N	1"		C	1"		MF						Installation record	N			Field inspection only	Y			Cross-connection survey
1621	COMMANCHE AVENUE			C	N	1"		C			MF						Installation record	N			Installation record	N			
1630	COMMANCHE AVENUE			P	N	8"		C	1"		NONRES					Diameter > 2 inches	Y			Field inspection only	Y			Cross-connection survey	
1639	COMMANCHE AVENUE			UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y			Cross-connection survey
1641	COMMANCHE AVENUE			UNK-NOLG	N	8"		C	1"		NONRES					this lateral comes off Packerle	Installation record	N			Field inspection only	Y			Cross-connection survey
3065	COMMODITY LANE	A		UNK-NOLG	N			P	1 1/2"		NONRES						Installation record	N			Field inspection only	Y			Cross-connection survey
3070	COMMODITY LANE			P	N	6"		P	1"		NONRES						Diameter > 2 inches	Y	2023	isp during install o	Field inspection only	Y			Cross-connection survey
3120	COMMODITY LANE			P	N			P	3"		NONRES						Diameter > 2 inches	Y	1981		Field inspection only	Y			Cross-connection survey
3142	COMMODITY LANE			P	N			C	1"		NONRES						Installation record	Y	1981		Field inspection only	Y			Cross-connection survey
3155	COMMODITY LANE			P	N			C	1"		NONRES						Installation record	Y	1981		Field inspection only	Y			Cross-connection survey
3160	COMMODITY LANE			UNK-NOLG	N			C	1 1/2"		NONRES						Installation record	N			Field inspection only	Y			Cross-connection survey
3181	COMMODITY LANE			UNK-NOLG	N			C	2"		NONRES						Installation record	N			Field inspection only	Y			Cross-connection survey
3200	COMMODITY LANE			UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y			Cross-connection survey
3220	COMMODITY LANE			UNK-NOLG	N			P	1"		NONRES						Installation record								

LOCATIONAL IDENTIFIER ADDRESS	LOCATIONAL IDENTIFIER STREET NAME	LOCATIONAL IDENTIFIER UNIT OR SUITE #	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
3230	COMMODITY LANE			UNK-NOLG	N			C	1"			NONRES					Installation record	N			Field inspection only	Y			Cross-connection survey
3280	COMMODITY LANE	1		UNK-NOLG	N	6"		C	1"			NONRES				this complex is fed by 6" lateral	Installation record	N			Field inspection only	Y			Cross-connection survey
3300	COMMODITY LANE			UNK-NOLG	N			C	1"			NONRES					Installation record	N			Field inspection only	Y			Cross-connection survey
3306	COMMODITY LANE			UNK-NOLG	N			C	1"			NONRES					Installation record	N			Field inspection only	Y			Cross-connection survey
3330	COMMODITY LANE			UNK-NOLG	N			C	1"			NONRES					Installation record	N			Field inspection only	Y			Cross-connection survey
3333	COMMODITY LANE	1		UNK-NOLG	N	6"		C	1"			NONRES				this is fed with 6" lateral	Installation record	Y			Field inspection only	Y			Cross-connection survey
3350	COMMODITY LANE	C		C	N	2"		C	1"			NONRES				2" lateral feeds this comple	Field inspection only	Y	Visual insp at mete		Field inspection only	Y			Cross-connection survey
3355	COMMODITY LANE			UNK-NOLG	N			C	1"			NONRES					Installation record	N			Field inspection only	Y			Cross-connection survey
3431	COMMODITY LANE			UNK-NOLG	N			C	1"			NONRES					Installation record	N			Field inspection only	Y			Cross-connection survey
1135	CONTRACT DRIVE			UNK-NOLG	N			C	1"			NONRES					Installation record	N			Field inspection only	Y			Cross-connection survey
1136	CONTRACT DRIVE			UNK-NOLG	N			P	1"			NONRES					Installation record	N			Field inspection only	Y			Cross-connection survey
1160	CONTRACT DRIVE			P	N			P	1 1/2"			NONRES					Installation record	Y			Field inspection only	Y			Cross-connection survey
1176	CONTRACT DRIVE			P	N			P	2"			NONRES					Installation record	Y			Field inspection only	Y			Cross-connection survey
1201	CONTRACT DRIVE			P	N	8"		P	1"			NONRES					Installed after lead ban	Y	2023	isp during install o	Field inspection only	Y			Cross-connection survey
1240	CONTRACT DRIVE			UNK-NOLG	N			C	1 1/2"			NONRES					Installation record	N			Field inspection only	Y			Cross-connection survey
1247	CONTRACT DRIVE			UNK-NOLG	N			C	3/4"			NONRES					Installation record	N			Field inspection only	Y			Cross-connection survey
1271	CONTRACT DRIVE			UNK-NOLG	N			C	1 1/2"			NONRES					Installation record	N			Field inspection only	Y			Cross-connection survey
1301	CONTRACT DRIVE			UNK-NOLG	N			C	1"			NONRES					Installation record	N			Field inspection only	Y			Cross-connection survey
1311	CONTRACT DRIVE			UNK-NOLG	N			C	2"			NONRES					Installation record	N			Field inspection only	Y			Cross-connection survey
1330	CONTRACT DRIVE			UNK-NOLG	N			C	2"			NONRES					Installation record	N			Field inspection only	Y			Cross-connection survey
1869	CORMIER RD			C	N	1"		C				SF					Installation record	N			Installation record	N			
523	CORMIER ROAD			C	N	1"		C				SF					Installation record	N			Installation record	N			
535	CORMIER ROAD			P	N	2"		C	1 1/2"			NONRES					Installed after lead ban	Y	2018	isp during install o	Field inspection only	Y			Cross-connection survey
556	CORMIER ROAD			C	N	1"		C	3/4"			MF					Installation record	N			Field inspection only	Y			Cross-connection survey
566	CORMIER ROAD			C	N	1"		C				SF					Installation record	N			Installation record	N			
580	CORMIER ROAD			P	N	2"		P	1"			NONRES					Installed after lead ban	Y	2018	isp during install o	Field inspection only	Y			Cross-connection survey
660	CORMIER ROAD			C	N			DI	1"			NONRES					Installation record	Y			Field inspection only	Y			Cross-connection survey
670	CORMIER ROAD			P	N	6"		DI	6"			NONRES					Installed after lead ban	Y	2018	isp during install o	Field inspection only	Y			Cross-connection survey
680	CORMIER ROAD			P	N	2"		C	2"			SCH/CC					Installed after lead ban	Y	2018	isp during install o	Field inspection only	Y			Cross-connection survey
700	CORMIER ROAD			P	N	2"		P	1 1/2"			NONRES					Installed after lead ban	Y	2018	isp during install o	Field inspection only	Y			Cross-connection survey
727	CORMIER ROAD	UP		P	N	2"		C	2"			NONRES					Installation record	Y	2018	isp during install o	Field inspection only	Y			Cross-connection survey
737	CORMIER ROAD			P	N	2"		C	1"			NONRES					Installed after lead ban	Y			Field inspection only	Y			Cross-connection survey
786	CORMIER ROAD			P	N	2"		C	2"			NONRES					Installed after lead ban	Y	2018	isp during install o	Field inspection only	Y			Cross-connection survey
800	CORMIER ROAD			P	N	2"		C	1"			NONRES					Installed after lead ban	Y	2018	isp during install o	Field inspection only	Y			Cross-connection survey
812	CORMIER ROAD			P	N	2"		C	1 1/2"			NONRES					Installed after lead ban	Y	2018	isp during install o	Field inspection only	Y			Cross-connection survey
821	CORMIER ROAD			P	N	2"		C	1 1/2"			NONRES					Installed after lead ban	Y	2018	isp during install o	Field inspection only	Y			Cross-connection survey
822	CORMIER ROAD			P	N	2"		P	2"			NONRES					Installed after lead ban	Y	2018	isp during install o	Field inspection only	Y			Cross-connection survey
823	CORMIER ROAD			P	N	2"		C	1 1/2"			NONRES					Installed after lead ban	Y	2018	isp during install o	Field inspection only	Y			Cross-connection survey
825	CORMIER ROAD			P	N	2"		C	1 1/2"			NONRES					Installed after lead ban	Y	2018	isp during install o	Field inspection only	Y			Cross-connection survey
827	CORMIER ROAD			P	N	2"		P	1 1/2"			NONRES					Installed after lead ban	Y	2018	isp during install o	Field inspection only	Y			Cross-connection survey
845	CORMIER ROAD			P	N	2"		P	1"			NONRES					Installed after lead ban	Y	2018	isp during install o	Field inspection only	Y			Cross-connection survey
849	CORMIER ROAD			P	N	2"		C	1"			NONRES					Installed after lead ban	Y	2018	isp during install o	Field inspection only	Y			Cross-connection survey
944	CORMIER ROAD			C	N	1"		C	1"			SF					Installation record	N			Installation record	N			Cross-connection survey
950	CORMIER ROAD			C	N	1"		C				SF					Installation record	N			Installation record	N			
956	CORMIER ROAD			C	N	1"		C	1"			SF					Installation record	N			Field inspection only	Y			Cross-connection survey
966	CORMIER ROAD			C	N	1"		C				SF					Installation record	N			Installation record	N			
976	CORMIER ROAD			C	N	1"		C				SF					Installation record	N			Installation record	N			
980	CORMIER ROAD			C	N	1"		C	3/4"			SF					Installation record	N			Field inspection only	Y			Cross-connection survey
986	CORMIER ROAD			C	N	1"		C	3/4"			SF					Installation record	N			Installation record	N			Cross-connection survey
988	CORMIER ROAD			C	N	1"		C	3/4"			MF					Installation record	N			Field inspection only	Y			Cross-connection survey
990	CORMIER ROAD			C	N	1"		C	3/4"			MF					Installation record	N			Field inspection only	Y			Cross-connection survey
996	CORMIER ROAD			C	N	1"		C	1"			MF					Installation record	N			Field inspection only	Y			Cross-connection survey
1001	CORMIER ROAD			UNK-NOLG	N			C	2"			NONRES					Installation record	N			Field inspection only	Y			Cross-connection survey
1006	CORMIER ROAD			C	N	1"		C	3/4"			SF					Installation record	N			Field inspection only	Y			Cross-connection survey
1055	CORMIER ROAD			UNK-NOLG	N			C	2"			NONRES					Installation record	N			Field inspection only	Y			Cross-connection survey
1071	CORMIER ROAD			P	N	2"		C	1"			NONRES					Installed after lead ban	Y	2018	isp during install o	Field inspection only	Y			Cross-connection survey
1080	CORMIER ROAD			C	N	1"		C				SF					Installation record	N			Installation record	N			
1088	CORMIER ROAD			C	N	1"		C				SF					Installation record	N			Installation record	N			
1098	CORMIER ROAD			C	N	1"		C	3/4"			SF					Installation record	N			Field inspection only	Y			Cross-connection survey
1105	CORMIER ROAD			C	N	1"		C				SF					Installation record	N			Installation record	N			
1106	CORMIER ROAD			C	N	1"		C	3/4"			SF					Installation record	N			Field inspection only	Y			Cross-connection survey
1111	CORMIER ROAD			C	N	1"		C				SF					Installation record	N			Installation record	N			
1116	CORMIER ROAD			C	N	1"		C	3/4"			SF					Installation record	N			Field inspection only	Y			Cross-connection survey
1119	CORMIER ROAD			C	N	1"		C				SF					Installation record	N			Installation record	N			
1124	CORMIER ROAD			C	N	1"		C	3/4"			SF					Installation record	N			Field inspection only	Y			Cross-connection survey
1125	CORMIER ROAD			C	N	1"		C				SF					Installation record	N			Installation record	N			
1131	CORMIER ROAD			C	N	1"		C	3/4"			SF					Installation record	N			Field inspection only	Y			Cross-connection survey
1132	CORMIER ROAD			C	N	1"		C				SF					Installation record	N			Installation record	N			
1139	CORMIER ROAD			C	N	1"		C				SF					Installation record	N							









LOCATIONAL IDENTIFIER ADDRESS	LOCATIONAL IDENTIFIER STREET NAME	LOCATIONAL IDENTIFIER UNIT OR SUITE #	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
1112	DAISY LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
1113	DAISY LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
1120	DAISY LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1121	DAISY LANE			C	N	1"		C	1"		SF						Installation record	N			Installation record	N			Cross-connection survey
1124	DAISY LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1127	DAISY LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
1134	DAISY LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1135	DAISY LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2336	DEW LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2342	DEW LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2347	DEW LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2348	DEW LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2355	DEW LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2356	DEW LANE			C	N	1"		C	3/4"		SF						Installation record	N			Installation record	N			Cross-connection survey
2361	DEW LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2362	DEW LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2369	DEW LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2370	DEW LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2375	DEW LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2376	DEW LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2381	DEW LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2382	DEW LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2388	DEW LANE			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2391	DEW LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2394	DEW LANE			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2436	DONEY STREET			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2437	DONEY STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2444	DONEY STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2445	DONEY STREET			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2452	DONEY STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2453	DONEY STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2458	DONEY STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2459	DONEY STREET			C	N	1"		C	3/4"		SF						Installation record	N			Installation record	N			Cross-connection survey
2466	DONEY STREET			C	N	1"		C	1"		SF						Installation record	N			Installation record	N			Cross-connection survey
2467	DONEY STREET			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2297	DORN DRIVE			C	N	1"		C	1"		SF						Installation record	N			Installation record	Y			Cross-connection survey
2305	DORN DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2306	DORN DRIVE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2326	DORN DRIVE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2331	DORN DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2336	DORN DRIVE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2341	DORN DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2346	DORN DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2349	DORN DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2352	DORN DRIVE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2357	DORN DRIVE			C	N	1"		C	1"		SF						Installation record	N			Installation record	N			Cross-connection survey
2140	DOROTHY LANE			C	N	1"		C	3/4"		SF						Installation record	N			Installation record	N			Cross-connection survey
2141	DOROTHY LANE			C	N	1"		C			MF						Installation record	N			Installation record	N			
2146	DOROTHY LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2149	DOROTHY LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2152	DOROTHY LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2157	DOROTHY LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2160	DOROTHY LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2163	DOROTHY LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2166	DOROTHY LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2171	DOROTHY LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2172	DOROTHY LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2177	DOROTHY LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2178	DOROTHY LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2185	DOROTHY LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2186	DOROTHY LANE			C	N	1"		C	1"		SF						Installation record	N			Installation record	N			Cross-connection survey
2191	DOROTHY LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2192	DOROTHY LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2197	DOROTHY LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2198	DOROTHY LANE			C	N	1"		C	3/4"		SF						Installation record	N			Installation record	N			Cross-connection survey
2205	DOROTHY LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2206	DOROTHY LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2212	DOROTHY LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2213	DOROTHY LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2219	DOROTHY LANE			C	N	1"		C			MF						Installation record	N			Installation record	N			
2220	DOROTHY LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2080	DOVE STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2099	DOVE STREET			C	N	1"		C	3/4"		MF						Installation record	N			Field inspection only	Y			Cross-connection survey
2100	DOVE STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2109	DOVE STREET			C	N	1"		C	1/2"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2110	DOVE STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
1241	DOVER LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
1247	DOVER LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
1250	DOVER LANE			C	N	1"		C			SF						Installation record	N			Installation record	Y			
1253	DOVER LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
1260	DOVER LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
1261	DOVER LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
1266	DOVER LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1267	DOVER LANE			C	N	1"		C			SF						Installation record	N			Field inspection only	N			
1272	DOVER LANE			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey

LOCATIONAL IDENTIFIER ADDRESS	LOCATIONAL IDENTIFIER STREET NAME	LOCATIONAL IDENTIFIER UNIT OR SUITE #	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
1275	DOVER LANE			C	N	1"		C	1"		SF						Installation record	N			Installation record	Y			Cross-connection survey
1276	DOVER LANE			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
1280	DOVER LANE			C	N	1"		C			SF						Installation record	N			Installation record	Y			
1281	DOVER LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
912	DUCHATEAU AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
913	DUCHATEAU AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
917	DUCHATEAU AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
920	DUCHATEAU AVENUE			C	N	1"		C	1"		SF						Installation record	N			Installation record	N			Cross-connection survey
921	DUCHATEAU AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
924	DUCHATEAU AVENUE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
931	DUCHATEAU AVENUE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
932	DUCHATEAU AVENUE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
936	DUCHATEAU AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
937	DUCHATEAU AVENUE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
944	DUCHATEAU AVENUE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
945	DUCHATEAU AVENUE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
950	DUCHATEAU AVENUE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
951	DUCHATEAU AVENUE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
956	DUCHATEAU AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
957	DUCHATEAU AVENUE			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
964	DUCHATEAU AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
965	DUCHATEAU AVENUE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
970	DUCHATEAU AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
971	DUCHATEAU AVENUE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
976	DUCHATEAU AVENUE			C	N	1"		C	3/4"		SF						Installation record	N			Installation record	N			Cross-connection survey
979	DUCHATEAU AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
984	DUCHATEAU AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
985	DUCHATEAU AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
460	DUTTON AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
464	DUTTON AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
465	DUTTON AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
468	DUTTON AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
469	DUTTON AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
473	DUTTON AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
477	DUTTON AVENUE			C	N	1"		C			MF						Installation record	N			Installation record	N			
479	DUTTON AVENUE			C	N	1"		C	3/4"		MF						Installation record	N			Field inspection only	Y			Cross-connection survey
480	DUTTON AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
482	DUTTON AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
483	DUTTON AVENUE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
485	DUTTON AVENUE			C	N	1"		C			MF						Installation record	N			Installation record	N			
493	DUTTON AVENUE			C	N	1"		C			MF						Installation record	N			Installation record	N			
502	DUTTON AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
505	DUTTON AVENUE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
508	DUTTON AVENUE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
509	DUTTON AVENUE			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
512	DUTTON AVENUE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
513	DUTTON AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
514	DUTTON AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
516	DUTTON AVENUE			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
517	DUTTON AVENUE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
520	DUTTON AVENUE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
525	DUTTON AVENUE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
526	DUTTON AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
532	DUTTON AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
533	DUTTON AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
536	DUTTON AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
537	DUTTON AVENUE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
543	DUTTON AVENUE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1401	E MARHILL ROAD			C	N	3/4"		C			SF						Installation record	Y	1964	isp during install o	Installation record	N			
1408	E MARHILL ROAD			C	N	3/4"		C			SF						Installation record	Y	1965	isp during install o	Installation record	N			
1410	E MARHILL ROAD			C	N	3/4"		C	3/4"		SF						Installation record	Y	1964	isp during install o	Field inspection only	Y			Cross-connection survey
1411	E MARHILL ROAD			C	N	3/4"		C	3/4"		SF						Installation record	Y	1964	isp during install o	Field inspection only	Y			Cross-connection survey
1423	E MARHILL ROAD			C	N	3/4"		C			SF						Installation record	Y	1964	isp during install o	Installation record	N			
1424	E MARHILL ROAD			C	N	3/4"		C	3/4"		SF						Installation record	Y	1965	isp during install o	Installation record	N			Cross-connection survey
1434	E MARHILL ROAD			C	N	3/4"		P	1"		SF						Installation record	Y	1964	isp during install o	Field inspection only	Y			Cross-connection survey
1437	E MARHILL ROAD			C	N	3/4"		C			SF						Installation record	Y	1964	isp during install o	Installation record	N			
3573	E. Hank Av			P	N	1"		P	1"		SF						Installed after lead ban	Y	2022		Installed after lead ban	Y			Visual insp during install or repair
3576	E. Hank Av			P	N	1"		P	1"		SF						Installed after lead ban	Y	2022		Installed after lead ban	Y			Visual insp during install or repair
3579	E. Hank Av			P	N	1"		P			SF						Installed after lead ban	Y	2022		Installed after lead ban	Y			Visual insp during install or repair
3582	E. Hank Av			P	N	1"		P	1"		SF						Installed after lead ban	Y	2022		Installed after lead ban	Y			Visual insp during install or repair
3585	E. Hank Av			P	N	1"		P			SF						Installed after lead ban	Y	2022		Installed after lead ban	Y			Visual insp during install or repair
3591	E. Hank Av			P	N	1"		P	1"		SF						Installed after lead ban	Y	2022		Installed after lead ban	Y			Visual insp during install or repair
3594	E. Hank Av			P	N	1"		P	1"		SF						Installed after lead ban	Y	2022		Installed after lead ban	Y			Visual insp during install or repair
3597	E. Hank Av			P	N	1"		P	1"		SF						Installed after lead ban	Y	2022		Installed after lead ban	Y			Visual insp during install or repair
3603	E. Hank Av			P	N	1"		P			SF						Installed after lead ban	Y	2022		Installed after lead ban	Y			Visual insp during install or repair
3609	E. Hank Av			P	N	1"		P	1"		SF						Installed after lead ban	Y	2022		Installed after lead ban	Y			Visual insp during install or repair
3612	E. Hank Av			P	N	1"		P	1"		SF						Installed after lead ban	Y	2022		Installed after lead ban	Y			Visual insp during install or repair
3615	E. Hank Av			P	N	1"		P			SF						Installed after lead ban	Y	2022		Installed after lead ban	Y			Visual insp during install or repair
3627	E. Hank Av			P	N	1"		P			SF						Installed after lead ban	Y	2022		Installed after lead ban	Y			Visual insp during install or repair
3639	E. Hank Av			P	N	1"		P	1"		SF						Installed after lead ban	Y	2022		Installed after lead ban	Y			Visual insp during install or repair
2127	EARLY ST			C	N	1"		C			SF						Installation record	N			Installation record	N			
2118	EARLY STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2122	EARLY STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2126	EARLY STREET			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey



LOCATIONAL IDENTIFIER ADDRESS	LOCATIONAL IDENTIFIER STREET NAME	LOCATIONAL IDENTIFIER UNIT OR SUITE #	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
2131	EARLY STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2134	EARLY STREET			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2135	EARLY STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2139	EARLY STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2143	EARLY STREET			C	N	1"		C			MF						Installation record	N			Installation record	N			
2151	EARLY STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2152	EARLY STREET			C	N	1"		C	1"		MF						Installation record	N			Field inspection only	Y			Cross-connection survey
2153	EARLY STREET			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2155	EARLY STREET			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2156	EARLY STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2157	EARLY STREET			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2158	EARLY STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2159	EARLY STREET			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2160	EARLY STREET			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2187	EARLY STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2190	EARLY STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2198	EARLY STREET			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2200	EARLY STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2204	EARLY STREET			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2205	EARLY STREET			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2207	EARLY STREET			C	N	1"		C	1"		SF						Installation record	N			Installation record	N			Cross-connection survey
2217	Early Street			C	N	1"		P	1"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2222	EARLY STREET			UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y			Cross-connection survey
2227	EARLY STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2230	EARLY STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2231	EARLY STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2237	EARLY STREET			C	N	1"		C			MF						Installation record	N			Installation record	N			
2238	EARLY STREET			C	N	1"		C	3/4"		MF						Installation record	N			Field inspection only	Y			Cross-connection survey
2241	EARLY STREET			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2246	EARLY STREET			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2247	EARLY STREET			C	N	1"		C			MF						Installation record	N			Installation record	N			
2248	EARLY STREET			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2250	EARLY STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2255	EARLY STREET			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
1064	ECHO LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1065	ECHO LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1070	ECHO LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
1071	ECHO LANE			C	N	1"		C	3/4"		SF						Installation record	N			Installation record	N			Cross-connection survey
1077	ECHO LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1078	ECHO LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
1084	ECHO LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
1085	ECHO LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1091	ECHO LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1097	ECHO LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1105	ECHO LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1110	ECHO LANE			UNK-NOLG	N			P	2"		NONRES						Installation record	N			Field inspection only	Y			Cross-connection survey
1115	ECHO LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
1121	ECHO LANE			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
1127	ECHO LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1130	ECHO LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1135	ECHO LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
1140	ECHO LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
1154	ECHO LANE			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
1160	ECHO LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1161	ECHO LANE			C	N	1"		C			MF						Installation record	N			Installation record	N			
1166	ECHO LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1172	ECHO LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
1178	ECHO LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
1184	ECHO LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
1191	ECHO LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
1192	ECHO LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1198	ECHO LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1204	ECHO LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1210	ECHO LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
1216	ECHO LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1217	ECHO LANE			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
1237	ECHO LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1242	ECHO LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1247	ECHO LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1248	ECHO LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1253	ECHO LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1254	ECHO LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1261	ECHO LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1262	ECHO LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1267	ECHO LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1268	ECHO LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
1274	ECHO LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1280	ECHO LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1284	ECHO LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
1285	ECHO LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1289	ECHO LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1294	ECHO LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
1295	ECHO LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1302	ECHO LANE			C	N	1"		C	3/4"		MF						Installation record	N			Field inspection only	Y			Cross-connection survey
1311	ECHO LANE			UNK-NOLG	N			C	1 1/2"		MF						Installation record	N			Field inspection only	Y			Cross-connection survey

LOCAL IDENTIFIER ADDRESS	LOCAL IDENTIFIER STREET NAME	LOCATIONAL IDENTIFIER UNIT OR SUITE #	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
746	Element Way	Bldg 1		P	N	8"		P	3"		MF						Installed after lead ban		2019	isp during install o	Field inspection only	Y		Cross-connection survey	
772	Element Way	Bldg 2		P	N	8"		P	3"		MF						Installed after lead ban	Y	2019	isp during install o	Field inspection only	Y		Cross-connection survey	
798	Element Way	Bldg 3		P	N	8"		P	3"		MF						Installed after lead ban	Y	2019	isp during install o	Field inspection only	Y		Cross-connection survey	
833	Element Way			P	N	8"		P	1"		MF						Installed after lead ban	Y	2019	isp during install o	Field inspection only	Y		Cross-connection survey	
840	Element Way	Bldg 4		P	N	8"		P	4"		MF						Installed after lead ban	Y	2019	isp during install o	Field inspection only	Y		Cross-connection survey	
3641	Ella Jo Wy			P	N	1"		P	1"		SF						Installed after lead ban	Y	2022		Installed after lead ban	Y		Visual insp during install or repair	
2100	ELMVIEW DRIVE			C	N	3/4"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2101	ELMVIEW DRIVE			C	N	3/4"		C	3/4"		SF						Installation record	N			Installation record	N		Cross-connection survey	
2104	ELMVIEW DRIVE			C	N	3/4"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2110	ELMVIEW DRIVE			C	N	3/4"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2111	ELMVIEW DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2120	ELMVIEW DRIVE	I		C	N	3/4"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
2130	ELMVIEW DRIVE	A		C	N	3/4"		C	3/4"		MF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1339	EMINENCE STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
1341	EMINENCE STREET			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1350	EMINENCE STREET			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1351	EMINENCE STREET			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1354	EMINENCE STREET			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1357	EMINENCE STREET			C	N	1"		C	1"		SF						Installation record	N			Installation record	N		Cross-connection survey	
1360	EMINENCE STREET			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1363	EMINENCE STREET			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1366	EMINENCE STREET			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1369	EMINENCE STREET			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1374	EMINENCE STREET			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1377	EMINENCE STREET			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1380	EMINENCE STREET			C	N	1"		C	1"		SF						Installation record	N			Installation record	N		Cross-connection survey	
1383	EMINENCE STREET			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1386	EMINENCE STREET			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1389	EMINENCE STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
1394	EMINENCE STREET			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1395	EMINENCE STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
1398	EMINENCE STREET			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1401	EMINENCE STREET			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1404	EMINENCE STREET			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1407	EMINENCE STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
1412	EMINENCE STREET			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1415	EMINENCE STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
1418	EMINENCE STREET			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1421	EMINENCE STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
1342	EMIR STREET			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1343	EMIR STREET			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1350	EMIR STREET			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1351	EMIR STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
1356	EMIR STREET			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1357	EMIR STREET			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1362	EMIR STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
1363	EMIR STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
1368	EMIR STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
1371	EMIR STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
1374	EMIR STREET			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1377	EMIR STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
1382	EMIR STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
1383	EMIR STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
1388	EMIR STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
1391	EMIR STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
1394	EMIR STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
1397	EMIR STREET			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1402	EMIR STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
1403	EMIR STREET			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1408	EMIR STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
1409	EMIR STREET			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y		Cross-connection survey	
1414	EMIR STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
1415	EMIR STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
1420	EMIR STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
1423	EMIR STREET			C	N	1"		C			SF						Installation record	N			Installation record	N			
2701	EXECUTIVE DRIVE			P	N	6"		DI	6"		NONRES						Installation record	Y	1986	isp during install o	Field inspection only	Y		Cross-connection survey	
2710	EXECUTIVE DRIVE			P	N	6"		P	2"		NONRES						Installation record	Y	1986	isp during install o	Field inspection only	Y		Cross-connection survey	
2710	FENTON WAY			C	N	1"		C			SF						Installation record	N			Installation record	N			
2721	FENTON WAY			C	N	1"		C			SF						Installation record	N			Installation record	N			
1310	FERNANDO DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1319	FERNANDO DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1330	FERNANDO DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1333	FERNANDO DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N		</	

LOCATIONAL IDENTIFIER ADDRESS	LOCATIONAL IDENTIFIER STREET NAME	LOCATIONAL IDENTIFIER UNIT OR SUITE #	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
1450	FERNANDO DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1453	FERNANDO DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1471	FERNANDO DRIVE			C	N	1"		P	1"		SF						Installation record	N			Installation record	N			Cross-connection survey
1486	FERNANDO DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1489	FERNANDO DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1490	FERNANDO DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1501	FERNANDO DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1511	FERNANDO DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1516	FERNANDO DRIVE			P	N	6"		DI	6"		NONRES						Installed after lead ban	Y	1999		Field inspection only	Y			Cross-connection survey
1531	FERNANDO DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1610	FERNANDO DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1640	FERNANDO DRIVE			P	N	2"		P	1"		NONRES						Installed after lead ban	Y	1999		Field inspection only	Y			Cross-connection survey
1259	FINCH LANE			C	N	1"		C			SF						Installed after lead ban	Y	1987		Installed after lead ban	N			
1264	FINCH LANE			C	N	1"		C	1"		SF						Installed after lead ban	Y	1987		Installed after lead ban	N			Cross-connection survey
1265	FINCH LANE			C	N	1"		C	3/4"		SF						Installed after lead ban	Y	1987		Field inspection only	Y			Cross-connection survey
1270	FINCH LANE			C	N	1"		C			SF						Installed after lead ban	Y	1987		Installed after lead ban	N			
1271	FINCH LANE			C	N	1"		C			SF						Installed after lead ban	Y	1987		Installed after lead ban	N			
1278	FINCH LANE			C	N	1"		C			SF						Installed after lead ban	Y	1987		Installed after lead ban	N			
1279	FINCH LANE			C	N	1"		C	1"		SF						Installed after lead ban	Y	1987		Installed after lead ban	N			Cross-connection survey
1284	FINCH LANE			C	N	1"		C	1"		SF						Installed after lead ban	Y	1987		Field inspection only	Y			Cross-connection survey
1285	FINCH LANE			C	N	1"		C			SF						Installed after lead ban	Y	1987		Installed after lead ban	N			
1290	FINCH LANE			C	N	1"		C	1"		SF						Installed after lead ban	Y	1987		Installation record	Y			Visual insp during install or repair
1291	FINCH LANE			C	N	1"		C	1"		SF						Installed after lead ban	Y	1987		Field inspection only	Y			Cross-connection survey
1296	FINCH LANE			P	N	1"		C			SF						Installed after lead ban	Y	1987		Installed after lead ban	N			
1310	FINCH LANE			P	N	1"		C			SF						Installed after lead ban	Y	1987		Installed after lead ban	N			
1311	FINCH LANE			C	N	1"		C			SF						Installed after lead ban	Y	1987		Installed after lead ban	N			
1320	FINCH LANE			P	N	1"		P	1"		SF						Installed after lead ban	Y	1987		Field inspection only	Y			Cross-connection survey
1321	FINCH LANE			C	N	1"		C			SF						Installed after lead ban	Y	1987		Installed after lead ban	N			
1330	FINCH LANE			C	N	1"		C			SF						Installed after lead ban	Y	1987		Installed after lead ban	N			
1331	FINCH LANE			C	N	1"		C	1"		SF						Installed after lead ban	Y	1987		Field inspection only	Y			Cross-connection survey
1340	FINCH LANE			P	N	1"		C			SF						Installed after lead ban	Y	1987		Installed after lead ban	N			
1341	FINCH LANE			C	N	1"		C			SF						Installed after lead ban	Y	1987		Installed after lead ban	N			
1350	FINCH LANE			C	N	1"		C			SF						Installed after lead ban	Y	1987		Installed after lead ban	N			
1351	FINCH LANE			C	N	1"		C			SF						Installed after lead ban	Y	1987		Installed after lead ban	N			
1360	FINCH LANE			P	N	1"		C			SF						Installed after lead ban	Y	1987		Installed after lead ban	N			
1370	FINCH LANE			P	N	1"		C			SF						Installed after lead ban	Y	1987		Installed after lead ban	N			
1371	FINCH LANE			P	N	1"		C	1"		SF						Installed after lead ban	Y	1992		Field inspection only	Y			Cross-connection survey
1380	FINCH LANE			C	N	1"		C	1"		SF						Installed after lead ban	Y	1987		Field inspection only	Y			Cross-connection survey
1390	FINCH LANE			P	N	1"		C	1"		SF						Installed after lead ban	Y	1992		Field inspection only	Y			Cross-connection survey
1391	FINCH LANE			P	N	1"		C	1"		SF						Installed after lead ban	Y	1992		Field inspection only	Y			Cross-connection survey
1400	FINCH LANE			P	N	1"		P	3/4"		SF						Installed after lead ban	Y	1992		Field inspection only	Y			Cross-connection survey
1401	FINCH LANE			P	N	1"		C			SF						Installed after lead ban	Y	1992		Installed after lead ban	N			
1410	FINCH LANE			P	N	1"		P			SF						Installed after lead ban	Y	1992		Installed after lead ban	N			
1411	FINCH LANE			P	N	1"		C			SF						Installed after lead ban	Y	1992		Installed after lead ban	N			
1420	FINCH LANE			C	N	1"		C			SF						Installed after lead ban	Y	1987		Installed after lead ban	N			
1421	FINCH LANE			P	N	1"		P	1"		SF						Installed after lead ban	Y	1992		Field inspection only	Y			Cross-connection survey
1430	FINCH LANE			P	N	1"		P			SF						Installed after lead ban	Y	1992		Installed after lead ban	N			
1431	FINCH LANE			P	N	1"		P	1"		SF						Installed after lead ban	Y	1992		Field inspection only	Y			Cross-connection survey
1440	FINCH LANE			P	N	1"		P			SF						Installed after lead ban	Y	1992		Installed after lead ban	N			
1441	FINCH LANE			P	N	1"		C			SF						Installed after lead ban	Y	1987		Installed after lead ban	N			
1450	FINCH LANE			C	N	1"		C			SF						Installed after lead ban	Y	1987		Installed after lead ban	N			
1451	FINCH LANE			P	N	1"		P	1"		SF						Installed after lead ban	Y	1987		Field inspection only	Y			Cross-connection survey
1454	FINCH LANE			P	N	1"		P			SF						Installed after lead ban	Y	1992		Installed after lead ban	N			
1456	FINCH LANE			P	N	1"		P			SF						Installed after lead ban	Y	1992		Installed after lead ban	N			
1461	FINCH LANE			P	N	1"		C			SF						Installed after lead ban	Y	1992		Installed after lead ban	N			
1466	FINCH LANE			P	N	1"		P			SF						Installed after lead ban	Y	1992		Installed after lead ban	N			
1469	FINCH LANE			C	N	1"		C			SF						Installed after lead ban	Y	1987		Installed after lead ban	N			
1470	FINCH LANE			P	N	1"		C			SF						Installed after lead ban	Y	1992		Installed after lead ban	N			
1474	FINCH LANE			P	N	1"		P	1"		SF						Installed after lead ban	Y	1992		Field inspection only	Y			Cross-connection survey
2205	FOX HEIGHTS LANE			UNK-NOLG	N			C	1"		NONRES						Installation record	N	1966		Field inspection only	Y			Cross-connection survey
2229	FOX HEIGHTS LANE			UNK-NOLG	N			C	1"		NONRES						Installation record	N	1966		Field inspection only	Y			Cross-connection survey
2244	FOX HEIGHTS LANE	Ste 101		C	N	1"		C	3/4"		SF						Installation record	N			Installation record	N			Cross-connection survey
2247	FOX HEIGHTS LANE	A		C	N	2"		C	1"		NONRES						Installation record	N	1966		Field inspection only	Y			Cross-connection survey
2250	FOX HEIGHTS LANE			UNK-NOLG	N			C	1"		NONRES						Installation record	N	1966		Field inspection only	Y			Cross-connection survey
2252	FOX HEIGHTS LANE			C	N	1"		C	1"		NONRES						Installation record	Y	1966	isp during install o	Field inspection only	Y			Cross-connection survey
2255	FOX HEIGHTS LANE			UNK-NOLG	N			P	4"		NONRES						Installation record	N	1966		Field inspection only	Y			Cross-connection survey
2263	FOX HEIGHTS LANE			C	N	1"		C	1"		NONRES						Installation record	Y	1966	isp during install o	Field inspection only	Y			Cross-connection survey
2269	FOX HEIGHTS LANE			UNK-NOLG	N			C	1"		NONRES						Installation record	N	1966		Field inspection only	Y			Cross-connection survey
2271	FOX HEIGHTS LANE			UNK-NOLG	N			C	1"		NONRES						Installation record	N	1966		Field inspection only	Y			Cross-connection survey
2870	FOXFORD COURT			P	N	1"		P			SF						Installed after lead ban	Y	1994		Installed after lead ban	N			
2875	FOXFORD COURT			P	N	1"		P			SF						Installed after lead ban	Y	1994		Installed after lead ban	N			
2876	FOXFORD COURT			P	N	1"		P			SF						Installed after lead ban	Y	1994		Installed after lead ban	N			
2877	FOXFORD COURT			P	N	1"		P			SF						Installed after lead ban	Y	1994		Installed after lead ban	N			
2879	FOXFORD COURT			P	N	1"		P			SF						Installed after lead ban	Y	1994		Installed after lead ban	N			
2880	FOXFORD COURT			P	N	1"		P	1"		SF						Installed after lead ban	Y	1994		Field inspection only	Y			Cross-connection survey
2881	FOXFORD COURT			P	N	1"		P			SF						Installed after lead ban	Y	1994		Installed after lead ban	N			
2885	FOXFORD COURT			P	N	1"		P			SF						Installed after lead ban	Y	1994		Installed after lead ban	N			
2890	FOXFORD COURT			P	N	1"		P			SF						Installed after lead ban	Y	1994		Installed after lead ban	N			
2895	FOXFORD COURT			P	N	1"		P			SF						Installed after lead ban	Y	1994		Installed after lead ban	N			
2920	FOXFORD DRIVE			P	N	1"		P	1"		SF						Installed after lead ban	Y	1994		Field inspection only	Y			Cross-connection survey
2925	FOXFORD DRIVE			P	N	1"		P			SF						Installed after lead ban	Y	1994		Installed after lead ban	N			
2930	FOXFORD DRIVE			P	N	1"		P			SF						Installed after lead ban	Y	1994		Installed after lead ban	N			
2936	FOXFORD DRIVE																								

LOCATIONAL IDENTIFIER ADDRESS	LOCATIONAL IDENTIFIER STREET NAME	LOCATIONAL IDENTIFIER UNIT OR SUITE #	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
2950	FOXFORD DRIVE			P	N	1"		P			SF						Installed after lead ban	Y	1994		Installed after lead ban	N			
2959	FOXFORD DRIVE			P	N	1"		P			SF						Installed after lead ban	Y	1994		Installed after lead ban	N			
2960	FOXFORD DRIVE			P	N	1"		P			SF						Installed after lead ban	Y	1994		Installed after lead ban	N			
2970	FOXFORD DRIVE			P	N	1"		P			SF						Installed after lead ban	Y	1994		Installed after lead ban	N			
1218	GERHARDT LANE			C	N	1"		C	1"		SF						Installation record	N	1980		Field inspection only	Y			Cross-connection survey
1219	GERHARDT LANE			C	N	1"		C			SF						Installation record	N	1980		Installation record	N			
1223	GERHARDT LANE			C	N	1"		C			SF						Installation record	N	1980		Installation record	N			
1230	GERHARDT LANE			C	N	1"		C			SF						Installation record	N	1980		Installation record	N			
1231	GERHARDT LANE			C	N	1"		C	3/4"		SF						Installation record	N	1980		Field inspection only	Y			Cross-connection survey
1239	GERHARDT LANE			C	N	1"		C			SF						Installation record	N	1980		Installation record	N			
1242	GERHARDT LANE			C	N	1"		C			SF						Installation record	N	1980		Installation record	N			
1247	GERHARDT LANE			C	N	1"		C			SF						Installation record	N	1980		Installation record	N			
1255	GERHARDT LANE			C	N	1"		C			SF						Installation record	N	1980		Installation record	N			
1258	GERHARDT LANE			C	N	1"		C	3/4"		SF						Installation record	N	1980		Field inspection only	Y			Cross-connection survey
1261	GERHARDT LANE			C	N	1"		C	3/4"		SF						Installation record	N	1980		Field inspection only	Y			Cross-connection survey
1268	GERHARDT LANE			C	N	1"		C			SF						Installation record	N	1980		Installation record	N			
1269	GERHARDT LANE			C	N	1"		C	1"		SF						Installation record	N	1980		Field inspection only	Y			Cross-connection survey
1275	GERHARDT LANE			C	N	1"		C	1"		SF						Installation record	N	1980		Field inspection only	Y			Cross-connection survey
1277	GERHARDT LANE			C	N	1"		P	1"		SF						Installation record	N	1980		Field inspection only	Y			Cross-connection survey
2112	GILSON COURT			C	N	1 1/2"		C			SF						Installation record	N			Installation record	N			
2124	GILSON COURT			C	N	1 1/2"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2130	GILSON COURT			C	N	1 1/2"		C	1"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2138	GILSON COURT			C	N	1 1/2"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2146	GILSON COURT			C	N	1 1/2"		C			SF						Installation record	N			Installation record	N			
2153	GILSON COURT			C	N	1 1/2"		C			SF						Installation record	N			Installation record	N			
2161	GILSON COURT			C	N	1 1/2"		C	3/4"		SF						Installation record	N			Installation record	N			Cross-connection survey
2169	GILSON COURT			C	N	1 1/2"		C			SF						Installation record	N			Installation record	N			
2175	GILSON COURT			C	N	1 1/2"		C			SF						Installation record	N			Installation record	N			
2183	GILSON COURT			C	N	1 1/2"		C	1"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2189	GILSON COURT			C	N	1 1/2"		C			SF						Installation record	N			Installation record	N			
2195	GILSON COURT			C	N	1 1/2"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2203	GILSON COURT			C	N	1 1/2"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2217	GILSON COURT			C	N	1 1/2"		C			SF						Installation record	N			Installation record	N			
1332	GLEN ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1333	GLEN ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1340	GLEN ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1343	GLEN ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1346	GLEN ROAD			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
1352	GLEN ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1360	GLEN ROAD			C	N	1"		C	3/4"		SF						Installation record	N			Installation record	N			Cross-connection survey
1366	GLEN ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1367	GLEN ROAD			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
1372	GLEN ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1373	GLEN ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1378	GLEN ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1381	GLEN ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1386	GLEN ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1387	GLEN ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1414	GLEN ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1415	GLEN ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1420	GLEN ROAD			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
1421	GLEN ROAD			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
1428	GLEN ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1429	GLEN ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1434	GLEN ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1435	GLEN ROAD			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
1440	GLEN ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1441	GLEN ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1446	GLEN ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1447	GLEN ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1452	GLEN ROAD			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
1453	GLEN ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1478	GLEN ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1479	GLEN ROAD			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
1484	GLEN ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1485	GLEN ROAD			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
1492	GLEN ROAD			C	N	1"		C	3/4"		SF						Installation record	N			Installation record	N			Cross-connection survey
1493	GLEN ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1498	GLEN ROAD			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
1499	GLEN ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1504	GLEN ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1505	GLEN ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1510	GLEN ROAD			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
1511	GLEN ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1516	GLEN ROAD			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
1517	GLEN ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1523	GLEN ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1524	GLEN ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1530	GLEN ROAD			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
1531	GLEN ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1538	GLEN ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1539	GLEN ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1560	GLEN ROAD			C	N	1"		C	3/4"		SF						Installation record	N			Installation record	N			Cross-connection survey
1566	GLEN ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1571	GLEN ROAD			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey

LOCATIONAL IDENTIFIER ADDRESS	LOCATIONAL IDENTIFIER STREET NAME	LOCATIONAL IDENTIFIER UNIT OR SUITE #	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION	
1572	GLEN ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N				
1578	GLEN ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N				
1579	GLEN ROAD			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey	
1584	GLEN ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N				
1587	GLEN ROAD			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey	
1592	GLEN ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N				
1595	GLEN ROAD			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey	
1601	GLEN ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N				
1611	GLEN ROAD			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey	
1616	GLEN ROAD			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey	
1617	GLEN ROAD			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey	
1622	GLEN ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N				
1625	GLEN ROAD			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey	
1630	GLEN ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N				
1633	GLEN ROAD			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey	
1638	GLEN ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N				
1641	GLEN ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N				
1644	GLEN ROAD			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey	
1649	GLEN ROAD			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey	
1657	GLEN ROAD			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey	
1665	GLEN ROAD			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey	
486	GLOBE AVENUE			P	N			DI	6"		NONRES						Diameter > 2 inches	Y			Field inspection only	Y			Cross-connection survey	
516	GLOBE AVENUE			P	N			DI	4"		NONRES						Diameter > 2 inches	Y			Field inspection only	Y			Cross-connection survey	
750	GLORY ROAD			C	N	1"		C			SF						Installed after lead ban	Y	1986		Installation record	N				
765	GLORY ROAD			C	N	1"		C			SF						Installed after lead ban	Y	1986		Installation record	N				
775	GLORY ROAD			C	N	1"		C			SF						Installed after lead ban	Y	1986		Installation record	N				
778	GLORY ROAD			C	N	1"		C	3/4"		SF						Installed after lead ban	Y	1986		Field inspection only	Y			Cross-connection survey	
784	GLORY ROAD			C	N	1"		C			SF						Installed after lead ban	Y	1986		Installation record	N				
790	GLORY ROAD			C	N	1"		C			SF						Installed after lead ban	Y	1986		Installation record	N				
796	GLORY ROAD			C	N	1"		C			SF						Installed after lead ban	Y	1986		Installation record	N				
802	GLORY ROAD			C	N	1"		C			SF						Installed after lead ban	Y	1986		Installation record	N				
814	GLORY ROAD			C	N	1"		C			SF						Installed after lead ban	Y	1986		Installation record	N				
820	GLORY ROAD			C	N	1"		C			SF						Installed after lead ban	Y	1986		Installation record	N				
855	GLORY ROAD			UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y			Cross-connection survey	
911	GLORY ROAD			UNK-NOLG	N			C	1"		NONRES						Installation record	N		1973		Field inspection only	Y			Cross-connection survey
937	GLORY ROAD			C	N	1"		C			SF						Installed after lead ban	Y	1986		Installation record	N				
954	GLORY ROAD	A		UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y			Cross-connection survey	
975	GLORY ROAD			P	N			P	1 1/2"		NONRES						Installation record	Y			Field inspection only	Y			Cross-connection survey	
976	GLORY ROAD			UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y			Cross-connection survey	
998	GLORY ROAD			UNK-NOLG	N			C	3/4"		NONRES						Installation record	N			Field inspection only	Y			Cross-connection survey	
999	GLORY ROAD			P	N			P	1 1/2"		NONRES						Installation record	Y			Field inspection only	Y			Cross-connection survey	
1020	GLORY ROAD			UNK-NOLG	N			P	1"		NONRES						Installation record	N			Field inspection only	Y			Cross-connection survey	
1048	GLORY ROAD	A		UNK-NOLG	N			P	1"		NONRES						Installation record	N			Field inspection only	Y			Cross-connection survey	
1050	GLORY ROAD	A		UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y			Cross-connection survey	
1055	GLORY ROAD			C	N	1"		C	3/4"		SF						Installed after lead ban	Y	1986		Field inspection only	Y			Cross-connection survey	
1140	GLORY ROAD			UNK-NOLG	N			P	2"		NONRES						Installation record	N			Field inspection only	Y			Cross-connection survey	
1150	GLORY ROAD			UNK-NOLG	N			P	1"		NONRES						Installation record	N			Field inspection only	Y			Cross-connection survey	
1163	GLORY ROAD			UNK-NOLG	N			DI	3"		NONRES						Diameter > 2 inches	Y			Field inspection only	Y			Cross-connection survey	
1221	GLORY ROAD			UNK-NOLG	N			P	2"		NONRES						Installation record	N			Field inspection only	Y			Cross-connection survey	
1250	GLORY ROAD			P	N			DI	8"		NONRES						Diameter > 2 inches	Y			Field inspection only	Y			Cross-connection survey	
1275	GLORY ROAD			UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y			Cross-connection survey	
1327	GLORY ROAD			P	N			C	3"		NONRES						Diameter > 2 inches	Y			Field inspection only	Y			Cross-connection survey	
1330	GLORY ROAD			P	N			DI	8"		NONRES						Diameter > 2 inches	Y			Field inspection only	Y			Cross-connection survey	
1361	GLORY ROAD			UNK-NOLG	N			C	1"		NONRES						Installed after lead ban	N		1991		Field inspection only	Y			Cross-connection survey
1370	GLORY ROAD			UNK-NOLG	N			C	1"		NONRES						Installed after lead ban	N		1991		Field inspection only	Y			Cross-connection survey
1515	GLORY ROAD	101		UNK-NOLG	N			P	2"		NONRES						Installed after lead ban	N		1991		Field inspection only	Y			Cross-connection survey
1555	GLORY ROAD			UNK-NOLG	N			C	1"		NONRES						Installed after lead ban	N		1991		Field inspection only	Y			Cross-connection survey
1620	GRANT STREET			C	N	1"		C			SF						Installation record	N			Installation record	N				
2024	GRANT STREET			C	N	1"		C			SF						Installation record	N			Installation record	N				
1043	GRIFFITHS LANE			UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y			Cross-connection survey	
1055	GRIFFITHS LANE			C	N	1 1/2"		C	1 1/2"		SCH/CC						Installation record	Y			Field inspection only	Y			Cross-connection survey	
1080	GRIFFITHS LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey	
1083	GRIFFITHS LANE			C	N	1"		C			SF						Installation record	N			Installation record	N				
600	HANSEN ROAD			UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y			Cross-connection survey	
611	HANSEN ROAD			UNK-NOLG	N			C	2"		NONRES						Installation record	N			Field inspection only	Y			Cross-connection survey	
734	HANSEN ROAD	FRONT		UNK-NOLG	N			C	1 1/2"		NONRES						Installation record	N			Field inspection only	Y			Cross-connection survey	
750	HANSEN ROAD			UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y			Cross-connection survey	
790	HANSEN ROAD	A		P	N	8"		P	2"		NONRES						Installation record	Y	2015	isp during install o	Field inspection only	Y			Cross-connection survey	
800	HANSEN ROAD			UNK-NOLG	N			C	2"		NONRES						Installation record	N			Field inspection only	Y			Cross-connection survey	
850	HANSEN ROAD			UNK-NOLG	N			P	1"		NONRES						Installation record	N			Field inspection only	Y			Cross-connection survey	
855	HANSEN ROAD			UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y			Cross-connection survey	
858	HANSEN ROAD			UNK-NOLG	N			P	4"		NONRES						Installation record	N			Field inspection only	Y			Cross-connection survey	
862	HANSEN ROAD			UNK-NOLG	N			P	2"		NONRES						Installation record	N			Field inspection only	Y			Cross-connection survey	
871	HANSEN ROAD			UNK-NOLG	N			P	1"		NONRES						Installation record	N			Field inspection only	Y			Cross-connection survey	
900	HANSEN ROAD			UNK-NOLG	N			C	2"		NONRES						Installation record	N			Field inspection only	Y			Cross-connection survey	
901	HANSEN ROAD			UNK-NOLG	N			C	2"		NONRES						Installation record	N			Field inspection only	Y			Cross-connection survey	
906	HANSEN ROAD			UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y			Cross-connection survey	
909	HANSEN ROAD			UNK-NOLG	N			C	2"		NONRES						Installation record	N			Field inspection only	Y			Cross-connection survey	
940	HANSEN ROAD	A		P	N	8"		C	2"		NONRES						Installation record	Y		Visual insp during install o	Field inspection only	Y			Cross-connection survey	
960	HANSEN ROAD			UNK-NOLG	N			P	1"		NONRES						Installation record	N			Field inspection only	Y			Cross-connection survey	
975	HANSEN ROAD			UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y			Cross-connection survey	
1060	HANSEN ROAD			UNK-NOLG	N			C	2"		NONRES						Installation record	N			Field inspection only	Y			Cross-connection survey	
1181	HANSEN ROAD			UNK-NOLG	N			P	3"		NONRES						Installation record	N			Field inspection only	Y			Cross-connection survey	
1192	HANSEN ROAD	100		UNK-NOLG																						

LOCATIONAL IDENTIFIER ADDRESS	LOCATIONAL IDENTIFIER STREET NAME	LOCATIONAL IDENTIFIER UNIT OR SUITE #	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
2654	HARMONY DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2655	HARMONY DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2671	HARMONY DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2674	HARMONY DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2677	HARMONY DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2680	HARMONY DRIVE			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2683	HARMONY DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2688	HARMONY DRIVE			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2691	HARMONY DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2701	HARMONY DRIVE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
1124	HAWTHORN ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1125	HAWTHORN ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1132	HAWTHORN ROAD			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
1133	HAWTHORN ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1138	HAWTHORN ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1139	HAWTHORN ROAD			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
1144	HAWTHORN ROAD			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
1150	HAWTHORN ROAD			C	N	1"		C			SF						Installation record	N			Installation record	N			
1300	HIAWATHA CIRCLE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1310	HIAWATHA CIRCLE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1315	HIAWATHA CIRCLE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1331	HIAWATHA CIRCLE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1345	HIAWATHA CIRCLE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1351	HIAWATHA CIRCLE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1352	HIAWATHA CIRCLE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1365	HIAWATHA CIRCLE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1374	HIAWATHA CIRCLE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	N			Cross-connection survey
1375	HIAWATHA CIRCLE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1320	Highland Ridge Dr			P	N	1"		P			SF						Installed after lead ban	Y	2022		Installed after lead ban	Y			Visual insp during install or repair
1345	Highland Ridge Dr			P	N	1"		P	1"		SF						Installed after lead ban	Y	2022		Installed after lead ban	Y			Visual insp during install or repair
1350	Highland Ridge Dr			P	N	1"		P			SF						Installed after lead ban	Y	2022		Installed after lead ban	Y			Visual insp during install or repair
2013	HILLTOP DRIVE			C	N	1"		C	1"		MF						Installation record	N			Field inspection only	Y			Cross-connection survey
2019	HILLTOP DRIVE			C	N	1"		C			MF						Installation record	N			Installation record	N			
2020	HILLTOP DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2027	HILLTOP DRIVE			C	N	1"		C	1"		MF						Installation record	N			Field inspection only	Y			Cross-connection survey
2030	HILLTOP DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2033	HILLTOP DRIVE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2038	HILLTOP DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2041	HILLTOP DRIVE			C	N	1"		C			MF						Installation record	N			Installation record	N			
2044	HILLTOP DRIVE			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2050	HILLTOP DRIVE			C	N	1"		C	1"		SF						Installation record	N			Installation record	N			Cross-connection survey
2051	HILLTOP DRIVE			C	N	2"		C	1"		MF						Installation record	N			Field inspection only	Y			Cross-connection survey
2058	HILLTOP DRIVE			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2061	HILLTOP DRIVE			C	N	2"		C	1"		MF						Installation record	N			Field inspection only	Y			Cross-connection survey
2066	HILLTOP DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2071	HILLTOP DRIVE			C	N	2"		P	1 1/2"		MF						Installation record	N			Field inspection only	Y			Cross-connection survey
2072	HILLTOP DRIVE			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2089	HILLTOP DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2090	HILLTOP DRIVE			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2093	HILLTOP DRIVE			C	N	1"		C	3/4"		MF						Installation record	N			Field inspection only	Y			Cross-connection survey
2094	HILLTOP DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2100	HILLTOP DRIVE			C	N	1"		P	1"		SF						Installation record	N			Installation record	N			Cross-connection survey
2101	HILLTOP DRIVE			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2109	HILLTOP DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2116	HILLTOP DRIVE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2119	HILLTOP DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2143	HILLTOP DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2146	HILLTOP DRIVE			C	N	1"		C	1"		SF						Installation record	N			Installation record	N			Cross-connection survey
2151	HILLTOP DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2152	HILLTOP DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2159	HILLTOP DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2160	HILLTOP DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2167	HILLTOP DRIVE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2170	HILLTOP DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2173	HILLTOP DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2174	HILLTOP DRIVE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2181	HILLTOP DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2182	HILLTOP DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2190	HILLTOP DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2191	HILLTOP DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2198	HILLTOP DRIVE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2204	HILLTOP DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2209	HILLTOP DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2210	HILLTOP DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2217	HILLTOP DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2218	HILLTOP DRIVE			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2224	HILLTOP DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2230	HILLTOP DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2235	HILLTOP DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2236	HILLTOP DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2242	HILLTOP DRIVE			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2245	HILLTOP DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2250	HILLTOP DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2256	HILLTOP DRIVE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2262	HILLTOP DRIVE			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey

LOCATIONAL IDENTIFIER ADDRESS	LOCATIONAL IDENTIFIER STREET NAME	LOCATIONAL IDENTIFIER UNIT OR SUITE #	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
2268	HILLTOP DRIVE			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2269	HILLTOP DRIVE			C	N	1"		C	1"		SF						Installation record	N			Installation record	N			
2271	HILLTOP DRIVE			C	N	1"		C	1"		SF						Installation record	N			Installation record	N			
2272	HILLTOP DRIVE			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2299	HOCK STREET			C	N	1"		C	1"		SF						Installation record	N			Installation record	N			
2300	HOCK STREET			C	N	1"		C	1"		SF						Installation record	N			Installation record	N			
2305	HOCK STREET			C	N	1"		C	1"		SF						Installation record	N			Installation record	N			
2306	HOCK STREET			C	N	1"		C	1"		SF						Installation record	N	1980		Field inspection only	Y			Cross-connection survey
2311	HOCK STREET			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2317	HOCK STREET			C	N	1"		C	1"		SF						Installation record	N			Installation record	N			
2324	HOCK STREET			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2325	HOCK STREET			C	N	1"		C	1"		SF						Installation record	N			Installation record	N			
2331	HOCK STREET			C	N	1"		C	1"		SF						Installation record	N			Installation record	N			
2332	HOCK STREET			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2337	HOCK STREET			C	N	1"		C	1"		SF						Installation record	N			Installation record	N			
2343	HOCK STREET			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2345	HOCK STREET			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2153	Holmgren Way			P	N			DI	6"		NONRES						Diameter > 2 inches	Y			Field inspection only	Y			Cross-connection survey
1919	HOLMGREN WAY			UNK-NOLG	N			C	1"		NONRES						Installed after lead ban	Y	1998		Field inspection only	Y			Cross-connection survey
1929	HOLMGREN WAY			UNK-NOLG	N			C	1"		NONRES						Installed after lead ban	Y	1998		Field inspection only	Y			Cross-connection survey
1931	HOLMGREN WAY			UNK-NOLG	N			C	1"		NONRES						Installed after lead ban	Y	1998		Field inspection only	Y			Cross-connection survey
1941	HOLMGREN WAY			UNK-NOLG	N			C	3/4"		NONRES						Installed after lead ban	Y	1998		Field inspection only	Y			Cross-connection survey
1963	HOLMGREN WAY			P	N			P	1 1/2"		NONRES						Installed after lead ban	Y	1998		Field inspection only	Y			Cross-connection survey
1978	HOLMGREN WAY			P	N			P	3"		NONRES						Installed after lead ban	Y	1998		Field inspection only	Y			Cross-connection survey
1992	HOLMGREN WAY			P	N			P	2"		NONRES						Installed after lead ban	Y	1998		Field inspection only	Y			Cross-connection survey
2041	HOLMGREN WAY			P	N			C	2"		NONRES						Installed after lead ban	Y	1998		Field inspection only	Y			Cross-connection survey
2042	HOLMGREN WAY			P	N			P	1"		NONRES						Installed after lead ban	Y	1998		Field inspection only	Y			Cross-connection survey
2052	HOLMGREN WAY			P	N			C	1"		NONRES						Installed after lead ban	Y	1998		Field inspection only	Y			Cross-connection survey
2067	HOLMGREN WAY			P	N	2"		C	1"		NONRES						Installation record	Y			Field inspection only	Y			Cross-connection survey
2070	HOLMGREN WAY			UNK-NOLG	N			P	2"		NONRES						Installed after lead ban	Y	1998		Field inspection only	Y			Cross-connection survey
2080	HOLMGREN WAY			UNK-NOLG	N			C	1"		NONRES						Installed after lead ban	Y	1998		Field inspection only	Y			Cross-connection survey
2083	HOLMGREN WAY			P	N			P	1"		NONRES						Installed after lead ban	Y	1998		Field inspection only	Y			Cross-connection survey
2100	HOLMGREN WAY			P	N			P	2"		MF						Installed after lead ban	Y	1998		Field inspection only	Y			Cross-connection survey
2132	HOLMGREN WAY			P	N			P	3"		MF						Installed after lead ban	Y	1998		Field inspection only	Y			Cross-connection survey
2140	HOLMGREN WAY			P	N			P	2"		NONRES						Installed after lead ban	Y	1998		Field inspection only	Y			Cross-connection survey
2150	HOLMGREN WAY			P	N			C	1"		NONRES						Installed after lead ban	Y	1998		Field inspection only	Y			Cross-connection survey
2155	Holmgren Way			P	N			P	3"		NONRES						Diameter > 2 inches	Y			Field inspection only	Y			Cross-connection survey
2160	HOLMGREN WAY			P	N	2"		P	1 1/4"		NONRES						Installation record	Y			Field inspection only	Y			Cross-connection survey
2200	HOLMGREN WAY			P	N	2"		C	1"		NONRES						Installation record	Y			Field inspection only	Y			Cross-connection survey
2220	HOLMGREN WAY			P	N			P	2"		NONRES						Installed after lead ban	Y	1998		Field inspection only	Y			Cross-connection survey
2231	Holmgren Way			P	N			P	2"		NONRES						Diameter > 2 inches	Y			Field inspection only	Y			Cross-connection survey
2240	HOLMGREN WAY			UNK-NOLG	N			C	1"		NONRES						Installed after lead ban	Y	1998		Field inspection only	Y			Cross-connection survey
2250	HOLMGREN WAY			P	N			P	1"		NONRES						Installed after lead ban	Y	1998		Field inspection only	Y			Cross-connection survey
2270	HOLMGREN WAY	A		P	N	2"		P	1"		NONRES						Installed after lead ban	Y	2018	isp during install o	Field inspection only	Y			Cross-connection survey
2280	HOLMGREN WAY			UNK-NOLG	N			C	1 1/2"		NONRES						Installed after lead ban	Y	1998		Field inspection only	Y			Cross-connection survey
2301	HOLMGREN WAY	A		P	N	2"		C	1"		NONRES						Installed after lead ban	Y	1999		Field inspection only	Y			Cross-connection survey
2325	HOLMGREN WAY	110		P	N			C	1"		NONRES						Installed after lead ban	Y	1998		Field inspection only	Y			Cross-connection survey
2351	HOLMGREN WAY			UNK-NOLG	N			C	1"		NONRES						Installed after lead ban	Y	1998		Field inspection only	Y			Cross-connection survey
2363	HOLMGREN WAY	B		UNK-NOLG	N			C	1"		NONRES						Installed after lead ban	Y	1998		Field inspection only	Y			Cross-connection survey
2385	HOLMGREN WAY	101		UNK-NOLG	N			P	2"		NONRES						Installed after lead ban	Y	1998		Field inspection only	Y			Cross-connection survey
2391	HOLMGREN WAY	A & B		P	N			P & C	2"		NONRES						Installed after lead ban	Y	1998		Field inspection only	Y			Cross-connection survey
2401	HOLMGREN WAY			UNK-NOLG	N			C	1"		NONRES						Installed after lead ban	Y	1998		Field inspection only	Y			Cross-connection survey
2411	HOLMGREN WAY			P	N			P	2"		NONRES						Installed after lead ban	Y	1998		Field inspection only	Y			Cross-connection survey
2441	HOLMGREN WAY			P	N			P	1"		NONRES						Installed after lead ban	Y	1998		Field inspection only	Y			Cross-connection survey
2461	HOLMGREN WAY			UNK-NOLG	N	8"		DI	8"		NONRES						Installed after lead ban	Y	2015	isp during install o	Field inspection only	Y			Cross-connection survey
2590	HOLMGREN WAY			P	N			P	2"		NONRES						Installation record	N			Field inspection only	Y			Cross-connection survey
2600	HOLMGREN WAY	101		P	N			C	1"		NONRES						Installation record	N			Field inspection only	Y			Cross-connection survey
2610	HOLMGREN WAY	110		P	N			C	1"		NONRES						Installation record	N			Field inspection only	Y			Cross-connection survey
2611	HOLMGREN WAY			P	N			C	2"		NONRES						Installed after lead ban	Y	1998		Field inspection only	Y			Cross-connection survey
2666	HOLMGREN WAY			UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y			Cross-connection survey
2689	HOLMGREN WAY			P	N			C	1"		NONRES						Installed after lead ban	Y	1998		Field inspection only	Y			Cross-connection survey
2707	HOLMGREN WAY			UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y			Cross-connection survey
2775	HOLMGREN WAY			UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y			Cross-connection survey
2799	HOLMGREN WAY			C	N			P	1"		NONRES						Installation record	Y			Field inspection only	Y			Cross-connection survey
2870	HOLMGREN WAY			P	N			C	1"		NONRES						Installed after lead ban	Y	1998		Field inspection only	Y			Cross-connection survey
2929	HOLMGREN WAY			C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y			Cross-connection survey
2930	HOLMGREN WAY			UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y			Cross-connection survey
2944	HOLMGREN WAY			UNK-NOLG	N			C	1"		NONRES						Installation record	N			Field inspection only	Y			Cross-connection survey
2954	HOLMGREN WAY	1		P	N	2"		C	1"		NONRES						Installation record	Y			Field inspection only	Y			Cross-connection survey
2981	HOLMGREN WAY			P	N	8"		P	2"		MF						Installation record	Y			Field inspection only	Y			Cross-connection survey
2983	HOLMGREN WAY			P	N	8"		P	2"		MF						Installation record	Y			Field inspection only	Y			Cross-connection survey
2984	HOLMGREN WAY	1		P	N	2"		C	1"		NONRES						Installation record	Y			Field inspection only	Y			Cross-connection survey
2985	HOLMGREN WAY			P	N	8"		P	2"		MF						Installation record	Y			Field inspection only	Y			Cross-connection survey
2987	HOLMGREN WAY			P	N	8"		P	3"		MF						Installation record	Y			Field inspection only	Y			Cross-connection survey
2989	HOLMGREN WAY			P	N	8"		P	2"		MF						Installation record	Y			Field inspection only	Y			Cross-connection survey
2991	HOLMGREN WAY			P	N	8"		P	2"		MF						Installation record	Y			Field inspection only	Y			Cross-connection survey
2993	HOLMGREN WAY			P	N	8"		P	2"		MF						Installation record	Y			Field inspection only	Y			Cross-connection survey
2995	HOLMGREN WAY			P	N	8"		P	1"		MF						Installation record	Y			Field inspection only	Y			Cross-connection survey
3014	HOLMGREN WAY			UNK-NOLG	N			C	1"		NONRES						Installed after lead ban	Y	1998		Field inspection only	Y			Cross-connection survey
3019	HOLMGREN WAY			P	N	2"		C	1"		NONRES						Installation record	Y			Field inspection only	Y			Cross-connection survey
3021	HOLMGREN WAY			P	N	2"		C	1"		NONRES						Installation record	Y			Field inspection only	Y			Cross-connection survey
3030	HOLMGREN WAY	A		P	N	8"																			

LOCATIONAL IDENTIFIER ADDRESS	LOCATIONAL IDENTIFIER STREET NAME	LOCATIONAL IDENTIFIER UNIT OR SUITE #	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
3100	HOLMGREN WAY			P	N			C	1"			NONRES				Installed after lead ban			1998		Field inspection only	Y			Cross-connection survey
3101	HOLMGREN WAY	A		P	N			P	2"			NONRES				Installation record	N				Field inspection only	Y			Cross-connection survey
3120	HOLMGREN WAY			P	N			C	1"			NONRES				Installed after lead ban	Y		1998		Field inspection only	Y			Cross-connection survey
3121	HOLMGREN WAY			P	N			C	1"			NONRES				Installed after lead ban	Y		1998		Field inspection only	Y			Cross-connection survey
3134	HOLMGREN WAY			P	N			C	1"			NONRES				Installation record	N				Field inspection only	Y			Cross-connection survey
3135	HOLMGREN WAY			P	N			C	1"			NONRES				Installed after lead ban	Y		1998		Field inspection only	Y			Cross-connection survey
3154	HOLMGREN WAY			P	N			P	2"			NONRES				Installed after lead ban	Y		1998		Field inspection only	Y			Cross-connection survey
3161	HOLMGREN WAY			P	N			C	1"			NONRES				Installed after lead ban	Y		1998		Field inspection only	Y			Cross-connection survey
3171	HOLMGREN WAY			P	N			C	1"			NONRES				Installed after lead ban	Y		1998		Field inspection only	Y			Cross-connection survey
3176	HOLMGREN WAY			P	N			C	1"			NONRES				Installed after lead ban	Y		1998		Field inspection only	Y			Cross-connection survey
3185	HOLMGREN WAY			P	N			C	1 1/2"			NONRES				Installed after lead ban	Y		1998		Field inspection only	Y			Cross-connection survey
3190	HOLMGREN WAY			P	N	2"		P	1"			NONRES				Installation record	Y				Field inspection only	Y			Cross-connection survey
3206	HOLMGREN WAY			P	N	2"		C	1"			NONRES				Installation record	Y				Field inspection only	Y			Cross-connection survey
3211	HOLMGREN WAY			P	N			C	1"			NONRES				Installed after lead ban	Y		1998		Field inspection only	Y			Cross-connection survey
740	INDUSTRY COURT			P	N	2"		P	2"			NONRES				Installation record	Y				Field inspection only	Y			Cross-connection survey
2625	INDUSTRY COURT			P	N	2"		P	2"			NONRES				Installation record	Y				Field inspection only	Y			Cross-connection survey
2661	INDUSTRY COURT			P	N	2"		P	1"			NONRES				Installation record	Y				Field inspection only	Y			Cross-connection survey
2666	INDUSTRY COURT			P	N	2"		P	2"			NONRES				Installation record	Y				Field inspection only	Y			Cross-connection survey
2669	INDUSTRY COURT			P	N	6"		DI	4"			NONRES				Installation record	Y				Field inspection only	Y			Cross-connection survey
2385	INGOLD COURT			C	N	1"		C				SF				Installation record	N		1980		Installation record	N			
2391	INGOLD COURT			C	N	1"		C	3/4"			SF				Installation record	N		1980		Field inspection only	Y			Cross-connection survey
2395	INGOLD COURT			C	N	1"		C	1"			SF				Installation record	N		1980		Installation record	N			Cross-connection survey
2400	INGOLD COURT			C	N	1"		C				SF				Installation record	N		1980		Installation record	N			
2401	INGOLD COURT			C	N	1"		C	1"			SF				Installation record	N		1980		Field inspection only	Y			Cross-connection survey
2406	INGOLD COURT			C	N	1"		C	1"			SF				Installation record	N		1980		Field inspection only	Y			Cross-connection survey
2407	INGOLD COURT			C	N	1"		C				SF				Installation record	N		1980		Installation record	N			
2413	INGOLD COURT			C	N	1"		C	3/4"			SF				Installation record	N		1980		Field inspection only	Y			Cross-connection survey
2416	INGOLD COURT			C	N	1"		C				SF				Installation record	N		1980		Installation record	N			
2420	INGOLD COURT			C	N	1"		C				SF				Installation record	N		1980		Installation record	N			
2421	INGOLD COURT			C	N	1"		C	3/4"			SF				Installation record	N		1980		Field inspection only	Y			Cross-connection survey
2427	INGOLD COURT			C	N	1"		C	1"			SF				Installation record	N		1980		Field inspection only	Y			Cross-connection survey
2428	INGOLD COURT			C	N	1"		C				SF				Installation record	N		1980		Installation record	N			
2433	INGOLD COURT			C	N	1"		C				SF				Installation record	N		1980		Installation record	N			
2434	INGOLD COURT			C	N	1"		P	1"			SF				Installation record	N		1980		Installation record	N			Cross-connection survey
2440	INGOLD COURT			C	N	1"		C	3/4"			SF				Installation record	N		1980		Field inspection only	Y			Cross-connection survey
2441	INGOLD COURT			C	N	1"		C	1"			SF				Installation record	N		1980		Field inspection only	Y			Cross-connection survey
2445	INGOLD COURT			C	N	1"		C				SF				Installation record	N		1980		Installation record	N			
2446	INGOLD COURT			C	N	1"		C	1"			SF				Installation record	N		1980		Field inspection only	Y			Cross-connection survey
2450	INGOLD COURT			C	N	1"		C				SF				Installation record	N		1980		Installation record	N			
2453	INGOLD COURT			C	N	1"		C				SF				Installation record	N		1980		Installation record	N			
2456	INGOLD COURT			C	N	1"		C	1"			SF				Installation record	N		1980		Field inspection only	Y			Cross-connection survey
2825	JEAN COURT			C	N	1"		C	1"			SF				Installation record	N				Field inspection only	Y			Cross-connection survey
2828	JEAN COURT			C	N	1"		C	1"			SF				Installation record	N				Field inspection only	Y			Cross-connection survey
2837	JEAN COURT			C	N	1"		C	3/4"			SF				Installation record	N				Field inspection only	Y			Cross-connection survey
451	JOANNES AVENUE			P	N	8"		P	1"			NONRES				Installation record	Y				Field inspection only	Y			Cross-connection survey
2039	KASSNER DRIVE			C	N	1"		C				SF				Installation record	N				Installation record	N			
2045	KASSNER DRIVE			C	N	1"		C				SF				Installation record	N				Installation record	N			
2050	KASSNER DRIVE			C	N	1"		C	3/4"			SF				Installation record	N				Field inspection only	Y			Cross-connection survey
2053	KASSNER DRIVE			C	N	1"		C				SF				Installation record	N				Installation record	N			
2059	KASSNER DRIVE			C	N	1"		C	3/4"			SF				Installation record	N				Field inspection only	Y			Cross-connection survey
2060	KASSNER DRIVE			C	N	1"		C	3/4"			SF				Installation record	N				Field inspection only	Y			Cross-connection survey
2065	KASSNER DRIVE			C	N	1"		C				SF				Installation record	N				Installation record	N			
2071	KASSNER DRIVE			C	N	1"		C				SF				Installation record	N				Installation record	N			
2072	KASSNER DRIVE			C	N	1"		C				SF				Installation record	N				Installation record	N			
2077	KASSNER DRIVE			C	N	1"		C	3/4"			SF				Installation record	N				Installation record	N			
2080	KASSNER DRIVE			C	N	1"		C	3/4"			SF				Installation record	N				Field inspection only	Y			Cross-connection survey
2100	KASSNER DRIVE			C	N	1"		C				SF				Installation record	N				Installation record	N			
2101	KASSNER DRIVE			C	N	1"		C	3/4"			SF				Installation record	N				Field inspection only	Y			Cross-connection survey
2107	KASSNER DRIVE			C	N	1"		C	3/4"			SF				Installation record	N				Field inspection only	Y			Cross-connection survey
2110	KASSNER DRIVE			C	N	1"		C				SF				Installation record	N				Installation record	N			
2113	KASSNER DRIVE			C	N	1"		C	3/4"			SF				Installation record	N				Field inspection only	Y			Cross-connection survey
2117	KASSNER DRIVE			C	N	1"		C				SF				Installation record	N				Installation record	N			
2120	KASSNER DRIVE			C	N	1"		C				SF				Installation record	N				Installation record	N			
2125	KASSNER DRIVE			C	N	1"		C	3/4"			SF				Installation record	N				Field inspection only	Y			Cross-connection survey
2130	KASSNER DRIVE			C	N	1"		C	3/4"			SF				Installation record	N				Field inspection only	Y			Cross-connection survey
2131	KASSNER DRIVE			C	N	1"		C	3/4"			SF				Installation record	N				Field inspection only	Y			Cross-connection survey
2139	KASSNER DRIVE			C	N	1"		C	1"			SF				Installation record	N				Field inspection only	Y			Cross-connection survey
2144	KASSNER DRIVE			C	N	1"		C	3/4"			SF				Installation record	N				Installation record	N			
2147	KASSNER DRIVE			C	N	1"		C				SF				Installation record	N				Installation record	N			
2153	KASSNER DRIVE			C	N	1"		C				SF				Installation record	N				Installation record	N			
2154	KASSNER DRIVE			C	N	1"		C				SF				Installation record	N				Installation record	N			
2161	KASSNER DRIVE			C	N	1"		P	1"			SF				Installation record	N				Field inspection only	Y			Cross-connection survey
2165	KASSNER DRIVE			C	N	1"		C	3/4"			SF				Installation record	N				Field inspection only	Y			Cross-connection survey
2170	KASSNER DRIVE			C	N	1"		C	3/4"			SF				Installation record	N				Field inspection only	Y			Cross-connection survey
2173	KASSNER DRIVE			C	N	1"		C	3/4"			SF				Installation record	N				Field inspection only	Y			Cross-connection survey
2178	KASSNER DRIVE			C	N	1"		C	3/4"			SF				Installation record	N				Field inspection only	Y			Cross-connection survey
2194	KASSNER DRIVE			C	N	1"		C	3/4"			SF				Installation record	N				Field inspection only	Y			Cross-connection survey
2195	KASSNER DRIVE			C	N	1"		C				SF				Installation record	N				Installation record	N			
2201	KASSNER DRIVE			C	N	1"		C	3/4"			SF				Installation record	N				Field inspection only	Y			Cross-connection survey
2206	KASSNER DRIVE			C	N	1"		C				SF				Installation record	N				Installation record	N			
2207	KASSNER DRIVE			C	N	1"		C	1"			SF				Installation record	N				Installation record	N			
2215	KASSNER DRIVE			C	N	1"		C	3/4"			SF				Installation record	N				Field inspection only	Y			Cross-connection survey
2220	KASSNER DRIVE			C	N	1"		C	3/4"			SF				Installation record	N				Installation record	N			
2223	KASSNER DRIVE			C	N	1"		C	3/4"			SF				Installation record	N				Field inspection only	Y			Cross-connection survey
2230	KASSNER DRIVE																								



LOCATIONAL IDENTIFIER ADDRESS	LOCATIONAL IDENTIFIER STREET NAME	LOCATIONAL IDENTIFIER UNIT OR SUITE #	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
2231	KASSNER DRIVE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2237	KASSNER DRIVE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
1265	KEN COURT			C	N	3/4"		C	1"		SF						Installation record	N			Installation record	N			Cross-connection survey
1266	KEN COURT			C	N	3/4"		C	1"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
1273	KEN COURT			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1294	KEN DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1295	KEN DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1302	KEN DRIVE			C	N	3/4"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
1321	KEN DRIVE			C	N	3/4"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
1327	KEN DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1330	KEN DRIVE			C	N	3/4"		P	1"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
1338	KEN DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1339	KEN DRIVE			C	N	3/4"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
1345	KEN DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1346	KEN DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1347	KEN DRIVE			C	N	3/4"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
1354	KEN DRIVE			C	N	3/4"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
1357	KEN DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
1374	KEN DRIVE			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2372	KEY WAY			C	N	3/4"		C	1"		SF						Installation record	N			Installation record	N			
2378	KEY WAY			C	N	3/4"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2379	KEY WAY			C	N	3/4"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2384	KEY WAY			C	N	3/4"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2385	KEY WAY			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2390	KEY WAY			C	N	3/4"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
1243	KILLDEER LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1251	KILLDEER LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1252	KILLDEER LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
1259	KILLDEER LANE			C	N	1"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
1260	KILLDEER LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1267	KILLDEER LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1268	KILLDEER LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1275	KILLDEER LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
1278	KILLDEER LANE			C	N	1"		C	1"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
1283	KILLDEER LANE			C	N	1"		C			SF						Installation record	N			Installation record	N			
2370	KIMBERLY STREET			C	N	1"		C	3/4"		MF						Installation record	N			Field inspection only	Y			Cross-connection survey
2371	KIMBERLY STREET			C	N	1"		C			MF						Installation record	N			Installation record	N			
2380	KIMBERLY STREET			C	N	1"		C	1"		MF						Installation record	N			Field inspection only	Y			Cross-connection survey
2381	KIMBERLY STREET			C	N	1"		C	3/4"		MF						Installation record	N			Field inspection only	Y			Cross-connection survey
2396	KIMBERLY STREET			C	N	1"		C	3/4"		MF						Installation record	N			Field inspection only	Y			Cross-connection survey
2397	KIMBERLY STREET			C	N	1"		C	3/4"		MF						Installation record	N			Field inspection only	Y			Cross-connection survey
2415	KIMBERLY STREET			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2431	KIMBERLY STREET			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2436	KIMBERLY STREET			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2437	KIMBERLY STREET			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2444	KIMBERLY STREET			C	N	3/4"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2445	KIMBERLY STREET			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2452	KIMBERLY STREET			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2453	KIMBERLY STREET			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2459	KIMBERLY STREET			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2460	KIMBERLY STREET			C	N	3/4"		C	1"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
2466	KIMBERLY STREET			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2467	KIMBERLY STREET			C	N	3/4"		C			SF						Installation record	N			Installation record	N			
2350	KUBALE LANE			C	N	1"		C	3/4"		SF						Installation record	N	1981		Field inspection only	Y			Cross-connection survey
2351	KUBALE LANE			C	N	1"		C	3/4"		SF						Installation record	N	1981		Field inspection only	Y			Cross-connection survey
2357	KUBALE LANE			C	N	1"		C	3/4"		SF						Installation record	N	1981		Field inspection only	Y			Cross-connection survey
2364	KUBALE LANE			C	N	1"		C			SF						Installation record	N	1981		Installation record	N			
2365	KUBALE LANE			C	N	1"		C	3/4"		SF						Installation record	N	1981		Field inspection only	Y			Cross-connection survey
2371	KUBALE LANE			C	N	1"		C			SF						Installation record	N	1981		Installation record	N			
2376	KUBALE LANE			C	N	1"		C	1"		SF						Installation record	N	1981		Field inspection only	Y			Cross-connection survey
2377	KUBALE LANE			C	N	1"		C			SF						Installation record	N	1981		Installation record	N			
2382	KUBALE LANE			C	N	1"		C			SF						Installation record	N	1981		Installation record	N			
2383	KUBALE LANE			C	N	1"		C	1"		SF						Installation record	N	1981		Field inspection only	Y			Cross-connection survey
2387	KUBALE LANE			C	N	1"		C	1"		SF						Installation record	N	1981		Field inspection only	Y			Cross-connection survey
2388	KUBALE LANE			C	N	1"		C			SF						Installation record	N	1981		Installation record	N			
2393	KUBALE LANE			C	N	1"		C	1"		SF						Installation record	N	1981		Field inspection only	Y			Cross-connection survey
2394	KUBALE LANE			C	N	1"		C			SF						Installation record	N	1981		Installation record	N			
2399	KUBALE LANE			C	N	1"		C	3/4"		SF						Installation record	N	1981		Installation record	N			Cross-connection survey
2400	KUBALE LANE			C	N	1"		C			SF						Installation record	N	1981		Installation record	N			
2405	KUBALE LANE			C	N	1"		C			SF						Installation record	N	1981		Installation record	N			
2406	KUBALE LANE			C	N	1"		C	1"		SF						Installation record	N	1981		Field inspection only	Y			Cross-connection survey
2411	KUBALE LANE			C	N	1"		C	1"		SF						Installation record	N	1981		Installation record	N			Cross-connection survey
2412	KUBALE LANE			C	N	1"		C			SF						Installation record	N	1981		Installation record	N			
2417	KUBALE LANE			C	N	1"		C			SF						Installation record	N	1981		Installation record	N			
2420	KUBALE LANE			C	N	1"		C	3/4"		SF						Installation record	N	1981		Field inspection only	Y			Cross-connection survey
2423	KUBALE LANE			C	N	1"		C	3/4"		SF						Installation record	N	1981		Field inspection only	Y			Cross-connection survey
2426	KUBALE LANE			C	N	1"		C			SF						Installation record	N	1981		Installation record	N			
2431	KUBALE LANE			C	N	1"		C			SF						Installation record	N	1981		Installation record	N			
2434	KUBALE LANE			C	N	1"		C	1"		SF						Installation record	N	1981		Field inspection only	Y			Cross-connection survey
2437	KUBALE LANE			C	N	1"		C	1"		SF						Installation record	N	1981		Field inspection only	Y			Cross-connection survey
2440	KUBALE LANE			C	N	1"		C	1"		SF						Installation record	N	1981		Installation record	N			Cross-connection survey
2443	KUBALE LANE			C	N	1"		C			SF						Installation record	N	1981		Installation record	N			
2446	KUBALE LANE			C	N	1"		C	1"		SF						Installation record	N	1981		Field inspection only	Y			Cross-connection survey
911	LA CROIX AVENUE			C	N	3/4"		C	3/4"		SF						Installation record	N			Field inspection only	Y			Cross-connection survey
912	LA CROIX AVENUE			C	N	3/4"		C			SF						Installation record	N		</					



LOCATIONAL IDENTIFIER ADDRESS	LOCATIONAL IDENTIFIER STREET NAME	LOCATIONAL IDENTIFIER UNIT OR SUITE #	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
1641	LEDVINA STREET			C	N	1"		C			SF						Installation record	Y	1984		Installation record	N			
1646	LEDVINA STREET			C	N	1"		C			SF						Installation record	Y	1984		Installation record	N			
1649	LEDVINA STREET			C	N	1"		C			SF						Installation record	Y	1984		Installation record	N			
1652	LEDVINA STREET			C	N	1"		C			SF						Installation record	Y	1984		Installation record	N			
1657	LEDVINA STREET			C	N	1"		C	3/4"		SF						Installation record	Y	1984		Field inspection only	Y			Cross-connection survey
1660	LEDVINA STREET			C	N	1"		C			SF						Installation record	Y	1984		Installation record	N			
1661	LEDVINA STREET			C	N	1"		C	3/4"		SF						Installation record	Y	1984		Field inspection only	Y			Cross-connection survey
1669	LEDVINA STREET			C	N	1"		C	3/4"		SF						Installation record	Y	1984		Field inspection only	Y			Cross-connection survey
1675	LEDVINA STREET			C	N	1"		C	1"		SF						Installation record	Y	1984		Field inspection only	Y			Cross-connection survey
1681	LEDVINA STREET			C	N	1"		C	1"		SF						Installation record	Y	1984		Field inspection only	Y			Cross-connection survey
2400	LEONA DRIVE			C	N	1"		C	3/4"		SF						Installation record	Y	1973		Field inspection only	Y			Cross-connection survey
2405	LEONA DRIVE			C	N	1"		C			SF						Installation record	Y	1973		Installation record	N			
2406	LEONA DRIVE			C	N	1"		C			SF						Installation record	Y	1973		Installation record	N			
2411	LEONA DRIVE			C	N	1"		C			SF						Installation record	Y	1973		Installation record	N			
2412	LEONA DRIVE			C	N	1"		C			SF						Installation record	Y	1973		Installation record	N			
2417	LEONA DRIVE			C	N	1"		C			SF						Installation record	Y	1973		Installation record	N			
2418	LEONA DRIVE			C	N	1"		C			SF						Installation record	Y	1973		Installation record	N			
2424	LEONA DRIVE			C	N	1"		C			SF						Installation record	Y	1973		Installation record	N			
2428	LEONA DRIVE			C	N	1"		C			SF						Installation record	Y	1973		Installation record	N			
2429	LEONA DRIVE			C	N	1"		C			SF						Installation record	Y	1973		Installation record	N			
2432	LEONA DRIVE			C	N	1"		C			SF						Installation record	Y	1973		Installation record	N			
2436	LEONA DRIVE			C	N	1"		C			SF						Installation record	Y	1973		Installation record	N			
2440	LEONA DRIVE			C	N	1"		C			SF						Installation record	Y	1973		Installation record	N			
2444	LEONA DRIVE			C	N	1"		C			SF						Installation record	Y	1973		Installation record	N			
608	LIDA LANE			C	N	3/4"		C			SF						Installation record	Y	1982		Installation record	N			
610	LIDA LANE			C	N	3/4"		C			SF						Installation record	Y	1982		Installation record	N			
611	LIDA LANE			C	N	3/4"		C			SF						Installation record	Y	1982		Installation record	N			
612	LIDA LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1982		Field inspection only	Y			Cross-connection survey
613	LIDA LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1982		Field inspection only	Y			Cross-connection survey
620	LIDA LANE			C	N	3/4"		C			SF						Installation record	Y	1982		Installation record	N			
621	LIDA LANE			C	N	3/4"		C			SF						Installation record	Y	1982		Installation record	N			
631	LIDA LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1982		Field inspection only	Y			Cross-connection survey
635	LIDA LANE			C	N	3/4"		C			SF						Installation record	Y	1982		Installation record	N			
639	LIDA LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1982		Field inspection only	Y			Cross-connection survey
645	LIDA LANE			C	N	3/4"		C			SF						Installation record	Y	1982		Installation record	N			
646	LIDA LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1982		Field inspection only	Y			Cross-connection survey
650	LIDA LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1982		Field inspection only	Y			Cross-connection survey
651	LIDA LANE			C	N	3/4"		C			SF						Installation record	Y	1982		Installation record	N			
653	LIDA LANE			C	N	3/4"		C			SF						Installation record	Y	1982		Installation record	N			
654	LIDA LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1982		Field inspection only	Y			Cross-connection survey
660	LIDA LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1982		Field inspection only	Y			Cross-connection survey
663	LIDA LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1982		Field inspection only	Y			Cross-connection survey
664	LIDA LANE			C	N	3/4"		C			SF						Installation record	Y	1982		Installation record	N			
669	LIDA LANE			C	N	3/4"		C	1"		SF						Installation record	Y	1982		Field inspection only	Y			Cross-connection survey
672	LIDA LANE			C	N	3/4"		C			SF						Installation record	Y	1982		Installation record	N			
675	LIDA LANE			C	N	3/4"		C			SF						Installation record	Y	1982		Installation record	N			
678	LIDA LANE			C	N	3/4"		C			SF						Installation record	Y	1982		Installation record	N			
679	LIDA LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1982		Field inspection only	Y			Cross-connection survey
684	LIDA LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1982		Installation record	N			Cross-connection survey
685	LIDA LANE			C	N	3/4"		C			SF						Installation record	Y	1982		Installation record	N			
690	LIDA LANE			C	N	3/4"		C			SF						Installation record	Y	1982		Installation record	N			
691	LIDA LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1982		Field inspection only	Y			Cross-connection survey
694	LIDA LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1982		Field inspection only	Y			Cross-connection survey
695	LIDA LANE			C	N	3/4"		C			SF						Installation record	Y	1982		Installation record	N			
700	LIDA LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1982		Field inspection only	Y			Cross-connection survey
701	LIDA LANE			C	N	3/4"		C	1"		SF						Installation record	Y	1982		Installation record	N			Cross-connection survey
707	LIDA LANE			C	N	3/4"		C			SF						Installation record	Y	1982		Installation record	N			
1626	LILY DRIVE			C	N	3/4"		C			SF						Installation record	Y	1966		Installation record	N			
1629	LILY DRIVE			C	N	3/4"		C			SF						Installation record	Y	1966		Installation record	N			
1632	LILY DRIVE			C	N	3/4"		C			SF						Installation record	Y	1966		Installation record	N			
1635	LILY DRIVE			C	N	3/4"		C			SF						Installation record	Y	1966		Installation record	N			
1640	LILY DRIVE			C	N	3/4"		C			SF						Installation record	Y	1966		Installation record	N			
1641	LILY DRIVE			C	N	3/4"		C			SF						Installation record	Y	1966		Installation record	N			
1646	LILY DRIVE			C	N	3/4"		C			SF						Installation record	Y	1966		Installation record	N			
1647	LILY DRIVE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1966		Field inspection only	Y			Cross-connection survey
1652	LILY DRIVE			C	N	3/4"		C			SF						Installation record	Y	1966		Installation record	N			
1655	LILY DRIVE			C	N	3/4"		C			SF						Installation record	Y	1966		Installation record	N			
1660	LILY DRIVE			C	N	3/4"		C	1"		SF						Installation record	Y	1966		Field inspection only	Y			Cross-connection survey
1661	LILY DRIVE			C	N	1"		C	3/4"		MF						Installation record	Y	1966		Field inspection only	Y			Cross-connection survey
1663	LILY DRIVE			C	N	1"		C	3/4"		MF						Installation record	Y	1966		Field inspection only	Y			Cross-connection survey
1667	LILY DRIVE			C	N	1"		C			MF						Installation record	Y	1966		Installation record	N			
1669	LILY DRIVE			C	N	1"		C			MF						Installation record	Y	1966		Installation record	N			
1435	LIMERICK COURT			P	N	1"		P			SF						Installed after lead ban	Y	1995		Installed after lead ban	N			
1440	LIMERICK COURT			P	N	1"		P	1"		SF						Installed after lead ban	Y	1995		Installed after lead ban	Y			Cross-connection survey
1444	LIMERICK COURT			P	N	1"		P	1"		SF						Installed after lead ban	Y	1995		Installed after lead ban	Y			Cross-connection survey
1454	LIMERICK COURT			P	N	1"		C			SF						Installed after lead ban	Y	1995		Installed after lead ban	N			
1460	LIMERICK COURT			P	N	1"		P			SF						Installed after lead ban	Y	1995		Installed after lead ban	N			
1465	LIMERICK COURT			P	N	1"		P	1"		SF						Installed after lead ban	Y	1995		Installed after lead ban	Y			Cross-connection survey
1470	LIMERICK COURT			P	N	1"		C			SF						Installed after lead ban	Y	1995		Installed after lead ban	N			
1475	LIMERICK COURT			P	N	1"		P	3/4"		SF						Installed after lead ban	Y	1995		Installed after lead ban	Y			Cross-connection survey
2893	LIMERICK LANE			P	N	1"		P			SF						Installed after lead ban	Y	1995		Installed after lead ban	N			
2895	LIMERICK LANE			P	N	1"		P			SF						Installed after lead ban	Y	1995		Installed after lead ban	N			
2896	LIMERICK LANE			P	N	1"		P			SF						Installed after lead ban	Y	1995		Installed after lead ban	N			
2898</																									



























LOCATIONAL IDENTIFIER ADDRESS	LOCATIONAL IDENTIFIER STREET NAME	LOCATIONAL IDENTIFIER UNIT OR SUITE #	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION	
2210	ORRIE LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1966	isp during install o	Installation record	N		Cross-connection survey		
2218	ORRIE LANE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1966	isp during install o	Field inspection only	Y		Cross-connection survey		
2234	ORRIE LANE			C	N	3/4"		C	1"		SF						Installation record	Y	1966	isp during install o	Field inspection only	Y		Cross-connection survey		
2720	OTTO COURT			C	N	1"		UNK-NOLG			SF						Installation record	Y	1978	isp during install o	Installation record	N				
2721	OTTO COURT			C	N	1"		C	3/4"		SF						Installation record	Y	1978	isp during install o	Field inspection only	Y		Cross-connection survey		
2724	OTTO COURT			C	N	1"		UNK-NOLG			SF						Installation record	Y	1978	isp during install o	Installation record	N				
2729	OTTO COURT			C	N	1"		C	1"		SF						Installation record	Y	1978	isp during install o	Field inspection only	Y		Cross-connection survey		
2730	OTTO COURT			C	N	1"		C	1"		SF						Installation record	Y	1978	isp during install o	Field inspection only	Y		Cross-connection survey		
2734	OTTO COURT			C	N	1"		UNK-NOLG			SF						Installation record	Y	1978	isp during install o	Installation record	N				
2740	OTTO COURT			C	N	1"		C	3/4"		SF						Installation record	Y	1978	isp during install o	Field inspection only	Y		Cross-connection survey		
2741	OTTO COURT			C	N	1"		UNK-NOLG			SF						Installation record	Y	1978	isp during install o	Installation record	N				
2746	OTTO COURT			C	N	1"		UNK-NOLG			SF						Installation record	Y	1978	isp during install o	Installation record	N				
2753	OTTO COURT			C	N	1"		UNK-NOLG			SF						Installation record	Y	1978	isp during install o	Installation record	N				
2758	OTTO COURT			C	N	1"		UNK-NOLG			SF						Installation record	Y	1978	isp during install o	Installation record	N				
2759	OTTO COURT			C	N	1"		UNK-NOLG			SF						Installation record	Y	1978	isp during install o	Installation record	N				
2764	OTTO COURT			C	N	1"		UNK-NOLG			SF						Installation record	Y	1978	isp during install o	Installation record	N				
2765	OTTO COURT			C	N	1"		UNK-NOLG			SF						Installation record	Y	1978	isp during install o	Installation record	N				
2770	OTTO COURT			C	N	1"		C	3/4"		SF						Installation record	Y	1978	isp during install o	Field inspection only	Y		Cross-connection survey		
2771	OTTO COURT			C	N	1"		UNK-NOLG			SF						Installation record	Y	1978	isp during install o	Installation record	N				
2775	OTTO COURT			C	N	1"		UNK-NOLG			SF						Installation record	Y	1978	isp during install o	Installation record	N				
2776	OTTO COURT			C	N	1"		UNK-NOLG			SF						Installation record	Y	1978	isp during install o	Installation record	N				
2779	OTTO COURT			C	N	1"		UNK-NOLG			SF						Installation record	Y	1978	isp during install o	Installation record	N				
2782	OTTO COURT			C	N	1"		C	3/4"		SF						Installation record	Y	1978	isp during install o	Installation record	N				
2785	OTTO COURT			C	N	1"		UNK-NOLG			SF						Installation record	Y	1978	isp during install o	Installation record	N				
2786	OTTO COURT			C	N	1"		UNK-NOLG			SF						Installation record	Y	1978	isp during install o	Installation record	N				
2793	OTTO COURT			C	N	1"		C	3/4"		SF						Installation record	Y	1978	isp during install o	Installation record	N			Cross-connection survey	
2811	OTTO COURT			C	N	1"		UNK-NOLG			SF						Installation record	Y	1978	isp during install o	Installation record	N				
2817	OTTO COURT			C	N	1"		UNK-NOLG			SF						Installation record	Y	1978	isp during install o	Installation record	N				
2818	OTTO COURT			C	N	1"		UNK-NOLG			SF						Installation record	Y	1978	isp during install o	Installation record	N				
2824	OTTO COURT			C	N	1"		C	1"		SF						Installation record	Y	1978	isp during install o	Field inspection only	Y		Cross-connection survey		
2825	OTTO COURT			C	N	1"		UNK-NOLG			SF						Installation record	Y	1978	isp during install o	Installation record	N				
2831	OTTO COURT			C	N	1"		UNK-NOLG			SF						Installation record	Y	1978	isp during install o	Installation record	N				
2832	OTTO COURT			C	N	1"		UNK-NOLG			SF						Installation record	Y	1978	isp during install o	Installation record	N				
2838	OTTO COURT			C	N	1"		UNK-NOLG			SF						Installation record	Y	1978	isp during install o	Installation record	N				
2844	OTTO COURT			C	N	1"		C	3/4"		SF						Installation record	Y	1978	isp during install o	Field inspection only	Y		Cross-connection survey		
3171	Packerland Dr			P	N	2"		P	1 1/2"		NONRES						Installed after lead ban	Y	2020	isp during install o	Field inspection only	Y		Cross-connection survey		
2304	PACKERLAND DRIVE			C	N	1"		UNK-NOLG			SF						Installation record	N	1973		Field inspection only	Y		Cross-connection survey		
2555	PACKERLAND DRIVE			P	N			P	3"		NONRES						Diameter > 2 inches	N	1993	isp during install o	Field inspection only	Y		Cross-connection survey		
2571	PACKERLAND DRIVE			C	N	1"		C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey		
2581	PACKERLAND DRIVE			C	N	1 1/2"		C	1 1/2"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey		
2600	PACKERLAND DRIVE			C	N	2"		C	2"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey		
2615	PACKERLAND DRIVE			P	N			C	1"		NONRES						Installed after lead ban	N	1993	isp during install o	Field inspection only	Y		Cross-connection survey		
2620	PACKERLAND DRIVE			C	N			P	2"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey		
2625	PACKERLAND DRIVE			C	N	1"		C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey		
2631	PACKERLAND DRIVE	100		C	N	1"		C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey		
2632	PACKERLAND DRIVE			C	N	1 1/2"		C	1 1/2"		NONRES						Installation record	Y	1973	isp during install o	Field inspection only	Y		Cross-connection survey		
2642	PACKERLAND DRIVE			C	N			P	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey		
2648	PACKERLAND DRIVE			C	N			P	4"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey		
2650	PACKERLAND DRIVE			C	N	1"		P	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey		
2651	PACKERLAND DRIVE			C	N	1"		UNK-NOLG			NONRES						Installation record	N	1973		Installation record	N				
2657	PACKERLAND DRIVE			C	N	1"		C			NONRES						Installation record	N	1973		Installation record	N				
2662	PACKERLAND DRIVE			C	N	1"		C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey		
2665	PACKERLAND DRIVE			C	N	1"		UNK-NOLG			NONRES						Installation record	N	1973		Installation record	N				
2670	PACKERLAND DRIVE			C	N	1"		C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey		
2673	PACKERLAND DRIVE			C	N	1"		UNK-NOLG			NONRES						Installation record	N	1973		Installation record	N				
2679	PACKERLAND DRIVE			C	N	1"		C	3/4"		NONRES						Installation record	N	1973		Installation record	N			Cross-connection survey	
2687	PACKERLAND DRIVE			C	N	1"		C	3/4"		NONRES						Installation record	N	1973		Field inspection only	Y		Cross-connection survey		
2688	PACKERLAND DRIVE			C	N	1 1/2"		C	1 1/2"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey		
2695	PACKERLAND DRIVE			C	N	1"		C	1"		NONRES						Installation record	Y	1973	isp during install o	Field inspection only	Y		Cross-connection survey		
2696	PACKERLAND DRIVE	A		C	N	1"		C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey		
2701	PACKERLAND DRIVE			C	N	1"		C	1"		NONRES						Installation record	N	1973		Field inspection only	Y		Cross-connection survey		
2707	PACKERLAND DRIVE			C	N			C	2"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey		
2710	PACKERLAND DRIVE	B		C	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey		
2713	PACKERLAND DRIVE			C	N	1"		C	1"		SF						Installation record	N	1973		Field inspection only	Y		Cross-connection survey		
2735	PACKERLAND DRIVE			C	N	1"		UNK-NOLG			SF						Installation record	N	1973		Installation record	N				
2739	PACKERLAND DRIVE	A		C	N	1"		P	1"		MF						Installation record	N	1973		Field inspection only	Y		Cross-connection survey		
2740	PACKERLAND DRIVE	A		C	N			C	1"		NONRES						Installation record	N			Field inspection only	Y		Cross-connection survey		
2747	PACKERLAND DRIVE			C	N	1"		C	1"		MF						Installation record	N	1973		Field inspection only	Y		Cross-connection survey		
2755	PACKERLAND DRIVE			C	N	1"		C	1"		MF						Installation record	N	1973		Field inspection only	Y		Cross-connection survey		
2763	PACKERLAND DRIVE			C	N	1"		UNK-NOLG			MF						Installation record	N	1973		Installation record	N				
2943	PACKERLAND DRIVE			C	N	1"		C	3/4"		SF						Installation record	N	1973		Field inspection only	Y		Cross-connection survey		
2949	PACKERLAND DRIVE			C	N	1"		UNK-NOLG			SF						Installation record	N	1973		Field inspection only	Y		Cross-connection survey		
2965	PACKERLAND DRIVE			C	N	1"		UNK-NOLG			SF						Installation record	N	1973		Field inspection only	Y		Cross-connection survey		
3101	PACKERLAND DRIVE			P	N	8"		P	4"		NONRES						Installed after lead ban	Y	1996	isp during install o	Field inspection only	Y		Cross-connection survey		
3120	PACKERLAND DRIVE			P	N			C	1 1/2"		NONRES						Installed after lead ban	N	1993	isp during install o	Field inspection only	Y		Cross-connection survey		
3200	PACKERLAND DRIVE	A		P	N	1"		C	1"		NONRES						Installed after lead ban	Y	1994	isp during install o	Field inspection only	Y		Cross-connection survey		
3297	PACKERLAND DRIVE			P	N			P	1 1/2"		SCH/CC						Installed after lead ban	Y	1994	isp during install o	Field inspection only	Y		Cross-connection survey		
3301	PACKERLAND DRIVE	A		P	N			C	1"		NONRES						Installed after lead ban	Y	1994	isp during install o	Field inspection only	Y		Cross-connection survey		
3321	PACKERLAND DRIVE	A		P	N			C	1"		NONRES						Installed after lead ban	Y	1994	isp during install o	Field inspection only	Y		Cross-connection survey		
3376	PACKERLAND DRIVE			P	N			P	1 1/2"		NONRES						Installed after lead ban	Y	1994	isp during install o	Field inspection only	Y		Cross-connection survey		
3377	PACKERLAND DRIVE	1																								



LOCATIONAL IDENTIFIER ADDRESS	LOCATIONAL IDENTIFIER STREET NAME	LOCATIONAL IDENTIFIER UNIT OR SUITE #	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
3685	PACKERLAND DRIVE			C	N	1"		UNK-NOLG			SF						Installation record	N	1973		Installation record	N			
3879	PACKERLAND DRIVE			P	N			C	1 1/2"		NONRES						Installed after lead ban	Y	1994	isp during install o	Field inspection only	Y			Cross-connection survey
1017	PAGELS PLACE			P	N	1"		P	1"		SF						Installation record	Y	2011	isp during install o	Installed after lead ban	Y			Visual insp during install or repair
1018	PAGELS PLACE			P	N	1"		P	1"		SF						Installation record	Y	2011	isp during install o	Installed after lead ban	Y			Visual insp during install or repair
1033	PAGELS PLACE			P	N	1"		P	1"		SF						Installation record	Y	2011	isp during install o	Installed after lead ban	Y			Visual insp during install or repair
1034	PAGELS PLACE			P	N	1"		P	1"		SF						Installation record	Y	2011	isp during install o	Installed after lead ban	Y			Visual insp during install or repair
1041	PAGELS PLACE			P	N	1"		P	1"		SF						Installation record	Y	2011	isp during install o	Installed after lead ban	Y			Visual insp during install or repair
1042	PAGELS PLACE			P	N	1"		P	1"		SF						Installation record	Y	2011	isp during install o	Installed after lead ban	Y			Visual insp during install or repair
1049	PAGELS PLACE			P	N	1"		P	1"		SF						Installation record	Y	2011	isp during install o	Installed after lead ban	Y			Visual insp during install or repair
1050	PAGELS PLACE			P	N	1"		P	1"		SF						Installation record	Y	2011	isp during install o	Installed after lead ban	Y			Visual insp during install or repair
1057	PAGELS PLACE			P	N	1"		P	1"		SF						Installation record	Y	2011	isp during install o	Installed after lead ban	Y			Visual insp during install or repair
1058	PAGELS PLACE			P	N	1"		P	1"		SF						Installation record	Y	2011	isp during install o	Installed after lead ban	Y			Visual insp during install or repair
1525	PARK PLACE			P	N			C	2"		NONRES						Installed after lead ban	Y	1989	isp during install o	Field inspection only	Y			Cross-connection survey
1537	PARK PLACE			P	N			C	2"		NONRES						Installed after lead ban	Y	1989	isp during install o	Field inspection only	Y			Cross-connection survey
1543	PARK PLACE			P	N			C	2"		NONRES						Installed after lead ban	Y	1989	isp during install o	Field inspection only	Y			Cross-connection survey
1551	PARK PLACE			P	N			C	2"		NONRES						Installed after lead ban	Y	1989	isp during install o	Field inspection only	Y			Cross-connection survey
904	PARK RIDGE DRIVE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1962	isp during install o	Installation record	N			
910	PARK RIDGE DRIVE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1962	isp during install o	Installation record	N			
913	PARK RIDGE DRIVE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1962	isp during install o	Installation record	N			
916	PARK RIDGE DRIVE			C	N	3/4"		UNK-NOLG			SF						Installation record	Y	1962	isp during install o	Installation record	N			
919	PARK RIDGE DRIVE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1962	isp during install o	Installation record	N			Cross-connection survey
922	PARK RIDGE DRIVE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1962	isp during install o	Field inspection only	Y			Cross-connection survey
925	PARK RIDGE DRIVE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1962	isp during install o	Field inspection only	Y			Cross-connection survey
928	PARK RIDGE DRIVE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1962	isp during install o	Field inspection only	Y			Cross-connection survey
936	PARK RIDGE DRIVE			C	N	3/4"		C	3/4"		SF						Installation record	Y	1962	isp during install o	Installation record	N			Cross-connection survey
3081	PARKVIEW COURT			C	N	1"		UNK-NOLG			MF						Installed after lead ban	Y	1995	isp during install o	Installed after lead ban	N			
3090	PARKVIEW COURT			C	N	1"		UNK-NOLG			MF						Installed after lead ban	Y	1995	isp during install o	Installed after lead ban	N			
3096	PARKVIEW COURT			C	N	1"		P	3/4"		MF						Installed after lead ban	Y	1995	isp during install o	Field inspection only	Y			Cross-connection survey
3097	PARKVIEW COURT			C	N	1"		C	3/4"		MF						Installed after lead ban	Y	1995	isp during install o	Installed after lead ban	N			Cross-connection survey
3101	PARKVIEW COURT			C	N	1"		P	1"		MF						Installed after lead ban	Y	1995	isp during install o	Field inspection only	Y			Cross-connection survey
3117	PARKVIEW COURT			C	N	1"		C	3/4"		MF						Installed after lead ban	Y	1995	isp during install o	Field inspection only	Y			Cross-connection survey
3120	PARKVIEW COURT			C	N	1"		UNK-NOLG			MF						Installed after lead ban	Y	1995	isp during install o	Installed after lead ban	N			
3121	PARKVIEW COURT			C	N	1"		C	2"		MF						Installed after lead ban	Y	1995	isp during install o	Field inspection only	Y			Cross-connection survey
3122	PARKVIEW COURT			C	N	1"		UNK-NOLG			MF						Installed after lead ban	Y	1995	isp during install o	Installed after lead ban	N			
700	PARKVIEW ROAD			C	N	1"		UNK-NOLG			MF						Installation record	Y	1982	isp during install o	Installation record	N			
701	PARKVIEW ROAD			C	N	1"		C	1"		MF						Installation record	Y	1982	isp during install o	Installation record	N			Cross-connection survey
702	PARKVIEW ROAD			C	N	1"		UNK-NOLG			MF						Installation record	Y	1982	isp during install o	Installation record	N			
703	PARKVIEW ROAD			C	N	1"		C	1"		MF						Installation record	Y	1982	isp during install o	Field inspection only	Y			Cross-connection survey
706	PARKVIEW ROAD			C	N	1"		UNK-NOLG			MF						Installation record	Y	1982	isp during install o	Installation record	N			
707	PARKVIEW ROAD			C	N	1"		P	3/4"		MF						Installation record	Y	1982	isp during install o	Field inspection only	Y			Cross-connection survey
708	PARKVIEW ROAD			C	N	1"		UNK-NOLG			MF						Installation record	Y	1982	isp during install o	Installation record	N			
709	PARKVIEW ROAD			C	N	1"		UNK-NOLG			MF						Installation record	Y	1982	isp during install o	Installation record	N			
712	PARKVIEW ROAD			C	N	1"		UNK-NOLG			MF						Installation record	Y	1982	isp during install o	Installation record	N			
713	PARKVIEW ROAD			C	N	1"		C	1"		MF						Installation record	Y	1982	isp during install o	Field inspection only	Y			Cross-connection survey
714	PARKVIEW ROAD			C	N	1"		P	1"		MF						Installation record	Y	1982	isp during install o	Installation record	N			Cross-connection survey
715	PARKVIEW ROAD			C	N	1"		P	1 1/2"		MF						Installation record	Y	1982	isp during install o	Field inspection only	Y			Cross-connection survey
724	PARKVIEW ROAD			C	N	1"		UNK-NOLG			SF						Installation record	Y	1982	isp during install o	Installation record	N			
741	PARKVIEW ROAD			C	N	1"		UNK-NOLG	1"		SF						Installation record	Y	1982	isp during install o	Installation record	N			Cross-connection survey
750	PARKVIEW ROAD			C	N			P	1"		NONRES						Installation record	Y			Field inspection only	Y			Cross-connection survey
751	PARKVIEW ROAD			C	N	1"		C	3/4"		SF						Installation record	Y	1982	isp during install o	Field inspection only	Y			Cross-connection survey
780	PARKVIEW ROAD			C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y			Cross-connection survey
790	PARKVIEW ROAD			C	N			P	1"		NONRES						Installation record	Y			Field inspection only	Y			Cross-connection survey
807	PARKVIEW ROAD			C	N			C	1 1/4"		NONRES						Installation record	Y			Field inspection only	Y			Cross-connection survey
810	PARKVIEW ROAD			C	N			P	1"		NONRES						Installation record	Y			Field inspection only	Y			Cross-connection survey
821	PARKVIEW ROAD			P	N			DI	4"		NONRES						Installation record	Y			Field inspection only	Y			Cross-connection survey
885	PARKVIEW ROAD			C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y			Cross-connection survey
901	PARKVIEW ROAD			C	N			P	1"		NONRES						Installation record	Y			Field inspection only	Y			Cross-connection survey
974	PARKVIEW ROAD			C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y			Cross-connection survey
975	PARKVIEW ROAD	1		P	N			DI	4"		NONRES						Installation record	Y			Field inspection only	Y			Cross-connection survey
984	PARKVIEW ROAD	A		C	N			P	1"		NONRES						Installation record	Y			Field inspection only	Y			Cross-connection survey
1011	PARKVIEW ROAD			C	N			C	1 1/2"		NONRES						Installation record	Y			Field inspection only	Y			Cross-connection survey
1014	PARKVIEW ROAD	A		C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y			Cross-connection survey
1030	PARKVIEW ROAD			C	N			C	1 1/2"		NONRES						Installation record	Y			Field inspection only	Y			Cross-connection survey
1044	PARKVIEW ROAD			C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y			Cross-connection survey
1055	PARKVIEW ROAD			C	N			P	2"		NONRES						Installation record	Y			Field inspection only	Y			Cross-connection survey
1067	PARKVIEW ROAD			C	N			P	1"		NONRES						Installation record	Y			Field inspection only	Y			Cross-connection survey
1085	PARKVIEW ROAD			C	N			C	1"		NONRES						Installation record	Y			Field inspection only	Y			Cross-connection survey
1179	PARKVIEW ROAD																								











LOCATIONAL IDENTIFIER ADDRESS	LOCATIONAL IDENTIFIER STREET NAME	LOCATIONAL IDENTIFIER UNIT OR SUITE #	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
2770	S ASHLAND AVENUE			UNK-NOLG	N				3/4"			NONRES					Installation record	N			Field inspection only	Y			Cross-connection survey
2800	S ASHLAND AVENUE			C	N			P	1"			NONRES					Installation record	Y			Field inspection only	Y			Cross-connection survey
2830	S ASHLAND AVENUE			C	N			P	1"			NONRES					Installation record	Y			Field inspection only	Y			Cross-connection survey
2850	S ASHLAND AVENUE			UNK-NOLG	N			P	3"			NONRES					Diameter > 2 inches	Y			Field inspection only	Y			Cross-connection survey
1919	S BROADWAY			C	N			P	2"			NONRES					Installation record	Y			Field inspection only	Y			Cross-connection survey
1930	S BROADWAY			C	N			P	2"			NONRES					Installation record	Y			Field inspection only	Y			Cross-connection survey
2052	S BROADWAY			P	N	1"		C	3/4"			SF					SL repair/replace record	Y	2000		Field inspection only	Y			Cross-connection survey
2056	S BROADWAY			P	N	1"		C				SF					SL repair/replace record	Y	2000		Field inspection only	Y			Cross-connection survey
2092	S BROADWAY			P	N	1"		C				SF					SL repair/replace record	Y	2000		Installation record	N			Cross-connection survey
2096	S BROADWAY			P	N	1"		C	3/4"			SF					SL repair/replace record	Y	2000		Field inspection only	Y			Cross-connection survey
2108	S BROADWAY			P	N	1"		C				SF					SL repair/replace record	Y	2000		Installation record	N			Cross-connection survey
2109	S BROADWAY			P	N	1"		C				SF					SL repair/replace record	Y	2000		Field inspection only	Y			Cross-connection survey
2116	S BROADWAY			P	N	1"		C	3/4"			SF					SL repair/replace record	Y	2000		Field inspection only	Y			Cross-connection survey
2117	S BROADWAY			P	N	1"		C	3/4"			SF					SL repair/replace record	Y	2000		Field inspection only	Y			Cross-connection survey
2120	S BROADWAY			P	N	1"		C				SF					SL repair/replace record	Y	2000		Installation record	N			Cross-connection survey
2121	S BROADWAY			P	N	1"		C				SF					SL repair/replace record	Y	2000		Field inspection only	Y			Cross-connection survey
2125	S BROADWAY			P	N	1"		C				SF					SL repair/replace record	Y	2000		Installation record	N			Cross-connection survey
2128	S BROADWAY			P	N	1"		C				SF					SL repair/replace record	Y	2000		Installation record	N			Cross-connection survey
2129	S BROADWAY			P	N	1"		C				SF					SL repair/replace record	Y	2000		Installation record	N			Cross-connection survey
2132	S BROADWAY			P	N	1"		C				SF					SL repair/replace record	Y	2000		Field inspection only	Y			Cross-connection survey
2135	S BROADWAY			P	N	1"		P	1"			SF					SL repair/replace record	Y	2000		Field inspection only	Y			Cross-connection survey
2136	S BROADWAY			P	N	1"		C	3/4"			SF					SL repair/replace record	Y	2000		Field inspection only	Y			Cross-connection survey
2149	S BROADWAY			P	N	1"		C				SF					SL repair/replace record	Y	2000		Installation record	N			Cross-connection survey
2150	S BROADWAY			P	N	1"		C				SF					SL repair/replace record	Y	2000		Installation record	N			Cross-connection survey
2151	S BROADWAY			P	N	1"		C				MF					SL repair/replace record	Y	2000		Installation record	N			Cross-connection survey
2157	S BROADWAY			P	N	1"		C				SF					SL repair/replace record	Y	2000		Installation record	N			Cross-connection survey
2159	S BROADWAY			P	N	1"		P				SF					SL repair/replace record	Y	2000		Field inspection only	Y			Cross-connection survey
2191	S BROADWAY			P	N	1"		C				SF					SL repair/replace record	Y	2000		Installation record	N			Cross-connection survey
2192	S BROADWAY			P	N	1"		P	1"			SF					SL repair/replace record	Y	2000		Field inspection only	Y			Cross-connection survey
2196	S BROADWAY			P	N	1"		C	3/4"			SF					SL repair/replace record	Y	2000		Field inspection only	Y			Cross-connection survey
2197	S BROADWAY			P	N	1"		C				SF					SL repair/replace record	Y	2000		Field inspection only	Y			Cross-connection survey
2203	S BROADWAY			P	N	1"		C	3/4"			MF					SL repair/replace record	Y	2000		Installation record	N			Cross-connection survey
2208	S BROADWAY			P	N	1"		C	3/4"			SF					SL repair/replace record	Y	2000		Field inspection only	Y			Cross-connection survey
2218	S BROADWAY			P	N	1"		C	3/4"			SF					SL repair/replace record	Y	2000		Field inspection only	Y			Cross-connection survey
2221	S BROADWAY			P	N	1"		C	3/4"			SF					SL repair/replace record	Y	2000		Field inspection only	Y			Cross-connection survey
2222	S BROADWAY			P	N	1"		C				SF					SL repair/replace record	Y	2000		Installation record	N			Cross-connection survey
2224	S BROADWAY			P	N	1"		C				SF					SL repair/replace record	Y	2000		Field inspection only	Y			Cross-connection survey
2236	S BROADWAY			P	N	1"		C	3/4"			SF					SL repair/replace record	Y	2000		Field inspection only	Y			Cross-connection survey
2245	S BROADWAY			P	N	1"		C				SF					SL repair/replace record	Y	2000		Installation record	N			Cross-connection survey
2249	S BROADWAY			P	N	1"		C	3/4"			SF					SL repair/replace record	Y	2000		Field inspection only	Y			Cross-connection survey
2253	S BROADWAY			P	N	1"		C				SF					SL repair/replace record	Y	2000		Installation record	N			Cross-connection survey
2257	S BROADWAY			P	N	1"		C	3/4"			SF					SL repair/replace record	Y	2000		Field inspection only	Y			Cross-connection survey
2261	S BROADWAY			P	N	1"		C	3/4"			SF					SL repair/replace record	Y	2000		Field inspection only	Y			Cross-connection survey
2273	S BROADWAY			P	N	1"		C				SF					SL repair/replace record	Y	2000		Installation record	N			Cross-connection survey
2280	S BROADWAY			C	N			C	2"			SCH/CC					Installation record	Y			Field inspection only	Y			Cross-connection survey
2285	S BROADWAY			P	N			DI	4"			NONRES			8" main feed this property		Installed after lead ban	Y	2001	isp during install o	Field inspection only	Y			Cross-connection survey
2490	S BROADWAY			P	N			P	1"			NONRES					Installed after lead ban	Y	1998	isp during install o	Field inspection only	Y			Cross-connection survey
2531	S BROADWAY			P	N			DI	4"			NONRES					Diameter > 2 inches	Y			Field inspection only	Y			Cross-connection survey
2538	S BROADWAY			P	N			C	1 1/2"			NONRES					Installed after lead ban	Y	1998	isp during install o	Field inspection only	Y			Cross-connection survey
2561	S BROADWAY			P	N	6"		DI	6"			NONRES					Installed after lead ban	Y	1998	isp during install o	Field inspection only	Y			Cross-connection survey
2580	S BROADWAY			P	N			DI	8"			NONRES					Diameter > 2 inches	Y			Field inspection only	Y			Cross-connection survey
2612	S BROADWAY			P	N			C	4"			NONRES					Diameter > 2 inches	Y			Field inspection only	Y			Cross-connection survey
2660	S BROADWAY			P	N			DI	4"			NONRES					Diameter > 2 inches	Y			Field inspection only	Y			Cross-connection survey
2700	S BROADWAY			P	N	2"		C	1"			NONRES					Installed after lead ban	Y	1998	isp during install o	Field inspection only	Y			Cross-connection survey
2741	S BROADWAY			P	N	1"		C				SF					SL repair/replace record	Y	2000		Field inspection only	Y			Cross-connection survey
2785	S BROADWAY			P	N	1"		C	3/4"			SF					SL repair/replace record	Y	1998		Field inspection only	Y			Cross-connection survey
2795	S BROADWAY			P	N	1"		C	3/4"			SF					SL repair/replace record	Y	1998		Field inspection only	Y			Cross-connection survey
2805	S BROADWAY			P	N	1"		P	1"			SF					SL repair/replace record	Y	1998		Field inspection only	Y			Cross-connection survey
2817	S BROADWAY			P	N	1"		C				SF					SL repair/replace record	Y	1998		Installation record	N			Cross-connection survey
2839	S BROADWAY			P	N	1"		C	3/4"			SF					SL repair/replace record	Y	1998		Field inspection only	Y			Cross-connection survey
2853	S BROADWAY			P	N	1"		P	1"			SF					SL repair/replace record	Y	1998		Field inspection only	Y			Cross-connection survey
2867	S BROADWAY			P	N	1"		C	1"			SF					SL repair/replace record	Y	1998		Field inspection only	Y			Cross-connection survey
2870	S BROADWAY			P	N			C	1 1/2"			NONRES					Installed after lead ban	Y	2004	isp during install o	Field inspection only	Y			Cross-connection survey
2871	S BROADWAY			P	N	1"		C				MF					SL repair/replace record	Y	1998		Installation record	N			Cross-connection survey
2872	S BROADWAY			P	N			P	2"			NONRES					Installation record	Y			Field inspection only	Y			Cross-connection survey
2876	S BROADWAY			P	N			P	2"			NONRES					Installation record	Y			Field inspection only	Y			Cross-connection survey
2878	S BROADWAY			P	N			C	2"			NONRES					Installed after lead ban	Y	2004	isp during install o	Field inspection only	Y			Cross-connection survey
2881	S Broadway			P	N			DI	4"			NONRES					Diameter > 2 inches	Y			Field inspection only	Y			Cross-connection survey
2141	S COURTLAND DRIVE			P	N	1"		C				SF					Installed after lead ban	Y	1992		Installation record	N			Cross-connection survey
2150	S COURTLAND DRIVE			P	N	1"		P	1"			SF					Installed after lead ban	Y	1992		Field inspection only	Y			Cross-connection survey
2151	S COURTLAND DRIVE			P	N	1"		P	1"			SF					Installed after lead ban	Y	1992		Field inspection only	Y			Cross-connection survey
2160	S COURTLAND DRIVE			P	N	1"		P	1"			SF					Installed after lead ban	Y	1992		Field inspection only	Y			Cross-connection survey
2161	S COURTLAND DRIVE			P	N	1"		C	3/4"			SF					Installed after lead ban	Y	1992		Field inspection only	Y			Cross-connection survey
2166	S COURTLAND DRIVE			P	N	1"		C	3/4"			SF					Installed after lead ban	Y	1992		Field inspection only	Y			Cross-connection survey
2167	S COURTLAND DRIVE			P	N	1"		C	1"			SF					Installed after lead ban	Y	1992		Field inspection only	Y			Cross-connection survey
2170	S COURTLAND DRIVE			P	N	1"		C				SF					Installed after lead ban	Y	1992		Installation record	N			Cross-connection survey
2171	S COURTLAND DRIVE			P	N	1"		C				SF					Installed after lead ban	Y	1992		Installation record	N			Cross-connection survey
2174	S COURTLAND DRIVE			P	N	1"		C				SF					Installed after lead ban	Y	1992		Installation record	N			Cross-connection survey
2175	S COURTLAND DRIVE			P	N	1"		C				SF					Installed after lead ban	Y	1992		Installation record	N			Cross-connection survey
2302	S Oneida St			P	N			P	2"			NONRES					Installed after lead ban	Y	1998-2011	isp during install o	Field inspection only				









































LOCATIONAL IDENTIFIER ADDRESS	LOCATIONAL IDENTIFIER STREET NAME	LOCATIONAL IDENTIFIER UNIT OR SUITE #	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
3635	WOODS EDGE WAY			P	N	1"		P	1"		SF						Installation record	Y	2013	isp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3641	WOODS EDGE WAY			P	N	1"		P	1"		SF						Installation record	Y	2013	isp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3647	WOODS EDGE WAY			P	N	1"		P	1"		SF						Installation record	Y	2013	isp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3655	WOODS EDGE WAY			P	N	1"		P	1"		SF						Installation record	Y	2013	isp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3661	WOODS EDGE WAY			P	N	1"		P	1"		SF						Installation record	Y	2013	isp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3667	WOODS EDGE WAY			P	N	1"		P	1"		SF						Installation record	Y	2013	isp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3675	WOODS EDGE WAY			P	N	1"		P	1"		SF						Installation record	Y	2013	isp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3681	WOODS EDGE WAY			P	N	1"		P	1"		SF						Installation record	Y	2013	isp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3689	WOODS EDGE WAY			P	N	1"		P	1"		SF						Installation record	Y	2013	isp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3697	WOODS EDGE WAY			P	N	1"		P	1"		SF						Installation record	Y	2013	isp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3698	WOODS EDGE WAY			P	N	1"		P	1"		SF						Installation record	Y	2013	isp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3702	WOODS EDGE WAY			P	N	1"		P	1"		SF						Installation record	Y	2013	isp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3703	WOODS EDGE WAY			P	N	1"		P	1"		SF						Installation record	Y	2013	isp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3706	WOODS EDGE WAY			P	N	1"		P	1"		SF						Installation record	Y	2013	isp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3709	WOODS EDGE WAY			P	N	1"		P	1"		SF						Installation record	Y	2013	isp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3710	WOODS EDGE WAY			P	N	1"		P	1"		SF						Installation record	Y	2013	isp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3713	WOODS EDGE WAY			P	N	1"		P	1"		SF						Installation record	Y	2013	isp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3717	WOODS EDGE WAY			P	N	1"		P	1"		SF						Installation record	Y	2013	isp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3721	WOODS EDGE WAY			P	N	1"		P	1"		SF						Installation record	Y	2013	isp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3725	WOODS EDGE WAY			P	N	1"		P	1"		SF						Installation record	Y	2013	isp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3729	WOODS EDGE WAY			P	N	1"		P	1"		SF						Installation record	Y	2013	isp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3733	WOODS EDGE WAY			P	N	1"		P	1"		SF						Installation record	Y	2013	isp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3739	WOODS EDGE WAY			P	N	1"		P	1"		SF						Installation record	Y	2013	isp during install o	Installed after lead ban	Y		Visual insp during install or repair	
3745	WOODS EDGE WAY			P	N	1"		P	1"		SF						Installation record	Y	2013	isp during install o	Installed after lead ban	Y		Visual insp during install or repair	
1310	WREN LANE			C	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1988	isp during install o	Installed after lead ban	N			
1320	WREN LANE			C	N	1"		C	1"		SF						Installed after lead ban	Y	1988	isp during install o	Field inspection only	Y		Cross-connection survey	
1321	WREN LANE			C	N	1"		C	3/4"		SF						Installed after lead ban	Y	1988	isp during install o	Field inspection only	Y		Cross-connection survey	
1330	WREN LANE			C	N	1"		C	1"		SF						Installed after lead ban	Y	1988	isp during install o	Field inspection only	Y		Cross-connection survey	
1331	WREN LANE			C	N	1"		C	1"		SF						Installed after lead ban	Y	1988	isp during install o	Installed after lead ban	N		Cross-connection survey	
1340	WREN LANE			C	N	1"		UNK-NOLG			SF						Installed after lead ban	Y	1988	isp during install o	Installed after lead ban	N			
1341	WREN LANE			C	N	1"		C	3/4"		SF						Installed after lead ban	Y	1988	isp during install o	Field inspection only	Y		Cross-connection survey	
1345	WREN LANE			C	N	1"		P	1"		SF						Installed after lead ban	Y	1988	isp during install o	Installed after lead ban	N		Cross-connection survey	
1346	WREN LANE			C	N	1"		C	1"		SF						Installed after lead ban	Y	1988	isp during install o	Field inspection only	Y		Cross-connection survey	